

# Stage 2 Structural Assessment Report

Mayo County Council

January 2025



### **Notice**

This document and its contents have been prepared and are intended solely as information for Mayo County Council and use in relation to TO315 Mayo Bridges Assessments & Strengthening 2023.

WS Atkins Ireland Limited assumes no responsibility to any other party in respect of or arising out of or in connection with this document and/or its contents.

### **Document history**

Document title: MO-N58-001.00 Strade River Bridge Stage 2 Assessment

Document reference: 0088572DG0018


Revision	Purpose description	Originated	Checked	Reviewed	Authorised	Date
0.0	Draft for Comment	POS	VP	MG	MJ	22/10/2024
1.0	Final Issue	POS	MG	MJ	MJ	31/01/2025

### **Client signoff**

Client	Mayo County Council
Project	TASK ORDER NO.315 MAYO BRIDGE ASSESSMENTS & STRENGTHENING 2023
Job number	0088572
Client	

signature/date







### Task Order No.315- Mayo Bridge Assessments

### **Contents**

1.	Introduction						
	1.1	Background information covering the origins for the need for the structural assessment	1				
	1.2	Previous reports and their recommendations	1				
2.	Execu	tive Summary	2				
3.	Struct	ure Description	3				
	3.1	General description of structure	3				
	3.2	Span arrangements	3				
	3.3	Foundation Type	3				
	3.4	Substructure	3				
	3.5	Superstructure	3				
	3.6	Articulation arrangements, joints and bearings	3				
	3.7	Parapet	3				
	3.8	Materials	4				
	3.9	Changes to Material Properties	4				
4.	Stage	1 Structural Assessment Summary	4				
	4.1	Date of assessment	4				
	4.2	Assessing organisation	4				
	4.3	Review of testing undertaken as part of Stage 1 Assessment	4				
	4.4	Review of the results of the Stage 1 Structural Assessment	4				
	4.5	Extent to which the structure failed the assessment	5				
	4.6 assess	Detailed commentary on the significance of all of the original assumptions made during the stage 1 sment in terms of the assessed capacity of the structure					
	4.7	Mode of failure	5				
	4.8	Details of any strengthening works undertaken as a result of the assessment	5				
	4.9 assess	Description of any changes to the load effects or assessment resistance since the original sment	6				
	4.10	Results of any monitoring or inspections undertaken	6				
	4.11	The assessed capacity	6				
5.	Stage	2 Structural Assessment Inspection Summary	6				
	5.1	Detailed description of the findings of the visual inspection	6				
	5.2 structu	Identification and justification of the condition factor used in the assessment calculations for each	8				
	5.3	Detailed description of the testing undertaken	8				
	5.4	Results of all testing undertaken	9				



	5.5	Summary of safety partial factors used in the assessment	9
	5.6	Summary of all material properties used in the assessment	9
6.	Assess	sment Method1	0
	6.1	Summary of analysis methodology undertaken as part of Stage 1 Structural Assessment1	0
		Detailed description of method of analysis undertaken for Stage 2 analysis including justification as this has led to an increase in the assessed capacity for the superstructure, substructure and ions	
	6.3	Description of the model and software used for the analysis1	0
	6.4	Assessment live loading1	1
	6.5	Abnormal loading1	1
	6.6	Additional loading requirements1	1
7.	Assess	sment Commentary1	1
	7.1	Assumptions made during the Stage 2 Structural Assessment	1
	7.2	Significance of these assumptions in relation to the overall capacity of the structure or element1	1
8.	Assess	sment Results1	2
9.	Recom	mendations1	3
Appen	dix A.	Archive Information about the Structure	
Appen	dix B.	Results of Additional Literature Search	
Appen	dix C.	General Arrangement Drawings	
Appen	dix D.	Structural Condition Drawing	
Appen	dix E.	Copy of Materials Testing Report	
Appen	dix F.	Structure Idealisation Model and Model Inputs	
Appen	dix G.	Calculations	
Appen	dix H.	Photographs	



### 1. Introduction

AtkinsRéalis were appointed by Mayo County Council for Eirspan Task Order 315 – Mayo Bridge Assessments and Strengthening 2023, comprising the assessment and rehabilitation of 10no. bridges on the national road network throughout County Mayo. 7no. structures required structural assessment to determine the condition of the structures and their load-carrying capacity for HA, HB and SV loading. The assessment of the structures was undertaken in accordance with TII Publications AM-STR-06056 Stage 1 Structural Assessment of Road Structures and AM-STR-06057 Stage 2 Structural Assessment of Sub-Standard Road Structures.

The assessment of MO-N58-001.00 Strade River Bridge comprised the Stage 2 assessment of the 2no. span filler beam slab structure.

### 1.1 Background information covering the origins for the need for the structural assessment

The need for the Stage 2 structural assessment was outlined in the recommendations of the 2012 Stage 1 assessment report, refer to Appendix A of this report for the Stage 1 Assessment Report. The Stage 1 Assessment determined a bending capacity of 18t and a shear capacity of 40t for the structure but less than 3t capacity for bond with the low concrete strength and area of steel found to be the cause of low structural capacity.

### 1.2 Previous reports and their recommendations

The following table outlines the previous reports, with the 2012 Stage 1 assessment report recommending that a Stage 2 assessment be undertaken to the structure. The 2024 Principal Inspection report found the structure to be in poor condition due to the spalling and delamination to the deck slab soffit.

Table 1-1 Previous Reports

Document Reference	Document Title
-	Strade River Bridge Stage 1 Assessment Report (May 2012)
-	MO-N58-001.00 Strade River Bridge PI Report (May 2024)



### 2. Executive Summary

MO-N58-001.00 Strade River Bridge carries the N58 National Secondary Road over the Strade River in Co. Mayo. The structure comprises a two span filler beam deck structure with the filler beam deck slab comprising railway girders encased in concrete and supported on a mass concrete pier and abutments. The structure has skew span lengths of 3.82m and 3.79m for the south and north spans respectively with an overall structure length of 8.6m. The structure has a skew of 26 degrees. The overall width out-to-out of the structure is 10.3m.

The assessment of the structure comprised the Stage 2 assessment of the 2no. span filler beam slab structure. The need for the Stage 2 structural assessment was outlined in the recommendations of the Stage 1 assessment report completed by Atkins in May 2012. The Stage 1 Assessment determined a bending capacity of 18t and a shear capacity of 40t for the structure but less than 3t capacity for bond with the low concrete strength and area of steel found to be the cause of low structural capacity.

A visual inspection for the Stage 2 assessment was undertaken by Atkins in July 2024 with the structure in poor overall condition due to the extensive spalling and delamination noted to the deck soffit. Structural investigations were also undertaken to the structure by Triur Construction Ltd. in July 2024 to confirm the parameters for the Stage 2 assessment.

The initial assessment of the filler beam deck slab was carried out using the strip analysis method as per *AM-STR-06026* and *AM-STR-06037* followed by a grillage analysis as per *AM-STR-06057*. The assessment live loading comprised 40t HA loading in accordance with TII Publication *AM-STR-06026*. Abnormal loading considered as part of the assessment comprised SV196 loading in accordance with TII Publication *AM-STR-06048* The Assessment of Road Bridges and Structures for the Effects of Abnormal and Exceptional Abnormal Load Vehicles using SV and SOV Load Models and 45 Units HB loading in accordance with *AM-STR-06030 Loads for Highway Bridges*.

The initial strip analysis showed a bending capacity of 3t HA loading alone, with no capacity for HB and SV loading. The filler beam was found unsuitable for composite action as it failed under the bond stress check, resulting in a bond capacity of less than 3t GVW.

The grillage analysis determined a reduction in the assessment load effects due to the transverse distributions of loads, which resulted in a bending capacity of 40t GVW for the structure when considering composite action. The bond capacity of the section limits the slab capacity to 7.5t however.

Structure ID	Structure Name	Structure Type	No. of Spans	Span Length	Assessed Capacity (ALL)	HB Capacity	SV Capacity
MO-N58-001.00	Strade Bridge	Filler Beam	2	3.79m(north) 3.82m(south)	7.5t	Fails HB30 units	Fails SV80

Based on the findings of the assessment the structure is determined to have a reduced load capacity due to bond failure between the concrete and steel beams with the significant delamination and spalling visible to the deck slab soffit providing evidence of the issue. As a result no further assessment measures are deemed required for the structure as they are not likely to increase the bond capacity to 40t loading due to the low compressive strength values found for the concrete in the soffit of the structure.

The deck slab is therefore recommended to be removed and a new deck installed across the structure, in either a single or two span structural arrangement.

Although there are extensive defects to the deck soffit as there is no evidence of failure or excess deformation of the slab a load restriction is not recommended at this time. Monitoring of the structure should be taken annually however to check for any further evidence of deformation or failure of the deck. Regular term maintenance should also be undertaken to the structure to maintain its condition in the interim.



### 3. Structure Description

### 3.1 General description of structure

MO-N58-001.00 Strade River Bridge carries the N58 National Secondary Road over the Strade River in Co. Mayo. The structure comprises a two span filler beam deck structure with the filler beam deck slab comprising railway girders encased in concrete and supported on mass concrete piers and abutments.

The structure has square spans of 3.44m and 3.42m and skew spans of 3.82m and 3.79m for the south and north spans respectively. The overall square length of the structure is 7.59m with a skew length of 8.6m. The structure has a skew of 26 degrees.

The overall kerb-to-kerb width on the bridge is 6.90m with the carriageway measuring 5.70m wide. Concrete verges are provided across the structure measuring 1.1m and 1.7m wide respectively with concrete parapets also provided measuring 900mm and 750mm high respectively. The overall width out-to-out of the structure is 10.3m square to the carriageway with a skewed width of 11.4m.

### 3.2 Span arrangements

The structure comprises 2no. spans measuring as follows: South Span = 3.82m (square 3.42m) North Span = 3.79m (square 3.44m)

### 3.3 Foundation Type

Unknown.

### 3.4 Substructure

The substructure comprises mass concrete abutments, pier and wing walls.

### 3.5 Superstructure

The superstructure comprises a filler beam deck slab formed by railway girders. The average thickness of the filler beam deck slab is 310mm.

### 3.6 Articulation arrangements, joints and bearings

The spans are separated by a transverse joint across the central pier with the support conditions considered as simply supported for the purpose of assessment.

### 3.7 Parapet

The parapets are of mass concrete construction with heights of 750mm and 900mm. The parapets have a thickness of 290mm.



### 3.8 Materials

The superstructure is comprised of steel railway girders and secondary reinforcement encased in concrete and the substructure comprises mass concrete.

### 3.9 Changes to Material Properties

The Stage 1 investigation report found the estimated worst credible concrete strength of the deck slab to be 13.3 N/mm<sup>2</sup>. Further concrete strength testing undertaken as part of the Stage 2 assessment determined an increased concrete strength of 18.9 N/mm<sup>2</sup>, accredited to a lower void % found in the core samples.

### 4. Stage 1 Structural Assessment Summary

### 4.1 Date of assessment

31st May 2012.

### 4.2 Assessing organisation

Atkins.

### 4.3 Review of testing undertaken as part of Stage 1 Assessment

The testing undertaken as part of the Stage 1 assessment comprised the following:

- 1no. trial pit was excavated over the filler beam deck to establish the internal thickness of the slab and the depth of the fill.
- Covermeter survey at 4 different locations at the soffit of the RC beam and slab to identify the reinforcing bar spacing, arrangement and orientation.
- 2no. concrete breakouts at the base of the slab to determine articulation details
- 3no. concrete cores drilled from the deck soffit of each span for the compressive strength testing of the concrete.

### 4.4 Review of the results of the Stage 1 Structural Assessment

Stage 1 assessment was carried out for filler beam structure in accordance with UK Highways Agency Design Manual for Roads and Bridges (BD21/01, BD44/95 & BD44/96). The structure was assessed using the strip method for HA loading, single axle and single wheel loads in accordance with BD21/01 and the methods outlined in BD44/95. Each span was assessed separately.



The live load capacity of both spans was 7.5 tonnes Gross Vehicle Weight (GVW) for bending and 40 tonnes for shear. An additional check carried out on the bond also indicated the capacity of the structure of less than 3 tonnes assessment loading for both spans.

As the adequacy of the structures in bending for 40t live loading was 60% for span 1 and 73% for span 2 using the strip method, a grillage analysis was carried out, which increased the load capacity of the structure in bending to 18 tonnes assessment loading for Span 1 and to 40 tonnes for Span 2. The variation in capacity was due to the variation in concrete strengths found in both spans.

The structure was also assessed for 45 units of HB live loading as per BD37/01. The results indicated that the structure had a HB rating of 30HB units for bending and 45HB units for shear, while for bond the structure had less than 30HB units capacity.

### 4.5 Extent to which the structure failed the assessment

The filler beam deck was found to have a sufficient capacity of 40t for span 2 and have a reduced capacity of 18t in bending for span 1 due to the decreased concrete strength found. Both spans had sufficient capacity of 40t in shear but had less than 3t capacity in bond.

# 4.6 Detailed commentary on the significance of all of the original assumptions made during the stage 1 assessment in terms of the assessed capacity of the structure

A condition factor of 0.9 was assumed for both spans of the structure based on the condition of the structure at the time of assessment with water seepage and calcite staining evident. The shear at supports was assumed to be carried by the steel sections only with a 40t capacity in shear determined for the structure. The loadings on the slab were assumed to be dispersed in both the longitudinal and transverse direction, increasing the capacity of the slab in the grillage analysis. A varying concrete strength was assumed for both spans which resulted in different assessment capacities.

### 4.7 Mode of failure

The mode of failure for the filler beam slab was identified as bond failure and bending for the south span.

### 4.8 Details of any strengthening works undertaken as a result of the assessment

There were no known structural strengthening works undertaken as a result of the Stage 1 assessment.



## 4.9 Description of any changes to the load effects or assessment resistance since the original assessment

An increased worst credible concrete strength of 18.9 N/mm<sup>2</sup> has been determined by the Stage 2 structural investigations.

### 4.10 Results of any monitoring or inspections undertaken

Regular Principal Inspections have been undertaken on the structure since the Stage 1 assessment with the condition of the deck further deteriorating since the assessment. The most recent Principal Inspection found the deck to be in poor condition. See the most recent inspection report dated May 2024 in Appendix A of this report.

Crack pips were installed to the north abutment and the north span deck soffit as part of the 2023 Principal Inspection to the structure. No change has occurred to the pip measurements since installation. Refer to Section 5.1 for further details.

### 4.11 The assessed capacity

The Stage 1 Assessment of the structure determined a capacity of 18t assessment loading for bending, 40t assessment loading for shear and less than 3 tonnes assessment loading for bond.

### 5. Stage 2 Structural Assessment Inspection Summary

### 5.1 Detailed description of the findings of the visual inspection

The Inspection of the structure was undertaken in June 2024. Photographs from the inspection are provided in Appendix H of this report. The condition of the structure is outlined below.

### **Bridge Surface**

The bridge surface is in good condition apart cracking evident to the carriageway on the northwest approach. See Photograph H-1 to view the surface looking south and see Photograph H-2 to view the cracking to the northwest approach.

### **Expansion Joints**

Not applicable.



### **Footways**

The footways are in good condition apart from vegetation debris. See Photograph H-3 for the east footway and see Photograph H-4 for the west footway.

### **Parapets**

The parapets are in good overall condition. See Photograph H-5 and H-6 for views of the east and west parapets, respectively.

#### **Embankments**

The embankments are in good condition apart from vegetation growth at both elevations to be cut back during routine maintenance. See Photograph H-7 to view the northwest embankment and Photograph H-8 for the southeast embankment.

### Wing/Spandrel walls

The wing walls are in good condition apart from vegetation growth. See Photograph H-9 for a view of the southwest wing wall.

#### **Abutments**

The abutments are in good condition apart from algae and calcite staining evident. A 0.6mm crack is evident to the west side of the north abutment with previously installed (2023) crack pips measuring 25.91mm. The cause of the crack is unconfirmed with no signs of differential settlement to the structure and may be a shrinkage crack from the construction stage linked to the mass concrete nature of the abutments. The crack was reported in the 2012 PI with no significant deterioration since.

See Photograph H-10 for the south abutment and see Photograph H-11 for the north abutment.

#### Pier

The pier is in good condition apart from algae and calcite staining evident. Minor honeycombing evident to the east side upstream of the pier. Cracking sealed with calcite is evident to the north face of the pier. See Photograph H-12 and H-13 for a view of the northeast and south faces. See Photograph H-14 to view the cracking to the north face of the pier sealed with calcite.

### **Bearings**

Not applicable.

#### **Deck**

The deck is in poor condition with multiple areas of spalling noted with exposed filler beams evident. Extensive delamination is noted throughout both spans which is concentrated below each beam location, with water seepage and calcite staining evident. Refer to the defect plan in Appendix C.

Previously installed crack pips (2023 PI) are located on a 0.5mm wide longitudinal crack in the north span, approximately 5m from the west elevation and measured 25.56mm at the time of inspection. The widespread cracking is attributed to the low bond capacity between the concrete and steel girders found by the assessment, resulting in the cracking and delamination of the concrete at each girder bottom flange.

See Photograph H-15 and H-16 for a general view of the north and south spans. See Photograph H-17 and H-18 for a view of cracking sealed with calcite and the exposed filler beam to the south span. See Photograph H-19 for a view



of cracking sealed with calcite, water staining and spalling to the north span and Photograph H-20 for a view of the exposed filler beam at the north span.

#### **Beams**

Included in deck component above.

#### Riverbed

The riverbed is in good condition with a 600mm high raised concrete apron provided under the south span of the structure to direct flow through the north span. See Photograph H-21.

#### **Overall Structure**

The structure is in poor condition due to the defects to the deck slab soffit. See Photograph H-22 for the west elevation of the structure and Photograph H-23 for the east elevation of the structure.

# 5.2 Identification and justification of the condition factor used in the assessment calculations for each structural element

The condition factor for the reinforced concrete slab was taken as 0.8 for assessment purposes due to the delamination to the concrete soffit and areas of spalling with exposed filler beams. The condition factor decreased from 0.9 used in the previous Stage 1 assessment due to deterioration in the deck soffit with additional cracking, delamination and spalling noted.

### 5.3 Detailed description of the testing undertaken

The testing undertaken to the structure for the Stage 2 assessment by Triur Construction Ltd. in July 2024 comprised the following:

- 2no. concrete cores and strength testing to both spans(4no. total)
- 4no. pilot holes to confirm deck thickness
- 4no. areas of breakout to areas of the steel beams for condition survey (2no. internal 2no. external beams)
- Delamination survey to both spans
- Durability testing to 6no. areas (2no. top, 2no. fascias, 2no. soffits)
- Waterproofing pull off testing
- Covermeter & GPR survey to 1no. areas of abutments and pier with breakouts (3no. areas total)
- 2no. pilot holes to confirm abutment thickness
- Durability testing to 2no. areas of each substructure element (6no. total)

For further information on the structural investigations undertaken refer to Appendix E of this report.



### 5.4 Results of all testing undertaken

The trial pit to the concrete verge found a total depth of fill of 420mm with no waterproofing present on the deck slab. The pilot hole cores drilled through the deck varied from 300mm and 320 mm in depth. The steel beams encased in the deck slab comprised a 125mm high railway girder at 600mm spacing with 23x13mm transverse bars at 600mm spacing between the girders. The concrete strength of the slab varied between 18.9 N/mm2 and 57.10 N/mm2.

For further information on the structural investigations results refer to Appendix E of this report.

### 5.5 Summary of safety partial factors used in the assessment

For the concrete, the values of  $\gamma_m$  is taken as 1.2 considering worst credible strengths which is taken from Table 4A (4.3.3.3.) of AM-STR-06031. For structural steel the  $\gamma_m$  is taken as 1.05.

The partial safety factors taken from *AM-STR-06030 Appendix A* are represented below in Table 5-1. Refer to Appendix G calculations for more details.

Table 5-1 - Partial Safety Factors for Assessment

Loading	Yf3 for ULS	YfL for ULS
Dead Load	1.1	1.15
Super Imposed Dead Load	1.1	1.75
Soil Fill	1.1	1.2
Type HA Loading	1.1	1.5
Type HB Loading	1.1	1.3
SV Loading	1.1	1.1

### 5.6 Summary of all material properties used in the assessment

<u>Fill Material:</u> (Structural fill) Unit weight of fill = 22kN/m<sup>3</sup> Angle of Friction, phi = 30°

Road Surfacing: Unit Weight = 24kN/m<sup>3</sup>

#### Filler beam concrete slab:

The estimated worst credible concrete strength of the concrete deck slab is taken as 18.9 N/mm<sup>2</sup>. This is based on compression testing data of concrete core samples and is derived in accordance with *AM-STR-06031*. In the absence of test data on the characteristic yield strength of the structural steel sections, it was assumed as 230 N/mm<sup>2</sup> as per AM-STR-06026 CI 4.3.



### 6. Assessment Method

### 6.1 Summary of analysis methodology undertaken as part of Stage 1 Structural Assessment

Assessment of the Filler Beam deck was carried out in accordance with the NRA Stage 1 Assessment Methodology Report (Revision C) and the methods outlined in the UK Highways Agency Design Manual for Roads and Bridges (BD21/01, BD44/95 & BA44/96). The structure was assessed using the strip method for HA loading, single axle and single wheel loads in accordance with BD21/01 and the methods outlined in BD44/95. A grillage analysis was also subsequently undertaken as part of the Stage 1 Assessment.

# 6.2 Detailed description of method of analysis undertaken for Stage 2 analysis including justification as to how this has led to an increase in the assessed capacity for the superstructure, substructure and foundations

The initial assessment of the filler beam deck slab was carried out using the strip analysis method as per *AM-STR-06026* and *AM-STR-06037* followed by a grillage analysis as per *AM-STR-06057*. A refined grillage analysis including transverse distribution and enhanced material properties from the structural investigations was used for the Stage 2 analysis. Using Midas Civil the main longitudinal members were defined as line elements and assigned composite section properties, which produced improved results compared to the stage 1 analysis.

The assessment live loading comprised 40t HA loading in accordance with TII Publication *AM-STR-06026*. Abnormal loading considered as part of the assessment comprised SV196 loading in accordance with TII Publication *AM-STR-06048* The Assessment of Road Bridges and Structures for the Effects of Abnormal and Exceptional Abnormal Load Vehicles using SV and SOV Load Models and 45 Units HB loading in accordance with *AM-STR-06030* Loads for Highway Bridges.

An increase in the bending capacity of the structure from the Stage 1 assessment when considering composite action was found due to the increase in the worst credible concrete strength as determined by the structural investigations. However, the check on the bond between the beams and the concrete slab to enable composite action found a reduced capacity for the structure of 7.5t.

### 6.3 Description of the model and software used for the analysis

The filler beam concrete slab was analysed with a grillage model using MIDAS Civil software. The grillage model was created with main longitudinal beams modelled as composite steel sections and transverse dummy elements for transverse distribution.

The diagram of the model and the model inputs are shown in Appendix F of this report.



### 6.4 Assessment live loading

Assessment live loading comprised 40t HA loading in accordance with TII Publication AM-STR-06026.

### 6.5 Abnormal loading

Abnormal loading considered as part of the assessment comprised SV196 loading in accordance with TII Publication AM-STR-06048 The Assessment of Road Bridges and Structures for the Effects of Abnormal and Exceptional Abnormal Load Vehicles using SV and SOV Load Models and 45 Units HB loading in accordance with AM-STR-06030 Loads for Highway Bridges.

### 6.6 Additional loading requirements

Dead and superimposed dead loads were applied to the structure based on the information gathered during the site investigation works and the inspection for assessment.

### 7. Assessment Commentary

### 7.1 Assumptions made during the Stage 2 Structural Assessment

The section property and capacity calculations of the composite steel beams were calculated in accordance with *BS 5400 Part 3:2000*. A condition factor of 0.8 was applied due to the delamination and spalling of the concrete deck soffit in both spans. As the year of construction and yield strength of the steel beams is unknown, a minimum yield strength of 230N/mm² was assumed for structural steel as per *AM-STR-06026 Cl 4.3*. The worst credible strength of concrete for the superstructure was taken as 18.9 N/mm² based on the findings of the structural investigations. Transverse distribution has been assumed across the deck based on structural investigations confirming the presence of transverse reinforcement in the slab. The dispersion of traffic loading through the fill was not considered due to the shallow depth of fill over the structure.

### 7.2 Significance of these assumptions in relation to the overall capacity of the structure or element

The filler beam structure is found to have sufficient loading for 40t HA loading when considering full composite action however the capacity is reduced due to bond failure in the section which prevents full composite action from occurring.



### 8. Assessment Results

The initial strip analysis undertaken for the Stage 2 assessment showed a bending capacity of 3t HA loading, with no capacity for HB and SV loading. The filler beam was found unsuitable for composite action as it failed under the bond stress check, resulting in a bond capacity of less than 3t GVW.

The bridge was also assessed using grillage analysis for live load capacity of 40t HA, combined HA+HB45, HB45, and SV196 loading with the results shown in Table 8-1 below as per the guidance from *AM-STR-06057*. The detailed calculations for each load case are provided in Appendix G of this report.

Table 8-1 - Grillage Assessment results for Filler beam slab

Element	Load Effect	R <sub>A*</sub>	S <sub>D*</sub>	S <sub>HA40t*</sub>	S <sub>HA+HB45*</sub>	S <sub>HB45*</sub>	<b>S</b> sv <sub>196*</sub>	R <sub>A</sub> */S <sub>A</sub> *
	Moment near Support (Sagging) (kNm)	73	5	12	20	14	18	3.64
Filler beam concrete slab	Max. Sagging Moment (kNm)	73	17	56	84	75	66	0.87
concrete stab	Max. Shear (kN)	101	53	85	146	121	110	0.69
	Bond Capacity		7.5t		< HB 30	units	< S\	V 80

#### Where

R<sub>A</sub>\* = Assessment Resistance (flexure, shear etc.)

S<sub>D</sub>\* = Assessment load effects due to dead and superimposed dead loads

S<sub>HA</sub>\* = Assessment load effect due to the associated Type HA loading and Permanent loads (ULS)

S<sub>HA+HB</sub>\* = Assessment load effect due to the Combined Type HA+HB loading and Permanent loads (ULS)

S<sub>HB</sub>\* = Load effect due to HB loading and Permanent loads (ULS)

S<sub>SV</sub>\* = Load effect due to Special Vehicle loading and Permanent loads (ULS)

S<sub>A</sub>\* = Assessment load effects (Maximum of ULS Combination)

 $R_A^*/S_A^*$  = Structural Assessment Factor (shown for the critical case from the ULS cases)

The grillage analysis determined a reduction in the assessment load effects due to the transverse distributions of loads, which resulted in a bending capacity of 40t GVW for the structure when considering composite action. The bond capacity of the section limits the slab capacity to 7.5t however.

The assessment summary is provided in the Table 8-2 below.

Table 8-2 - Assessment summary for Structure

Structure ID	Structure Name	Structure Type	No. of Spans	Span Length	Assessed Capacity (ALL)	HB Capacity	SV Capacity
MO-N58-001.00	Strade Bridge	Filler Beam	2	3.82m / 3.79m	7.5t	Fails HB30 units	Fails SV80



### 9. Recommendations

Based on the findings of the assessment the structure is determined to have a reduced load capacity due to bond failure between the concrete and steel beams with the significant delamination and spalling visible to the deck slab soffit providing evidence of the issue. As a result no further assessment measures are deemed required for the structure as they are not likely to increase the bond capacity to 40t loading due to the low compressive strength values found for the concrete in the soffit of the structure. The deck slab is therefore recommended to be either strengthened or replaced.

Due to the extensive defects to the soffit of the structure and the presence of railway girders acting as primary structural members the strengthening of the structure is not recommended. A full deck replacement is instead recommended with the existing deck slab removed and a new deck installed across the structure, in either a single or two span arrangement.

Although there are extensive defects to the deck soffit as there is no evidence of failure or excess deformation of the slab a load restriction is not recommended at this time. Monitoring of the structure should be taken annually however to check for any further evidence of deformation or failure of the deck. Regular term maintenance should also be undertaken to the structure to maintain its condition in the interim.



# Appendices

### Appendix A. Archive Information about the **Structure**



TII EIRSPAN Printed Page
Inspection Report 4-Oct-2024 1 of 38

### MO-N58-001.00 Strade River Bridge

Maintaining Agent:	23	MO - Mayo
Road:	Bellavary - Foxfor	rd, County Mayo
Side of road:	0	
Region:	1	Connacht\Ulster
Struct. reg. no:	1155	
Year of construction	:	
Year of reconstruction	:	
Primary passage Overbrid	lge/Underbridge:	U
Dir. of chainage on prim	nary road:	N
Access equipment needed.	:	0 Nothing
Data collected: Date	:	15 May 2024
Inspecto	or Initials:	CS

Checker Initials....: CP

### EIRSPAN **Inspection Report** 4-Oct-2024 2 of 38

Printed Page

### MO-N58-001.00 Strade River Bridge

### Geographical position (ITM):

Northing:	797496.734
	Northing:

### Geometry:

Number of spans:	2
Min span length( $\mathfrak{m}$ ):	3.79
Max span length( $\mathfrak{m}$ ):	3.79
Overall length( $\mathfrak{m}$ ):	8.70
Width out-to-out(m):	10.30
Width of median( $\mathfrak{m}$ ):	0.00
Width of footway left( $\mathfrak{m}$ ):	1.67
Width of footway right( $\mathfrak{m}$ ):	1.09
Width of carriageway( $\mathfrak{m}$ ):	5.70
Width kerb-to-kerb( $\mathfrak{m}$ ):	6.90
Width of approach( $\mathfrak{m}$ ):	5.70
Area(m2):	89.61
Minimum Parapet Height(m):	0.88
Width of Soft Verge Left( $\mathfrak{m}$ ):	0.00
Width of Soft Verge Right.(m):	0
Approach Skew 1(deg):	15.00
Approach Skew 2(deg):	15.00
Bridge curved(Y/N):	N
Skew(deg):	30

### Span Lengths:

<pre>Span 1(m):</pre>	3.79	Span 6(m):	Span	11(m):
Span 2(m):	3.79	<pre>Span 7(m):</pre>	Span	12(m):
<pre>Span 3(m):</pre>		Span 8(m):	Span	13(m):
<pre>Span 4(m):</pre>		Span 9(m):	Span	14(m):
Span 5(m):		Span 10(m):		

	HIRDI 11		11111000	- 450
	Inspection	Report	4-Oct-2024	3 of 38
MO-N58-00	1.00 Strade River Bridg	e		
Superstruc	cture, principal type:			
Standard	design(Y/N):	Y		
Design of	cross section:	10	Slab	
Design of	elevation:	40	Frame, constant section	cross
Material	of primary members:	42	Composite steel	& concrete
Superstru	cture, secondary type (i	f applica.	ble):	
Standard	design( $Y/N$ ):	N		
Design of	cross section:	91	Not applicable	
Design of	elevation:	91	Not applicable	
Material	of primary members:	91	Not applicable	
Superstru	cture, tertiary type (if	applicab	le):	
Standard	design( $Y/N$ ):	N		
Design of	cross section:	91	Not applicable	
Design of	elevation:	91	Not applicable	
Material	of primary members:	91	Not applicable	
Substruct	ure:			
Abutment:	Type:	10	Abutm. wall, in walls	teg. wing
	Material:	21	Reinforced conc	rete
	Foundation:	92	Unknown	
Pier:	Type:	10	Solid wall	
	Material:	21	Reinforced conc	rete

92

Unknown

Foundation...:

EIRSPAN

Printed

Page

TII

TII	EIRSPAN	Printed	Page
	Inspection Report	4-Oct-2024	4 of 38

Details:							
Type of parapet:	30	Concrete cast in situ					
Type of safety barrier:	0	No guard rail					
Type of wearing surface:	23	Hot rolled asphalt					
Type of expansion joint:	91	Not applicable					
Type of fixed bearings on support:	91	Not applicable					
Type of free bearings on support:	91	Not applicable					
Type of fixed bearings on girders:	91	Not applicable					
Type of free bearings on girders:	91	Not applicable					
Obstacle:							
Type of passage:	31	River					
Passage id:		RIVER					
Passage name:		Strade River					
Road side:							
Vertical Clearance:							
Primary passage(m):	L:	LM: RM: R:					
Secondary passage(m):		LM: 2.33 RM: 2.33 R: 2.33					
2000000007 [ 200005 200000000000000000000000000000							
Miscellaneous:							
Design Load:							
Load Distribution:	2	Distribution in 1					
		direction					
Technical Standards:	0	Unknown standard					
Assessed Capacity Normal:	7	18T GVW					
Assessed Capacity Abnormal:	32	30 Units HB					
Weight Restriction:	1	N/A					
Owner:	23	Mayo County Council					
Maintaining Agent:	23	Mayo County Council					
Inspection Consultant:	96	Atkins					
Designer/Consultant:	92	Unknown					
Technical installations:	2	Other electrical					
Technical installations:	_	Other electrical Allation Water supply pipeline					

### **EIRSPAN** Printed Page Inspection Report 4-Oct-2024 5 of 38

### MO-N58-001.00 Strade River Bridge

#### Remarks:

The deck slab comprises a composite filler beam slab construction. The vertical clearance at the north span is 2.33m and the south span is 1.65m.

The skew span is 3.79m and the square span is 3.44m for both spans. Technical installations over the structure include a water main and overhead ESB.

The 2012 Stage 1 Report gives a capacity of 18 tonnes in bending however this reduces to less than 3 tonnes when bond stress is considered.

Chronologic Date Remarks	cal Overview Activity	1 Br	2 Ex	3 Fo	4 Pa	5 Em	6 Wi	7 Ab	8 Pi	9 Be	10 De	11 Be	12 Ri	13 Ot	14 St
01 Jan 2012	Assessment	Sta	ige	1 /	18T	GVW	/ /	Y							
Bending Mid-S	Span														
14 Aug 2012	Principal inspection	0	_	2	1	0	0	1	1	-	2	-	0	-	2
18 Aug 2017	Principal inspection	2	_	-	1	0	0	1	1	_	1	_	1	_	1
09 Mar 2022	Principal inspection	1	_	0	0	1	0	1	1	_	2	_	1	_	2
29 May 2023	Principal inspection	1	_	1	1	1	1	2	1	-	3	1	1	_	3
15 May 2024	Principal inspection	1	_	0	0	1	1	2	1	_	3	_	0	_	3

### EIRSPAN Printed Page Inspection Report 4-Oct-2024 6 of 38

### MO-N58-001.00 Strade River Bridge

### Principal Inspection:

Date....: 15 May 2024

Team Leader Name..... Curtis Swanepoel

Initials....: CS

Weather....: Sunny

Temperature.....(deg. C): 14

Traffic:Annual Average Daily Traffic.: 6274

Percentage, light vehicles...: 96

Percentage, heavy vehicles...: 4

Year for next Principal Inspection...: 2025

#### Remark:

AADT Information sourced from TII Traffic Counter Data from 'TMU N58 010.0 N' in year 2023, based on 100% coverage.

### EIRSPAN Printed Page Inspection Report 4-Oct-2024 7 of 38

No Component	Component					ck			
Repair work Damage descripti Type of damage	on	Con rtg	Mtn req	Spe Ins	T P	Qty	Year	Cost	Pho tos
1 Bridge surface		1	Y	N					2
The bridge surface condition overall, for a view north. cracking evident to carriageway at the corner to be seale routine maintenance.	see P1.1 There is o the northwest d during								
2 Expansion joints		_		N					0
3 Footways/median		0	N	N					1
The rubbing strips good condition, so view of the easter strip.	e P3.1 for a								
4 Parapets/Safety barr:	.er	0	N	N					1
The parapets are i condition, see P4. of the western par	1 for a view								
5 Embankments/Revetment	s	1	Y	N					1
The embankments ar condition apart from the condition growth be cut back from a embankments during P5.1 for a view of southeast embankments.	om that should ll the RM, see the								
6 Wing/Spandrel/Retain:	ng Walls	1	N	N					2
The wing walls are condition, see P6. of the northeast wall, see P6.2.	1 for a view ing wall. s repair								
7 Abutments		2	N	N					2

### EIRSPAN Printed Page Inspection Report 4-Oct-2024 8 of 38

No	Component				Repair Work				
	Repair work Damage description Type of damage	Con rtg	Mtn req	Spe Ins	T P	Qty	Year	Cost	Pho tos
	E: Injection of cracks  Both abutments are in a fair condition, see P7.1 for view of the southern abutment. The previously reported crack to the west side of the northern abutment remains 0.6mm wide, see P7.2. The previously installed crack pips have a measurement of 25.91mm (The previous base reading 23.1mm is confirmed to be incorrect with 25.91mm the new base reading). The crack should be injection repaired.  Cracking of concrete				E	1	2026	500	
8 P	The pier is in a good overall condition, see P8.1 for view of the south face of the pier looking east. There is minor honeycombing to the east side upstream of the pier which requires no action, see P8.2. There is a crack sealed with calcite on the concrete protection to the north face of the pier, see P8.3.	1	N	N					3

### EIRSPAN Printed Page **Inspection Report** 4-Oct-2024 9 of 38

No	Component					Repair Work			
	Repair work Damage description Type of damage	Con rtg	Mtn req	Spe Ins	T P	Qty	Year	Cost	Pho tos
9 Be	earings	-		N					0
10 De	eck/slab/arch barrel	3	N	N					6
	A : Concrete repair (without reinforcement)				A	6	2025	3210	

The deals is in a new			1 1	ĺ		
The deck is in a poor						
condition, see P10.1 for view						
of the southern span deck						
looking east with areas of						
spalling evident below the						
filler beams. There is						
spalling with exposed beams in						
the northern span also, see						
P10.2. See P10.3 for closer						
view of large spalling to the						
south span deck. All areas of						
spalling should be repaired.						
There are longitudinal cracks						
that are self healed with						
calcite on the east and west						
side of the deck under the						
headwalls of the northern						
span. There are also						
longitudinal cracks that are						
self healed with calcite on						
the east side of the southern						
span, see P10.4.						
There is a 0.5mm wide						
longitudinal crack in the						
northern span located 5.35m						
from the western elevation.						
Previously installed crack						
pips have a reading of 25.56mm						
(The previous base reading of						
23.4mm is confirmed to be						
incorrect, with 25.56mm the						
new base reading), see P10.5.						
All cracks appear to be						
replicating the behaviour of						
spalling of the exposed beams						
with widespread delamination						
identified.						
The 2012 Stage 1 Assessment						
report indicated that the						
structure is substandard due						
to failure of bond stress						
checks in the deck. The						
spalling and delamination of						
concrete noted above is						
consistent with debonding of						
the concrete to the soffit of						
the steel beams. Otherwise						
there was no deformation or						
transverse cracking in the						
deck that would suggest						
failure in bending/shear. The						
condition of the deck does not						
appear to have deteriorated						
<del></del>						
further since the last PI.						

EIRSPAN Printed Page
Inspection Report 4-Oct-2024 11 of 38

Spalling						
11 Beams/girders/transverse beams	_		N			0
12 Riverbed  The riverbed is in good	0	N	N			1
condition, see P12.1 for a view downstream east.						
13 Other elements	_		N			0
14 Structure in general	3	Y	N			2
The structure is in a fair condition with cracking to the northern abutment and spalling and delamination to the southern and northern deck slabs with exposed beams evident. Routine Maintenance is also required. See P14.1 and P14.2 for views of the western and eastern elevations respectively.  The inspection of the structure has been undertaken in accordance with the requirements of TII AM-STR-06039 (BD 79) outside of the normal PI schedule due to the 2012 Stage 1 Assessment Report finding the structure to have a reduced load capacity due to failure of the bond stress checks between the filler beams and surrounding concrete.						
Total Cost:					3710	

#### EIRSPAN Printed **Inspection Report** 4-Oct-2024

12 of 38

Page

MO-N58-001.00 Strade River Bridge

#### Component No. Bridge surface

The bridge surface is in good condition overall, see P1.1 for a view north. There is cracking evident to the carriageway at the northwest corner to be sealed during routine maintenance, see P1.2.

Condition/Mainten.



#### EIRSPAN Printed Inspection Report 4-Oct-2024


13 of 38

Page

### MO-N58-001.00 Strade River Bridge

#### Component No. Bridge surface

The bridge surface is in good condition overall, see P1.1 for a view north. There is cracking evident to the carriageway at the northwest corner to be sealed during routine maintenance, see P1.2.



TII EIRSPAN Printed Page

**Inspection Report** 4-Oct-2024 14 of 38

### MO-N58-001.00 Strade River Bridge

### Component No. 3 Footways/median

The rubbing strips are both in good condition, see P3.1 for a view of the eastern rubbing strip.



### EIRSPAN **Inspection Report** 4-Oct-2024 15 of 38

Printed Page

### MO-N58-001.00 Strade River Bridge

#### Parapets/Safety barrier Component No. The parapets are in good condition, see P4.1 for a view of the western parapet.

Condition/Mainten.



### EIRSPAN Inspection Report 4-Oct-2024

Printed Page 16 of 38

MO-N58-001.00 Strade River Bridge

#### Embankments/Revetments Component No.

The embankments are in a good condition apart from vegetation growth that should be cut back from all the embankments during RM, see P5.1 for a view of the southeast embankment.

Condition/Mainten.



#### EIRSPAN **Inspection Report** 4-Oct-2024 17 of 38

Printed Page

#### MO-N58-001.00 Strade River Bridge

#### Wing/Spandrel/Retaining Walls Component No.

The wing walls are in good condition, see P6.1 for a view of the northeast wing wall. There is a previous repair evident to the northwest wing wall, see P6.2.

Condition/Mainten.

1 / N



#### EIRSPAN Inspection Report 4-Oct-2024

Printed

Page 18 of 38

#### MO-N58-001.00 Strade River Bridge

#### Wing/Spandrel/Retaining Walls Component No.

The wing walls are in good condition, see P6.1 for a view of the northeast wing wall. There is a previous repair evident to the northwest wing wall, see P6.2.

Condition/Mainten. 1 / N



#### EIRSPAN Printed Inspection Report 4-Oct-2024

19 of 38

Page

#### MO-N58-001.00 Strade River Bridge

#### Component No. Abutments

Both abutments are in a fair condition, see P7.1 for view of the southern abutment. The previously reported crack to the west side of the northern abutment remains 0.6mm wide, see P7.2. The previously installed crack pips have a measurement of 25.91mm (The previous base reading 23.1mm is confirmed to be incorrect with 25.91mm the new base reading). The crack should be injection repaired.

Condition/Mainten.



## **EIRSPAN** Printed Inspection Report 4-Oct-2024

Page

20 of 38

MO-N58-001.00 Strade River Bridge

#### Component No. 7 Abutments

Both abutments are in a fair condition, see P7.1 for view of the southern abutment. The previously reported crack to the west side of the northern abutment remains 0.6mm wide, see P7.2. The previously installed crack pips have a measurement of 25.91mm (The previous base reading 23.1mm is confirmed to be incorrect with 25.91mm the new base reading). The crack should be injection repaired.

Condition/Mainten. 2 / N



## EIRSPAN Printed Inspection Report 4-Oct-2024

Page

21 of 38

#### MO-N58-001.00 Strade River Bridge

#### Component No. 8 Piers

The pier is in a good overall condition, see P8.1 for view of the south face of the pier looking east. There is minor honeycombing to the east side upstream of the pier which requires no action, see P8.2. There is a crack sealed with calcite on the concrete protection to the north face of the pier, see P8.3.

Condition/Mainten. 1 / N



#### EIRSPAN Inspection Report 4-Oct-2024

Printed

22 of 38

Page

#### MO-N58-001.00 Strade River Bridge

#### Piers Component No.

The pier is in a good overall condition, see P8.1 for view of the south face of the pier looking east. There is minor honeycombing to the east side upstream of the pier which requires no action, see P8.2. There is a crack sealed with calcite on the concrete protection to the north face of the pier, see P8.3.

Condition/Mainten. 1 / N



## **EIRSPAN** Printed Page Inspection Report 4-Oct-2024 23 of 38

#### MO-N58-001.00 Strade River Bridge

#### Component No. 8 Piers

The pier is in a good overall condition, see P8.1 for view of the south face of the pier looking east. There is minor honeycombing to the east side upstream of the pier which requires no action, see P8.2. There is a crack sealed with calcite on the concrete protection to the north face of the pier, see P8.3.

Condition/Mainten. 1 / N



## EIRSPAN Inspection Report

4-Oct-2024

Printed

24 of 38

Page

MO-N58-001.00 Strade River Bridge

#### Component No. 10 Deck/slab/arch barrel

The deck is in a poor condition, see P10.1 for view of the southern span deck looking east with areas of spalling evident below the filler beams. There is spalling with exposed beams in the northern span also, see P10.2. See P10.3 for closer view of large spalling to the south span deck. All areas of spalling should be repaired. There are longitudinal cracks that are self healed with calcite on the east and west side of the deck under the headwalls of the northern span. There are also longitudinal cracks that are self healed with calcite on the east side of the southern span, see P10.4. There is a 0.5mm wide longitudinal crack in the northern span located 5.35m from the western elevation. Previously installed crack pips have a reading of 25.56mm (The previous base reading of 23.4mm is confirmed to be incorrect, with 25.56mm the new base reading), see P10.5. All cracks appear to be replicating the behaviour of spalling of the exposed beams with widespread delamination identified.

The 2012 Stage 1 Assessment report indicated that the structure is substandard due to failure of bond stress checks in the deck. The spalling and delamination of concrete noted above is consistent with debonding of the concrete to the soffit of the steel beams. Otherwise there was no deformation or transverse cracking in the deck that would suggest failure in bending/shear. The condition of the deck does not appear to have deteriorated further since the last PI.

Condition/Mainten. 3 / N

EIRSPAN Printed Page
Inspection Report 4-Oct-2024 25 of 38

MO-N58-001.00 Strade River Bridge



## EIRSPAN Inspection Report

4-Oct-2024

Printed

26 of 38

Page

MO-N58-001.00 Strade River Bridge

#### Component No. 10 Deck/slab/arch barrel

The deck is in a poor condition, see P10.1 for view of the southern span deck looking east with areas of spalling evident below the filler beams. There is spalling with exposed beams in the northern span also, see P10.2. See P10.3 for closer view of large spalling to the south span deck. All areas of spalling should be repaired. There are longitudinal cracks that are self healed with calcite on the east and west side of the deck under the headwalls of the northern span. There are also longitudinal cracks that are self healed with calcite on the east side of the southern span, see P10.4. There is a 0.5mm wide longitudinal crack in the northern span located 5.35m from the western elevation. Previously installed crack pips have a reading of 25.56mm (The previous base reading of 23.4mm is confirmed to be incorrect, with 25.56mm the new base reading), see P10.5. All cracks appear to be replicating the behaviour of spalling of the exposed beams with widespread delamination identified.

The 2012 Stage 1 Assessment report indicated that the structure is substandard due to failure of bond stress checks in the deck. The spalling and delamination of concrete noted above is consistent with debonding of the concrete to the soffit of the steel beams. Otherwise there was no deformation or transverse cracking in the deck that would suggest failure in bending/shear. The condition of the deck does not appear to have deteriorated further since the last PI.

Condition/Mainten. 3 / N

EIRSPAN Printed Page TII **Inspection Report** 4-Oct-2024 27 of 38

MO-N58-001.00 Strade River Bridge



## EIRSPAN Inspection Report

**Printed** 4-Oct-2024

28 of 38

Page

MO-N58-001.00 Strade River Bridge

#### Component No. 10 Deck/slab/arch barrel

The deck is in a poor condition, see P10.1 for view of the southern span deck looking east with areas of spalling evident below the filler beams. There is spalling with exposed beams in the northern span also, see P10.2. See P10.3 for closer view of large spalling to the south span deck. All areas of spalling should be repaired. There are longitudinal cracks that are self healed with calcite on the east and west side of the deck under the headwalls of the northern span. There are also longitudinal cracks that are self healed with calcite on the east side of the southern span, see P10.4. There is a 0.5mm wide longitudinal crack in the northern span located 5.35m from the western elevation. Previously installed crack pips have a reading of 25.56mm (The previous base reading of 23.4mm is confirmed to be incorrect, with 25.56mm the new base reading), see P10.5. All cracks appear to be replicating the behaviour of spalling of the exposed beams with widespread delamination identified.

The 2012 Stage 1 Assessment report indicated that the structure is substandard due to failure of bond stress checks in the deck. The spalling and delamination of concrete noted above is consistent with debonding of the concrete to the soffit of the steel beams. Otherwise there was no deformation or transverse cracking in the deck that would suggest failure in bending/shear. The condition of the deck does not appear to have deteriorated further since the last PI.

Condition/Mainten. 3 / N

EIRSPAN Printed Page
Inspection Report 4-Oct-2024 29 of 38

MO-N58-001.00 Strade River Bridge



## EIRSPAN Inspection Report

4-Oct-2024

Printed

30 of 38

Page

MO-N58-001.00 Strade River Bridge

#### Component No. 10 Deck/slab/arch barrel

The deck is in a poor condition, see P10.1 for view of the southern span deck looking east with areas of spalling evident below the filler beams. There is spalling with exposed beams in the northern span also, see P10.2. See P10.3 for closer view of large spalling to the south span deck. All areas of spalling should be repaired. There are longitudinal cracks that are self healed with calcite on the east and west side of the deck under the headwalls of the northern span. There are also longitudinal cracks that are self healed with calcite on the east side of the southern span, see P10.4. There is a 0.5mm wide longitudinal crack in the northern span located 5.35m from the western elevation. Previously installed crack pips have a reading of 25.56mm (The previous base reading of 23.4mm is confirmed to be incorrect, with 25.56mm the new base reading), see P10.5. All cracks appear to be replicating the behaviour of spalling of the exposed beams with widespread delamination identified.

The 2012 Stage 1 Assessment report indicated that the structure is substandard due to failure of bond stress checks in the deck. The spalling and delamination of concrete noted above is consistent with debonding of the concrete to the soffit of the steel beams. Otherwise there was no deformation or transverse cracking in the deck that would suggest failure in bending/shear. The condition of the deck does not appear to have deteriorated further since the last PI.

Condition/Mainten. 3 / N

TII EIRSPAN Printed Page
Inspection Report 4-Oct-2024 31 of 38

MO-N58-001.00 Strade River Bridge



## EIRSPAN Inspection Report

4-Oct-2024

Printed

32 of 38

Page

MO-N58-001.00 Strade River Bridge

#### Component No. 10 Deck/slab/arch barrel

The deck is in a poor condition, see P10.1 for view of the southern span deck looking east with areas of spalling evident below the filler beams. There is spalling with exposed beams in the northern span also, see P10.2. See P10.3 for closer view of large spalling to the south span deck. All areas of spalling should be repaired. There are longitudinal cracks that are self healed with calcite on the east and west side of the deck under the headwalls of the northern span. There are also longitudinal cracks that are self healed with calcite on the east side of the southern span, see P10.4. There is a 0.5mm wide longitudinal crack in the northern span located 5.35m from the western elevation. Previously installed crack pips have a reading of 25.56mm (The previous base reading of 23.4mm is confirmed to be incorrect, with 25.56mm the new base reading), see P10.5. All cracks appear to be replicating the behaviour of spalling of the exposed beams with widespread delamination identified.

The 2012 Stage 1 Assessment report indicated that the structure is substandard due to failure of bond stress checks in the deck. The spalling and delamination of concrete noted above is consistent with debonding of the concrete to the soffit of the steel beams. Otherwise there was no deformation or transverse cracking in the deck that would suggest failure in bending/shear. The condition of the deck does not appear to have deteriorated further since the last PI.

Condition/Mainten. 3 / N

TII EIRSPAN Printed Page
Inspection Report 4-Oct-2024 33 of 38

MO-N58-001.00 Strade River Bridge



## EIRSPAN Inspection Report

4-Oct-2024

Printed

34 of 38

Page

MO-N58-001.00 Strade River Bridge

#### Component No. 10 Deck/slab/arch barrel

The deck is in a poor condition, see P10.1 for view of the southern span deck looking east with areas of spalling evident below the filler beams. There is spalling with exposed beams in the northern span also, see P10.2. See P10.3 for closer view of large spalling to the south span deck. All areas of spalling should be repaired. There are longitudinal cracks that are self healed with calcite on the east and west side of the deck under the headwalls of the northern span. There are also longitudinal cracks that are self healed with calcite on the east side of the southern span, see P10.4. There is a 0.5mm wide longitudinal crack in the northern span located 5.35m from the western elevation. Previously installed crack pips have a reading of 25.56mm (The previous base reading of 23.4mm is confirmed to be incorrect, with 25.56mm the new base reading), see P10.5. All cracks appear to be replicating the behaviour of spalling of the exposed beams with widespread delamination identified.

The 2012 Stage 1 Assessment report indicated that the structure is substandard due to failure of bond stress checks in the deck. The spalling and delamination of concrete noted above is consistent with debonding of the concrete to the soffit of the steel beams. Otherwise there was no deformation or transverse cracking in the deck that would suggest failure in bending/shear. The condition of the deck does not appear to have deteriorated further since the last PI.

Condition/Mainten. 3 / N

EIRSPAN Printed Page TII **Inspection Report** 4-Oct-2024 35 of 38

MO-N58-001.00 Strade River Bridge



#### EIRSPAN Printed Page **Inspection Report** 4-Oct-2024 36 of 38

#### MO-N58-001.00 Strade River Bridge



#### EIRSPAN Printed Inspection Report 4-Oct-2024

37 of 38

Page

MO-N58-001.00 Strade River Bridge

#### Component No. 14 Structure in general

The structure is in a fair condition with cracking to the northern abutment and spalling and delamination to the southern and northern deck slabs with exposed beams evident. Routine Maintenance is also required. See P14.1 and P14.2 for views of the western and eastern elevations respectively. The inspection of the structure has been undertaken in accordance with the requirements of TII AM-STR-06039 (BD 79) outside of the normal PI schedule due to the 2012 Stage 1 Assessment Report finding the structure to have a reduced load capacity due to failure of the bond stress checks between the filler beams and surrounding concrete.

Condition/Mainten. 3 / Y



## EIRSPAN Printed Inspection Report 4-Oct-2024

Page

38 of 38

MO-N58-001.00 Strade River Bridge

#### Component No. 14 Structure in general

The structure is in a fair condition with cracking to the northern abutment and spalling and delamination to the southern and northern deck slabs with exposed beams evident. Routine Maintenance is also required. See P14.1 and P14.2 for views of the western and eastern elevations respectively. The inspection of the structure has been undertaken in accordance with the requirements of TII AM-STR-06039 (BD 79) outside of the normal PI schedule due to the 2012 Stage 1 Assessment Report finding the structure to have a reduced load capacity due to failure of the bond stress checks between the filler beams and surrounding concrete.

Condition/Mainten. 3 / Y







## STRADE RIVER BRIDGE STRUCTURE ID: MO-N58-001.00 STAGE I ASSESSMENT REPORT



Revision 0 May 2012



#### EIRSPAN BRIDGE MANAGEMENT SYSTEM

## TASK ORDER NO. 213 : STAGE 1 STRUCTURAL ASSESSMENTS OF BRIDGES IN DONEGAL, SLIGO, MAYO AND GALWAY

#### STRADE RIVER BRIDGE

STRUCTURE ID: MO-N58-001.00

#### STAGE 1 ASSESSMENT REPORT

#### **Notice**

This document has been produced by ATKINS solely for the purpose of the Eirspan Bridge Management System. It may not be used by any person for any other purpose other than that specified without the express written permission of ATKINS. Any liability arising out of use by a third party of this document for purposes not wholly connected with the above shall be the responsibility of that party who shall indemnify ATKINS against all claims costs damages and losses arising out of such use.

#### **Document History**

PROJECT NO.: 3044			DOCUMENT REF: DG-TO213-69			
			Local Reference: 3044/30/32/321			
Revision	Purpose and Originated Description		Checked	Reviewed	Authorised	Date
0	NRA Approval	S. Counihan	C. Maunsell	P. Garg	M. Jennings	31.05.12



#### **CONTENTS**

Execu	itive Summary	1
Locat	ion Map	2
1.0	Introduction	3
2.0	Description of Structure	3
3.0	Visual Inspection of structure	3
4.0	Site Investigation Results	4
5.0	Assessment of Structure	5
6.0	Conclusions	7
7.0	Recommendations	8

#### **APPENDICES**

Appendix B: Photographs

Appendix C: Site Investigation Results

Appendix D: Calculations

Appendix E: Sub-Standard Structure Summary

Appendix F: Interim Measures Feasibility Assessment



#### **Executive Summary**

Strade River Bridge, MO-N58-001.00 carries the N58 national secondary road across the Strade River in County Mayo. This bridge is a two span Filler Beam deck structure with skew spans of 3.81m and 3.79m, and square spans of 3.56m and 3.34m.

Assessment of this structure was carried out in accordance with the NRA Stage 1 Assessment Methodology Report (Revision C) and the methods outlined in the UK Highways Agency Design Manual for Roads and Bridges (BD21/01, BD44/95 & BA44/96 for the RC Slab). A summary of Stage 1 Assessment Results is presented in the following table.

Structure ID	Structure Name	Structure Type	No of Spans	Skew Span Lengths (m)	Assessed Capacity	HB Rating
MO-N58-	Strade	Filler		Span 1: 3.81	18t Bending 40t Shear <3t Bond	30HB Bending 45HB Shear <30HB Bond
001.00	River Bridge	Beam	2	Span 2: 3.79	40t Bending 40t Shear <3t Bond	30HB Bending 45HB Shear <30HB Bond

**Table 1.0: Structure Assessment Summary Results** 

A site investigation was carried out by Stanger Testing Services Limited for this structure to establish the concrete slab thickness, concrete strength and layout and cover to the filler beams.

The Stage 1 Assessment of the filler beam deck structure indicated that both spans could withstand 7.5 tonnes assessment in bending and 40 tonnes in shear, however the bond load capacity was less than 3 tonnes for both spans. As the adequacy of the structures in bending for 40t live loading was 60% for span 1 and 73% for span 2 using the strip method, a grillage analysis was carried out, which increased the load capacity of the structures in bending to 18 tonnes assessment loading for Span 1 and to 40 tonnes for Span 2.


A low concrete strength and low area of steel components are the main causes of the low carrying capacity of the structure.

The following works are recommended for the structure:

- (i) Stage 2 Assessment of the filler beam deck in the form of Plastic Analysis or Finite Element Method and subsequent strengthening using FRP plates or similar;
- (ii) The grass verges on both sides of the carriageway should be replaced with paved/raised verges and the entire structure should be waterproofed (such as impermeable layer should be placed under the pavement);
- (iii) Both parapets should be upgraded to meet current standards.

It is recommended that the structure be inspected in year 2012, as per the Principal Inspection Report dated 1<sup>st</sup> October, 2008.





ORDNANCE SURVEY IRELAND LICENCE No. AR 0082511 © ORDNANCE SURVEY IRELAND / GOVERNMENT OF IRELAND



#### 1.0 Introduction

Atkins was appointed by the National Roads Authority in August 2011 to carry out the structural assessment of 136 bridges in Donegal, Sligo, Mayo and Galway as part of Task Order 213.

Strade River Bridge MO-N58-001.00, which is located in County Mayo and carries the N58 across the Strade River, is a part of this Task Order. The co-ordinates of the structure are:

Latitude Y: 297482.729 Longitude X: 125785.401

The most recent Principal Inspection of this structure was carried out on 1<sup>st</sup> October, 2008. An Inspection for Assessment was carried out by Atkins on 18<sup>th</sup> December, 2011.

The layout of the Assessment Report follows the layout as described in Section 7 of the NRA Stage 1 Assessment Methodology Report, Rev C.

#### 2.0 Description of Structure

Strade River Bridge is a two span Filler Beam deck structure with skew spans of 3.81m and 3.79m, and square spans of 3.56m and 3.34m.

The structure carries the N58 national secondary route across the Strade River. The overall width of the structure from outside of the west parapet to the outside of the east parapet is 10.17m (skew length 11.54m).

#### 3.0 Visual Inspection of structure

#### General:

The visual inspection was carried out in dry weather from the river, inside the structure and from the carriageway over the bridge. Photos are given in Appendix B. Eastern and western elevations of the structure are shown in photos 1 & 2. The structure was on a straight alignment.

#### Surfacing:

The surfacing of the 5.62m wide carriageway was noted to be in good condition, apart from minor wear. There were no obvious signs of rutting or ponding over the main carriageway. Road markings were showing signs of wear (Ref. photo 3, 4 & 5).

#### Footways/verges:

There were no footways on this structure. There were 0.42m wide hard strips on both sides of the carriageway. Additionally, there was a 1.80m wide grassed verge on the west side of the structure and a 1.45m wide grassed verge on the east side (Ref. photo 6 & 7).



#### Parapet walls / Headwalls:

There were concrete parapets and spandrel walls on both sides of the structure.

The western parapet was 980mm high and the eastern parapet was 930mm high. Both parapets were 230mm thick. Both parapets were in good condition. Cracks to both parapets as outlined in the previous Principal Inspection Report have been repaired and the ivy growth removed (Ref. photo 6 & 7).

Both head walls were in good condition and there was no defects recorded (Ref. photo 8 & 9).

#### Deck:

The thickness of the Filler Beam deck was 340mm. The deck slab was noted to be in good condition, apart from some minor water seepage, calcite staining and stalactites in span 1 at the eastern end. There was also water seepage noted under span 2 at the western end (Ref. photo 10 & 11). The cracks identified in the previous principal inspection have been repaired and were not detected at the time of inspection.

#### Abutments / Pier:

There were concrete abutments on both sides of the structure. The abutments were noted to be in good condition, apart from honeycombing noted to both components (Ref. photo 12 & 13). There was 210mm wide x 230mm high scour protection on the southern abutment and the south face of the pier. There was also 210mm wide x 770mm high scour protection on the abutment and north face of the pier. The pier was in good condition apart from honeycombing to the east cut water as outlined in the previous inspection. The ivy growth has been removed from the west face of the pier (Ref. photo 14).

#### **River Bed:**

The riverbed was in good condition. The river bed in span 1 had a raised 540mm thick concrete apron and was dry at the time of inspection (Ref. photo 15 to 18).

#### 4.0 Site Investigation Results

Stanger Testing Services Limited carried out the intrusive site investigations at this structure.

As part of the site investigations, a trial pit was excavated over the Filler Beam deck to establish the internal thickness of the slab and the depth of the fill. The site investigation also showed that the deck was waterproofed.

Four covermeter scans were carried out to the soffit of the RC beam and slab deck to establish the beam spacing, arrangement and orientation. Additionally, 2 no. breakouts were performed at the base of the slab to determine the articulation.

3 no. cores were extracted from the deck soffit of each span. The cores were then sent for laboratory compression testing.

For full details and results of the site investigation, refer to Appendix C for Site Investigation Report.



#### 5.0 Assessment of Structure

#### **Assessment of Filler Beam Deck Structure:**

Assessment of this Filler Beam Deck structure was carried out in accordance with the NRA Stage 1 Assessment Methodology Report (Revision C) and the methods outlined in the UK Highways Agency Design Manual for Roads and Bridges (BD21/01, BD44/95 & BA44/96). The structure was assessed using the strip method for HA loading, single axle and single wheel loads in accordance with BD21/01 and the methods outlined in BD44/95. Due to water seepage, a condition factor of 0.9 was assumed for both spans of the Filler Beam Deck. Both spans were assessed separately.

As per the Stage 1 assessment, the live load capacity of both spans was 7.5 tonnes Gross Vehicle Weight (GVW) for bending and 40 tonnes for shear. An additional check carried out on the bond also indicated the capacity of the structure of less than 3 tonnes assessment loading for both spans. The results are summarised in Table 5.1a & 5.1b.

Assessment Live Load Capacity				
	HA UDL & Single Axle Single KEL Load Wheel Load			
Bending	40t	7.5t	7.5t	
Shear	40t	40t	40t	
Bond	<3t	-	-	
Hence Overall Rating of <3t				

Table 5.1a Assessed RC Slab Load Capacity - Span 1

Assessment Live Load Capacity				
	HA UDL & Single Axle Single KEL Load Wheel Load			
Bending	40t	7.5t	7.5t	
Shear	40t	40t	40t	
Bond	<3t	-	-	
Hence Overall Rating of <3t				

Table 5.1b Assessed RC Slab Load Capacity – Span 2

Using strip method analysis, the adequacy of the structure in bending was only 60% for span 1 and 73% for span 2 for 40t single wheel loading. Hence, a grillage analysis was carried out for the structure, which increased the bending load capacity of the structure to 18 tonnes assessment loading for span 1 and to 40 tonnes assessment loading for span 2. The results are summarised in Table 5.2a & 5.2b.



Live Load Capacity – Grillage Analysis		
Bending 18 t		
Shear	40 t	
Bond <3 t		
Hence Overall Rating of <3 t		

Table 5.2a Assessed Grillage Analysis Load Capacity - Span 1

Live Load Capacity – Grillage Analysis		
Bending 40 t		
Shear	40 t	
Bond <3 t		
Hence Overall Rating of <3 t		

Table 5.2b Assessed Grillage Analysis Load Capacity - Span 2

The structure was also assessed for 45 units of HB live loading in accordance with NRA Design Manual for Roads and Bridges BD37/01. As per Stage 1 Assessment, the HB rating of both spans was found to be 30HB units for bending, 45HB units for shear and less than 30HB units for bond. The results are summarised in Table 5.3a & 5.3b.

HB Live Load Capacity			
Bending 30 HB			
Shear	45 HB		
Bond <30 HB			
Hence Overall Rating of <30 HB			

Table 5.3a Assessed HB Load Capacity - Span 1

HB Live Load Capacity			
Bending	Bending 30 HB		
Shear	45 HB		
Bond <30 HB			
Hence Overall Rating of <30 HB			

Table 5.3b Assessed HB Load Capacity - Span 2



#### **Abutments and Pier:**

A qualitative assessment was carried out for the substructure. The abutments and pier were in good condition and not showing any signs of distress apart from those mentioned in Section 3 of the report, which however were not considered to be structurally significant. Hence, the components were considered satisfactory in accordance with BD21/01 & BA 16/97.

#### **Headwalls**

The headwalls were assessed qualitatively. Both headwalls were found to be in good condition with no signs of structural defects. Hence, the headwalls were considered satisfactory.

#### **Parapets**

The western parapet was 980mm high and the eastern parapet was 930mm high. Both parapets were 230mm thick.

These parapets heights are substandard for a National Road as per clause 4.5 of NRA BD52/07.

Additionally, both parapets are inadequate for normal containment level with an impact speed of 80kph as per figure 4 of BS6779: Part 4.

Hence, it is advised that both parapets should be upgraded to meet current standards.

#### 6.0 Conclusions

The Stage 1 Assessment of the structure in its present condition indicates that both spans of the Filler Beam Deck structure have a live load capacity of 7.5 tonnes assessment loading for bending, 40 tonnes assessment loading for shear and less than 3 tonnes assessment loading for bond. As the adequacy of the structures in bending for 40t live loading was 60% for span 1 and 73% for span 2 using the strip method, a grillage analysis was carried out, which increased the load capacity of the structure in bending to 18 tonnes assessment loading for Span 1 and to 40 tonnes for Span 2.

The Stage 1 Assessment also indicated that the structure had a HB rating of 30HB units for bending and 45HB units for shear, while for bond the structure could not achieve even 30HB units.

The structure was noted to be in good condition and not showing any signs of structural defects. The main causes of low carrying capacity of the structure were low concrete strength and low area of steel components.

It is considered likely that Stage 2 Assessment of the Filler Beam Deck would increase the assessment load capacity of the structure, but may not increase it to 40 tonnes assessment loading.



#### 7.0 Recommendations


The following works are recommended for the structure:

- (i) Stage 2 Assessment of the filler beam deck in the form of Plastic Analysis or Finite Element Method and subsequent strengthening using FRP plates or similar;
- (ii) The grass verges on both sides of the carriageway should be replaced with paved/raised verges and the entire structure should be waterproofed (such as an impermeable layer should be placed under the pavement);
- (iii) Both parapets should be upgraded to meet current standards.

It is recommended that the structure be inspected in year 2012, as per the Principal Inspection Report dated 1<sup>st</sup> October, 2008.



## Appendix A Sketches



.



# Appendix B Photographs





Photo 1. General view - Eastern elevation



Photo 2. General view - Western elevation





**Photo 3. Northern Departure (Increasing Chainage)** 



**Photo 4. Southern Departure (Decreasing Chainage)** 



Photo 5. Road surface



Photo 6. Western parapet



Photo 7. Eastern parapet



Photo 8. Eastern Headwall



Photo 9. Western Headwall



Photo 10. Span 1 soffit – water seepage & calcite staining




Photo 11. Span 2 soffit – water seepage



Photo 12. Southern abutment



Photo 13. Northern abutment



Photo 14. North face of pier



Photo 15. View through span 1



Photo 16. View through span 2





Photo 17. Upstream channel view



**Photo 18. Downstream Channel View** 



# Appendix C Site Investigation Results

### WS ATKINS IRELAND LTD.

STRADE RIVER BRIDGE
MO-N58-001.00
ISSUE DATE:
24<sup>TH</sup> JANUARY 2012

**REVISION NO. 1** 

Revision No.: 1

Our Ref : LMS/8623


**Issue Date**: 24<sup>th</sup> January 2012

Stanger
Stanger Testing Services Limited
Cambuslang Laboratory

Cambuslang Laboratory
Bogleshole Road Cambuslang
Glasgow G72 7DD
Telephone (0141) 641 3623
Fax (0141) 641 927

WS Atkins Ireland Limited Atkins House 150-155 Airside Business Park Swords Co. Dublin

#### REPORT ON THE INVESTIGATION OF BRIDGE: STRADE RIVER BRIDGE MAP REF 69 STRUCTURE I.D: MO-N58-001.00 STRUCTURE FORM: SLAB, SLAB



**Prepared by:** James Maddison B.Eng (Hons)

Engineer

Approved by: // Billy Johnstone B.Eng (Hons)

Manager/Engineer

#### **CONTENTS**

- 1. INTRODUCTION
- 2. SITE WORKS
- 3. RESULTS
- 4. QUALITY STATEMENT

APPENDIX A - LOCATION PLAN

APPENDIX B – CORE LOGS AND COMPRESSIVE STRENGTH CERTIFICATES

APPENDIX C – FERROSCANS

APPENDIX D - PLATE PAGES

#### 1. INTRODUCTION

Stanger Testing Services Ltd. were instructed by WS Atkins Ireland Ltd. on behalf of The National Roads Authority to carry out an investigation under task order 213 stage of Strade River bridge .

The object of the investigation was to determine the following:

- 1). Core strength of various elements
- 2). Typical reinforcement and cover to concrete elements
- 3). Articulation of the slab
- 4). Type and presence of water proofing
- 5). Depth of slab
- 6). Beam dimensions
- 7). Depth of fill over slab

#### 2. SITE WORKS

Stanger Testing Services carried out the investigation on the 1<sup>ST</sup> December 2011. All traffic management was in accordance with Chapter 8 of the Traffic Signs Manual 2009. Prior to hand excavating trial pits, the area was scanned for services using a cat scan. Wet drilling techniques were used to extract core samples. Each core was logged, photographed and individually numbered prior to being sealed in a sample bag for return to the laboratory for testing. A Hilti Ferrocan was used to determine the cover and the reinforcement layout a small breakout was performed at main and secondary steel to confirm the results of the Ferroscan. A breakout was performed at the base of the slab to determine the articulation. All core holes and breakout were repaired using a fast setting concrete repair material. Trial pits were reinstated and compacted in layers not exceeding 100mm and stabilized with cement.

#### 3. RESULTS

#### A) Concrete Cores

Core No.	Location	Compressive Strength (N/mm²)	As Received Density (kg/m³)
C1	Soffit span 1	30.9	2380
C2	Soffit span 1	27.4	2360
C3	Soffit span 1	32.1	2390
C4	Soffit span 2	32.6	2430
C5	Soffit span 2	38.1	2420
C6A	Soffit span 2	28.5	2380
C6B	Soffit span 2	13.5	2320

#### B) Cover Meter

Location: Soffit Span 1, Mid Span 1.8x1.8m (See Scan FB 011622)

Horizontal: Steel Beams Running From Abutment To Abutment (Slight Skew)

Beam Size: 125x125mm

Spacing: 600mm Cover: 70mm

Vertical: Secondary Steel Running Parallel To Abutment (Slight Skew) Between Beams

Bar Size: 28x14mm Rectangular Bar

Spacing: 140mm Cover: 60mm



Location: Soffit Span 1, Near Abutment 1.0x1.0m (See Scan FB 011626)

Horizontal: Steel Beams Running From Abutment To Abutment (Slight Skew)

Beam Size: 125x125mm

Spacing: 600mm Cover: 70mm

Vertical: Secondary Steel Running Parallel To Abutment (Slight Skew) Between Beams

Bar Size: 28x14mm Rectangular Bar

Spacing: 140mm Cover: 60mm



Location: Soffit Span 2, Mid Span 1.8x1.8m (See Scan FB 011621)

Horizontal: Steel Beams Running From Abutment To Abutment (Slight Skew)

Beam Size: 125x125mm

Spacing: 600mm Cover: 60mm

Vertical: Secondary Steel Running Parallel To Abutment (Slight Skew) Between Beams

Bar Size: 28x14mm Rectangular Bar

Spacing: 140mm Cover: 70mm



Location: Soffit Span 2, Near Abutment 1.0x1.0m (See Scan FB 011620)

Horizontal: Steel Beams Running From Abutment To Abutment (Slight Skew)

Beam Size: 125x125mm

Spacing: 600mm Cover: 60mm


Vertical: Secondary Steel Running Parallel To Abutment (Slight Skew) Between Beams

Bar Size: 28x14mm Rectangular Bar

Spacing: 140mm Cover: 70mm




#### Strade River Bridge



#### C) Articulation -

Location: Span No 1 (See Scan FB 11624)


None Found






Location: Span No 2 (See Scan FB 11619)

None Found





D) Trial Pit -

Location: Above Middle Pier In Verge 500mm From Parapet.

Note: Slab Is Not Continuous Over The Pier.

0.0 – 0.10 Topsoil

0.10 – 0.21 Granular Fill 0.21 – 0.23 Blacktop 10mm

0.23 - 0.57 Concrete




#### 4. QUALITY STATEMENT

We can confirm that in preparing this report we have exercised all reasonable skill and care.

### **APPENDIX A**

**LOCATION PLAN** 



### APPENDIX B

## CORE LOGS & COMP STRENGTH CERTIFICATES

Your Ref

Our Ref LMS/8623

Date 21 December 2011

W.S Atkins Ireland Limited

Atkins House

150-155 Airside Business Park

Swords Co.Dublin

#### CERTIFICATE OF TEST FOR COMPRESSIVE STRENGTH OF CONCRETE CORES TO BS EN 12504-1: 2009

Contract Strade River Bridge

Designation

Core Location Soffit Span 1 Date Cored 01/12/2011 Date Cast Not Stated Date Received 12/12/2011 Sample Ref. C1

GRN 23960

Cored By Stanger Testing Services Ltd.

Estimated Maximum Aggregate Size 40mm Max & Min Length as Received (mm) 160/150 Coring Direction Vertical Up Mean Diameter (mm) 92

Mean Length before End Preparation (mm) 90 Length/Diameter Ratio of Prepared Specimen (mm) 1.033

Position Relative to Total Length (mm) 20mm from top of core

Average Length after End Preparation (mm)

Method of End Preparation Sulphur Sand

Density as Received (kg/m³) 2380

Method Water Displacement

Date of Test 16/12/2011 Age at Test Date N/A Time Stored in Water before Test (days) 1 Day Surface Moisture at Test Moist

Maximum Load at Failure (kN) 205.7 Appearance at Failure Normal

Size, Position and Spacing of

Reinforcement Bars Not Applicable

Compressive Strength (N/mm<sup>2</sup>) 30.9 Estimated In-Situ Cube Strength (N/mm<sup>2</sup>) 31.3

Remarks:

Compaction Good Voids (%) 1 Honeycombing None Cracks None Aggregate Distribution Even

N.B.: Please be advised that all samples (if not destroyed during the testing process) will be disposed of 7 days from the date of issue of this report unless we received written instruction to retain them, in which case charges may apply.

Allan Reid

Billy Johnstone

James Maddison

Technical Director

Laboratory Supervisor

Manager/Engineer

Engineer

Stanger Testing Services Limited

Cambuslang Laboratory Bogleshole Road Cambuslang Glasgow G72 7DD

Telephone (0141) 641 3623 Email: stangertesting@aol.com

Fax (0141) 641 9279

Dundee Telephone (01382) 535272 Fax (01382) 530899



Group

CLIENT:	W.S Atkins Ireland L	imited	FILE REF:	8623		
STRUCTURE:	Strade River Bridge		LOCATION:	Soffit S	pan 1	
DATE CORED:	01/12/2011	CORED BY: Stanger	DATE R	EC'D: <u>1</u>	12/12/20	11
CORE MARK/N	Vo: <u>C1</u>	PHOTOGRAPH: Yes	GRN:		23960	
0 20	40 60 80	100 120 140 160				
20						
40 —	Compressive					
60 —	Strength		Aggregate Distribu	ution	:	Even
80 —			Nominal Maximur	n Size	:	40mm
100—			Compaction Rema	rks:		
			Compaction Excess Voidage		:	Good 1.0%
120-			Honeycombing		ì	None
140			Cracks		:	None
160			No of pieces		:	1
100						
180			Type of Aggregate Shape of Aggregate		: :	Crushed Rock Angular
220—			Presence of Microc	cracking	:	N/A
-						
240			Max/Min Length (r Diameter (mm)	nm)	: :	150/160 92mm
260			Depth of Carbonati	on	:	<1mm
280—						
300			Render	:	:	None
320			Repairs	:	:	None
340			Reinforcing Bars	:		None
360			No: N/A D	iameter:		N/A
380			Orientation of core			
400			With respect to struc	cture :		Vertical Up
420						
440						
460			Checked by :	-	S.Lilley	<u> </u>
480			Date :		16/12/20	11

500\_\_\_

CLIENT: W.S Atkins Ireland Limited FILE REF: 8623

STRUCTURE: Strade River Bridge LOCATION: Soffit Span 1

DATE CORED: <u>01/12/2011</u> CORED BY: <u>Stanger</u> DATE REC'D: <u>12/12/2011</u>

CORE MARK/No: C1 PHOTOGRAPH: Yes GRN: 23960



Your Ref

: :

Our Ref

LMS/8623

Date

21 December 2011

W.S Atkins Ireland Limited

Atkins House

150-155 Airside Business Park

Swords Co.Dublin

#### CERTIFICATE OF TEST FOR COMPRESSIVE STRENGTH OF CONCRETE CORES TO BS EN 12504-1: 2009

Contract

Strade River Bridge

Designation

Core Location Date Cored Date Cast

Soffit Span 1 01/12/2011 Not Stated

Date Received Sample Ref. **GRN** 

12/12/2011 C2

Cored By

23960 Stanger Testing Services Ltd.

Estimated Maximum Aggregate Size

40mm 140/120

Max & Min Length as Received (mm) Coring Direction Mean Diameter (mm)

Vertical Up 92

92

Mean Length before End Preparation (mm) Length/Diameter Ratio of Prepared Specimen (mm) :

1.054 20mm from top of core

Position Relative to Total Length (mm)

Average Length after End Preparation (mm)

Sulphur Sand

Method of End Preparation Density as Received (kg/m<sup>3</sup>)

Method Date of Test

Water Displacement 16/12/2011

Age at Test Date Time Stored in Water before Test (days) Surface Moisture at Test Maximum Load at Failure (kN)

N/A 1 Day Moist

Appearance at Failure

185.0 Normal

Size, Position and Spacing of

Reinforcement Bars

Not Applicable

Compressive Strength (N/mm<sup>2</sup>) Estimated In-Situ Cube Strength (N/mm<sup>2</sup>) 27.4 28.0

Remarks:

Compaction Voids (%) Honeycombing Cracks

Aggregate Distribution

Fair 1.0 None

None Even

N.B.: Please be advised that all samples (if not destroyed during the testing process) will be disposed of 7 days from the date of issue of this report unless we received written instruction to retain them, in which case charges may apply.

Allan Reid

Billy Johnstone

James Maddison

Technical Director

Laboratory Supervisor

Manager/Engineer

Engineer

Stanger Testing Services Limited

Cambuslang Laboratory Bogleshole Road Cambuslang Glasgow G72 7DD Telephone (0141) 641 3623 Fax (0141) 641 9279

Email: stangertesting@aol.com

Stanger Testing Services Limited Registered in Scotland No. SC219023 'Stanger' is a trademark VAT Registration No. 774 7634 86



CLIENT: <u>W.S</u>	Atkins Ireland Limited		FILE REF:	8623		
STRUCTURE: Strade River Bridge			LOCATION: Soffit Span 1			
DATE CORED: 01/1	<u>2/2011</u> C	ORED BY: Stanger	DATE	REC'D: 1	2/12/20	11
CORE MARK/No: <u>C2</u>		PHOTOGRAPH: Yes	_ GRN:		23960	
0 20 40	60 80 100	120 140 160				
40 — Comp Stren	pressive ngth		Aggregate Distri	bution	:	Even
80 —			Nominal Maxim	um Size	:	20mm
120			Compaction Ren Compaction Excess Voidage Honeycombing Cracks	narks:	:	Fair 1.5% None None
160—			No of pieces		:	1
180			Type of Aggrega Shape of Aggreg		:	Crushed Rock Angular
200—			Presence of Micr	ocracking	:	N/A
240—			Max/Min Length Diameter (mm)		© :	140/120 92mm
280—			Depth of Carbona	ation	:	<1mm
300						
320—			Render		:	None
340			Repairs		:	None
360			Reinforcing Bars	1	: !	None
380			No: N/A	Diameter	:	N/A
400			Orientation of cor With respect to st		1	Vertical Up
420						
440						
460			Checked by	: _	S.Lilley	8
480		1	Date	:	16/12/20	11
500						

CLIENT: W.S Atkins Ireland Limited FILE REF: 8623

STRUCTURE: Strade River Bridge LOCATION: Soffit Span 1

DATE CORED: 01/12/2011 CORED BY: Stanger DATE REC'D: 12/12/2011

CORE MARK/No: C2 PHOTOGRAPH: Yes GRN: 23960



Your Ref

Our Ref LMS/8623

Date 21 December 2011

W.S Atkins Ireland Limited

Atkins House

150-155 Airside Business Park

Swords Co.Dublin

#### CERTIFICATE OF TEST FOR COMPRESSIVE STRENGTH OF CONCRETE CORES TO BS EN 12504-1: 2009

Contract Strade River Bridge

Designation

Core Location Soffit Span 1 Date Cored 01/12/2011 Date Cast Not Stated Date Received 12/12/2011 Sample Ref.

C3 GRN 23960

Cored By Stanger Testing Services Ltd.

Estimated Maximum Aggregate Size 40mm Max & Min Length as Received (mm) 180/170 Coring Direction Vertical Up Mean Diameter (mm) 92

Mean Length before End Preparation (mm) 85 Length/Diameter Ratio of Prepared Specimen (mm) 0.99

Position Relative to Total Length (mm) 20mm from top of core

Average Length after End Preparation (mm)

Method of End Preparation Sulphur Sand

Density as Received (kg/m<sup>3</sup>) 2390

Method Water Displacement

Date of Test 16/12/2011 Age at Test Date N/A Time Stored in Water before Test (days) 1 Day Surface Moisture at Test Moist Maximum Load at Failure (kN) 213.3

Appearance at Failure Size, Position and Spacing of

Reinforcement Bars Not Applicable

Compressive Strength (N/mm<sup>2</sup>) 32.1 Estimated In-Situ Cube Strength (N/mm<sup>2</sup>) 31.7

Remarks:

Compaction Fair Voids (%) 1.5 Honeycombing None Cracks None Aggregate Distribution Even

N.B.: Please be advised that all samples (if not destroyed during the testing process) will be disposed of 7 days from the date of issue of this report unless we received written instruction to retain them, in which case charges may apply.

Allan Reid Billy Johnstone

James Maddison

Technical Director Laboratory Supervisor Manager/Engineer Engineer

Stanger Testing Services Limited

Cambuslang Laboratory Bogleshole Road Cambuslang Glasgow G72 7DD

Telephone (0141) 641 3623 Email: stangertesting@aol.com

Fax (0141) 641 9279

Dundee Telephone (01382) 535272 Fax (01382) 530899

Normal



CLIENT:	W.S Atkins Ireland Lim	nited	FILE REF: 862	3	
STRUCTURE:	STRUCTURE: Strade River Bridge		LOCATION: Soffit Span 1		
DATE CORED:	01/12/2011	CORED BY: Stanger	DATE REC'I	D: 12/12/2	011
CORE MARK/N	o: <u>C3</u>	PHOTOGRAPH: Yes	GRN:	23960	100
0 20	40 60 80 1	00 120 140 160			
20					
40 —	Compressive				
60 —	Strength		Aggregate Distribution	:	Even
80 —			Nominal Maximum Siz	e :	20mm
			Compaction Remarks:		
100			Compaction	:	Fair
120			Excess Voidage Honeycombing	:	1.5% None
			Cracks	:	None
140			No of pieces	:	1
160—					
180-			Type of Aggregate	:	Crushed Rock
200—			Shape of Aggregate	:	Angular
220—			Presence of Microcrack	ing:	N/A
240—			Man /Mi - T 1 / N		100/170
			Max/Min Length (mm) Diameter (mm)	:	180/170 92mm
260—			Depth of Carbonation	:	<1mm
280—			- I	•	
300—					
320			Render	1	None
340			Repairs	:	None
360			Reinforcing Bars	:	None
380			No: N/A Diame	ter:	N/A
			Orientation of core		
400			With respect to structure	:	Vertical Up
420					
440					
460		1	Checked by :	S.Lilley	ý
480		1	Date :	16/12/20	011
500					

CLIENT: W.S Atkins Ireland Limited FILE REF: 8623

STRUCTURE: Strade River Bridge LOCATION: Soffit Span 1

DATE CORED: 01/12/2011 CORED BY: Stanger DATE REC'D: 12/12/2011

CORE MARK/No: C3 PHOTOGRAPH: Yes GRN: 23960



Your Ref :

Our Ref : LMS/8623

Date : 21 December 2011

W.S Atkins Ireland Limited

Atkins House

150-155 Airside Business Park

Swords Co.Dublin

#### CERTIFICATE OF TEST FOR COMPRESSIVE STRENGTH OF CONCRETE CORES TO BS EN 12504-1 : 2009

Contract : Strade River Bridge

Designation : C4

 Core Location
 : Soffit Span 2

 Date Cored
 : 01/12/2011

 Date Cast
 : Not Stated

 Date Received
 : 12/12/2011

 Sample Ref.
 : C4

GRN : 23960

Cored By : Stanger Testing Services Ltd.

Estimated Maximum Aggregate Size : 20mm

Max & Min Length as Received (mm) : 225/225

Coring Direction : Vertical Up

Mean Diameter (mm) : 92

Mean Diameter (mm) : 92
Mean Length before End Preparation (mm) : 93
Length/Diameter Ratio of Prepared Specimen (mm) : 1.065

Position Relative to Total Length (mm) : 30mm from top of core

Average Length after End Preparation (mm) : 98

Method of End Preparation : Sulphur Sand

Density as Received (kg/m<sup>3</sup>) : 2430

Method : Water Displacement

Date of Test : 16/12/2011
Age at Test Date : N/A
Time Stored in Water before Test (days) : 1 Day
Surface Moisture at Test : Moist
Maximum Load at Failure (kN) : 217.0

Appearance at Failure : Normal

Size, Position and Spacing of

Reinforcement Bars : Not Applicable

Compressive Strength (N/mm<sup>2</sup>) : 32.6 Estimated In-Situ Cube Strength (N/mm<sup>2</sup>) : 33.5

Remarks:

Compaction: GoodVoids (%): 1Honeycombing: NoneCracks: NoneAggregate Distribution: Even

N.B.: Please be advised that all samples (if not destroyed during the testing process) will be disposed of 7 days from the date of issue of this report unless we received written instruction to retain them, in which case charges may apply.

Laurie Murphy Allan Reid
Technical Director Laboratory Sup

Billy Johnstone

James Maddison

Laboratory Supervisor Manager/Engineer Engineer

Stanger Testing Services Limited

Cambuslang Laboratory Bogleshole Road Cambuslang Glasgow G72 7DD

Telephone (0141) 641 3623 Fax (0141) 641 9279

Email: stangertesting@aol.com

Stanger Testing Services Limited Registered in Scotland No. SC219023 'Stanger' is a trademark VAT Registration No. 774 7634 86 Dundee Telephone (01382) 535272 Fax (01382) 530899



DATE CORED   1/12/2011   CORED BY; SIBBURET   DATE REC'D: 12/12/2011	CLIENT:	CLIENT: W.S Atkins Ireland Limited		FILE REF: 86	23		
O 20 40 60 80 100 120 140 160	STRUCTURE:	STRUCTURE: Strade River Bridge		LOCATION: Sof	fit Span 2		
20	DATE CORED:	01/12/2011	CORED E	BY: Stanger	DATE REC	'D: <u>12/12/2</u> 0	011
20   Compressive Strength   Aggregate Distribution : Even	CORE MARK/N	To: <u>C4</u>	РНОТО	GRAPH: Yes	GRN:	23960	)
20   Compressive Strength   Aggregate Distribution : Even							
Aggregate Distribution : Even	0 20	40 60 80	100 120	140 160			
Aggregate Distribution : Even							
Strength   Aggregate Distribution : Even	20						
Nominal Maximum Size : 20mm					Aggregate Distribution	n :	Even
Compaction Remarks:   Compaction   Good     Excess Voidage   1.0%     Honeycombing   None     Cracks   None     No of pieces   1     Type of Aggregate   Crushed Rock     Shape of Aggregate   Angular     Presence of Microcracking: N/A					Nominal Maximum Si	ize :	20mm
Excess Voidage						:	
Honeycombing   None	100						
Cracks	120—					:	
140	-					:	
Type of Aggregate	140—				No of nieces	•	
Shape of Aggregate : Angular  Presence of Microcracking: N/A  Max/Min Length (mm) : 225/225 Diameter (mm) : 92mm  Depth of Carbonation : <1mm  Render : None  Repairs : None  Reinforcing Bars : None  No: N/A Diameter: N/A  Orientation of core With respect to structure : Vertical Up  400  Checked by : S.Lilley  440  Checked by : S.Lilley  Date : 16/12/2011	160—				The of pieces	•	
200 220 240  Max/Min Length (mm) : 225/225 260  280  Depth of Carbonation : <imm 12="" 16="" 2011<="" 320="" 340="" 440="" 480="" :="" a="" bars="" by="" checked="" core="" date="" diameter:="" n="" no:="" none="" of="" orientation="" reinforcing="" render="" repairs="" respect="" s.lilley="" structure="" td="" to="" up="" vertical="" with=""><td>180</td><td></td><td></td><td></td><td></td><td>:</td><td>Crushed Rock</td></imm>	180					:	Crushed Rock
220 240  Max/Min Length (mm) : 225/225 Diameter (mm) : 92mm  Depth of Carbonation : <imm 12="" 16="" 2011<="" 400="" 480="" :="" a="" bars="" by="" checked="" core="" date="" diameter:="" n="" no:="" none="" of="" orientation="" reinforcing="" render="" repairs="" respect="" s.lilley="" structure="" td="" to="" up="" vertical="" with=""><td>200—</td><td></td><td></td><td></td><td>Shape of Aggregate</td><td>:</td><td>Angular</td></imm>	200—				Shape of Aggregate	:	Angular
Diameter (mm)	220—				Presence of Microcrac	king:	N/A
Diameter (mm)	240				Max/Min I ength (mm)	٠.	225/225
Depth of Carbonation							
Render	-				Depth of Carbonation	:	<1 mm
Render							
Repairs					Render	•	None
Reinforcing Bars : None    No: N/A   Diameter: N/A					Repairs	:	None
No: N/A Diameter: N/A  Orientation of core With respect to structure : Vertical Up  440  Checked by : S.Lilley  Date : 16/12/2011					Reinforcing Bars	:	None
Orientation of core With respect to structure : Vertical Up  420  440  Checked by : S.Lilley  Date : 16/12/2011					No: N/A Diam	ieter:	N/A
400	380				Orientation of		
420	400					re :	Vertical Un
440	420				<b>→</b>	- S	» ««« • • • • • • • • • • • • • • • • •
460	_						
480					Checked by	Q T :11	
A COLUMN AND A COL							
					Date :	16/12/20	011

CLIENT:	W.S Atkins Ireland Limited	FILE REF:	8623
STRUCTURE:	Strade River Bridge	LOCATION:	Soffit Span 2

DATE CORED: 01/12/2011 CORED BY: Stanger DATE REC'D: 12/12/2011

CORE MARK/No: C4 PHOTOGRAPH: Yes GRN: 23960



Your Ref :

Our Ref : LMS/8623

Date : 21 December 2011

W.S Atkins Ireland Limited

Atkins House

150-155 Airside Business Park

Swords Co.Dublin

#### CERTIFICATE OF TEST FOR COMPRESSIVE STRENGTH OF CONCRETE CORES TO BS EN 12504-1 : 2009

Contract : Strade River Bridge

Designation : C5

 Core Location
 : Soffit Span 2

 Date Cored
 : 01/12/2011

 Date Cast
 : Not Stated

 Date Received
 : 12/12/2011

 Sample Ref.
 : C5

 GRN
 : 23960

Cored By : Stanger Testing Services Ltd.

Estimated Maximum Aggregate Size : 40mm

Max & Min Length as Received (mm) : 135/125

Coring Direction : Vertical Up

Mean Diameter (mm) : 92
Mean Length before End Preparation (mm) : 94
Length/Diameter Ratio of Prepared Specimen (mm) : 1.076

Position Relative to Total Length (mm) : 20mm from top of core

Average Length after End Preparation (mm) : 99

Method of End Preparation : Sulphur Sand

Density as Received (kg/m<sup>3</sup>) : 2420

Method : Water Displacement
Date of Test : 16/12/2011

Date of Test : 16/12/2011

Age at Test Date : N/A

Time Stored in Water before Test (days) : 1 Day

Surface Moisture at Test : Moist

Maximum Load at Failure (kN) : 253.0

Appearance at Failure : Normal

Size, Position and Spacing of

Reinforcement Bars : Not Applicable

Compressive Strength (N/mm<sup>2</sup>) : 38.1 Estimated In-Situ Cube Strength (N/mm<sup>2</sup>) : 39.2

Remarks:

Compaction: GoodVoids (%): 1Honeycombing: NoneCracks: NoneAggregate Distribution: Even

N.B.: Please be advised that all samples (if not destroyed during the testing process) will be disposed of 7 days from the date of issue of this report unless we received written instruction to retain them, in which case charges may apply.

Laurie Murphy Allan Reid Billy Johnstone James Maddison Technical Director Laboratory Supervisor Manager/Engineer Engineer

Stanger Testing Services Limited

Cambuslang Laboratory Bogleshole Road Cambuslang Glasgow G72 7DD

Telephone (0141) 641 3623 Fax (0141) 641 9279

Email: stangertesting@aol.com Stanger Testing Services Limited Registered in Scotland No. SC219023

'Stanger' is a trademark VAT Registration No. 774 7634 86

Dundee Telephone (01382) 535272 Fax (01382) 530899



CLIENT: W.S Atkins Ireland Limited FILE REF: 8623 STRUCTURE: Strade River Bridge LOCATION: Soffit Span 2 DATE CORED: 01/12/2011 CORED BY: Stanger DATE REC'D: 12/12/2011 CORE MARK/No: C5 PHOTOGRAPH: Yes GRN: 23960 0 20 40 60 80 100 120 140 160 20 40 Compressive Strength Aggregate Distribution Even 60 Nominal Maximum Size : 40mm 80 Compaction Remarks: 100-Compaction Good Excess Voidage 1.0% 120-Honeycombing None Cracks None 140-No of pieces 1 160-180-Type of Aggregate Crushed Rock Shape of Aggregate Angular 200-Presence of Microcracking: N/A 220-240-Max/Min Length (mm) 125/135 Diameter (mm) 92mm 260-Depth of Carbonation <1mm 280-300-Render None : 320-Repairs None 340-Reinforcing Bars None 360-No: N/A Diameter: N/A 380-Orientation of core 400-With respect to structure: Vertical Up 420-440\_ 460\_ Checked by S.Lilley 480\_ Date 16/12/2011

500

CLIENT: W.S Atkins Ireland Limited FILE REF: 8623

STRUCTURE: Strade River Bridge LOCATION: Soffit Span 2

DATE CORED: 01/12/2011 CORED BY: Stanger DATE REC'D: 12/12/2011

CORE MARK/No: C5 PHOTOGRAPH: Yes GRN: 23960



## Stanger

Your Ref

O D s

Our Ref : LMS/8623

Date: 21 December 2011

W.S Atkins Ireland Limited

Atkins House

150-155 Airside Business Park

Swords Co.Dublin

#### CERTIFICATE OF TEST FOR COMPRESSIVE STRENGTH OF CONCRETE CORES TO BS EN 12504-1 : 2009

Contract : Strade River Bridge

 Designation
 : C6A

 Core Location
 : Soffit Span 2

 Date Cored
 : 01/12/2011

 Date Cast
 : Not Stated

 Date Received
 : 12/12/2011

 Sample Ref.
 : C6A

 GRN
 : 23960

Cored By : Stanger Testing Services Ltd.

Estimated Maximum Aggregate Size : 20mm

Max & Min Length as Received (mm) : 340/340

Coring Direction : Vertical Down

Mean Diameter (mm) : 92
Mean Length before End Preparation (mm) : 85
Length/Diameter Ratio of Prepared Specimen (mm) : 0.98

Position Relative to Total Length (mm) : 20mm from top of core

Average Length after End Preparation (mm) : 90

Method of End Preparation : Sulphur Sand

Density as Received (kg/m<sup>3</sup>) : 2440

Method : Water Displacement

Date of Test : 16/12/2011
Age at Test Date : N/A
Time Stored in Water before Test (days) : 1 Day
Surface Moisture at Test : Moist
Maximum Load at Failure (kN) : 189.6
Appearance at Failure : Normal

Size, Position and Spacing of

Reinforcement Bars : Not Applicable

Compressive Strength (N/mm<sup>2</sup>) : 28.5 Estimated In-Situ Cube Strength (N/mm<sup>2</sup>) : 28.3

Remarks:

Compaction : Good
Voids (%) : 1.5
Honeycombing : None
Cracks : None
Aggregate Distribution : Even

N.B.: Please be advised that all samples (if not destroyed during the testing process) will be disposed of 7 days from the date of issue of this report unless we received written instruction to retain them, in which case charges may apply.

Laurie Murphy Allan Reid Billy Johnstone James Maddison
Technical Director Laboratory Supervisor Manager/Engineer Engineer

Stanger Testing Services Limited

Cambuslang Laboratory Bogleshole Road Cambuslang Glasgow G72 7DD

Telephone (0141) 641 3623 Fax (0141) 641 9279

Email: stangertesting@aol.com

Stanger Testing Services Limited Registered in Scotland No. SC219023 'Stanger' is a trademark VAT Registration No. 774 7634 86 Dundee Telephone (01382) 535272 Fax (01382) 530899





Your Ref :

Our Ref : LMS/8623

Date: 21 December 2011

W.S Atkins Ireland Limited

Atkins House

150-155 Airside Business Park

Swords Co.Dublin

### CERTIFICATE OF TEST FOR COMPRESSIVE STRENGTH OF CONCRETE CORES TO BS EN 12504-1 : 2009

Contract : Strade River Bridge

Designation : C6B

 Core Location
 :
 Soffit Span 2

 Date Cored
 :
 01/12/2011

 Date Cast
 :
 Not Stated

 Date Received
 :
 12/12/2011

 Sample Ref.
 :
 C6B

 GRN
 :
 23960

Cored By : Stanger Testing Services Ltd.

Estimated Maximum Aggregate Size : 20mm

Max & Min Length as Received (mm) : 340

Coring Direction : Vertical Up

Mean Diameter (mm) : 92
Mean Length before End Preparation (mm) : 85
Length/Diameter Ratio of Prepared Specimen (mm) : 0.99

Position Relative to Total Length (mm) : 220mm from top of core

Average Length after End Preparation (mm) : 91

Method of End Preparation : Sulphur Sand

Density as Received (kg/m<sup>3</sup>) : 2320

Method : Water Displacement

Date of Test : 16/12/2011
Age at Test Date : N/A
Time Stored in Water before Test (days) : 1 Day
Surface Moisture at Test : Moist
Maximum Load at Failure (kN) : 89.8
Appearance at Failure : Normal

Size, Position and Spacing of

Reinforcement Bars : Not Applicable

Compressive Strength (N/mm<sup>2</sup>) : 13.5 Estimated In-Situ Cube Strength (N/mm<sup>2</sup>) : 13.3

Remarks:

Compaction: GoodVoids (%): 2.0Honeycombing: NoneCracks: NoneAggregate Distribution: Even

N.B.: Please be advised that all samples (if not destroyed during the testing process) will be disposed of 7 days from the date of issue of this report unless we received written instruction to retain them, in which case charges may apply.

Laurie Murphy Allan Reid Billy Johnstone James Maddison
Technical Director Laboratory Supervisor Manager/Engineer Engineer

Stanger Testing Services Limited

Cambuslang Laboratory Bogleshole Road Cambuslang Glasgow G72 7DD

Telephone (0141) 641 3623 Fax (0141) 641 9279

Email: stangertesting@aol.com

Stanger Testing Services Limited Registered in Scotland No. SC219023 'Stanger' is a trademark VAT Registration No. 774 7634 86 Dundee Telephone (01382) 535272 Fax (01382) 530899



#### CONCRETE CORE LOG

CLIENT: W.S Atkins Ireland Limited FILE REF: 8623 STRUCTURE: Strade River Bridge LOCATION: Soffit Span 2 DATE CORED: 01/12/2011 CORED BY: Stanger DATE REC'D: 12/12/2011 CORE MARK/No: C6 PHOTOGRAPH: Yes GRN: 23960 0 20 40 60 80 100 120 140 160 20 40 Compressive Strength Aggregate Distribution Even 60 Nominal Maximum Size : 20mm 80 Compaction Remarks: 100-Compaction Good Excess Voidage 1.5% . 120-Honeycombing None Cracks None 140 No of pieces 3 160 180-Type of Aggregate Crushed Rock Shape of Aggregate Angular 200-Presence of Microcracking: N/A 220-240-Max/Min Length (mm) 340/340 Compressive Diameter (mm) 92mm 260-Strength Depth of Carbonation <1mm 280-300-Render None 320-Repairs None 340 Reinforcing Bars None 360-No: N/A Diameter: N/A 380-Orientation of core 400-With respect to structure: Vertical Up 420 440 460\_ Checked by S.Lilley 480\_ Date 16/12/2011

500

#### CONCRETE CORE LOG

CLIENT: W.S Atkins Ireland Limited FILE REF: 8623

STRUCTURE: Strade River Bridge LOCATION: Soffit Span 2

DATE CORED: 01/12/2011 CORED BY: Stanger DATE REC'D: 12/12/2011


CORE MARK/No: <u>C6</u> PHOTOGRAPH: <u>Yes</u> GRN: <u>23960</u>



LMS/8623 – Strade River Bridge WS Atkins Ireland Limited Unit 2B 2200 Cork Airport Business Park, Cork, Ireland

## APPENDIX C

**FERROSCANS** 



Customer: W.S Atkins

Location: Soffit Span No 1, Mid Span 1.8x1.8m Operator: B.Johnstone

#### Comment:

Horizontal: Steel Beams Running From Abutment To Abutment (Slight Skew)

Beam Size: 125x125mm

Spacing: 600mm Cover: 70mm


Vertical: Secondary Steel Running Parallel To Abutment (Slight Skew) Between Beams

Bar Size: 28x14mm Rectangular Bar

Spacing: 140mm Cover: 60mm

File Storage:

Z:\PROJEC~1\IRELAN~1\STRADE~1\Prj00003\FB011622.XFF



Customer: W.S Atkins

Location: Soffit Span No 1 Near Abutment 1.0x1.0marator: B.Johnstone

#### Comment:

Horizontal: Steel Beams Running From Abutment To Abutment (Slight Skew)

Beam Size: 125x125mm

Spacing: 600mm Cover: 70mm


Vertical: Secondary Steel Running Parallel To Abutment (Slight Skew) Between Beams

Bar Size: 28x14mm Rectangular Bar

Spacing: 140mm Cover: 60mm

File Storage:

Z:\scott\11111\MON580~1\Prj00003\FB011626.XFF



Customer: W.S Atkins

Location: Soffit Span No 2, Mid Span 1.8x1.8m Operator: B.Johnstone

#### Comment:

Horizontal: Steel Beams Running From Abutment To Abutment (Slight Skew)

Beam Size: 125x125mm


Spacing: 600mm Cover: 60mm

Vertical: Secondary Steel Running Parallel To Abutment (Slight Skew) Between Beams

Bar Size: 28x14mm Rectangular Bar

Spacing: 140mm Cover: 70mm Blockscan:

FB011620.XFF



Customer: W.S Atkins

Location: Soffit Span No 2 Near Abtument 1.0x1.0marator: B.Johnstone

#### Comment:

Horizontal: Steel Beams Running From Abutment To Abutment (Slight Skew)

Beam Size: 125x125mm

Spacing: 600mm Cover: 60mm


Vertical: Secondary Steel Running Parallel To Abutment (Slight Skew) Between Beams

Bar Size: 28x14mm Rectangular Bar

Spacing: 140mm Cover: 70mm



### FS011624.XFF



Customer: W.S Atkins


Location: Span No 1 Operator: B.Johnstone

Comment:

None Found

Imagescan:

FS011619.XFF



Customer: W.S Atkins

Location: Span No 2 Operator: B.Johnstone

Comment:

None Found

LMS/8623 – Stade River Bridge WS Atkins Ireland Limited Unit 2B 2200 Cork Airport Business Park, Cork, Ireland

# APPENDIX D

PLATE PAGES



**Beam** 




**Beam** 




**Beam** 



**Beam** 



**Beam** 




**Scan Location** 



## **Appendix D**

**Calculations** 



ΛΤK	INS		Project	NR	A Eirspan	Task Order	213	<b>Job ref</b> 3044		
			Part of Str	ucture				Calc shee		
			MO-N58-00	1.00				2	0	
			Drawing R	ef	Calc By		Date	Check by	Date	
			MO-N58-00		CP		13-Feb-12	PG	14-Feb-12	
Ref				Calcu	ılations			Οι	itput	
		ATION O			LE STRE	ENGTH				
						1	7			
				ESTIM						
		LOCATION	CORE	IN-SITU		(fc - MEAN) <sup>2</sup>				
			REFERENCE	STRENGTH						
App.C2			C4		33.5	23.36	1			
SI Report			C5		39.2	110.95				
			C6b		13.3	236.13	1			
						-				
							]			
						-	]			
						-	]			
						-				
						-	]			
					<u> </u>	=	]			
				TOTAL	86	370.44667				
			N	o of cores	3					
				MEAN	28.67					
			Standard	Deviation	13.61					
	n =	Note - onl	y use this fo	or cores take	en at the lo	= total numb cation of inte n^0.5)))/10				
							WCS =	25.4	N/mm <sup>2</sup>	
		/EST COF		I <b>GTH</b> :	N/mm2		WCS =	13.3	N/mm <sup>2</sup>	
	Using th	e above r	esults an	d engine	ering jud	lgement,			1	
		the	propose	d WCS =	13.3	N/mm <sup>2</sup>				

	AT1/1	NIC		Project	NRA Eirsp	an Task Order 2	Task Order 213 3044			
	<b>NTKI</b>	NS		Part of Stru MO-N58-00		Filler Beam Ca	pacity		Calc sheet no.	Re
				Drawing ref.		Calc by		Date	Check by	Date
Ref					Ca	CP alculations		13-02-12	PG	14-02-1
	9	AGGING - SE	CTION PROF	ERTIES (II	eina RS	5400 Part 3:2	000) for com	posite section		
	_	Tadiita - DE			Jing Do	1		- -		
	Slab	Slab	Width (mm)	Depth (mm)		fcu <sub>(MPa)</sub>	E(short Term) 23.6	Panel Length (mm)		Section depth mi
	Haunch		Width (mm)	Depth (mm)		fcu <sub>(MPa)</sub>	E(short Term)	4		
	Girder	Haunch	Width (mm)	Depth (mm)		f <sub>y (MPa)</sub>	E (GPa)	NA		m
	Girao.	Top Flange	50	30		230	205.0	1		8.6
		Web Bottom Flange	10 125	85 10		230 230	205.0 205.0			
		Bottom Cover		60	mm			_		ļ
	e) Plastic Section nb if NA lies below	the web this do	esn't work			Condition fact	tor for RC Filler	-	0.9	
	Stress in concrete = Stress in steel = $\sigma_{y/}$	00	γ <sub>m</sub> =	1.05						
		Depth (mm)	Width (mm)	Area (mm²)	Stress (Nmm <sup>-2</sup> )	Force (kN)	Force above NA (kN)	Force below NA (kN)	y above NA (mm)	y below NA (mm)
	Slab* Haunch	155 0	600 0	93000 0	5 0	495 0	495 0	-	91 0	-
	Top Flange Web	30 85	50 10	1500 850	219	329	147 0	182	7 -17	8 59
	Bottom Flange	10	125	1250	219 219	186 274	-	186 274	-17	107
	NA lies ir	n Top Flange	*Co	ncrete above	beam only	taken in properti	es			
	Depth of Neutral A	xis From Top SI	ab 1		Co	ncrete M <sub>plastic</sub> =	45	kNm		
	Slab	Depth (mm) 0.0			Single	Beam M <sub>plastic</sub> =	38	kNm		
	Haunch Top Flange	0.0 168.4								
	Web	0.0	m=	= 0.0						
9.3.7.2	f) Compactness Collif m < 0.5 If m > 0.5 If web fully in tension	Check web dept	h is less than			<sub>w</sub> )^0.5	n/a n/a	mm mm	(Compact?) n/a n/a yes	
	Section is Compac		AGGING - P	LASTIC CH	ECKS (U	sing BS 5400	Part 3;2000	1		
	2. ULS Bending Ca				-	-				
		M <sub>plastic</sub> =		kNm						
	M	$M_{pe (unfactored)} = M_{pe} / 1.05 \times 1.1 =$		kNm kNm	(Also Adiu	stad by condition	factor)			
3/9.9.2.2	3. ULS Pure Shear	P -		KINIII	(Also Adju	sted by conditior	i iacior)			
	Depth of panel = d <sub>w</sub>		=	85	mm					
	Aspect Ratio = $\varphi$ =		=	1.000						
	b <sub>fe</sub> (top flange)	2 0	=	- 0		b <sub>fe</sub> (bottom flan		0		
	$m_{fw}$ (top flange) = $\sigma$ Minimum value of n			0.1557		$m_{fw}(bot) = \sigma_{yf}b_{fe}$ $\lambda = (d_{we}/t_w)x(\sigma_{ye})$		0.0433 6.8		
	$\tau_{y} = \sigma_{yw}/\sqrt{3}$	iifw ioi use iii silea	r calcs. =	0.0433 132.79		$\Lambda = (\mathbf{u}_{We}/\mathbf{t}_{W})\mathbf{X}(\mathbf{u}_{y})$	<sub>w</sub> /333) =	0.0		
0/E: 10.10		0.0400		4 000		_	170 50			
3/Fig12-18	$\tau_I/\tau_y$ for $m_{fw}$ of $\tau_I/\tau_y$ for $m_{fw}$ of			= 1.300 = 1.300		T <sub>I =</sub> T <sub>I =</sub>				
3/9.9.2.2	$V_D = (d_w t_w x \tau_I) / (\gamma_m \gamma_f$	3)	=	= 114.3	kN	When m <sub>fw</sub> =	0.1557	(Adjusted by cond	lition factor)	
	V <sub>R</sub> = ""		=	= 114.3	kN	When m <sub>fw</sub> =	0.0000	(Adjusted by cond	lition factor)	
										1



Project NRA Eirspa	Job ref				
			3044		
Part of Structure	Filler Beam Capacity		Calc sheet no.		Rev
MO-N58-001.00			4		0
Drawing ref.	Calc by	Date	Check by	Date	
	CP	13-02-12	PG		14-02-12

mm

(Compact?)

n/a

Calculations Ref

#### SAGGING - SECTION PROPERTIES (Using BS 5400 Part 3:2000) for Steel Section (IGNORING CONCRETE)

Slab		Width (mm)	Donth		four	E(short Term)	D	,	l Castian danth :
Siab		Width (mm)	Depth (mm)		fcu <sub>(MPa)</sub>	E(Short Term)	Panei Length (mm)	3	Section depth r
	Slab	600	125		13.3	23.591			125
Haunch		Width (mm)	Depth (mm)		fcu (MPa)	E(short Term)	NA		
	Haunch	0	0		0	0	NA		
Girder		Width (mm)	Depth (mm)		f <sub>y (MPa)</sub>	E (GPa)			
	Top Flange	50	30		230	205			
	Web	10	85		230	205			
	Bottom Flange	125	10		230	205			
	Bottom Cover		60	mm					
e) Plastic Section	Properties				Condition fac	tor for RC Filler	-	0.9	

nb if NA lies below the web this doesn't work

Stress in concrete = 0.4\*f<sub>cu</sub>

Stress in steel =  $\sigma_y/\gamma_m$ 

 $\gamma_{\rm m} = 1.05$ 

	Depth (mm)	Width (mm)	Area (mm²)	Stress (Nmm <sup>-2</sup> )	Force (kN)	Force above NA (kN)	Force below NA (kN)	y above NA (mm)	y below NA (mm)
Slab*	-60	600	-36000	5	-192	-192	-	74	-
Haunch	0	0	0	0	0	0	-	0	-
Top Flange	30	50	1500	219	329	329	0	89	-74
Web	85	10	850	219	186	161	25	37	6
Bottom Flange	10	125	1250	219	274	-	274	-	16

\*Concrete above beam only taken in properties

Web

Depth of Neutral Axis From Top Slab Concrete M<sub>plastic</sub> = -14 kNm Single Beam M<sub>plastic</sub> = kNm Depth (mm) 36

Slab 0.0 Haunch 0.0 Top Flange 0.0 Web 43.7

NA lies in

m= 0.9

Depth of Plastic NA = 43.7

f) Compactness Check

9.3.7.2 If m < 0.5 Check web depth is less than  $(34t_w/m)^*(355/\sigma_{yw})^0.5$ n/a mm n/a If m > 0.5 Check web depth is less than  $(374t_w/(13m-1))^*(355/\sigma_{vw})^0.5$ 452.2410439 mm yes

If web fully in tension section is compact

Section is Compact

#### SAGGING - PLASTIC CHECKS (Using BS 5400 Part 3:2000)

#### 2. ULS Bending Capacity of Section


M<sub>plastic</sub> = 26 kNm 27 kNm  $M_{pe (unfactored)} =$ 


 $M_D = M_{pe} / 1.05 \times 1.1 =$ kNm (Also Adjusted by condition factor)


Ref BD21/01	Part of Structure MO-N58-001.00 Drawing Ref MO-N58-001.00						
Ref BD21/01 <b>S</b>			Assessm	ent using BD21/01	Filler Beam	Calc sheet no. rev	
Ref BD21/01 S	MO-N58-001.00		Calc By	20	Date	Check by Date	
BD21/01 <b>§</b>		Calcula		CP	13-Feb-12	PG 14-Feb- Output	
Cl 5.3.1.1 of		Odiodio	1110113			Output	
<u> </u>	Slab Details :	Filler Beam - Spa	an 1 (South)				
<u> </u>	Depth of slab		(mm)	340			
<u> </u>	Clear Span		(m)	3.36			
BD44/95	Effective Span		(m)	3.64			
<u> </u>	Slab width	(mm)	600				
<u> </u>	Depth of fill above RC Condition factor for RC		(mm) -	230		and antaite	
	Condition actor for no	Jolan			r seepage, locali ing & stalactites		
SI Report	Material Details :						
-		Beam Depth	(mm)	125			
	Main Tension Steel	Spacing	(mm)	600			
	Wall Follow Clock	As	(mm2)	4433			
C	Concrete cover to tension steel		(mm)	60			
	Secondary reinforcement dia		(mm)	0			
Is	s tension steel the outer layer of re		Y/N	Y			
	effective depth	d	(mm)	280			
	Concrete Density		kN/m3	23.9			
	Surfacing Density		kN/m3	23.0			
	Fill Density	WCS, fcu	kN/m3	20.0			
	Concrete WCS Strength Steel Characteristic Strength	fy	(N/mm2)	13 230			
	Material Factor for Concrete	Ymc	(14/1111112)	1.20			
	Material Factor for Steel	Yms		1.05			
	=>	xu	(mm)	168.4		Filler Beam Moment Capacity	
<u> </u>	=> M. Capacity	xu M <sub>C</sub>	(mm) (kNm/m)	168.4 72			
N	M. Capacity	M <sub>C</sub>	(kNm/m)	72		Moment Capacity	
<u>N</u>	M. Capacity  Calculation of Shear Capace Shear checked at 2 locations	M <sub>c</sub> city of Section  (i) a <sub>v</sub> = d from fac	(kNm/m) n near sup	72  ports: (with shear enhance	ement if applicab	Moment Capacity 71.7 kNm	
<u>N</u>	M. Capacity  Calculation of Shear Capace Shear checked at 2 locations	M <sub>c</sub> city of Section  (i) a <sub>v</sub> = d from fac	(kNm/m) n near sup	72 ports :	ement if applicab	Moment Capacity 71.7 kNm	
<u>N</u> S	M. Capacity  Calculation of Shear Capace Shear checked at 2 locations	M <sub>c</sub> city of Section  (i) a <sub>v</sub> = d from fac	(kNm/m) n near sup	72  ports: (with shear enhance	ement if applicab	Moment Capacity 71.7 kNm	
<u>N</u> <u>C</u> S	M. Capacity  Calculation of Shear Capace Shear checked at 2 locations	$M_{C}$ city of Section  (i) $a_{v} = d$ from fac  (ii) $a_{v} = 2d$ from f	(kNm/m) n near sup	72  ports: (with shear enhance of the content of th	ement if applicab	Moment Capacity 71.7 kNm	
<b>N S S</b>	M. Capacity  Calculation of Shear Capace Shear checked at 2 locations	M <sub>c</sub> city of Section  (i) a <sub>v</sub> = d from fac  (ii) a <sub>v</sub> = 2d from fac	(kNm/m) n near support ace of support	72  ports: (with shear enhance of the control of th	ement if applicab	Moment Capacity 71.7 kNm	
In Cable 4A of BD44/95	M. Capacity  Calculation of Shear Capace Shear checked at 2 locations  100As/b <sub>w</sub> d  Depth Factor Material FOS for Concrete in Shear Ultimate shear stress	$M_{C}$ city of Section  (i) $a_{v} = d$ from fac  (ii) $a_{v} = 2d$ from fac  - $\xi_{s}$ Ymc  VC	(kNm/m) n near support ace of support	72  ports: (with shear enhance of the first (without shear enlarge)  2.6  1.18  1.15  0.677	ement if applicab	Moment Capacity 71.7 kNm	
1 Cable 4A of BD44/95 US	M. Capacity  Calculation of Shear Capace Shear checked at 2 locations  100As/b <sub>w</sub> d  Depth Factor Material FOS for Concrete in Shear Ultimate shear stress Shear link diameter	$M_{C}$ city of Section  (i) $a_{v} = d$ from fac  (ii) $a_{v} = 2d$ from fac  - $\xi_{s}$ Ymc	n near support ace of support	72  ports: (with shear enhance of the control of th	ement if applicab	Moment Capacity 71.7 kNm	
1 D D D D D D D D D D D D D D D D D D D	M. Capacity  Calculation of Shear Capace Shear checked at 2 locations  100As/b <sub>w</sub> d  Depth Factor Material FOS for Concrete in Shear Ultimate shear stress Shear link diameter  No. Legs	M <sub>C</sub> city of Section  (i) a <sub>v</sub> = d from fac  (ii) a <sub>v</sub> = 2d from fac	n near support ace of support (N/mm2) mm	72  ports: (with shear enhance of the without shear endance of the without	ement if applicab	Moment Capacity 71.7 kNm	
able 4A of BD44/95	M. Capacity  Calculation of Shear Capace Shear checked at 2 locations  100As/b <sub>w</sub> d Depth Factor Material FOS for Concrete in Shear Ultimate shear stress Shear link diameter No. Legs Shear link spacing	M <sub>C</sub> city of Section  (i) a <sub>v</sub> = d from fac  (ii) a <sub>v</sub> = 2d from fac	n near support ace of support - (N/mm2) mm	72  ports: (with shear enhance of the control of th	ement if applicab	Moment Capacity 71.7 kNm	
able 4A of MBD44/95 S	M. Capacity  Calculation of Shear Capace Shear checked at 2 locations  100As/b <sub>w</sub> d  Depth Factor Material FOS for Concrete in Shear Ultimate shear stress Shear link diameter No. Legs Shear link spacing Asv	M <sub>C</sub> city of Section  (i) a <sub>v</sub> = d from fac  (ii) a <sub>v</sub> = 2d from fac	n near support ace of support (N/mm2) mm mm2	72  ports: (with shear enhance of the without shear enlarge)  2.6  1.18  1.15  0.677  0  0  0 0.0	ement if applicab hancement)	Moment Capacity 71.7 kNm	
able 4A of MBD44/95 S	M. Capacity  Calculation of Shear Capace Shear checked at 2 locations  100As/b <sub>w</sub> d Depth Factor Material FOS for Concrete in Shear Ultimate shear stress Shear link diameter No. Legs Shear link spacing	M <sub>C</sub> city of Section  (i) a <sub>v</sub> = d from fac  (ii) a <sub>v</sub> = 2d from fs  -  -  -  -  -  -  -  -  -  -  -  -  -	n near support ace of support - (N/mm2) mm	72  ports: (with shear enhance of the control of th	ement if applicab hancement)	Moment Capacity 71.7 kNm	
able 4A of MBD44/95 S	M. Capacity  Calculation of Shear Capace Shear checked at 2 locations  100As/b <sub>w</sub> d  Depth Factor Material FOS for Concrete in Shear Ultimate shear stress Shear link diameter No. Legs Shear link spacing Asv S. capacity section	M <sub>C</sub> city of Section  (i) a <sub>v</sub> = d from fac  (ii) a <sub>v</sub> = 2d from fac  -  -  -  -  -  -  -  -  -  -  -  -  -	n near support ace of support (N/mm2) mm mm2 kN/m	72  ports: (with shear enhance of the without shear endance of the without	ement if applicab hancement)	Moment Capacity 71.7 kNm  e) Slab Shear Capacity	
able 4A of MBD44/95 S	M. Capacity  Calculation of Shear Capace Shear checked at 2 locations  100As/b <sub>w</sub> d  Depth Factor Material FOS for Concrete in Shear Ultimate shear stress Shear link diameter No. Legs Shear link spacing Asv S. capacity section S. capacity links	M <sub>C</sub> city of Section  (i) a <sub>v</sub> = d from fac  (ii) a <sub>v</sub> = 2d from fac  -  -  -  -  -  -  -  -  -  -  -  -  -	n near support ace of support ace of support (N/mm2) mm mm2 kN/m kN/m	72  ports: (with shear enhance of the without shear enlarge)  2.6  1.18  1.15  0.677  0  0  0  114  0	ement if applicab hancement)	Moment Capacity 71.7 kNm  (e)  Slab Shear Capacity	

<b>ATKINS</b>	Project		NRA Eirs	pan Task Order	<b>Job ref</b> 3044		
	Part of Structure MO-N58-001.00			ment using BI		Calc sheet no. rev	
	Drawing Ref MO-N58-001.00		Calc By	СР	Date 13-Feb-12	Check by Date 2 PG 14-Feb-12	
Ref	INIO-1430-001.00	Calcu	lations	01	10-1 60-12	Output	
		Filler Beam - Sp				·	
	Calculation of Moment du	e to Permane	nt Loads	at Mid Spar	<u>1 &amp;</u>		
	Calculation of Shear due	to Permanent	Loads ne	ar supports	<u>8:</u>		
		Load	(kN/m2)	5.1	1		
Table 3.1/ BD21		Yfl	, ,	1.15			
CI.3. 1/ BD21 &	Self weight	Yf3		1.0			
CI. 4.2.3/ BD 44		M <sub>sw</sub>	(kNm/m)	9.7	SLS Shear (kN)		
		Vsw	(kN/m)	10.7	9.3		
Table 2.1/ BD21		Load Yfl	(kN/m2)	1.4	1		
Table 3.1/ BD21 Cl.3. 1/ BD21 &	Sunfacing	Yf3		1.75 1.0	-		
Cl. 4.2.3/ BD 44	Surfacing	M <sub>s</sub>	(kNm/m)	4.0	-		
01. 4.2.3/ DD 44		Vs	(kN/m)	4.4	2.5		
		Load	(kN/m2)	1.6	2.0		
Table 3.1/ BD21		Yfl		1.20	1	<u>Available</u>	
Cl.3. 1/ BD21 &	Fill	Yf3		1.0		Capacity for LL	
CI. 4.2.3/ BD 44		$M_{fill}$	(kNm/m)	3.1	]		
		$V_{\rm fill1}$	(kN/m)	3	2.8	Moment	
	Hence, Capacity Available for LL	, M <sub>CLL</sub>	(kNm/m)	55	14.7 kN	54.9 kNm	
				-			
	Distance (x) from support to face		(mm)	140			
	Shear at support	V <sub>LLsup</sub>	(kN/m)	19			
	Shear at av <sub>1</sub> = 2d	V <sub>LLav1 = 2d</sub>	(kN/m)	11			
	Shear at av <sub>2</sub> = d	$V_{LLav2 = d}$	(kN/m)	14		Shear	
	Hence, Capacity Available for LL		(kNm/m)	103	At 2	d 102.9 kN/m	
	Hence, Capacity Available for LL	, V <sub>CLL= d</sub>	(kNm/m)	100	Ate	d 100.1 kN/m	
Cl. 5.21/ BD 21	Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category		L/M/H	9 Medium Good Mg		Bridge Category Mg	
Figure 5.6	Factor <b>K</b> for 40 tonne loading			0.79	]	9	
	HA + KEL and Equiv. 40 t	Assessment	<u>Loading</u>				
CI. 5.18/ BD21	HA Loading	UDL	(kN/m)	141.4	]		
	Long Eggtor	KEL	(kN)	120.0	4		
CI 5.23/ BD 21	Lane Factor	AF		1.0	4		
UI 3.23/ DD 21	Adjustment Factor Therefore, Equivalent 40 t	UDL	(kN/m2)	1.46 <b>30.60</b>	1		
	loading	KEL	(kN/m)	25.97	1		
	-	Yfl	, , ,	1.50	1		
		Yf3		1.0			
	Moment Due 40 tonne loading	M <sub>LL</sub>	(kNm)	67	SLS shear		
	Shear due to 40t at support	V <sub>LLsup</sub>	(kN/m)	73	49 kN		
	Shear due to 40t av = 2d	$V_{av=2d}$	(kN/m)	51	]		
	Shear due to 40t av = d	$V_{LLav=d}$	(kN/m)	60	_		
CI 5.27/ BD 21	Factor C for Moment at midspan			0.65		(HA + KEL Eqv.) Moment Capacity	
	Loading Capacity Moment at mid	span		40t	as per Figure 5.6	40t	
	Factor C for Shear at 3*d Factor C for Shear at d			1.11 1.56		Shoar Canasit	
	Loading Capacity Shear			1.56 40t	as per Figure 5.6	Shear Capacity 40t	
Check bond stre	ess at support where shear is m	aximum		Bond	Permissble	401	
				Stress (N/mm2)	Stress (N/mm2)		
Ref page 10	SLS Shear at support Dead Load	kN	14.66	1.63	0.7		
	SLS Shear at support Live Load	kN	49.00	]		D 16 "	
	Is bond stress okay? Y/N	ovoocded		N -2+		Bond Capacity	
	Load Capacity where bond stress Adequacy Factor for Bond Stress			<b>&lt;3t</b> 13%	Assuming no contribution from Concrete	<3t	
	Adequacy Factor for Moment at N	Midspan		82%		40 t Adequacy	
	Adequacy Factor for Shear			140%		82%	


	Project	NUA Elish	an Task Orde			<b>b ref</b> 044		
	Part of Structure		Assessr	nent using B	D21/01 F	RC Slabs	Calc sheet no. re	
	MO-N58-001.00  Drawing Ref		Calc By			Date	7 Check by	Date 0
	MO-N58-001.00			CP	1	13-Feb-12		14-Feb
Ref		Calcula	tions		•	•	Ou	itput
					T	T		
	Single Axle Load	Filler Beam - Spa	ın 1 (South)	Moment	Shear	Adequacy		
able 5.3.1 of	Assessment Loading		(Tonne)	7.5	Check 40.0	for 40t 40.0		
D21	Nominal Single Axle Load		(kN)	86	170	170		
	Wheel Contact Area		(m)	0.198	0.278	0.278		
	Minimum Distance Possible from	on left side	(m)	0.50	0.58	0.50		
	edge of slab to centre line of first wheel in width direction	on right side	(m) (m)	0.58 10.96	10.96	0.58 10.96		
	Dispersion for one axle, in transve		beff	1.53	1.69	1.69		
	Dispersion for two axle, in transve		b'eff	2.99	3.23	3.23		
	Dispersion in longitudinal direction	n	b <sub>L</sub>	0.43	0.51	0.51		
	=> Load for one axle (P)		kN	86.0	170.0	170.0		
	Load for two axle (P') $w = P/b_{eff} b_1 \text{ assuming load dispersed le}$	ang & transversely	kN kN/m²	172 131.5	340 198.1	340 198.1		
	$w' = P'/b'_{eff} b_L$ assuming load dispersed $w' = P'/b'_{eff} b_L$ assuming load dispersed	• •	kN/m <sup>2</sup>	134.3	206.9	206.9		
	W = 1 /D eff DL assuming load dispersed	Yfl		1.50	1.50	1.50		
		Yf3		1.0	1.0	1.0		
	Moment due to one axle	M <sub>LL</sub>	(kNm)	72	-	128		
	Moment due to two axles	$M_LL$	(kNm)	74	-	133		
	Adequacy Factor			74%	-	41%	]	
	=>Loading Capacity (Moment)			<7.5t	-			
	Shear Due due to one axle at sup	•			140.4	140.4	Cinala Aul	-1
	Shear Due due to two axles at su Shear due to one axle at av = d		(kN/m)	-	146.7 129	146.7 129	Single Axl Moment C	
	Shear due to two axle at av = d	$V_{LLav = d}$ $V_{LLav = d}$	(kN/m)		135	135	<7.5t	араспу
	Adequacy Factor	V LLav = d	(KIN/III)		74%	74%	<1.51	
	=>Loading Capacity (Shear) (av =	I d)		-	<40t	-	Shear Cap	acity
	Shear due to one axle at av = 2d	$V_{av=2d}$	(kN/m)	-	117	117	<40t	•
	Shear due to two axles av = 2d	$V_{av=2d}$	(kN/m)	-	122	122		
	Adequacy Factor				84%	84%	40 t Adequ	асу
	=>Loading Capacity (Shear)(av =	2d)		-	<40t	-	41%	
	Cingle Wheel Lead		Г	Marra	01	A .1		
	Single Wheel Load		-	Moment Check	Shear Check	Adequacy for 40t		
able 5.3.1 of	Assessment Loading	<u> </u>	(Tonne)	7.5	40.0	40.0		
D21	Nominal Single Wheel Load		(kN)	43	86	86		
	Wheel Contact Area		(m)	0.198	0.280	0.280		
	Minimum Distance Possible from	l .						
	edge of slab to centre line of first		(m)	0.58	0.58	0.58		
	wheel	on right side	(m)	10.96	10.96	10.96		
	Dispersion for Wheel Load		beff	0.76	0.85	0.85		
	$w = P/b_{eff}^{2}$ assuming load dispersed lon	g. & transversely Yfl	kN/m²	73.6	120.0	120.0		
		YII YI3		1.50	1.50	1.50		
	Moment Due Single Wheel Load	M <sub>LL</sub>	(kNm)	1.0 <b>68.7</b>	-	122.6		
	Adequacy Factor	IVILL	(KINIII)	80%	-	45%		
	=>Loading Capacity (Moment)			<7.5t	+ -	45 /6	Single Wh	eel I oad
		<u>I</u>			1	1	Moment C	
	Shear Due Single Wheel Load	$V_{LL}$	(kN)	-	134.7	134.7	<7.5t	- •
	Shear due to 40t av = d	V <sub>LLav = d</sub>	(kN)	-	123.0	123.0		
	Adequacy Factor		. ,		81%	81%	Shear Cap	acity
	=>Loading Capacity (Shear) (av =	= d)			<40t	-	<40t	
	Shear due to 40t av = 2d	V <sub>av = 2d</sub>	(kN)	-	111.2	111.2	40 t Adequ	<b>ас</b> у
	Adequacy Factor				93%	93%	45%	
	=>Loading Capacity (Shear)(av =				<40t	-		
	Grillage Required  As Adequecy factor is only 41% for	Y/N or 40 toppos loadii	Y na narillnac	v analyie wae	carried out			
	Grillage Analysis Output due to		ig, a grillage	anaiyis was	camed out.		Grillage R	esults
	Gimago Finaryolo Output duo to	1011044	Moment		7		Grinago II	<del>oou.to</del>
			(kNm/m)					
efer page 4	Applied 40 t	(factored for ULS)	56.8		Moment of	94.7 kNm	Structure	Capacity
f Grillage O/p		city of the section	54.9		is for 1m, 5		18t	
		Capacity Factor, C			moment is	for 0.6m		
		ive Load Capacity						
	A -I	97%				40 t Adequ	ıacy	
	Adequa	acy Factor for 40t:	31 /6				070	•
	Adequa	acy Factor for 40t.	91 /6				97%	-








#### Project NRA Eirspan Task Order 213 Job ref **ATKINS** 3044 Filler Beam Capacity Part of Structure Rev Calc sheet MO-N58-001.00 11 Check by Drawing ref. Calc by Date CP 13-02-12 PG 14-02-12 Ref Calculations Ouptut Check bond stress of section Dimensions in mm b= 600 Allowable f<sub>cu</sub>= 13.3 Short Term Ec (BD 44/95 cl. 4.3.2.1) 1.05 $d_{c} = 340$ $Ec = (20 + 0.27f_{cu}) = 24$ 230 125 Es = 205 m = Es / Ec = 8.69Allowable f<sub>st</sub>= $d_s =$ 1.05 1500 Long Term Ec (BD 44/95 cl. 4.3.2.1) Twice Short Term m = 17.38 $\gamma_{f3} = 1.1$ 30 Bottom Cover= 60 10 t<sub>fb</sub>= A<sub>sb</sub>= Allowable Conc stress = $0.75f_{cu}/\gamma_{mc}\gamma_{f3}$ = **8.636** 1250 10 Allowable steel stress = $f_{st}/\gamma_{ms}\gamma_{f3}$ = 199.134 x ⊅<sub>NA</sub> $d_{\text{c}}$ ds Uncracked Section for Grillage Analysis Short Term Long Term Ec 8.69 17.38 184.63 195.83 X = Area of section (concrete units) = 235283.12 266566.23 mm<sup>2</sup> Area of section (steel units) = $27075.92 15337.96 mm^2$ $I_{NA}$ (concrete units)= 2.10E+09 2.22E+09 mm<sup>4</sup> I<sub>NA</sub> (steel units)= 2.72E+08 1.55E+08 mm<sup>4</sup> **Cracked Section** Short Term Long Term Ec 17.38 8.69 153.27 161.20 X = 96717.02 mm<sup>2</sup> Area of concrete in compression = 91962.82 Centroid of conc. in comp.(from NA) = 76.64 80.60 $I_{NA}$ (cracked section)= 7.79E+08 1.10E+09 mm<sup>4</sup> $A * y / I_{NA} = 0.00905$ 0.00709 /mm BD61/10 Cl 8.5.1: "The bond may be assumed to be developed uniformly only over both sides of the web and the upper surface of the top and bottom flanges of the steel beam where there is complete encasement and over both sides of the web and the upper surface of the top flange of the steel beam where the beam soffit is exposed." Hence, as cover to soffit of bottom flange is 60mm, Ls = mm





## **ATKINS**

Project NRA	roject NRA Eirspan Task Order 213				
			3044.00		
Part of Structure	Filler Beam Capacity		Calc sheet	Rev	
MO-N58-001.00			14	0.00	
Drawing ref.	Calc by	Date	Check by	Date	
	CP	2012-02-13	PG	2012-02-14	
Calculations			Ot	iptut	

#### **HB Live Load**

Ref

#### Check for Max Shear (at support) 45HB

Serviceability Loads (F)

Shear at support	kN
Dead Load	14.66
Live Load	72.98

#### Live Load Dead Load

Longt'l Shear Force = FAy/I<sub>NA</sub> 660.13 103.99 N/mm

0.310 N/mm<sup>2</sup> Bond stress using= 1.971

N/mm<sup>2</sup> Total bond stress using = 2.281

Allowable bond stress at SLS = 0.700 N/mm<sup>2</sup>

Result: Bond Stress (2.28) greater or equal than Permissible Bond Stress (0.7) hence section is unsuitable for composite action (see BD 61/10 Clause 8.5.1)

#### Check section at x

45HB

Vary x until bond stress = allowable bond stress

1.55 m Load 45.00 HB

reduce x Hint:Use Goalseek

**Loading** Try x =

Serviceability Loads (F)

Shear at location x	kN
Dead Load	2.14
Live Load	8.22

#### Check for Shear at x - 45HB

#### Note: If bottom flange is exposed use $L_{\text{S1}}$ otherwise use $L_{\text{S2}}$


	<u>Live Load</u>	Dead Load	
Longt'l Shear Force = FAv/lya	74	15.19	N/mm

Bond stress= 0.222 0.045 N/mm<sup>2</sup>

Total bond stress= 0.267 N/mm<sup>2</sup>

Allowable bond stress at SLS = 0.7 **0.700** N/mm<sup>2</sup>

Result: Bond stress okay using Ls2



beff =	0.83 m	
	(beff/2)	
Suggested values for x	0.41	m

#### Live Load at x

q	90.59	kN/section
а	1.14	m
b	0.83	m
С	1.67	m
L	3.64	m
Х	1.55	m

RA	42.98 kN		
RB	32.02 kN	ULS	
Vx	5.48 kN	8.22	kN
Vmax	42.98 kN	64.47	kN
Mx	59.03 kNm	88.55	kNm
Mmax	59.20 kNm	88.80	kNm

#### Dead Load at x

q	8.06	kN/m	unfactored
L	3.64	m	
х	1.55	m	

RA=RB =	14.66 kN
Vx	2.14 kN
Vmax	14.66 kN
Mx	13.06 kNm
Mmax	13.35 kNm

#### Check corresponding moment capacity at x

	ULS Moment at x	kNm
	Dead Load	15.02
Available ca	pacity for live load	23.39
45HB	Live Load	88.80

Adequacy 0.26 Fail

**Moment Capacity** <45HB

## **ATKINS**

Project NRA Eirspan Task Order 213			Jo	b ref
			3044.00	
Part of Structure	Filler Beam Capacity		Calc sheet	Rev
MO-N58-001.00			15	0.00
Drawing ref.	Calc by	Date	Check by	Date
	CP	2012-02-13	PG	2012-02-14

Ouptut

Check for Max Shear (at support) 30HB

Ref

Serviceability Loads (F	·)
Shear at support	kN
Dead Load	14.66
Live Load	48 65

#### Note: If bottom flange is exposed use $L_{\text{S1}}$ otherwise use $L_{\text{S2}}$

Calculations

 Longt'l Shear Force = FAy/I<sub>NA</sub>
 Live Load 440.08
 Dead Load 103.99
 N/mm

 Bond stress = 1.314
 0.310
 N/mm²

 Total bond stress = 1.624
 N/mm²

Allowable bond stress at SLS = 0.700 N/mm<sup>2</sup>

**Result:** Bond Stress (1.62) greater or equal than Permissible Bond Stress (0.7) hence section is unsuitable for composite action (see BD 61/10 Clause 8.5.1)

#### Check section at x 30HB

LoadingTry x =Vary x until bond stress = allowable bond stressI.55mLoad30HBreduce xHint:Use Goalseek

Serviceability Loads (F)

co. Hoodomity Edado (	
Shear at location x	kN
Dead Load	2.14
Live Load	8.22

<u>Live Load</u> <u>Dead Load</u>

Longt'l Shear Force = FAy/I<sub>NA</sub> 74 15.19 N/mm

Bond stress= 0.222 0.045 N/mm<sup>2</sup>

Total bond stress= **0.267** N/mm<sup>2</sup>


Allowable bond stress at SLS =  $0.7 \, 0.700 \, \text{N/mm}^2$ 

beff =

Result: Bond stress okay using Ls2

#### Use Composite Section

#### Live Load at x



RA	42.98 kN	
DD	33 U3 FM	111.0

0.83 m


а	1.14	m	RB	32.02	kN ULS	3
b	0.83	m	Vx	5.48	kN 8	8.22 kN
С	1.67	m	Vmax	42.98	kN 6	4.47 kN
L	3.64	m	Mx	59.03	kNm 8	8.55 kNm
Х	1.55	m	Mmax	59.20	kNm 8	8.80 kNm

Dead Load at x

q	8.06	kN/m	unfactored	RA=RB=	14.66 kN
L	3.64	m		Vx	2.14 kN
Х	1.55	m		Vmax	14.66 kN
			•	Mx	13.06 kNm
				Mmax	13.35 kNm

			_	
	ULS Moment at x	kNm	Ī	
	Dead Load	15.02	1	
Available ca	pacity for live load	23.39	Adequacy	
30HB	Live Load	88.80	0.26	Fail

Moment Capacity <30HB



<b>VLK</b>	INS		Project	NR	A Eirspan	Task Order	213		<b>ref</b> )44
			Part of Stru	ucture				Calc sheet	
			MO-N58-00	1.00				2	0
			Drawing R		Calc By		Date	Check by	Date
			MO-N58-00		CP		13-Feb-12	PG	14-Feb-12
Ref				Calcu	lations			Ou	tput
	CALCULATIO				LE STRE	NGTH			
	Input a maximun	n or 11	Core samp	ies					
				ESTIMA	ATED				
	LOCA	ATION	CORE	IN-SITU		(fc - MEAN) <sup>2</sup>			
Ann C0			REFERENCE	STRENGTH		0.00			
App.C2 SI Report			C1 C2		31.3 28.0	0.93 5.44			
or neport			C3		31.7	1.87			
					01.7	-			
						-			
						-			
						-			
						-			
						-			
				TOTAL	91	8.2466667			
			N	o of cores	3	8.2400007			
				MEAN	30.33				
			Standard	Deviation	2.03				
	WCS will be cal	iculate	ea using 2 o	lifferent me	tnoas:				
	n =	3				cation of inte	0n		2
							WCS =	26.8	N/mm <sup>2</sup>
	2) LOWEST	COF	E STREN	IGTH :					
	Lowes	t core	strength =	28.0	N/mm2				
							WCS =	28.0	N/mm <sup>2</sup>
	Using the ab	ove r	esults an	d engine	ering jud	gement.			
	Using the ab								
	Using the ab			d engined d WCS =		gement, N/mm <sup>2</sup>			
	Using the ab								
	Using the ab								
	Using the ab								
	Using the ab								
	Using the ab								
	Using the ab								
	Using the ab								
	Using the ab								
	Using the ab								
	Using the ab								
	Using the ab								

	AT1/1	NIC		Project	NRA Eirspa	an Task Order 2	213		Jo 3044	ob ref
	<b>ATKI</b>	NS		Part of Stru MO-N58-001		Filler Beam Ca	pacity		Calc sheet no.	
				Drawing ref.		Calc by		Date	Check by	Date
Ref					Ca	CP Ilculations		13-02-12	PG	14-02
	s	AGGING - SEC	CTION PROF	PERTIES (III	sing BS 5	3400 Part 3·2	000) for com	posite section		
		Taginta oz.				1		- -		
	Slab	Slab	Width (mm)	Depth (mm)		fcu <sub>(MPa)</sub>	E(short Term) 27.2	Panel Length (mm)		Section depth 50
	Haunch		Width (mm)	Depth (mm)		fcu (MPa)	E(short Term)			
	Girder	Haunch	Width (mm)	Depth (mm)		f <sub>y (MPa)</sub>	0 E <sub>(GPa)</sub>	NA		m
		Top Flange Web	50 85	30 10		230 230	205.0 205.0	=		7
		Bottom Flange	125	10		230	205.0			
		Bottom Cover		70	mm					  -
	e) Plastic Section nb if NA lies below		esn't work			Condition fac	tor for RC Filler	-	0.9	4
	Stress in concrete =	= 0.4*f <sub>cu</sub>			ı					
	Stress in steel = $\sigma_y$	$\gamma_{m}$	γ <sub>m</sub> =	1.05						
		Depth (mm)	Width (mm)	Area (mm²)	Stress	Force (kN)	Force above	Force below NA	y above NA	y below N
ì	Slab*	220	600	132000	(Nmm <sup>-2</sup> )	1417	NA (kN) 789	(kN) -	(mm) 61	(mm) -
	Haunch Top Flange	0 30	0 50	0 1500	0 219	0 329	0	329	0 -98	113
	Web	10	85	850	219	186	Ö	186	-128	133
	Bottom Flange	10	125	1250	219	274	-	274	-	143
	NA lies in	n Slab	*Co	ncrete above	beam only t	aken in propert	ies			
	Depth of Neutral A	xis From Ton Sl	ah		Co	ncrete M <sub>plastic</sub> =	: 48	kNm		
		Depth (mm)			Single	Beam M <sub>plastic</sub> =	: 91	kNm		
	Slab Haunch	122.5 0.0								
	Top Flange Web	0.0 0.0	m=	= 0.0						
_		•	•							
U	epth of Plastic NA =		217.	0						
	f) Compactness Cl	<u>heck</u>							(Compact?)	
9.3.7.2	If m < 0.5	Check web dept				\ <u>-</u>	n/a	mm	n/a	
	If m > 0.5 If web fully in tensio	Check web dept on section is comp		(3/4t <sub>w</sub> /(13m-	-1))*(355/σ <sub>yı</sub>	<sub>v</sub> )^0.5	n/a	mm	n/a yes	
	Section is Compac	·							,	
	Section is compac		AGGING - P	LASTIC CH	ECKS (U	sing BS 5400	Part 3;2000	)		
	2. ULS Bending Ca	apacity of Section	<u>n</u>							
		M <sub>plastic</sub> =	149	kNm						
		M <sub>pe (unfactored)</sub> =		kNm						
0/0 0 0 0		$M_{pe} / 1.05 \times 1.1 =$	122	kNm	(Also Adjus	sted by condition	n factor)			
3/9.9.2.2	3. ULS Pure Shear		<u>tion</u>							
	Depth of panel = $d_w$ Aspect Ratio = $\phi$ =		=	1.000	mm					
	$b_{fe}$ (top flange)	a/u <sub>we</sub>	-	= 0		b <sub>fe</sub> (bottom flar	) :	= 0		
	$m_{fw}$ (top flange) = $\sigma$			1.3235		$m_{fw}(bot) = \sigma_{yf}b_{f}$		0.3676		
	Minimum value of n $\tau_y = \sigma_{yw}/\sqrt{3}$	n <sub>fw</sub> for use in shea		0.3676 = 132.79		$\lambda = (d_{we}/t_w)x(\sigma_y$	<sub>w</sub> /355) <sup>1/2</sup> =	0.1		
			-	- 102.73						
3/Fig12-18	$\tau_l/\tau_y$ for $m_{fw}$ of $\tau_l/\tau_y$ for $m_{fw}$ of			= 3.547 = 3.547		T <sub>I =</sub> T <sub>I =</sub>				
			-	- 0.547			471.07			
3/9.9.2.2	$V_D = (d_w t_w x \tau_I) / (\gamma_m \gamma_f)$	3)	=	= 312.0	kN	When m <sub>fw</sub> =	1.3235	(Adjusted by cond	lition factor)	
	V _ ""			010.0	LNI	Whon m	0.0000	(Adjusted I	lition footo-\	
	V <sub>R</sub> = ""		=	= 312.0	KIN	When m <sub>fw</sub> =	0.0000	(Adjusted by cond	iition tactor)	
í										
	•									



Project	NRA Eirs	pan Task Order 213		Jo	ob ref	
				3044		
Part of Stru	icture	Filler Beam Capacity		Calc sheet no.		Rev
MO-N58-00	1.00			4		0
Drawing ref.		Calc by	Date	Check by	Date	
		CP	13-02-12	PG		14-02-12

Section depth mm 50

Calculations Ref

#### SAGGING - SECTION PROPERTIES (Using BS 5400 Part 3:2000) for Steel Section (IGNORING CONCRETE)

Slab		Width (mm)	Depth (mm)		fcu (MPa)	E(short Term)	Panel Length (mm)	
	Slab	600	50		26.8307417	27.24430026		
Haunch		Width (mm)	Depth (mm)		fcu (MPa)	E(short Term)	NA	
	Haunch	0	0		0	0	NA	
Girder		Width (mm)	Depth (mm)		f <sub>y (MPa)</sub>	E (GPa)		
	Top Flange	50	30		230	205		
	Web	85	10		230	205		
	Bottom Flange	125	10		230	205		
	Bottom Cover		70	mm				
e) Plastic Section	Properties				Condition fact	or for RC Filler	-	0.9

e) Plastic Section Properties

nb if NA lies below the web this doesn't work

Stress in concrete = 0.4\*f<sub>cu</sub>

Stress in steel =  $\sigma_V/\gamma_m$ 

 $y_{\rm m} = 1.05$ 

	Depth (mm)	Width (mm)	Area (mm²)	Stress (Nmm <sup>-2</sup> )	Force (kN)	Force above NA (kN)	Force below NA (kN)	y above NA (mm)	y below NA (mm)
Slab*	-70	600	-42000	11	-451	-451	-	35	-
Haunch	0	0	0	0	0	0	-	0	-
Top Flange	30	50	1500	219	329	329	0	55	-40
Web	10	85	850	219	186	186	0	35	-30
Bottom Flange	10	125	1250	219	274	-	274	-	-25

Concrete M<sub>plastic</sub> =

-16

16

kNm

kNm

(Compact?)

\*Concrete above beam only taken in properties

NA lies in Below Web

Depth of Neutral Axis From Top Slab Single Beam M<sub>plastic</sub> =

Depth (mm) Slab 0.0 Haunch 0.0 Top Flange 0.0 Web 0.0

m= 4.0

Depth of Plastic NA = 0.0

f) Compactness Check

9.3.7.2

If m < 0.5Check web depth is less than  $(34t_w/m)^*(355/\sigma_{yw})^{\circ}0.5$ n/a mm n/a

If m > 0.5 Check web depth is less than  $(374t_w/(13m-1))^*(355/\sigma_{yw})^0.5$ 774.40939 mm ves If web fully in tension section is compact n/a

Section is Compact

#### SAGGING - PLASTIC CHECKS (Using BS 5400 Part 3;2000)

#### 2. ULS Bending Capacity of Section


2 M<sub>plastic</sub> = kNm kNm  $M_{pe (unfactored)} =$ 


 $M_D = M_{pe} / 1.05 \times 1.1 =$ kNm (Also Adjusted by condition factor)


MO- Drav MO- Ref BD21/01	t of Structure		NRA Eirspa	an Task Order	213	<b>Job ref</b> 3044
Ref BD21/01	-N58-001.00		Assessme	ent using BD	21/01 Filler Beam	Calc sheet no. re
Ref BD21/01	wing Ref		Calc By		Date	Check by Date
BD21/01	-N58-001.00	0-11-		P	13-Feb-12	PG 14-Feb
Sla		Calcula	tions			Output
	ıb Details :	Filler Beam Spar	2 (North)			
		·	, ,		<u></u>	
	Depth of slab		(mm)	340		
	Clear Span		(m)	3.34	4	
l 5.3.1.1 of BD44/95	Effective Span Slab width		(m) (mm)	3.61 <b>600</b>	_	
DD44/95	Depth of fill above RC	C Slab	(mm)	230		
	Condition factor for Re		-	0.90	water seepage	
			ļ			
SI Report Mat	terial Details :					
		Beam Depth	(mm)	50	7	
	Main Tension Steel	Spacing	(mm)	600		
		As	(mm2)	4433		
	crete cover to tension steel		(mm)	70	4	
	ondary reinforcement dia ension steel the outer layer of	rehar?	(mm) Y/N	0 Y	4	
	ctive depth	d d	(mm)	270	-	
	crete Density		kN/m3	23.8	1	
	facing Density		kN/m3	23.0	1	
	Density		kN/m3	20.0		
	crete WCS Strength	WCS, fcu		27		
	el Characteristic Strength	fy Ymc	(N/mm2)	230	4	
	erial Factor for Concrete erial Factor for Steel	Yms		1.20	4	
=>	Iculation of Moment Ca	xu	(mm)	122.5	]	Filler Beam Moment Capacity
M. C	Capacity	M <sub>C</sub>	(kNm/m)	122		121.9 kNm
100/	As/b <sub>w</sub> d				enhancement if applicab near enhancement)	
	oth Factor	ξ <sub>s</sub>	-	1.19	-	
	erial FOS for Concrete in Shear	Ymc				
able 4A of Mate	mate shear stress			1.15	1	
	nate shear stress	VC	(N/mm2)	1.15 0.864		
BD44/95 Ultin	ar link diameter	dia.	(N/mm2) mm	0.864 0		
BD44/95 Ultin She No.	ear link diameter Legs	dia. -	mm	0.864 0 0	- - - -	
BD44/95 Ultin She No.	ear link diameter Legs ear link spacing		<u> </u>	0.864 0	- - - - -	
BD44/95 Ultin She No. She Asv	ear link diameter Legs ear link spacing	dia. - sv	mm	0.864 0 0 0	- - - - - -	Slab
BD44/95 Ultin She No. She Asv S. c. S. c.	ear link diameter Legs ear link spacing eapacity section eapacity links	dia sv Asv -	mm mm2 kN/m	0.864 0 0 0 0.0 312 0	- - - - - -	Shear Capacity
BD44/95 Ultin She No. She Asv S. c. S. c. S. C. S. C.	ear link diameter Legs ear link spacing eapacity section eapacity links apacity at av = 2d	dia sv Asv V <sub>C1</sub>	mm mm mm2 kN/m	0.864 0 0 0 0.0 312 0 312	At 2d	Shear Capacity 312.0 kN/m
BD44/95 Ultin She No. She Asv S. c. S. c. S. C. She She She She	ear link diameter Legs ear link spacing eapacity section eapacity links	dia sv Asv -	mm mm2 kN/m	0.864 0 0 0 0.0 312 0	At 2d At d	Shear Capacity

<b>ATKINS</b>				NRA Eirspan Task Order 213			<b>Job ref</b> 3044	
	Part of Structure MO-N58-001.00		Assessment using BD21/01 RC Slabs			Calc sheet no. rev		
	Drawing Ref MO-N58-001.00		Calc By	СР		ate 3-Feb-12	Check by	<b>Date</b> 14-Feb-12
Ref	1400 001.00	Calcu	ations	<u>.                                    </u>	<del>,</del>	0 1 00 12		tput
		Filler Beam Spa			_			
	Calculation of Moment du	<u>e to Permane</u>	nt Loads a	at Mid Spar	<u>1 &amp;</u>			
	Calculation of Shear due	to Permanent	Loads nea	ar supports	<u>s:</u>			
		Load	(kN/m2)	5.1	1			
Table 3.1/ BD21		Yfl		1.15				
Cl.3. 1/ BD21 &	Self weight	Yf3		1.0				
CI. 4.2.3/ BD 44		M <sub>sw</sub>	(kNm/m)	9.5	SLS Shear (k	<u>(N)</u>		
		Vsw Load	(kN/m)	10.6	9.2			
Table 3.1/ BD21		Yfl	(kN/m2)	1.4 1.75	1			
Cl.3. 1/ BD21 &	Surfacing	Yf3		1.75				
CI. 4.2.3/ BD 44	Surfacing	Ms	(kNm/m)	3.9				
JI. 4.2.0/ DD 44		Vs	(kN/m)	4.4	2.5			
		Load	(kN/m2)	1.6				
Table 3.1/ BD21		Yfl	, ,	1.20			<u>Available</u>	
CI.3. 1/ BD21 &	Fill	Yf3		1.0			Capacity for	or LL
CI. 4.2.3/ BD 44		M <sub>fill</sub>	(kNm/m)	3.0				
		$V_{\rm fill1}$	(kN/m)	3	2.8		Moment	
	Hence, Capacity Available for LL	1	(kNm/m)	105	14.5 k	N	105.4	kNm
				•	<b>=</b> _			
	Distance (x) from support to face	of support	(mm)	135				
	Shear at support	$V_{LLsup}$	(kN/m)	18				
	Shear at av <sub>1</sub> = 2d	V <sub>LLav1 = 2d</sub>	(kN/m)	11				
	Shear at av <sub>2</sub> = d	$V_{LLav2 = d}$	(kN/m)	14			Shear	
	Hence, Capacity Available for LL	, V <sub>CLL= 2d</sub>	(kNm/m)	301		At 2c	300.5	kN/m
	Hence, Capacity Available for LL	Va	(kNm/m)	298		At c	297.8	kN/m
	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles	ondition f P I Report)	(KIVIII)	4147 5%	]			
	Traffic Flows & Surface C Annual Average Daily Traffic (Re	ondition  f P I Report)  (AAHHGVF)	L/M/H				Bridge Cat	egor <u>y</u>
Cl. 5.21/ BD 21 Figure 5.6	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category Factor K for 40 tonne loading	ondition  f P I Report)  (AAHHGVF)  d/ Poor)	L/M/H	5% 9 Medium Good				degor <u>y</u>
Cl. 5.21/ BD 21 Figure 5.6	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category Factor K for 40 tonne loading  HA + KEL and Equiv. 40 t	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment	L/M/H	5% 9 Medium Good Mg 0.79				egor <u>y</u>
CI. 5.21/ BD 21	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category Factor K for 40 tonne loading	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment  UDL	L/M/H  Loading  (kN/m)	5% 9 Medium Good Mg 0.79				egor <u>y</u>
Cl. 5.21/ BD 21	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category Factor K for 40 tonne loading  HA + KEL and Equiv. 40 t  HA Loading	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment	L/M/H	5% 9 Medium Good Mg 0.79				egor <u>y</u>
Cl. 5.21/ BD 21 Figure 5.6 Cl. 5.18/ BD21	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category Factor K for 40 tonne loading  HA + KEL and Equiv. 40 t  HA Loading  Lane Factor	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment  UDL  KEL	L/M/H  Loading  (kN/m)	5% 9 Medium Good Mg 0.79				egor <u>y</u>
Cl. 5.21/ BD 21 Figure 5.6 Cl. 5.18/ BD21	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category Factor K for 40 tonne loading  HA + KEL and Equiv. 40 t  HA Loading  Lane Factor  Adjustment Factor	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment  UDL	L/M/H  Loading  (kN/m) (kN)	5% 9 Medium Good Mg 0.79 142.2 120.0 1.0 1.46				egor <u>y</u>
CI. 5.21/ BD 21 Figure 5.6 CI. 5.18/ BD21	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category Factor K for 40 tonne loading  HA + KEL and Equiv. 40 t  HA Loading  Lane Factor	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment  UDL  KEL  AF	L/M/H  Loading  (kN/m) (kN) (kN/m2)	5% 9 Medium Good Mg 0.79				egor <u>y</u>
CI. 5.21/ BD 21 Figure 5.6 CI. 5.18/ BD21	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category Factor K for 40 tonne loading  HA + KEL and Equiv. 40 t  HA Loading  Lane Factor  Adjustment Factor Therefore, Equivalent 40 t	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment  UDL  KEL  AF  UDL	L/M/H  Loading  (kN/m) (kN)	5% 9 Medium Good Mg 0.79 142.2 120.0 1.0 1.46 30.77				egor <u>y</u>
CI. 5.21/ BD 21 Figure 5.6 CI. 5.18/ BD21	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category Factor K for 40 tonne loading  HA + KEL and Equiv. 40 t  HA Loading  Lane Factor  Adjustment Factor Therefore, Equivalent 40 t	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment  UDL  KEL  AF  UDL  KEL	L/M/H  Loading  (kN/m) (kN) (kN/m2)	5% 9 Medium Good Mg 0.79 142.2 120.0 1.0 1.46 30.77 25.97				egor <u>v</u>
CI. 5.21/ BD 21 Figure 5.6 CI. 5.18/ BD21	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category Factor K for 40 tonne loading  HA + KEL and Equiv. 40 t  HA Loading  Lane Factor  Adjustment Factor Therefore, Equivalent 40 t	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment  UDL  KEL  AF  UDL  KEL  Yfl	L/M/H  Loading  (kN/m) (kN) (kN/m2)	5% 9 Medium Good Mg 0.79 142.2 120.0 1.0 1.46 30.77 25.97 1.50	SLS shear			egor <u>v</u>
CI. 5.21/ BD 21 Figure 5.6 CI. 5.18/ BD21 CI 5.23/ BD 21	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category Factor K for 40 tonne loading  HA + KEL and Equiv. 40 t  HA Loading  Lane Factor Adjustment Factor Therefore, Equivalent 40 t loading	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment  UDL  KEL  UDL  KEL  Yfl  Yf3	L/M/H  Loading  (kN/m) (kN)  (kN/m2) (kN/m)	5% 9 Medium Good Mg 0.79 142.2 120.0 1.0 1.46 30.77 25.97 1.50 1.0	SLS shear 49 k	N		egor <u>y</u>
CI. 5.21/ BD 21 Figure 5.6 CI. 5.18/ BD21 CI 5.23/ BD 21	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category Factor K for 40 tonne loading  HA + KEL and Equiv. 40 t  HA Loading  Lane Factor Adjustment Factor Therefore, Equivalent 40 t loading  Moment Due 40 tonne loading	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment  UDL  KEL  UDL  KEL  Yfl  Yf3  M <sub>LL</sub> V <sub>LLsup</sub>	L/M/H  Loading  (kN/m) (kN) (kN/m2) (kN/m) (kN/m)	5% 9 Medium Good Mg 0.79  142.2 120.0 1.0 1.46 30.77 25.97 1.50 1.0 66	1	N		egor <u>y</u>
Cl. 5.21/ BD 21 Figure 5.6 Cl. 5.18/ BD21 Cl 5.23/ BD 21	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category Factor K for 40 tonne loading  HA + KEL and Equiv. 40 t  HA Loading  Lane Factor Adjustment Factor Therefore, Equivalent 40 t loading  Moment Due 40 tonne loading Shear due to 40t at support	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment  UDL  KEL  UDL  KEL  Yfl  Yf3  MLL  V <sub>LLsup</sub> V <sub>av = 2d</sub>	L/M/H  Loading  (kN/m) (kN)  (kN/m)  (kN/m)	5% 9 Medium Good Mg 0.79  142.2 120.0 1.0 1.46 30.77 25.97 1.50 1.0 66 73	1	N		egor <u>y</u>
Cl. 5.21/ BD 21  Figure 5.6  Cl. 5.18/ BD21  Cl 5.23/ BD 21	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category Factor K for 40 tonne loading  HA + KEL and Equiv. 40 t  HA Loading  Lane Factor Adjustment Factor Therefore, Equivalent 40 t loading  Moment Due 40 tonne loading Shear due to 40t at support Shear due to 40t av = 2d	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment  UDL  KEL  UDL  KEL  Yfl  Yf3  M <sub>LL</sub> V <sub>LLsup</sub> V <sub>av = 2d</sub> V <sub>LLav = d</sub>	L/M/H  L/M/H  Loading  (kN/m) (kN/m)  (kN/m)  (kN/m)	5% 9 Medium Good Mg 0.79  142.2 120.0 1.0 1.46 30.77 25.97 1.50 1.0 66 73 51	1	N		Eqv.)
CI. 5.21/ BD 21 Figure 5.6 CI. 5.18/ BD21 CI 5.23/ BD 21	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category Factor K for 40 tonne loading  HA + KEL and Equiv. 40 t  HA Loading  Lane Factor Adjustment Factor Therefore, Equivalent 40 t loading  Moment Due 40 tonne loading Shear due to 40t at support Shear due to 40t av = 2d Shear due to 40t av = d	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment  UDL  KEL  UDL  KEL  Yfl  Yf3  M <sub>LL</sub> V <sub>LLsup</sub> V <sub>av = 2d</sub> V <sub>LLav = d</sub>	L/M/H  L/M/H  Loading  (kN/m) (kN/m)  (kN/m)  (kN/m)	5% 9 Medium Good Mg 0.79  142.2 120.0 1.0 1.46 30.77 25.97 1.50 1.0 66 73 51 60	1		Mg	Eqv.)
CI. 5.21/ BD 21 Figure 5.6 CI. 5.18/ BD21 CI 5.23/ BD 21	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category Factor K for 40 tonne loading  HA + KEL and Equiv. 40 t  HA Loading  Lane Factor Adjustment Factor Therefore, Equivalent 40 t loading  Moment Due 40 tonne loading Shear due to 40t at support Shear due to 40t av = 2d Shear due to 40t av = d  Factor C for Moment at midspan	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment  UDL  KEL  UDL  KEL  Yfl  Yf3  M <sub>LL</sub> V <sub>LLsup</sub> V <sub>av = 2d</sub> V <sub>LLav = d</sub>	L/M/H  L/M/H  Loading  (kN/m) (kN/m)  (kN/m)  (kN/m)	5% 9 Medium Good Mg 0.79  142.2 120.0 1.0 1.46 30.77 25.97 1.50 1.0 66 73 51 60 1.26	49 k		Mg  (HA + KEL  Moment C	Eqv.)
Cl. 5.21/ BD 21  Figure 5.6  Cl. 5.18/ BD21  Cl 5.23/ BD 21	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category Factor K for 40 tonne loading  HA + KEL and Equiv. 40 t  HA Loading  Lane Factor Adjustment Factor Therefore, Equivalent 40 t loading  Moment Due 40 tonne loading Shear due to 40t at support Shear due to 40t av = 2d Shear due to 40t av = d  Factor C for Moment at midspan Loading Capacity Moment at mid Factor C for Shear at 3*d Factor C for Shear at d	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment  UDL  KEL  UDL  KEL  Yfl  Yf3  M <sub>LL</sub> V <sub>LLsup</sub> V <sub>av = 2d</sub> V <sub>LLav = d</sub>	L/M/H  L/M/H  Loading  (kN/m) (kN/m)  (kN/m)  (kN/m)	5% 9 Medium Good Mg 0.79  142.2 120.0 1.0 1.46 30.77 25.97 1.50 1.0 66 73 51 60  1.26 40t	49 k		Mg  (HA + KEL  Moment C	Eqv.) apacity
Cl. 5.21/ BD 21  Cl. 5.18/ BD21  Cl. 5.23/ BD 21	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category Factor K for 40 tonne loading  HA + KEL and Equiv. 40 t  HA Loading  Lane Factor Adjustment Factor Therefore, Equivalent 40 t loading  Moment Due 40 tonne loading Shear due to 40t at support Shear due to 40t av = 2d Shear due to 40t av = d  Factor C for Moment at midspan Loading Capacity Moment at mid Factor C for Shear at 3*d	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment  UDL  KEL  UDL  KEL  Yfl  Yf3  M <sub>LL</sub> V <sub>LLsup</sub> V <sub>av = 2d</sub> V <sub>LLav = d</sub>	L/M/H  L/M/H  Loading  (kN/m) (kN/m)  (kN/m)  (kN/m)	5% 9 Medium Good Mg 0.79  142.2 120.0 1.0 1.46 30.77 25.97 1.50 1.0 66 73 51 60  1.26 40t 3.24	49 k	5.6	Mg  (HA + KEL  Moment C  40t	Eqv.) apacity
Cl. 5.21/ BD 21  Figure 5.6  Cl. 5.18/ BD21  Cl 5.23/ BD 21	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category Factor K for 40 tonne loading  HA + KEL and Equiv. 40 t  HA Loading  Lane Factor Adjustment Factor Therefore, Equivalent 40 t loading  Moment Due 40 tonne loading Shear due to 40t at support Shear due to 40t av = 2d Shear due to 40t av = d  Factor C for Moment at midspan Loading Capacity Moment at mid Factor C for Shear at 3*d Factor C for Shear at d	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment  UDL  KEL  UDL  KEL  Yfl  Yf3  MLL  VLLsup  Vav = 2d  VLLav = d	L/M/H  L/M/H  Loading  (kN/m) (kN/m)  (kN/m)  (kN/m)	5% 9 Medium Good Mg 0.79  142.2 120.0 1.0 1.46 30.77 25.97 1.50 1.0 66 73 51 60  1.26 40t 3.24 4.60 40t  Bond	as per Figure 9 as per Figure 9	5.6	Mg  (HA + KEL  Moment C  40t  Shear Cap	Eqv.) apacity
Cl. 5.21/ BD 21  Figure 5.6  Cl. 5.18/ BD21  Cl 5.23/ BD 21  Cl 5.27/ BD 21	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category Factor K for 40 tonne loading  HA + KEL and Equiv. 40 t  HA Loading  Lane Factor Adjustment Factor Therefore, Equivalent 40 t loading  Moment Due 40 tonne loading Shear due to 40t at support Shear due to 40t av = 2d Shear due to 40t av = d  Factor C for Moment at midspan Loading Capacity Moment at mid Factor C for Shear at 3*d Factor C for Shear at d Loading Capacity Shear	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment  UDL  KEL  AF  UDL  KEL  Yfl  Yf3  M <sub>LL</sub> V <sub>LLsup</sub> V <sub>av = 2d</sub> V <sub>LLav = d</sub> span	L/M/H  L/M/H  Loading  (kN/m) (kN/m)  (kN/m)  (kN/m) (kN/m)	5% 9 Medium Good Mg 0.79  142.2 120.0 1.0 1.46 30.77 25.97 1.50 1.0 66 73 51 60  1.26 40t 3.24 4.60 40t  Bond Stress (N/mm2)	as per Figure 9 as per Figure 9 Permissble Stress (N/mm2)	5.6	Mg  (HA + KEL  Moment C  40t  Shear Cap	Eqv.) apacity
Cl. 5.21/ BD 21  Figure 5.6  Cl. 5.18/ BD21  Cl 5.23/ BD 21  Cl 5.27/ BD 21	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Goor Therefore Bridge Category Factor K for 40 tonne loading  HA + KEL and Equiv. 40 t  HA Loading  Lane Factor Adjustment Factor Therefore, Equivalent 40 t loading  Moment Due 40 tonne loading Shear due to 40t at support Shear due to 40t av = 2d Shear due to 40t av = d  Factor C for Moment at midspan Loading Capacity Moment at mid Factor C for Shear at 3*d Factor C for Shear at d Loading Capacity Shear  Bess at support where shear is me SLS Shear at support Dead Load	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment    UDL  KEL  AF  UDL  KEL  Yfl  Yf3  MLL  VLLsup  Vav = 2d  VLLav = d	L/M/H  Loading  (kN/m) (kN/m) (kN/m) (kN/m) (kN/m) (kN/m) (kN/m)	5% 9 Medium Good Mg 0.79  142.2 120.0 1.0 1.46 30.77 25.97 1.50 1.0 66 73 51 60  1.26 40t 3.24 4.60 40t  Bond	as per Figure 9 as per Figure 9	5.6	Mg  (HA + KEL  Moment C  40t  Shear Cap	Eqv.) apacity
Ci. 5.21/ BD 21  Cigure 5.6  Ci. 5.18/ BD21  Ci 5.23/ BD 21  Ci 5.27/ BD 21	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category Factor K for 40 tonne loading  HA + KEL and Equiv. 40 t  HA Loading  Lane Factor Adjustment Factor Therefore, Equivalent 40 t loading  Moment Due 40 tonne loading Shear due to 40t at support Shear due to 40t av = 2d Shear due to 40t av = d  Factor C for Moment at midspan Loading Capacity Moment at mid Factor C for Shear at 3*d Factor C for Shear at d Loading Capacity Shear  SLS Shear at support Dead Load SLS Shear at support Live Load	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment  UDL  KEL  AF  UDL  KEL  Yfl  Yf3  M <sub>LL</sub> V <sub>LLsup</sub> V <sub>av = 2d</sub> V <sub>LLav = d</sub> span	L/M/H  L/M/H  Loading  (kN/m) (kN/m)  (kN/m)  (kN/m) (kN/m)	5% 9 Medium Good Mg 0.79  142.2 120.0 1.0 1.46 30.77 25.97 1.50 1.0 66 73 51 60  1.26 40t 3.24 4.60 40t  Bond Stress (N/mm2)	as per Figure 9 as per Figure 9 Permissble Stress (N/mm2)	5.6	Mg  (HA + KEL  Moment C  40t  Shear Cap  40t	Eqv.) apacity acity
Check bond street	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Goor Therefore Bridge Category Factor K for 40 tonne loading  HA + KEL and Equiv. 40 t  HA Loading  Lane Factor Adjustment Factor Therefore, Equivalent 40 t loading  Moment Due 40 tonne loading Shear due to 40t at support Shear due to 40t av = 2d Shear due to 40t av = d  Factor C for Moment at midspan Loading Capacity Moment at mid Factor C for Shear at 3*d Factor C for Shear at d Loading Capacity Shear  Bess at support where shear is me SLS Shear at support Dead Load	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment    UDL  KEL  AF  UDL  KEL  Yfl  Yf3  MLL  VLLsup  Vav = 2d  VLLav = d  span  kN  kN	L/M/H  Loading  (kN/m) (kN/m) (kN/m) (kN/m) (kN/m) (kN/m) (kN/m)	5% 9 Medium Good Mg 0.79  142.2 120.0 1.0 1.46 30.77 25.97 1.50 1.0 66 73 51 60  1.26 40t 3.24 4.60 40t  Bond Stress (N/mm2) 4.71	as per Figure 9 as per Figure 9 Permissble Stress (N/mm2) 0.7	5.6	Mg  (HA + KEL  Moment C  40t  Shear Cap	Eqv.) apacity acity
Check bond street	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category Factor K for 40 tonne loading  HA + KEL and Equiv. 40 t  HA Loading  Lane Factor Adjustment Factor Therefore, Equivalent 40 t loading  Moment Due 40 tonne loading Shear due to 40t at support Shear due to 40t av = 2d Shear due to 40t av = d  Factor C for Moment at midspan Loading Capacity Moment at mid Factor C for Shear at 3*d Factor C for Shear at d Loading Capacity Shear  SLS Shear at support Dead Load SLS Shear at support Live Load Is bond stress okay? Y/N	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment  UDL  KEL  AF  UDL  KEL  Yfl  Yf3  MLL  V <sub>LLsup</sub> V <sub>av = 2d</sub> V <sub>LLav = d</sub> span  kN  kN  s exceeded	L/M/H  Loading  (kN/m) (kN/m) (kN/m) (kN/m) (kN/m) (kN/m) (kN/m)	5% 9 Medium Good Mg 0.79  142.2 120.0 1.0 1.46 30.77 25.97 1.50 1.0 66 73 51 60  1.26 40t 3.24 4.60 40t  Bond Stress (N/mm2) 4.71 N	as per Figure 9 as per Figure 9 Permissble Stress (N/mm2)	5.6	Mg  (HA + KEL  Moment C  40t  Shear Cap  40t  Bond Capa	Eqv.) apacity acity
Cl. 5.21/ BD 21  Cl. 5.18/ BD21  Cl. 5.23/ BD 21  Cl. 5.27/ BD 21	Traffic Flows & Surface C  Annual Average Daily Traffic (Re Percentage of heavy vehicles Annual average hourly HGV flow Traffic Flow Cl.5.2.2 of BD 21 Condition of road surfacing (Good Therefore Bridge Category Factor K for 40 tonne loading  HA + KEL and Equiv. 40 t  HA Loading  Lane Factor Adjustment Factor Therefore, Equivalent 40 t loading  Moment Due 40 tonne loading Shear due to 40t at support Shear due to 40t av = 2d Shear due to 40t av = d  Factor C for Moment at midspan Loading Capacity Moment at mid Factor C for Shear at 3*d Factor C for Shear at d Loading Capacity Shear  SLS Shear at support Dead Load SLS Shear at support Live Load Is bond stress okay? Y/N Load Capacity where bond stress	ondition  f P I Report)  (AAHHGVF)  d/ Poor)  Assessment  UDL  KEL  AF  UDL  KEL  Yfl  Yf3  M <sub>LL</sub> V <sub>LLsup</sub> V <sub>LLav = d</sub> span  kN  kN  s exceeded	L/M/H  Loading  (kN/m) (kN/m) (kN/m) (kN/m) (kN/m) (kN/m) (kN/m)	5% 9 Medium Good Mg 0.79  142.2 120.0 1.0 1.46 30.77 25.97 1.50 1.0 66 73 51 60  1.26 40t 3.24 4.60 40t  Bond Stress (N/mm2) 4.71 N <3t	as per Figure 9 as per Figure 9 Permissble Stress (N/mm2) 0.7 Assuming no co	5.6	Mg  (HA + KEL  Moment C  40t  Shear Cap  40t  Bond Capa	Eqv.) apacity acity

Ref  Ref  Sable 5.3.1 of ABD21	Part of Structure MO-N58-001.00 Drawing Ref MO-N58-001.00			ment using B	D21/01 F	RC Slabs	Calc sheet	
Ref	Drawing Ref						/	
Ref			Calc By			Date	Check by	0 Date
able 5.3.1 of 7				CP		13-Feb-12		14-Feb
able 5.3.1 of		Calcula	tions		•	•	Ou	tput
able 5.3.1 of			1		1	1		
D21 [	Single Axle Load	Filler Beam Span	2 (North)	Moment	Shear	Adequacy		
D21 [	Assessment Loading		(Tonne)	7.5	Check 40.0	for 40t 40.0		
Ī	Nominal Single Axle Load		(kN)	86	170	170		
<u> </u>	Wheel Contact Area		(m)	0.198	0.278	0.278		
1	Minimum Distance Possible from	on left side	(m)	0.50	0.58	0.50		
	edge of slab to centre line of first wheel in width direction	on right side	(m) (m)	0.58 10.96	10.96	0.58 10.96		
	Dispersion for one axle, in transve		beff	1.35	1.51	1.51		
	Dispersion for two axle, in transve		b'eff	2.69	2.96	2.96		
<u> </u>	Dispersion in longitudinal direction	1	b∟	0.43	0.51	0.51		
<u> </u>	=> Load for one axle (P)		kN	86.0	170.0	170.0		
-	Load for two axle (P')  w = P/b <sub>eff</sub> b <sub>I</sub> assuming load dispersed lo	ana & transversely	kN/m <sup>2</sup>	172 149.5	340 222.2	340 222.2		
	$w' = P'/b'_{eff} b_L$ assuming load dispersed $w' = P'/b'_{eff} b_L$ assuming load dispersed	• •	kN/m <sup>2</sup>	149.5	226.2	226.2		
F	w _ i /b eff bL assuming load dispersed	Yfl		1.50	1.50	1.50		
		Yf3		1.0	1.0	1.0		
ī	Moment due to one axle	$M_LL$	(kNm)	81	-	142		
ī	Moment due to two axles	$M_LL$	(kNm)	81	-	145		
-	Adequacy Factor			129%	-	73%	]	
	=>Loading Capacity (Moment)			7.5t	-	-		
	Shear Due due to one axle at sup				157.4	157.4	Cimarla Avel	
-	Shear Due due to two axles at sur Shear due to one axle at av = d		(kN/m)	-	160.2 145	160.2 145	Single Axle Moment Ca	
-	Shear due to two axle at av = d	$V_{LLav = d}$ $V_{LLav = d}$	(kN/m)		147	143	7.5t	араспу
<u> </u>	Adequacy Factor	V LLav = d	(KIN/III)		202%	202%	7.50	
	=>Loading Capacity (Shear) (av =	d)		-	40t	-	Shear Cap	acity
	Shear due to one axle at av = 2d	$V_{av=2d}$	(kN/m)	-	132	132	40t	•
3	Shear due to two axles av = 2d	$V_{av=2d}$	(kN/m)	-	134	134		
	Adequacy Factor				223%	223%	40 t Adequ	acy
[	=>Loading Capacity (Shear)(av =	2d)		-	40t	-	73%	
	o		ſ		1 -	1		
3	Single Wheel Load			Moment	Shear	Adequacy		
abla 5 0 1 at	Assessment Loading		(Tauana)	Check	Check	for 40t		
	Nominal Single Wheel Load		(Tonne) (kN)	<b>7.5</b> 43	<b>40.0</b> 86	<b>40.0</b> 86		
	Wheel Contact Area		(m)	0.198	0.280	0.280		
<u> </u>	Minimum Distance Possible from		(***)					
	edge of slab to centre line of first	on left side	(m)	0.58	0.58	0.58		
	wheel	on right side	(m)	10.96	10.96	10.96		
	Dispersion for Wheel Load		beff	0.67	0.75	0.75		
<u>\</u>	$w = P/b_{eff}^{2}$ assuming load dispersed long		kN/m <sup>2</sup>	95.0	151.1	151.1		
		Yfl		1.50	1.50	1.50		
ļ.		Yf3	(1.1.1)	1.0	1.0	1.0		
<u> </u>	Moment Due Single Wheel Load	M <sub>LL</sub>	(kNm)	78.5	-	138.2		
<u> </u>	Adequacy Factor =>Loading Capacity (Moment)			134%	-	76%	Cinalo Wh	
<u> -</u>	->Loading Gapacity (Moment)			7.5t	<u> </u>		Single Who Moment Ca	
-  -	Shear Due Single Wheel Load	$V_{LL}$	(kN)		153.1	153.1	7.5t	apaoily
	Shear due to 40t av = d	$V_{LLav=d}$	(kN)		140.3	140.3	7.50	
<u> </u>	Adequacy Factor	• LLAV = d	(1414)		212%	212%	Shear Cap	acitv
<u> </u>	=>Loading Capacity (Shear) (av =	d)			40t	-	40t	-,
F	J 1 7 (= / (=	,						
ļ;	Shear due to 40t av = 2d	$V_{av=2d}$	(kN)	-	127.5	127.5	40 t Adequ	асу
7	Adequacy Factor				236%	236%	76%	
	=>Loading Capacity (Shear)(av =	2d)			40t	-		
	Grillage Required	Y/N	Y					
	As Adequecy factor is only 73% fo			-	carried out.		O-:!! D-	10
<u> </u>	Grillage Analysis Output due to	HA loading & Sil	Moment	<u>aa</u>	7		Grillage Re	esuits
			(kNm/m)					
efer page 4	Applied 40 t (	factored for ULS)	56.8		Moment of	94 7 kNm	Structure (	Capacity
f Grillage O/p		city of the section	105.4		is for 1m, 5		40t	ر ۵۰۰۰ م
Ş I-		apacity Factor, C			moment is t			
F		ve Load Capacity			1			
F	Adequa	acy Factor for 40t:	185%				40 t Adequ	асу
ļ ,					_		185%	







#### Project NRA Eirspan Task Order 213 Job ref **ATKINS** 3044 Part of Structure Filler Beam Capacity Calc sheet MO-N58-001.00 11 Date Check by Drawing ref. Calc by Date CP 13-02-12 PG 14-02-12 Ref Calculations Ouptut **Check bond stress of section** Dimensions in mm Allowable f<sub>cu</sub>= 26.83074 b= 600 Short Term Ec (BD 44/95 cl. 4.3.2.1) $\gamma_{mc} = 1.05$ $d_{c} = 340$ $Ec = (20 + 0.27f_{cu}) = 27$ Allowable f<sub>st</sub>= 230 $d_s = 50$ Es = 205 **m** = Es / Ec = 7.521.05 A<sub>st</sub>= 1500 Long Term Ec (BD 44/95 cl. 4.3.2.1) $\gamma_{ms}$ = Twice Short Term m = 15.0530 1.1 $\gamma_{f3}$ = t<sub>ft</sub>= 10 Bottom Cover= 70 t<sub>fb</sub>= Allowable Conc stress = $0.75f_{cu}/\gamma_{mc}\gamma_{f3}$ = **17.423** 1250 A<sub>sb</sub>= Allowable steel stress = $f_{st}/\gamma_{ms}\gamma_{f3}$ = 199.134 85 b × ‡<sub>NA</sub> $A_{st}$ $d_c$ $d_s$

Rev

0

#### Uncracked Section for Grillage Analysis

#### Short Term Long Term Ec 7.52 15.05

187.60 201.51 X =

Area of section (concrete units) = 231088.23 258176.47 mm<sup>2</sup>

Area of section (steel units) = 30711.40 17155.70 mm<sup>2</sup>

 $I_{NA}$  (concrete units)= 2.12E+09 2.25E+09 mm<sup>4</sup>

 $I_{NA}$  (steel units)= 3.34E+08 1.95E+08 mm<sup>4</sup>

#### **Cracked Section**

#### Short Term Long Term Ec

m = 7.52 15.05


157.33 168.64 X =

Area of concrete in compression = 94399.88 101183.60 mm<sup>2</sup> Centroid of conc. in comp.(from NA) = 78.67 84.32

I<sub>NA</sub> (cracked section)= 8.69E+08 1.23E+09 mmʻ

 $A * y / I_{NA} = 0.00855$ 0.00692 /mm


BD61/10 Cl 8.5.1: "The bond may be assumed to be developed uniformly only over both sides of the web and the upper surface of the top and bottom flanges of the steel beam where there is complete encasement and over both sides of the web and the upper surface of the top flange of the steel beam where the beam soffit is exposed." Hence, as cover to soffit of bottom flange is 70mm, Ls =



## **ATKINS**

Project NRA Eirs	Jo	b ref		
			3044	
Part of Structure	Filler Beam Capacity		Calc sheet	Rev
MO-N58-001.00			13	0.00
Drawing ref.	Calc by	Date	Check by	Date
	CP	2012-02-13	PG	2012-02-14

Ref Calculations Ouptut




р	18.46	kN/section
Г	3.61	m
Х	1.76	m

RA=RB = 33.33 kN Vx 0.77 kN Vmax 33.33 kN Mx 30.06 kNm Mmax 30.08 kNm


# 33.33 kN 0.77 kN 30.06 kNm 30.08 kNm -33.33 kN

#### **HA KEL Live Load**



Р	15.58	kN
L	3.61	m
а	1.76	
b	1.85	
Х	1.76	m

RA 7.97 kN
RB 7.61 kN
Vx 7.97 kN
Vmax 15.58 kN (P at support)
Mx 14.06 kNm
Mmax 14.06 kNm
Mmax P at centre 14.06 kNm



#### Combined Continuos + Point Load

per m width
Combined Moment Mx 44.12 kNm
Combined Shear Vx 8.74 kN

Max M 44.14 kNm Max V 48.91 kN ULS (Yf3=1.5) 66.21 kNm 73.36 kN

ULS (Yf3=1.5)

66.18

13.11

# **ATKINS**

Project NRA Eirspan Task Order 213			Jol	b ref
			3044.00	
Part of Structure	Filler Beam Capacity		Calc sheet	Rev
MO-N58-001.00			14	0.00
Drawing ref.	Calc by	Date	Check by	Date
	CP	2012-02-13	PG	2012-02-14
Calculations	•		Ou	iptut

Ref **HB Live Load** 

#### Check for Max Shear (at support) 45HB

Serviceability Loads (F)

Shear at support	kN
Dead Load	14.50
Live Load	81.73

Live Load Dead Load

Longt'l Shear Force = FAy/I<sub>NA</sub> 100.24 N/mm 698.69

N/mm<sup>2</sup> Bond stress using= 6.352 0.911

N/mm<sup>2</sup> Total bond stress using = 7.263

N/mm<sup>2</sup> Allowable bond stress at SLS = 0.700

Result: Bond Stress (7.26) greater or equal than Permissible Bond Stress (0.7) hence section is unsuitable for composite action (see BD 61/10 Clause 8.5.1)

#### Check section at x

Loading Try x =

45HB

Vary x until bond stress = allowable bond stress 45.00 HB

1.57 m Load reduce x Hint:Use Goalseek

Serviceability Loads (F)

Shear at location x	kN
Dead Load	1.92
Live Load	7.45

#### Check for Shear at x - 45HB


#### Note: If bottom flange is exposed use L<sub>S1</sub> otherwise use L<sub>S2</sub>

Live Load Dead Load Longt'l Shear Force =  $FAy/I_{NA}$ 64 13.28 N/mm

> N/mm<sup>2</sup> Bond stress= 0.579 0.121 N/mm<sup>2</sup>

Total bond stress= 0.700 N/mm<sup>2</sup> Allowable bond stress at SLS = 0.7 0.700

Result: Bond Stress (0.7) greater or equal than Permissible Bond Stress (0.7) hence section is unsuitable for composite action at this location (see BD 61/10 Clause 8.5.1)



beff =	0.74 m	
	(beff/2)	
Suggested values for x	0.37	m

#### Live Load at x

q	101.90	kN/section
а	1.20	m
b	0.74	m
С	1.68	m
L	3.61	m
Х	1.57	m

RA	42.47 kN		
RB	32.53 kN	ULS	
Vx	4.97 kN	7.45	kN
Vmax	42.47 kN	63.70	kN
Mx	59.60 kNm	89.40	kNm
Mmax	59.72 kNm	89.58	kNm

#### Dead Load at x

q	8.03	kN/m	unfactored
L	3.61	m	
Х	1.57	m	
			_

RA=RB =	14.50 kN
Vx	1.92 kN
Vmax	14.50 kN
Mx	12.85 kNm
Mmax	13.08 kNm

Fail

#### Check corresponding moment capacity at x

	ULS Moment at x	kNm	
	Dead Load	14.78	
Available ca	pacity for live load	-12.81	Adequacy
45HB	Live Load	89.58	-0.14

Moment Capacity <45HB

**ATKINS** 

Project NRA Eirspan Task Order 213		Jol	b ref	
			3044.00	
Part of Structure	Filler Beam Capacity		Calc sheet	Rev
MO-N58-001.00			15	0.00
Drawing ref.	Calc by	Date	Check by	Date
	CP	2012-02-13	<u>PG</u>	2012-02-14
Calculations			Ou	ıptut

#### Check for Max Shear (at support) 30HB

Serviceability Loads (F)

Ref

Shear at support	kN
Dead Load	14.50
Live Load	54.49

#### Note: If bottom flange is exposed use $L_{\text{S1}}$ otherwise use $L_{\text{S2}}$

<u>Live Load</u> <u>Dead Load</u>

Longt'l Shear Force =  $FAy/I_{NA}$ 465.79 100.24 N/mm

> Bond stress= 4.234 0.911 N/mm<sup>2</sup>

> > Total bond stress= 5.146 N/mm<sup>2</sup>

Allowable bond stress at SLS = 0.700 N/mm<sup>2</sup>

Result: Bond Stress (5.15) greater or equal than Permissible Bond Stress (0.7) hence section is unsuitable for composite action (see BD 61/10 Clause 8.5.1)

#### Check section at x 30HB

Loading Try x =

Vary x until bond stress = allowable bond stress

1.57 m Load 30 НВ reduce x Hint:Use Goalseek

Serviceability Loads (F)

Shear at location x	kN
Dead Load	1.92
Live Load	7.45

Live Load Dead Load

Longt'l Shear Force = FAy/I<sub>NA</sub> 64 13.28 N/mm


> Bond stress= 0.579 N/mm<sup>2</sup> 0.121

> > Total bond stress= 0.700 N/mm<sup>2</sup>

Allowable bond stress at SLS = 0.7 **0.700** N/mm<sup>2</sup>

Result: Bond Stress (0.7) greater or equal than Permissible Bond Stress (0.7) hence section is unsuitable for composite action (see BD 61/10 Clause 8.5.1)

#### Live Load at x



hoff _	0	71	m

q	101.90	kN/section
а	1.20	m
b	0.74	m
O	1.68	m
Г	3.61	m
X	1.57	m

RA	42.47 kN		
RB	32.53 kN	ULS	
Vx	4.97 kN	7.45	kN
Vmax	42.47 kN	63.70	kN
Mx	59.60 kNm	89.40	kNm
Mmax	59.72 kNm	89.58	kNm

#### Dead Load at x

q	8.03	kN/m	unfactored
L	3.61	m	
х	1.57	m	
			•

RA=RB =	14.50	kN
Vx	1.92	kN
Vmax	14.50	kΝ
Mx	12.85	kNm
Mmax	13.08	kNm

ULS Moment at x	kNm
Dead Load	14.78
Available capacity for live load	-12.81
30HB Live Load	89.58

Adequacy	
-0.14	Fail

**Moment Capacity** <30HB



Page: 1 Made by: CP Date: 9/5/12

Job No. : 3044 Checked by :

10:33 : 10/.V:\3044 Eirspan Task Order 213\30 Documents\32 Reports\321 Working Assessment Reports\69. MO-N58-001.00\MO-N58-001.00 Grillage.X00

#### Job Name: Eirspan TO213

Structure Type = Grillage No of joints = 60 No of members = 103

#### **Analysis Settings**

Analysis method = Linear Elastic

#### **Material Types**

Data last edited at 15:38 on 9/5/12

Units: E(kN/mm2) G(kN/mm2) CTE(/deg C) Density(kN/m3)

Туре	E	G Name
no	CTE	Density
1	31.0	11.6 Concrete
	1.2e-5	24.0

#### **Supports**

Data last edited at 15:45 on 9/5/12

Joint	DZ	RX	RY
No	(kN/m)	(kN.m/deg)	(kN.m/deg)
1	Rigid	Rigid	Free
6	Rigid	Rigid	Free
7	Rigid	Rigid	Free
12	Rigid	Rigid	Free
13	Rigid	Rigid	Free
18	Rigid	Rigid	Free
19	Rigid	Rigid	Free
24	Rigid	Rigid	Free
25	Rigid	Rigid	Free
30	Rigid	Rigid	Free
31	Rigid	Rigid	Free
36	Rigid	Rigid	Free
37	Rigid	Rigid	Free
42	Rigid	Rigid	Free
43	Rigid	Rigid	Free
48	Rigid	Rigid	Free
49	Rigid	Rigid	Free
54	Rigid	Rigid	Free
55	Rigid	Rigid	Free
60	Rigid	Rigid	Free
61	Rigid	Rigid	Free
66	Rigid	Rigid	Free
67	Rigid	Rigid	Free
72	Rigid	Rigid	Free

#### **Sections**

Data last edited at 15:43 on 9/5/12

#### Section 1:1000mm slab : Rectangle

Ax = 3400.00 cm2

Ix = 1029815.29 cm4



Page: 2 Made by: CP Date: 9/5/12

Job No. : 3044 Checked by :

 $10:33:10/V:\ 3044\ Eirspan\ Task\ Order\ 213\ 30\ Documents\ 321\ Working\ Assessment\ Reports\ 69.\ MO-N58-001.00\ MO-N58-001.00\ Grillage. X00$ 

#### Section 2: Support : Rectangle

Ax = 2176.00 cm2

Ix = 559717.50 cm4

 Dy = 640.0 mm
 Dz = 340.0 mm

 Tz = 0.0 mm
 Ty = 0.0 mm

 Cy = n/a
 Cz = 0.0 mm

 Ay = n/a
 Az = 1813.33 cm2

 Iy = 209621.33 cm4
 Iz = n/a

#### **Loadcase titles**

Data last edited at 10:32 on 10/5/12

 Loadcase
 Reference
 Title

 No
 1 B1
 HL:ALP: My at End2 : Member 69: LV 40t

#### **CURRENT: Minimum Member end forces**

Loadcases : B1

Analysed at 10:32 hrs on 10/5/12

Member	Joint	Torque	<b>Bending Moment</b>	Shear Force
		(kN.m)	(kN.m)	(kN)
38	61	-5.361 B1	-2.092h	80.654
126	66	5.946	-2.312 B1	-93.367
126	66	5.946	-2.312h	-93.367 B1

#### **CURRENT: Maximum Member end forces**

Loadcases: B1

Analysed at 10:32 hrs on 10/5/12

Member	Joint	Torque	Bending Moment	<b>Shear Force</b>
		(kN.m)	(kN.m)	(kN)
126	66	5.946 B1	-2.312h	-93.367
69	64	-1.644	95.101 B1	20.637
38	61	-5.361	-2.092h	80.654 B1



Page: 3

Made by : CP


Date: 9/5/12 Job No.: 3044

Checked by:

10:34 : 10/5/12

V:\3044 Eirspan Task Order 213\30 Documents\32 Reports\321 Working Assessment Reports\69. MO-N58-001.00\MO-N58-001.00 Grillage.X00

SCALES Structure 1:74





Structure Set : ALL



Page: 4

Made by : CP

Date: 9/5/12 Job No.: 3044

Checked by:


10:34 : 10/5/12

V:\3044 Eirspan Task Order 213\30 Documents\32 Reports\321 Working Assessment Reports\69. MO-N58-001.00\MO-N58-001.00 Grillage.X00

**SCALES** 

Structure 1:74

Moments 1 mm = 1.500 kN.m







## **Appendix E**

**Sub-Standard Structure Summary** 



# APPENDIX E: SUB-STANDARD STRUCTURE SUMMARY

Structure Name: **Strade River Bridge** Structure Ref. No.: **MO-N58-001.00** 

Stage 1 Assessment	Stage 2 Assessment		
21/05/2012			
DG-TO213-69			
Span 1: Bending 18t, Shear 40t, Bond <3t Span 2: Bending 40t, Shear 40t, Bond <3t			
Provisionally Sub-Standard			
21/05/2012			
Low Risk			
Provisionally Sub-Standard			
Monitoring of the substructure is not appropriate.			
21/05/2012			
Stage 2 Assessment of the structure and subsequent			
structure, if required.			
	21/05/2012  DG-TO213-69  Span 1: Bending 18t, Shear 40t, Bond <3t Span 2: Bending 40t, Shear 40t, Bond <3t Provisionally Sub-Standard  21/05/2012  Low Risk  Provisionally Sub-Standard  Monitoring of the substructure is not appropriate.  21/05/2012  Stage 2 Assessment of the structure and subsequent strengthening of the	21/05/2012  DG-TO213-69  Span 1: Bending 18t, Shear 40t, Bond <3t Span 2: Bending 40t, Shear 40t, Bond <3t Provisionally Sub-Standard  21/05/2012  Low Risk  Provisionally Sub-Standard  Monitoring of the substructure is not appropriate.  21/05/2012  Stage 2 Assessment of the structure and subsequent strengthening of the	21/05/2012  DG-TO213-69  Span 1: Bending 18t, Shear 40t, Bond <3t Span 2: Bending 40t, Shear 40t, Bond <3t Provisionally Sub-Standard  21/05/2012  Low Risk  Provisionally Sub-Standard  Monitoring of the substructure is not appropriate.  21/05/2012  Stage 2 Assessment of the structure and subsequent strengthening of the



## **Appendix F**

# Interim Measures Feasibility Assessment



# APPENDIX F: INTERIM MEASURES FEASIBILITY ASSESSMENT FOR BRIDGES

#### 1. GENERAL DETAILS

1.1 Structure name and assessment reference:

Structure Ref No: MO-N58-001.00

1.2 Location, route and county/area:

Strade River Bridge, N58, County Mayo

Latitude Y: 297482.729 Longitude X: 125785.401

1.3 Assessing Organisation:

**ATKINS** 

Assessed by: CM Checked by: PG

Assessment date: 21/05/2012

1.4 Structure type, form, span, skew:

Two Span Filler Beam Deck Structure, Skew Spans 3.81m & 3.79, Skew 28°.

1.5 Obstacle crossed and facility carried:

Carries the N58 National Secondary Route across the Strade River.

1.6 Estimated cost of permanent strengthening/replacement works:

Not applicable.

#### 2. ASSESSMENT PROGRESS

2.1 Level of assessment reached:

Stage 1 Assessment

2.2 Assessed capacity:

Span 1: 18 t (Bending), 40t (Shear) & <3t (Bond) Span 2: 40 t (Bending), 40t (Shear) & <3t (Bond)

2.3 Date of assessment:

21/05/2012

2.4 Assessment Report reference:

3044/30/32/DG-TO-213-69

2.5 Provisionally Sub-standard or Sub-standard?

Provisionally Sub-standard

2.6 Description of anticipated mode of failure, including its progressions from local overstress to global collapse mechanism.

Failure mode of the RC slab structure is likely to be due to bond stress between the steel components and the concrete.

2.7 Description of distress (if present):

No structural defects present.



#### 3. CONSIDERATION OF RISK POSED BY STRUCTURE IN CURRENT STATE

#### 3.1 Discussion

The Stage 1 Assessment indicated that both spans of the structure had a capacity of 7.5 tonnes assessment loading for bending, 40 tonnes for shear and less than 3 tonnes for bond. As the adequacy of the structures in bending for 40t live loading was 60% for span 1 and 73% for span 2 using the strip method, a grillage analysis was carried out, which increased the load capacity of the structures in bending to 18 tonnes assessment loading for Span 1 and to 40 tonnes for Span 2. The Stage 1 Assessment also indicated that the structure failed for 30 Units of HB loading in bond.

The structure was noted to be in good condition and not showing any signs of structural defects. The main causes of low carrying capacity of the structure were low concrete strength and low area of steel reinforcement components.

It is considered likely that Stage 2 Assessment of the structure would increase the assessment load capacity of the structure, but may not increase it to 40 tonnes assessment loading. Hence, based on the results of Stage 2 Assessment, the structure should be strengthened, if necessary.

3.2 Is the structure an Immediate Risk Structure?

No, the structure is not an immediate risk structure.

3.3 Is the structure a Low Risk Provisionally Sub-standard Structure?

Yes, the structure is a Low Risk Provisionally Sub-standard Structure.

#### 4. APPROPRIATENESS OF MONITORING

#### 4.1 Discussion

The structure was not showing any signs of structural defects. Hence, it is considered that the monitoring of the substructure is not appropriate.

4.2 Is the structure monitoring appropriate?

No, the structure is not monitoring appropriate.

#### 5. OPTIONS FOR LOAD MITIGATION INTERIM MEASURES

Load mitigation measures are not required at this stage

#### 6. OPTIONS FOR MONITORING INTERIM MEASURES

Monitoring interim measures are not required at this stage.

#### 7. RECOMMENDED OPTIONS FOR INTERIM MEASURES

7.1 Recommended Load Mitigation Interim Measures:

Load mitigation measures are not required at this stage.

7.2 Recommended Monitoring Interim Measures:

Monitoring interim measures are not required at this stage.


# **Appendix B. Results of Additional Literature Search**


No additional material found.



# **Appendix C. General Arrangement Drawings**







# **Appendix D. Structural Condition Drawing**

Refer to Appendix C for General Arrangement Drawings with the defect locations sketch included.



# Appendix E. Copy of Materials Testing Report





# Structural Investigation Report

MO-N58-001.00 - STRUCTURAL INVESTIGATION REPORT - [REV 1]

12<sup>TH</sup> December 2024

PREPARED FOR







#### SITE INVESTIGATION REPORT

CON	NTENTS	
1.	INTRODUCTION	1
2.	GENERAL DESCRIPTION OF STRUCTURE	2
3.	INVESTIGATION WORKS	2
4.	INVESTIGATION RESULTS	4
5	.DETAILED SKETCHES	6
6	REINSTATEMENT WORKS	
7.	PHOTO REPORT	18
7.	APPENDIX 1 – BRIDGE LAYOUT DRAWING	
8.	APPENDIX 2 - LAB TEST REPORT	

# TRIUR CONSTRUCTION LTD.

#### SITE INVESTIGATION REPORT

#### 1. INTRODUCTION

TRIUR Construction LTD carried out structural investigation works on Strade River Bridge (MO-N58-001.00) from the 8<sup>th</sup> to the 12<sup>th</sup> of July 2024

The Scope of the work included the following:

The site works were to consist of the following:

- · Mobilization and site set up
- Installation of traffic management measures (traffic lights)
- Excavation of 2no. trial pits in the concrete verges for depth of fill and deck exposure. One trial pit was
  excavated above the Northeastern abutment support while the second trial pit was excavated above the
  western pier support.
- Coring of 4x samples for strength testing of deck soffit (2no. in each span).
- The drilling of pilot holes in both the deck and the abutments, as required.
- Expose the deck slab and cleaning of the deck surface in adhesion test area.
- Carry out waterproofing adhesion test in Test Area 1
- Delamination survey to both spans
- Ferroscan and Concrete breakout of Test area 1-7.
- Chloride, cement content and carbonation samples obtained for BHP to lab test.
- Half-cell potential and Resistivity testing conducted by BHP.
- Detailed sketches made of breakout areas to include reinforcement sizing, location, spacing and cover.
- Reinstatement of the breakout and coring areas using PLANITOP RASA AND RIPARA R4 cementitious mortar.
- Reinstatement of any road openings as per Guidelines for Managing Openings in Public Roads (Guidelines on the Opening, Backfilling and Reinstatement of Openings in Public Roads) Second Edition Rev 1 (2017).
- Preparation of a detailed factual report on the investigation work undertaken at each bridge, i.e. one no.
   report required per bridge
- Removal of traffic management measures
- Demobilization
- The Bridge was reinstated on the 15<sup>th</sup> July 2024
- A detailed sketch was prepared, see below.
- A digital photographic record was carried out throughout the investigation works, see below.

#### SITE INVESTIGATION REPORT



#### 2. GENERAL DESCRIPTION OF STRUCTURE

The Strade River Bridge is a 2 span filler beam bridge. Each span is approx. 3.8m in length with a width of 11m. The Strade River predominantly flows in the northern span while the southern span consists of an elevated concrete floor which at the time of testing was above the river water level and completely dry. It carries the N58 national secondary road over the Strade Rriver which flows from east to west.

#### Location

Strade River Bridge

Co-ordinates: 53.921444, -9.130361 MO-N58-001.00, Strade



#### 3. INVESTIGATION WORKS

- The excavation of the Trial pits above the deck comprised of the breakout and removal of 2no. concrete rubbing strip located on the eastern and western verges. A layer of mesh and fill was also removed from each trial pit until the deck was exposed. Test area 1 (TA1) was located over the northeastern abutment while Test area 2 (TA2) was located over the western pier. No waterproofing layer was found above the concrete deck. No services or ducting were located in each respective trial pit.
- The excavation of a Trial pit (Test Area 01), located above the northeastern abutment to expose the RC slab for depth of fill and deck exposure. In this Trial Pit, a Covermeter and GPR survey was conducted to an area of the deck surface followed by concrete breakout to confirm cover and sizing of reinforcement members. The material covering this RC slab was observed to be 804 over layed with a concrete rubbing strip. A concrete core (C1) was also extracted for strength testing along with a pilot hole to obtain deck thickness. Durability testing was carried out by BHP.

# TRIUR CONSTRUCTION LTD.

#### SITE INVESTIGATION REPORT

- The excavation of a Trial pit (Test Area 02), located above the western end of the bridge pier to expose the RC slab for depth of fill and deck exposure. In this Trial Pit, a Covermeter and GPR survey was conducted to an area of the deck surface. No Steel was found on the deck side of the slab. A concrete core (C2) was also extracted for strength testing. A 25mm diameter pilot hole was drilled through the deck to obtain a value for the depth of the slab in this location. Durability testing was carried out by BHP.
- The investigation of Test Area 03, located in the the centre of the southern span on the western fascia. The area was scanned for reinforcement, samples acquired for testing and broken out to expose reinforcement.
- The investigation of Test area 3.1 located on the southeastern corner of the soffit of the southern span. In this area, a Concrete core (C3) was extracted for strength testing. A pilot hole was drilled to obtain measurements for deck thickness. A scan and breakout of the soffit in this area was undertaken to expose internal reinforcement.
- The investigation of Test Area 04, was located at the centre of the northern span on the western fascia. The area was scanned for reinforcement, samples acquired for testing and broken out to expose reinforcement.
- The investigation of Test area 4.1 located on the northwestern corner of the soffit on the Northern span. In this area, a Concrete core (C4) was extracted for strength testing. A pilot hole was drilled to obtain measurements for deck thickness. A scan and breakout of the soffit in this area was undertaken to expose internal reinforcement.
- The investigation of Test Area 05 located in the southern abutment approx. 3 meters from the the western edge. In this area, a Covermenter and GPR survey was conducted. 2no. durability tests were also conducted. This was followed by the drilling of a pilot hole to obtain the abutment thickness.
- The investigation of Test Area 06 located on the southern face of the pier at the midpoint. In this area, a Covermenter and GPR survey was conducted. 2no. durability tests were also conducted.
- The investigation of Test Area 07 located in the northern abutment approx. 3 meters from the eastern edge. In this area, a Covermenter and GPR survey was conducted. 2no. durability tests were also conducted. This was followed by the drilling of a pilot hole to obtain the abutment thickness.
- Adhesion pull off test on the deck top surface in Test Area 1 to determine the suitability of deck to a spray applied deck waterproofing system.
  - Reinforcement was found via breakouts in both the deck and in the soffit. Both longitudinal and
    transverse members were located and exposed on the deck and the soffit. The longitudinal
    reinforcement consisted of asymmetrical I-beams wherein the top flange was found to be narrower and
    thicker than the bottom flange. The transverse support consisted of smaller rectangular length of steel
    located close to the soffit. No connecction observed between the traverse reinforcement and the
    beams. Placed rebar detail.
- A delamination survey of both the southern and northern soffits was conducted. In the southern span, significant delamination was found across the whole width of the bridge. The areas where delamination had occurred were generally in the area covering each section of longitudinal reinforcement. The delamination ran in the direction of the longitudinal reinforcement while being consistent with the longitudinal reinforcement spacing.
  - In the northern span, delamination was present in the midsection of the bridge between 5m and 7.5m in from the eastern facia. There was evidence to suggest that this northern span had previously experienced delamination and been repaired.





#### 4. INVESTIGATION RESULTS

TEST AREA 1	mm
DeckTrial hole (east)	
cover of fill	420
cover on longitudinal bars	148
cover on transverse bars	124
Longitudinal bar sizing	125mm high rail
Transverse bar sizing	23x13mm bar
pilot hole 1	300
pilot hole 2	315
pilot hole 3	320
pilot hole 4	300
Core 1 – Area 1 – Deck	18.9 N/mm2
Core 2 – Area 1 – Deck	21.1 N/mm2

TEST AREA 2	mm	
DeckTrial hole (west)		
,	045	
cover of fill	315	
cover on longitudinal bars	n/a	
cover on transverse bars	n/a	
Longitudinal bar sizing	n/a	
Transverse bar sizing	n/a	
No reinforcement found above rail girders		

TEST AREA 3	mm
FACIA (south west)	
side cover on Web	129
cover on bottom flange	32
side cover bottom flange	68
side cover on top flange	105



#### SITE INVESTIGATION REPORT

TEST AREA 3.1	mm
soffit (south east)	
cover of fill	n/a
cover on longitudinal bars	34
cover on transverse bars	59
Longitudinal bar sizing	125 high rail
Transverse bar sizing	23x13mm bar
Core 3 – Area 3.1 – Soffit 1	49.6 N/mm2

TEST AREA 4	mm
FACIA (north west)	
The state of the s	
side cover on Web	132
	0.7
cover on bottom flange	37
side cover bottom flange	80
side cover on top flange	104
Core 4 – Area 4.1 – Soffit 2	57.1 N/mm2

TEST AREA 4.1	mm
soffit (north west)	
cover of fill	n/a
cover on longitudinal bars	47
cover on transverse bars	51
Longitudinal bar sizing	125 high rail
Transverse bar sizing	23x13mm bar



#### SITE INVESTIGATION REPORT

TEST AREA 5	mm	
Southern Abutment		
pilot hole	740	
cover on longitudinal bars	n/a	
cover on transverse bars	n/a	
Longitudinal bar sizing	n/a	
Transverse bar sizing	n/a	
No reinforcement found		

TEST AREA 6	mm	
Pier mid support (south west side )		
pilot hole	n/a	
cover on longitudinal bars	n/a	
cover on transverse bars	n/a	
Longitudinal bar sizing	n/a	
Transverse bar sizing	n/a	
No reinforcement found		

TEST AREA 7	mm	
Northern Abutment		
pilot hole	890	
cover on longitudinal bars	n/a	
cover on transverse bars	n/a	
Longitudinal bar sizing	n/a	
Transverse bar sizing	n/a	
No reinforcement found		

Plan of works area – Test Area locations – see Appendix 1 for more details.

#### Strade River Bridge Plan





Figure 1: Strade Bridge Plan



#### Test area 1

#### Test Area 1- Plan View



#### Test Area 1- Section





Figure 2: Test area 1 drawing



Test area 2

## Test Area 2- Plan View



## Test Area 2- Section




Figure 3: Test area 2 drawing

Test area 3

#### TA3 Facia - SIDE SECTION




Figure 4:Facia side section

## TA3 Facia - CROSS SECTION




Figure 5: TP3 Facia cross section



# TA3 Beam dimensions (mm)




Figure 6: External Beam Dimensions



Test area 3.1

# TA3.1 Soffit (south east corner)




Figure 7: Test area 3.1 Soffit



Test area 4

#### TA4 Facia - SIDE SECTION




Figure 8:TA4 Facia - Side Section

## TA3 Facia - CROSS SECTION




Figure 9: TA4 Facia - Cross Section



# TA4 Beam dimensions (mm)




Figure 10: TA4 Beam Dimensions



#### Test area 4.1

# T4.1 Soffit (south east corner)





Figure 11: Test Area 4.1



#### Delamination - shown in Red





#### **6.REINSTATEMENT DETAIL**

• Rubbing strip cutouts were backfilled with UGM A and infilled with 35N 10mm agg





Fosroc Renderoc HB45 was used to carry out concrete repairs to breakouts.







## 7.PHOTO REPORT

## **General bridge overview**











## TEST AREA 1



Figure 12: Test area 1 containing pilot hole, core sample hole and breakout.





Figure 13: Trial Pit layers





Figure 14: Deck cover on longitudinal steel



Figure 15: Concrete core hole (C1)






Figure 16: Adhesion testing



## Test Area 2



Figure 17: Trial pit on western edge





Figure 18: Trial pit layers



Figure 19: 90mm cutout in deck surface



## Test area 3



Figure 20: Breakout of external beam





Figure 21: Wide angle view of test area including drill holes for dust samples



Figure 22: Half cell potential testing





Figure 23: Carbonation test sample extracted to the left of breakout



## Test Area 3.1



Figure 24: Core hole from C3





Figure 25: Measurement of longitudinal beam flange





Figure 26: Transverse steel members running perpindicular to longitudinal members at 160mm spacing






Figure 27: Longitudinal cover was 39mm, Transverse cover wad 54mm




Figure 28: Delamination survey showed significant delamination underneath longitudinal sections on south arch



Figure 29: Further delamination on south arch





Figure 30: Exposed beams due to delamination of concrete cover





Figure 31: Delamination denoted by white x chalk marks



## Test Area 4



Figure 32: Half cell potential testing of TP04





Figure 33: Resistivity testing of TP04





Figure 34: Breakout at test area 4 exposing external beam



## Test Area 4.1




Figure 35: Breakout of internal beam showing transverse spacing marked via GPR





Figure 36: Half cell potential testing





Figure 37: Delamination found in northern arch





Figure 38: Delamination survey in Northern arch wide angle view





Figure 39: Core hole C4





Figure 40: Longitudinal bottom flange thickness





Figure 41: Cover of Transverse steel





Figure 42: 125mm wide bottom flange of internal beam





Figure 43: Wide angle view of breakout area

# Test Area 5



Figure 44: Pilot hole reinstatement along with dust sample holes





Figure 45: Pilot hole depth measurement





Figure 46: Outline of scanned area



# Test Area 6



Figure 47: Outline of scanned area with carbonation sample removed





Figure 48: Carbonation sample consisted of 100mm x 100mm x 80mm cuboid



Figure 49: TA6 carbonation sample depth into pier

# Test Area 7



Figure 50: Wide angle view of test area





Figure 51: Pilot hole reinstatement






Figure 52:Drill holes used for dust collection located on the northesatern end of the abutment



# Appendix 1 – Bridge Layout





# Appendix 2 – Lab Test report

Mayo Bridges Inspection – Strade River Bridge

**Concrete Testing Report** 



## **Document Issue Register**

Distribution	Report Status	Revision	Date of Issue	Prepared by	Approved by
Lurcan Donnellan Triur Construction	Final	A	27 <sup>th</sup> August 2024	Anton Hajek	James Purcell



#### **Contents**

1.0	Project Overview	Page 4
2.0	Project Requirements	Page 4
3.0	Location of Works	Page 4
4.0	Summary of Results	<b>Page 5 – 15</b>

Concrete Strength Test Report

Appendix A

Pull Off Test Report

Appendix B

Carbonation Test Report

Appendix C

Reinforcement Test Report

Appendix D

Chloride Ion Test Report

Appendix E

Cement Content Test Report

Appendix F

Half Cell and Resistivity Test Report

Appendix G



#### 1.0 Project Overview

BHP was contracted by Lurcan Donnellan of Triur Construction to provide a survey of the concrete bridge.

The investigation is intended to provide information for the employer in respect of the structural condition of the concrete deck and parapets and to assess the existing condition to enable evaluation of the proposed need for strengthening/rehabilitation works.

#### 2.0 Project Requirements


As directed by the project specification the requirements of the works included:

- Drill 4No. 100 diameter cores.
- Test for Density, Compressive strength and Visual examination.
- Chemical testing includes chloride content, cement content and depth of carbonation.
- Pull off testing on the concrete deck.
- Reinforcement scanning of concrete deck and parapets.
- Half-cell potential and concrete resistivity.

#### 3.0 Location of Works











#### 4.0 Summary of Results



**TOP Sketch of Strade River Bridge** 



\*Key

**X** Cores

**\* Half-cell** 

**X** Pull test

**X** Chloride

**X** Carbonation

**X** Cement

**3**12

#### 4.1 Concrete Cores – Compressive Strength

In line with the project specification, BHP removed several cores from the reinforced concrete elements. These were cored using a water-cooled diamond drill. The cores were individually marked and placed in sealed plastic bags for transportation to the laboratory.

The concrete cores were visually assessed by BHP's technical manager Seamus O'Connell.

A summary of the results with photographs is contained below:

BHP Ref:	Core Ref.	Details	Density kg/m3	Compressive Strength N/mm2
24/07/072-1	Core 1 – Area 1 – Deck	20mm Crushed Rock, 1.5% Voids	2280	18.9
24/07/072-2	Core 2 – Area 1 – Deck	20mm Crushed Rock, 2.5% Voids	2300	21.1
24/07/072-3	Core 3 – Area 3.1 – Soffit 1	20mm Crushed Rock, 0.5% Voids	2610	49.6
24/07/072-4	Core 4 – Area 4.1 – Soffit 2	20mm Crushed Rock, 0.5% Voids	2380	57.1

The mean result for compressive strength for the deck cores is 20.0N/mm² with a standard deviation of 1.56. The mean density of the test specimens is 2290kg/m³.

The mean result for compressive strength for all the cores is 53.4N/mm² with a standard deviation of 5.3. The mean density of the test specimens is 2500kg/m³.



#### 4.2 Pull Off Test

In accordance with the project specification, the pull off test was to be performed at one location in the concrete deck.

A summary of the results is contained below with full reports contained in Appendix B of this report.

Test Reference	Max Applied Load (MPa)	Depth of failure (mm)	Failure occurred in
Area 1 top deck	1.4	3	Below adhesive in concrete substrate
			(cohesion failure)
Area 1 top deck	1.7	4	Below adhesive in
			concrete substrate
			(cohesion failure)
Area 1 top deck	2.3	5.0	Below adhesive in
			concrete substrate
			(cohesion failure)
Area 1 top deck	0.9	0	Below adhesive on top
			of concrete surface
			(adhesion failure)
Area 1 top deck	2.6	4.0	Below adhesive in
			concrete substrate
			(cohesion failure)
Mean	1.78		



#### 4.3 Carbonation

In accordance with the project specification, the carbonation testing was to be performed at seven locations.

Carbonation testing is carried out to determine the depth of concrete affected due to a combined attack of atmospheric carbon dioxide and moisture causing a reduction in the level of alkalinity in concrete. Cement paste has a pH of approximately 13 which provides a protective layer (passive coating) to the steel reinforcement against corrosion. Loss of passivity occurs at about pH 9.

A 3% phenolphthalein indicator is used for the test. This is applied to freshly exposed concrete surface as detailed above.

Once the indicator is applied to the concrete surface, the change of colour of concrete to pink indicates that the concrete is in good health/condition. Where no change in colour takes place, it is suggestive of carbonation-affected concrete.

The results of the tests performed at Knockavrony Bridge, Co. Mayo are contained in Appendix C of this report.

A summary of the results is contained below:

Location	Depth of Carbonation (mm)
Carbonation Test 1 – Area 1 Top Deck	<1
Carbonation Test 2 – Area 2 Top Deck	<1
Carbonation Test 3 – Area 3 Face deck	<1
Carbonation Test – Area 3.1 Soffit	16
Carbonation Test 5 – Area 4 Face deck	<1
Carbonation Test 6 – Area 4.1 Soffit	<1
Carbonation Test 7 – Area 5 Abutment	>20
Carbonation Test 8 – Area 5 abutment	<1
Carbonation Test 9 – Area 6 abutment	<1
Carbonation Test 10 – Area 6 abutment	<1
Carbonation Test 11 – Area 7 abutment	<1
Carbonation Test 12 – Area 7 abutment	<1

There was no obvious reason for the differing levels of carbonation other than different locations. The two locations of high carbonation can be viewed as isolated instances of carbonation. All other results had negligible carbonation. At both soffit locations (3.1 and 4.1), there was clear visual spalling of concrete. However, the carbonation at 4.1 did not show high carbonation like at location 3.1. To understand a full assessment of carbonation, further samples would have to be taken at a number of locations throughout to ascertain the consistency. It must be noted that the chloride ingress into the concrete is very low, so refurbishment works including the application of protection paint/similar material should limit any increase in carbonation and reduce long-term risks of corrosion occurring.



#### 4.4 Reinforcement Details

In following page, a summary of reinforcement investigation on deck, parapet sections and information on the reinforcement found in breakouts have been compiled from the survey conducted in Strade River Bridge, Co. Mayo

Full details are in Appendix D of this report.

Scan Location	Rebar direction	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)	Minimum Spacing (mm)	Maximum Spacing (mm)
Area 1 top deck longitudinal scan 001	Т	153	n/a	n/a	n/a	n/a	n/a
Area 1 top deck transverse scan 001	L	164	158	170	180	n/a	n/a
Area 2 top of deck longitudinal scan	Т	160	137	183	640	n/a	n/a
Area 2 top of deck longitudinal scan 002	Т	156	150	162	620	n/a	n/a
Area 2 top of deck transverse scan 001	L	204	144	238	405	130	680
Area 3 deck face vertical scan 001	L	142	136	148	60	n/a	n/a
Area 3 deck face horizontal scan 001	Т	135	n/a	n/a	n/a	n/a	n/a
Area 3.1 soffit longitudinal scan 001	Т	38	28	48	684	560	710
Area 3.1 soffit longitudinal scan 002	Т	42	37	48	657	620	690
Area 3.1 soffit transverse scan 001	L	46	42	55	166	140	198
Area 3.1 soffit transverse scan 002	L	62	54	68	165	140	196
Area 4 Deck Face Vertical scan 001	L	106	92	120	120	n/a	n/a



Area 4 Deck Face Horizontal scan 001	Т	n/a	n/a	n/a	n/a	n/a	n/a
Area 4.1 Soffit longitudinal scan 001	Т	48	42	51	666	640	700
Area 4.1 Soffit longitudinal scan 002	Т	51	42	56	707	640	750
Area 4.1 Soffit transverse scan 001	L	60	44	69	227	120	330
Area 4.1 Soffit transverse scan 002	L	65	55	76	216	120	319
Area 5 Abutment vertical scan 001	L	n/a	n/a	n/a	n/a	n/a	n/a
Area 5 Abutment horizontal scan 001	Т	n/a	n/a	n/a	n/a	n/a	n/a
Area 6 Pier horizontal scan 001	Т	n/a	n/a	n/a	n/a	n/a	n/a
Area 6 Pier Vertical scan 001	L	n/a	n/a	n/a	n/a	n/a	n/a
Area 7 Abutment Vertical scan 001	L	n/a	n/a	n/a	n/a	n/a	n/a
Area 7 Abutment Horizontal scan 001	Т	n/a	n/a	n/a	n/a	n/a	n/a

Rebar directions: L-longitudinal, T-transverse

<sup>\*</sup> In Area 5 – Area 7 GPR did not find any reinforcement

Reinforcement found by completing a breakout	Actual cover (mm)	Diameter (mm)	Width(mm)
Area 1 top of deck top flange	150	N/A	N/A
Area 1 top of deck transverse rebar square	109	14.3 / 25.7	N/A
Area 3 face deck web	129	N/A	N/A
Area 3 face deck bottom flange	32	10.89	123
Area 3 face deck bottom side flange	68	N/A	N/A
Area 3 face deck top flange	104	N/A	N/A
Area 3 face deck distance top-bottom flange	117	N/A	N/A
Area 3.1 soffit bottom flange	34	N/A	N/A
Area 3.1 soffit transverse rebar square	59	15.3 / 28.9	N/A
Area 4 face deck top side flange	104	31.39	N/A
Area 4 face deck web	132	N/A	N/A
Area 4 face deck bottom flange	80	N/A	N/A
Area 4 face deck bottom flange	37	8.86	N/A
Area 4.1 soffit bottom flange	47	N/A	N/A
Area 4.1 soffit transverse rebar square	51	13.5 / 23.6	N/A



<sup>\*</sup> In Area 1(TP1), Area 2 (TP2) were not enough space to get more reinforcement readings due to lack of access for GPR as the Trail hole area only allowed for coring and breakouts

#### 4.5 Chloride Ion Testing

Corrosion of reinforcing steel and other embedded metals is the leading cause of deterioration in concrete. When steel corrodes, the resulting rust occupies a greater volume than the steel. This expansion creates tensile stresses in the concrete, which can eventually cause cracking, delamination and spalling.

Steel corrodes because it is not a naturally occurring material. Rather, iron ore is smelted and refined to produce steel. The production steps that transform iron ore into steel add energy to the metal. Steel, like most metals except gold and platinum, is thermodynamically unstable under normal atmospheric conditions and will release energy and revert back to its natural state – iron oxide, or rust. This process is called corrosion.

Corrosion is an electrochemical process involving the flow of charges (electrons and ions). At active sites on the reinforcement bar, called anodes, iron atoms lose electrons and move into the surrounding concrete as ferrous ions. This process is called a half-cell oxidation reaction, or anodic reaction.

Corrosion of embedded metals in concrete can be greatly reduced by placing crack-free concrete with low permeability and sufficient concrete cover. Additional measures to mitigate corrosion of steel reinforcement in concrete include the use of corrosion inhibiting admixtures, coating of reinforcement, and the use of sealers and membranes on the concrete surface.

As noted in section 4.3 carbonation, the breakdown in the protection of reinforcement bars leads to concrete spalling. The depth of carbonation provides a guide as to the risk of corrosion on a particular bar. Concrete that is not carbonated (or has very low levels of carbonation) protects the embedded steel reinforcement.

Exposure of reinforced concrete to chloride ions is the primary cause of premature corrosion of steel reinforcement. The intrusion of chloride ions present in deicing salts, seawater and other associated sources, into reinforced concrete can cause steel corrosion if oxygen and moisture are available to sustain the reaction. Chlorides dissolved in water can penetrate through sound concrete or reach the steel through cracks.

No other contaminant is documented as extensively in the literature as a cause of corrosion of metals in concrete than chloride ions. The risk of corrosion increases as the chloride content of concrete increases. For Strade River bridge, Co. Mayo, the major concern is the extent of any existing chloride within the various concrete structural elements. While the levels are assessed during this survey, as the concrete is continually exposed to the natural environments and weathering, the level of chloride in the concrete could increase with time.

To assess potentially chloride-contaminated concrete, it is necessary to determine the concentration of chloride ions at various depths in order to determine the likelihood of corrosion of the reinforcement steel. To do this dust samples are taken from incremental depths. As specified, this was to be carried out in four depths (5-30mm, 30-55mm, 55-80mm & 80-105mm). Note the first 5mm drilling are normally discarded as being non-representative. Care was taken to ensure all drilling dust was collected. This is important as studies have shown that more chloride is contained in the finer component of the dust.

In line with the Irish concrete standard (EN 206), the chloride content as a percentage of cement is to be below the maximum allowable of 0.4% for concrete mixes containing embedded steel. At all twelve locations, the chloride content as a percentage of cement is below this value.



#### A summary table of the results is found below:

	Sample	Depth	Chloride % by m	
Location Reference	Reference	(mm)	Sample	Cement
Area 1 - Car 1	24/07/072-1	5-30	0.01	80.0
		30-55	0.01	80.0
		55-80	0.02	0.15
		80-105	0.01	80.0
Area 2 - Car 2	24/07/072-2	5-30	0.04	0.20
		30-55	0.03	0.15
		55-80	0.03	0.15
		80-105	0.01	0.05
Area 3 - Car 3	24/07/072-3	5-30	0.02	0.13
		30-55	0.02	0.13
		55-80	0.02	0.13
		80-105	0.02	0.13
Area 3.1 - Car 4	24/07/072-4	5-30	0.03	0.20
		30-55	0.02	0.13
		55-80	0.03	0.20
		80-105	0.03	0.20
Area 4 - Car 5	24/07/072-5	5-30	0.04	0.19
		30-55	0.02	0.10
		55-80	0.02	0.10
		80-105	0.02	0.10
Area 4.1 - Car 6	24/07/072-6	5-30	0.04	0.33
]		30-55	0.03	0.25
		55-80	0.03	0.25
		80-105	0.04	0.33

	▼ Sample	Depth	Chloride % by m	Content vass of
Location Reference	Reference	(mm)	Sample	Cement
Area 5 - Car 7	24/07/072-7	5-30	0.02	0.20
		30-55	0.01	0.10
		55-80	0.01	0.10
		80-105	0.01	0.10
Area 5 - Car 8	24/07/072-8	5-30	0.02	0.25
		30-55	0.01	0.13
		55-80	0.01	0.13
		80-105	0.01	0.13
Area 6 - Car 9	24/07/072-9	5-30	0.01	0.07
		30-55	0.01	0.07
		55-80	0.01	0.07
		80-105	0.01	0.07
Area 6 - Car 10	24/07/072-10	5-30	0.03	0.21
		30-55	0.03	0.21
		55-80	0.03	0.21
		80-105	0.03	0.21
Area 7 - Car 11	24/07/072-11	5-30	0.01	0.08
		30-55	0.01	0.08
		55-80	0.01	0.08
		80-105	0.01	0.08
Area 7 - Car 12	24/07/072-12	5-30	0.03	0.17
		30-55	0.03	0.17
		55-80	0.02	0.11
		80-105	0.02	0.11



#### 4.6 Cement Content

The determination of the cement content (mix proportions) is undertaken largely for two reasons. The first is in the cases of problems to identify the reason for concrete failure or lack of quality. The second is to investigate old structural concrete for redevelopment and improvement works. This is the case in this project. The cement content analysis will also allow BHP to provide chloride and sulphate results as a percentage of cement for clear comparison with standard allowances.

We start by describing the raw materials that go into mortar and concrete and by defining some terms. Cement is a generic term meaning "glue." Portland cement is a gray powder that when mixed with water forms a paste that hardens and gains strength with time. This is the glue that holds mortar and concrete together. When sand or fine aggregate is added to paste the mixture is known as mortar which is suitable for thin cross sections. Grouts, plasters and stuccos are generally special mortars and contain much the same raw materials. Stone added to mortar makes concrete which can be used in structural or massive applications.

The cement most often used in construction is known as Portland cement. There are other types of construction cements, some used in masonry construction and other special cements used for repairs or high temperature applications. This paper addresses Portland cement and its derivatives only. The predominant chemical compounds in Portland cement are based upon oxides of calcium (lime), silicon (silica), aluminium (alumina) and iron. There are other compounds present in smaller quantities such as magnesia and carbon dioxide and a number of trace elements. The principal chemical compounds that combine with water (hydrate) to provide strength are calcium silicates. However, in all reported chemical analyses, the constituents of cement and concrete are reported simply as the appropriate oxides. Modern Portland cements, by definition, all tend to contain these compounds in a fairly tight range of values even if they come from different manufacturing facilities. Hydrated Portland cement has the unusual, and desirable, property that it will continue to gain strength (albeit at a decreasing rate) when in the presence of water. This complicates chemical analysis because the system is continually changing from the time of first mixing to the time of test.

The cement content analysis for Strade River bridge, Co. Mayo was undertaken on twelve samples. The samples came from deck, abutments and soffits in different levels. The mean cement content results for the twelve samples is 14% with a range of 8% - 20%. A summary table of the results is found below.

Location	Cement Content (%)	Compressive Strength (N/mm2) – from core test
Area 1 Top Deck	13	18.9
Area 2 Top Deck	20	21.1
Area 3 Face deck	16	-
Area 3.1 Soffit	15	49.6
Area 4 Face deck	21	-
Area 4.1 Soffit	12	57.1
Area 5 Abutment	10	-
Area 5 Abutment	8	-
Area 6 Pier	14	-
Area 6 Pier	14	-
Area 7 Abutment	12	-
Area 7 Abutment	18	-

A cement content of 16-17% would normally indicate an approximate in-situ compressive strength of 50N. The values found here find that the expected cement content for the soffit is a little lower than expected. The biggest different is the cement content in the top deck versus the actual compressive strength. Albeit one of the cores in the soffit contained reinforcement, the density of these concrete versus the concrete in the deck is much higher.

342

#### 4.7 Half Cell and Resistivity

Corrosion of steel in concrete is one of the major problems with respect to the durability of reinforced concrete structures. Most concrete structures perform well even after a long period of use in normal environments. However, there are various reinforced concrete structures important for our infrastructure, especially bridges and buildings, which exhibit premature damage due to environmental actions (EN 206).

In contrast to mechanical actions (load, wind, etc.) the environmental actions are not reversible and accumulate hazardous components (such as chloride ions) in the concrete. A high percentage of the damage is caused by insufficient planning, wrong estimation of severity of environmental actions and by bad workmanship and this many of these structures need to be repaired after a short service life.

Half-cell potential measurements can be performed on structures with ordinary or stainless-steel reinforcement. Corrosion of prestressing steel in concrete can be assessed in the same way. Prestressing steel in the ducts of posttensioned cables cannot be assessed.

Half-cell potential measurements are suitable mainly on reinforced concrete structures exposed to the atmosphere. The method can be applied regardless of the depth of concrete cover and the rebar size. Half-cell potential measurements will indicate corroding rebars not only in the most external layers of reinforcement facing the references electrode but also in greater depth. The method can be used at any time during the life of a structure and in any kind of climate providing the temperature is higher than +2°C. Hal-cell potential measurements should be taken only on a free concrete surface. The presence of isolating layers (asphalt, organic coatings or paints etc.) may make measurements erroneous or impossible.

In the assessment of the half-cell results, ASTM C876 uses a numeric technique to assess the half-cell potential results.

Table 1: Relationship between the potential values and corrosion probability (adapted from ASTM C876)

Measured Potential(mV CSE)	Probability of steelcorrosion activity
>-200	Less than 10%
-200 to -350	Uncertain
<-350	More than 90%

#### **Half Cell Potential Results**

Location	Mean (mV)	Lowest (mV)	Highest (mV)	Standard Deviation (mV)
Area 1 Top deck	-239	-268	-207	19.8
Area 3 Face deck	-54.9	-97	-27	21
Area 3.1 Soffit	-333.5	-368	-320	13.2
Area 4 Face deck	-237.7	-283	-198	28.3
Area 4.1 Soffit	-165.8	-179	-129	13



Based on this, it sets our three phases of corrosion activity – Initial Phase, Transient Phase, and the Final Phase. For any half-cell potential results that are > -200 it is deemed to be in the initial phase where the probability of corrosion activity is less than 10%. Where the half-cell potential results that are in the range of -200 to -350 (Transient Phase), the probability of corrosion activity is uncertain. Where the half-cell potential results that are <-350 (Final Phase), the probability of corrosion activity is more than 90%. Based on the results and visual examination of the bars on site when broken out, the likelihood of corrosion based on half-cell results is moving from the initial phase to the transient phase.

In addition to half-cell potential surveying of concrete, resistivity measurements of the same concrete material provide further information on the potential for further corrosion taking or to take place. Corrosion of reinforcing steel is an electro-chemical process. For corrosion of the steel to occur a current must pass between the anodic and cathodic regions of the concrete. The electrical resistivity of the concrete affects the flow of ions and the rate at which corrosion can occur. A higher concrete resistivity decreases the flow; an empirical relationship between corrosion rate and resistivity has been determined from measurements on actual structures.

Electrical resistivity measurement techniques are becoming popular among consulting / design engineers for the quality assessment and durability assessment of concrete. The concept of durability of concrete depends largely on the properties of its microstructure, such as pore size distribution and the shape of the interconnections (that is, tortuosity). A finer pore network, with less connectivity, leads to lower permeability. A porous microstructure with larger degree of interconnections, on the other hand, results in higher permeability and reduced durability in general. The principal idea behind most electrical resistivity techniques is to somehow quantify the conductive properties of the microstructure of concrete. Overall, the electrical resistivity of concrete can be described as the ability of concrete to withstand the transfer of ions subjected to an electrical field. In this context, resistivity measurement can be used to assess the size and extent of the interconnectivity of pores.

Various approaches for measuring resistivity are available but the four-probe device is the most suitable. Modern devices are spring-loaded and are applied directly to the surface. A current is applied between the two outer probes and the potential difference measured between the two inner probes. Resistivity measurement is useful for identifying areas of reinforced concrete at risk from corrosion. It should not be considered in isolation but used in conjunction with other techniques such as half-cell potential. BHP employed the use of the latest version of Proceq's Resipod with 50mm spacings between the four probes.

From the testing undertaken at this structure, we found that there was a negligible risk of corrosion based on the resistivity results.

Location	Result 1	Result 2	Result 3	Result 4	Result 5
Area 1 Top deck	106	112	172	185	190
Area 3 Face deck	69	55	72	-	-
Area 3.1 Soffit	285	278	303	256	272
Area 4 Face deck	186	156	194	-	-
Area 4.1 Soffit	196	206	209	255	272



# Appendix A





# COMPRESSIVE STRENGTH OF A CONCRETE CORE TEST REPORT



BHP/MTIField/F058 V1 29/05/24

Client: TRIUR Construction Ltd

13 Society Street Ballinasloe

Galway

FAO: Lurcan Donnellan

**BHP Ref. No**.: 24/07/072-1

Order No: Not Supplied Date Tested: 09/07/2024

Test Specification: Customer Spec.

Test Element: Concrete Core

Project: Mayo Bridges Investigation - Strade River Bridge

Location Reference: Area 1 C1 Deck
Test Standard: EN 12504-1:2019

	_	- · · ·	
Core Details			
Coring Date	12/07/2024	Age of specimen	Not Specified
End of core used as datum	Тор	Reinforcement in test Specimen: Size (mm)	N/A
Drilling Direction	Vertical	Reinforcement in test Specimen: Position (mm)	N/A
Visual Assessment			
Condition of specimen when received	Good	Maximum nominal size of aggregate (mm)	20
Compaction of concrete	Good	Distribution of materials	Even
Excess Voids	1.5%	Ribbing on core surface	None
Honeycombing	Yes	Flatness	Pass
Presence of cracks	None	Perpendicularity	Pass
Type of aggregate	Crushed Rock	Straightness	Pass
Test Information			
Preparation		Surface condition at time of test	Dry
Length after end preparation	102	Type of failure	Satisfactory
Diameter after end preparation	99	Average Diameter (mm)	99
Length / diameter ratio of specimen	1.03	Maximum length of specimen, as received	144
		Minimum length of specimen, as received	144
		Density of the specimen, as received (kg/m³)	2280
		Max Load (KN)	144.8
		Compressive Strength (N/mm²)	18.9

#### REMARKS:

Method of determining volume used was displacement. Method of end preparation used was sawn & capped. The sample was stored in a sealed container prior to testing.

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Sekox Lalander

For and On Behalf of BHP Laboratories Issue Date: 19/07/2024

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie

This test report shall not be duplicated in full without the permission of the test laboratory. Information identifying the 'Client', 'FAO', 'Project', 'Location Reference', 'Item', 'Test Specification' and 'Order No' has been provided by the customer. Results apply only to the sample tested and where the laboratory is not responsible for sampling, result apply to the sample as received. Sampling is outside the scope of accreditation.



# COMPRESSIVE STRENGTH OF A CONCRETE CORE TEST REPORT



BHP/MTIField/F058 V1 29/05/24

Client: TRIUR Construction Ltd

13 Society Street Ballinasloe

Galway

FAO: Lurcan Donnellan

BHP Ref. No.: 24/07/072-2

Order No: Not Supplied Date Tested: 09/07/2024

**Test Specification**: Customer Spec. **Test Element:** Concrete Core

Project: Mayo Bridges Investigation - Strade River Bridge

Location Reference: Area 2 C2 Deck
Test Standard: EN 12504-1:2019

Core Details			
Coring Date	12/07/2024	Age of specimen	Not Specified
End of core used as datum	Тор	Reinforcement in test Specimen: Size (mm)	N/A
Drilling Direction	Vertical	Reinforcement in test Specimen: Position (mm)	N/A
Visual Assessment			
Condition of specimen when received	Good	Maximum nominal size of aggregate (mm)	20
Compaction of concrete	Good	Distribution of materials	Even
Excess Voids	2.5%	Ribbing on core surface	None
Honeycombing	Yes	Flatness	Pass
Presence of cracks	None	Perpendicularity	Pass
Type of aggregate	Crushed Rock	Straightness	Pass
Test Information			
Preparation Surface condition at time of test Dry			Dry
Length after end preparation	102	Type of failure	Satisfactory
Diameter after end preparation	99	Average Diameter (mm)	99
Length / diameter ratio of specimen	1.03	Maximum length of specimen, as received	123
		Minimum length of specimen, as received	123
		Density of the specimen, as received (kg/m³)	2300
		Max Load (KN)	161.8
		Compressive Strength (N/mm²)	21.1

#### REMARKS:

Method of determining volume used was displacement. Method of end preparation used was sawn & capped. The sample was stored in a sealed container prior to testing.

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Lekos Lalander

For and On Behalf of BHP Laboratories Issue Date: 19/07/2024

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie

This test report shall not be duplicated in full without the permission of the test laboratory. Information identifying the 'Client', 'FAO', 'Project', 'Location Reference', 'Item', 'Test Specification' and 'Order No' has been provided by the customer. Results apply only to the sample tested and where the laboratory is not responsible for sampling, result apply to the sample as received. Sampling is outside the scope of accreditation.



# COMPRESSIVE STRENGTH OF A CONCRETE CORE TEST REPORT

BHP Ref. No.:

Date Tested:

**Test Element:** 

Order No:

24/07/072-3

Not Supplied

09/07/2024

Concrete Core

Test Specification: Customer Spec.



BHP/MTIField/F058 V1 29/05/24

Client: TRIUR Construction Ltd

13 Society Street
Ballinasloe
Galway

FAO: Lurcan Donnellan

Project: Mayo Bridges Investigation - Strade River Bridge

**Location Reference:** Area 3.1 C3 Soffit **Test Standard:** EN 12504-1:2019

Core Details						
Coring Date	12/07/2024	12/07/2024 Age of specimen				
End of core used as datum	Тор	Reinforcement in test Specimen: Size (mm)	Square (14x25mm)			
Drilling Direction	Vertical	Reinforcement in test Specimen: Position (mm)	60			
	Visual A	Assessment				
Condition of specimen when received	Good	Maximum nominal size of aggregate (mm)	20			
Compaction of concrete	Good	Distribution of materials	Even			
Excess Voids	0.5%	Ribbing on core surface	None			
Honeycombing	None	Flatness	Pass			
Presence of cracks	None	Perpendicularity	Pass			
Type of aggregate	Crushed Rock	Straightness	Pass			
	Test In	formation				
Preparation		Surface condition at time of test	Dry			
Length after end preparation	102	Type of failure	Satisfactory			
Diameter after end preparation	99	Average Diameter (mm)	99			
Length / diameter ratio of specimen	1.03	Maximum length of specimen, as received	145			
		Minimum length of specimen, as received	145			
		Density of the specimen, as received (kg/m³)	2610			
		Max Load (KN)	380.9			
		Compressive Strength (N/mm²)	49.6			

#### **REMARKS:**

Method of determining volume used was displacement. Method of end preparation used was sawn & capped. The sample was stored in a sealed container prior to testing.

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Sekas Lalander

For and On Behalf of BHP Laboratories

Issue Date:

28/08/2024

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie

This test report shall not be duplicated in full without the permission of the test laboratory. Information identifying the 'Client', 'FAO', 'Project',

'Location Reference', 'Item', 'Test Specification' and 'Order No' has been provided by the customer. Results apply only to the sample tested and where the laboratory is not responsible for sampling, result apply to the sample as received. Sampling is outside the scope of accreditation.



# COMPRESSIVE STRENGTH OF A CONCRETE CORE TEST REPORT

BHP Ref. No.:

Date Tested:

**Test Element:** 

Order No:

24/07/072-4

Not Supplied

Concrete Core

09/07/2024

Test Specification: Customer Spec.



BHP/MTIField/F058 V1 29/05/24

Client: TRIUR Construction Ltd

13 Society Street
Ballinasloe
Galway

FAO: Lurcan Donnellan

Project: Mayo Bridges Investigation - Strade River Bridge

**Location Reference:** Area 4.1 C4 Soffit **Test Standard:** EN 12504-1:2019

Core Details						
Coring Date	12/07/2024	12/07/2024 Age of specimen				
End of core used as datum	Тор	Reinforcement in test Specimen: Size (mm)	N/A			
Drilling Direction	Vertical	Reinforcement in test Specimen: Position (mm)	N/A			
	Visual A	ssessment				
Condition of specimen when received	Good	Maximum nominal size of aggregate (mm)	20			
Compaction of concrete	Good	Distribution of materials	Even			
Excess Voids	0.5%	Ribbing on core surface	None			
Honeycombing	None	Flatness	Pass			
Presence of cracks	None	Perpendicularity	Pass			
Type of aggregate	Crushed Rock	Straightness	Pass			
Test Information						
Preparation		Surface condition at time of test	Dry			
Length after end preparation	102	Type of failure	Satisfactory			
Diameter after end preparation	99	Average Diameter (mm)	99			
Length / diameter ratio of specimen	1.03	Maximum length of specimen, as received	135			
		Minimum length of specimen, as received	120			
		Density of the specimen, as received (kg/m³)	2380			
		Max Load (KN)	438.9			
		Compressive Strength (N/mm²)	57.1			

#### **REMARKS:**

Method of determining volume used was displacement. Method of end preparation used was sawn & capped. The sample was stored in a sealed container prior to testing.

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Sekox Lalander

For and On Behalf of BHP Laboratories

Issue Date:

28/08/2024

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie

This test report shall not be duplicated in full without the permission of the test laboratory. Information identifying the 'Client', 'FAO', 'Project',

'Location Reference', 'Item', 'Test Specification' and 'Order No' has been provided by the customer. Results apply only to the sample tested and where the laboratory is not responsible for sampling, result apply to the sample as received. Sampling is outside the scope of accreditation.

# Appendix B



#### BOND STRENGTH BY PULL OFF TEST REPORT



BHP/MTIField/F045 V1 15/04/24

Client: TRIUR Construction Ltd BHP Ref. No.: 24/07/072

13 Society StreetOrder No:Not SuppliedBallinasloeDate Tested:12/07/2024GalwayTest Specification:Customer Spec.

FAO: Lurcan Donnellan Test Element: Concrete Surface

Project: Mayo Bridges - Strade River Bridge

**Location Reference**: See below **Test Standard**: BS EN 1542

Surface Condition Wet

Deck Surface Condition As Supplied Test Direction Vertical

Test Reference	Max Applied Load (MPa)	Depth of Failure (mm)	Failure Occurred In
Area 1 deck	1.4	3.0	Below adhesive on top of substrate
Area 1 deck	1.7	4.0	Below adhesive on top of substrate
Area 1 deck	2.3	5.0	Below adhesive on top of substrate
Area 1 deck	0.9	0.0	Below adhesive on top of substrate
Area 1 deck	2.6	4.0	Below adhesive on top of substrate
Mean		1.78	3

REMARKS:	
Elcometer 506 Pull - Off Adhesion Tester	

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Sekas Laborated

For and On Behalf of BHP Laboratories

Issue Date: 13/08/2024

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie

This test report shall not be duplicated in full without the permission of the test laboratory. Information identifying the 'Client', 'FAO', 'Project', 'Location Reference', 'Item', 'Test Specification' and 'Order No' has been provided by the customer. Results apply only to the sample tested and where the laboratory is not responsible for sampling, result apply to the sample as received. Sampling is outside the scope of accreditation.

# Appendix C



#### **CARBONATION DEPTH OF CONCRETE TEST REPORT**



BHP/MTIField/F053 V1 15/05/24

Client: TRIUR Construction Ltd BHP Ref. No.: 24/07/072 Order No:

Test Element:

13 Society Street Ballinasloe Galway

Not Supplied Date Tested: 09/07/2024 Test Specification: Customer Spec.

FAO: Lurcan Donnellan Concrete Core

Project: Mayo Bridges Investigation - Strade River

See below

Location Reference: Test Standard: BS EN 14630

Location Reference	Carbonation (mm)	Notes
Car 1	<1.0	Area 1
Car 2	<1.0	Area 2
Car 3	<1.0	Area 3
Car 4	16	Area 3.1
Car 5	<1.0	Area 4
Car 6	<1.0	Area 4.1
Car 7	>20	Area 5
Car 8	<1.0	Area 5
Car 9	<1.0	Area 6
Car 10	<1.0	Area 6
Car 11	<1.0	Area 7
Car 12	<1.0	Area 7

REMARKS:			
Nill			

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Sekon Lalenthe

For and On Behalf of BHP Laboratories

Issue Date: 21/08/2024

 $Tested \ by \ BHP \ Laboratories, \ New \ Road, \ Thomondgate, \ Limerick. \ Phone: (061) \ 455399 \ Email: jamespurcell @bhp.ie$ 

This test report shall not be duplicated in full without the permission of the test laboratory. Information identifying the 'Client', 'FAO', 'Project', 'Location Reference', 'Item', 'Test Specification' and 'Order No' has been provided by the customer. Results apply only to the sample tested and where the laboratory is not responsible for sampling, result apply to the sample as received. Sampling is outside the scope of accreditation.

# Appendix D



#### **TEST REPORT**

Account: Triur Construction Ltd,

13 Society Street, Ballinasloe, Galway

Customer: Mr. Lurcan Donnellan.

BHP Ref No.: 24/
Order No.: No
Date Received: No
Date Tested: 12/
Specification: Cli

24/07/072 Not Supplied Not Applicable 12/07/2024 Client Specification Analysing Testing Consulting Calibrating



New Road Thomondgate Limerick Ireland

Tel +353 61 455399 Fax + 353 61 455447

E Mail: jamespurcell@bhp.ie

Customer Reference: Reinforcement Scanning at Strade River Bridge, Co. Mayo

#### **Steel Reinforcement Survey**

On Tuesday 9th July and Friday 12<sup>th</sup> July 2024, BHP Laboratories visited Strade River bridge, Co. Mayo. The purpose of these specific works was to conduct a series of reinforcement scans to determine the concrete cover and reinforcement layout in top deck, face deck and soffit of bridge.

BHP undertook scans of the top deck, face deck and soffit to ascertain the reinforcement position and cover. BHP conducted this reinforcement scanning using the latest from Proceq – Ground Penetrating Radar (GPR).

#### **Site Location**





The scanning of the top deck, face deck and soffit bridge has found the following information / key points:

Scan Location	Rebar directions	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)	Minimum Spacing (mm)	Maximum Spacing (mm)
Area 1 top deck longitudinal scan 001	Т	153	n/a	n/a	n/a	n/a	n/a
Area 1 top deck transverse scan 001	L	164	158	170	180	n/a	n/a
Area 2 top of deck longitudinal scan	Т	160	137	183	640	n/a	n/a
Area 2 top of deck longitudinal scan 002	Т	156	150	162	620	n/a	n/a
Area 2 top of deck transverse scan 001	L	204	144	238	405	130	680
Area 3 deck face vertical scan 001	L	142	136	148	60	n/a	n/a
Area 3 deck face horizontal scan 001	Т	135	n/a	n/a	n/a	n/a	n/a
Area 3.1 soffit longitudinal scan 001	Т	38	28	48	684	560	710
Area 3.1 soffit longitudinal scan 002	Т	42	37	48	657	620	690
Area 3.1 soffit transverse scan 001	L	46	42	55	166	140	198
Area 3.1 soffit transverse scan 002	L	62	54	68	165	140	196
Area 4 Deck Face Vertical scan 001	L	106	92	120	120	n/a	n/a
Area 4 Deck Face Horizontal scan 001	Т	n/a	n/a	n/a	n/a	n/a	n/a
Area 4.1 Soffit longitudinal scan 001	Т	48	42	51	666	640	700
Area 4.1 Soffit longitudinal scan 002	Т	51	42	56	707	640	750
Area 4.1 Soffit transverse scan 001	L	60	44	69	227	120	330
Area 4.1 Soffit transverse scan 002	L	65	55	76	216	120	319
Area 5 Abutment vertical scan 001	L	n/a	n/a	n/a	n/a	n/a	n/a



Scan Location	Rebar directions	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	<b>a</b> •	Minimum Spacing (mm)	Maximum Spacing (mm)
Area 5 Abutment horizontal scan 001	T	n/a	n/a	n/a	n/a	n/a	n/a
Area 6 Abutment horizontal scan 001	Т	n/a	n/a	n/a	n/a	n/a	n/a
Area 6 Abutment Vertical scan 001	L	n/a	n/a	n/a	n/a	n/a	n/a
Area 7 Abutment Vertical scan 001	L	n/a	n/a	n/a	n/a	n/a	n/a
Area 7 Abutment Horizontal scan 001	Т	n/a	n/a	n/a	n/a	n/a	n/a

<sup>\*</sup>Rebar directions: L- longitudinal, T- transverse

<sup>\*</sup> In Area 5 – Area 7 GPR did not find any reinforcement


Reinforcement found by completing a	Actual cover	Diameter (mm)	Width(mm)
breakout	(mm)		
Area 1 top of deck top flange	150	n/a	n/a
Area 1 top of deck transverse rebar square	109	14.3/25.7	n/a
Area 3 face deck web	129	n/a	n/a
Area 3 face deck bottom flange	32	10.89	123mm
Area 3 face deck bottom side flange	68	n/a	n/a
Area 3 face deck top flange	104	n/a	n/a
Area 3 face deck distance top-bottom	117	n/a	n/a
flange			
Area 3.1 soffit bottom flange	34mm	n/a	n/a
Area 3.1 soffit transverse rebar square	59	15.3/28.9	n/a
Area 4 face deck top side flange	104	31.39	
Area 4 face deck web	132	n/a	n/a
Area 4 face deck bottom flange	80	n/a	n/a
Area 4 face deck bottom flange	37	8.86	n/a
Area 4.1 soffit bottom flange	47	n/a	n/a
Area 4.1 soffit transverse rebar square	51	13.5/23.6	




<sup>\*</sup> In Area 1(TP1), Area 2 (TP2) were not enough space to get more reinforcement readings due to lack of access for GPR

## Area 3 beam sketch


### Area 3.1 beam sketch







### Area 4 beam sketch

Area 4.1 beam sketch






Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 1 top of footpath longitudinal scan	139	87	184	191



Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 1 top of footpath transverse scan first layer	31	30	32	290


Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 1 top of footpath transverse l scan second layer	166	159	171	295






Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 1 top of footpath transverse scan first layer 002	32	30	34	310

Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 1 top of footpath transverse scan second layer 002	159	152	164	227




Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 1 top deck longitudinal scan 001	153	n/a	n/a	n/a






Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 1 top deck transverse scan 001	164	158	170	180



Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 2 top of footpath longitudinal scan 001	34	34	34	1400


Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 2 top of footpath longitudinal scan 001	153	n/a	n/a	n/a






Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 2 top of footpath transverse scan 001 first layer	67	57	85	385

Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 2 top of footpath transverse scan 001 second layer	116	102	138	260




Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 2 top of footpath transverse scan 002	146	138	154	196






Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 2 top of deck longitudinal scan 001	160	137	183	640




Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 2 top of deck longitudinal scan 002	156	150	162	620






Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 2 top of deck transverse scan 001	204	144	238	405




Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 3 deck face vertical scan 001	142	136	148	60






Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 3 deck face horizontal scan 001	135	n/a	n/a	n/a

## Transverse Reinforcement




Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 3.1 soffit longitudinal scan 001	38	28	48	249






Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 3.1 soffit longitudinal scan 002	42	37	48	657




Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 3.1 soffit transverse scan 001	46	42	55	166






Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 3.1 soffit transverse scan 002	62	54	68	165




Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 4 Deck Face Vertical scan 001	106	92	120	120






Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 4 Deck Face Vertical scan 001	106	92	120	120



Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 4.1 Soffit longitudinal scan 001	48	42	51	666







Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 4.1 Soffit longitudinal scan 002	51	42	56	707

Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 4.1 Soffit transverse scan 001	60	44	69	227






Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 4.1 Soffit transverse scan 002	65	55	76	216




Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 5 Abutment vertical scan 001	n/a	n/a	n/a	n/a






Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 5 Abutment horizontal scan 001	n/a	n/a	n/a	n/a




Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 6 Abutment horizontal scan 001	n/a	n/a	n/a	n/a






Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 6 Abutment vertical scan 001	n/a	n/a	n/a	n/a



Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 7 Abutment vertical scan 001	n/a	n/a	n/a	n/a






Scan Location	Mean Cover (mm)	Lowest Cover (mm)	Highest Cover (mm)	Mean Spacing (mm)
Area 7 Abutment horizontal scan 001	n/a	n/a	n/a	n/a


## Photographs of breakout



































James Purcell

Structural Testing Manager For and on behalf of BHP Laboratories Ltd.

Test results relate only to this item. This test report shall not be duplicated except in full and with the permission of the test laboratory



# Appendix E



### CHLORIDE CONTENT OF CONCRETE TEST REPORT



BHP/MTIField/F063 V1 08/07/24

Client: TRIUR Construction Ltd

 TRIUR Construction Ltd
 BHP Ref. No.:
 24/07/072-1-6

 13 Society Street
 Order No:
 Not Supplied

 Ballinasloe
 Date Tested:
 20/08/2024

 Galway
 Test Specification:
 Customer Spec.

 Lurcan Donnellan
 Test Element:
 Concrete Dust

FAO: Lurcan Donnellan

Project: Mayo Bridges Investigation - Strade River Bridge

Location Reference: See below
Test Standard: BS 1881 Part 124

	Sample	Depth (mm)	Chloride Content % by mass of	
ocation Reference	Sample Reference		Sample	Cement
Area 1 - Car 1	24/07/072-1	5-30	0.01	0.08
		30-55	0.01	0.08
		55-80	0.02	0.15
		80-105	0.01	0.08
Area 2 - Car 2	24/07/072-2	5-30	0.04	0.20
		30-55	0.03	0.15
		55-80	0.03	0.15
		80-105	0.01	0.05
Area 3 - Car 3	24/07/072-3	5-30	0.02	0.13
		30-55	0.02	0.13
		55-80	0.02	0.13
		80-105	0.02	0.13
Area 3.1 - Car 4	24/07/072-4	5-30	0.03	0.20
		30-55	0.02	0.13
		55-80	0.03	0.20
		80-105	0.03	0.20
Area 4 - Car 5	24/07/072-5	5-30	0.04	0.19
		30-55	0.02	0.10
		55-80	0.02	0.10
		80-105	0.02	0.10
Area 4.1 - Car 6	24/07/072-6	5-30	0.04	0.33
		30-55	0.03	0.25
		55-80	0.03	0.25
		80-105	0.04	0.33

#### REMARKS:

The Chloride Content is a Acid Soluble Chloride value.

The Chloride Content as a % by mass of cements as stated in EN 206 is a maxium allowable of 0.4% (containing embedded steel).

Approv	ved By:	Signature:
	z Zalewski Service Manager	Likox Lalandes

For and On Behalf of BHP Laboratories

Issue Date: 27/08/2024

 $Tested \ by \ BHP \ Laboratories, \ New \ Road, \ Thomondgate, \ Limerick. \ Phone: (061) \ 455399 \ Email: jamespurcell @bhp.ie$ 

This test report shall not be duplicated in full without the permission of the test laboratory. Information identifying the 'Client', 'FAO', 'Project',

### CHLORIDE CONTENT OF CONCRETE TEST REPORT



BHP/MTIField/F063 V1 08/07/24

Client: TRIUR Construction Ltd

 TRIUR Construction Ltd
 BHP Ref. No.:
 24/07/072-7-12

 13 Society Street
 Order No:
 Not Supplied

 Ballinasloe
 Date Tested:
 20/08/2024

 Galway
 Test Specification:
 Customer Spec.

 Lurcan Donnellan
 Test Element:
 Concrete Dust

FAO: Lurcan Donnellan

Project: Mayo Bridges Investigation - Strade River Bridge

Location Reference: See below
Test Standard: BS 1881 Part 124

		5	Chloride Content % by mass of	
Location Reference	Sample Depth on Reference (mm)	Depth (mm)	Sample	Cement
Area 5 - Car 7	24/07/072-7	5-30	0.02	0.20
		30-55	0.01	0.10
		55-80	0.01	0.10
		80-105	0.01	0.10
Area 5 - Car 8	24/07/072-8	5-30	0.02	0.25
		30-55	0.01	0.13
		55-80	0.01	0.13
		80-105	0.01	0.13
Area 6 - Car 9	24/07/072-9	5-30	0.01	0.07
		30-55	0.01	0.07
		55-80	0.01	0.07
		80-105	0.01	0.07
Area 6 - Car 10	24/07/072-10	5-30	0.03	0.21
		30-55	0.03	0.21
		55-80	0.03	0.21
		80-105	0.03	0.21
Area 7 - Car 11	24/07/072-11	5-30	0.01	0.08
		30-55	0.01	0.08
		55-80	0.01	0.08
		80-105	0.01	0.08
Area 7 - Car 12	24/07/072-12	5-30	0.03	0.17
		30-55	0.03	0.17
		55-80	0.02	0.11
		80-105	0.02	0.11

EI			

The Chloride Content is a Acid Soluble Chloride value.

The Chloride Content as a % by mass of cements as stated in EN 206 is a maxium allowable of 0.4% (containing embedded steel).

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Likox Lalanded

For and On Behalf of BHP Laboratories

Issue Date: 27/08/2024

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie

This test report shall not be duplicated in full without the permission of the test laboratory. Information identifying the 'Client', 'FAO', 'Project',

'Location Reference', 'Item', 'Test Specification' and 'Order No' has been provided by the customer. Results apply only to the sample tested and

where the laboratory is not responsible for sampling, result apply to the sample as received. Sampling is outside the scope of accreditation.

# Appendix F





21/08/2024

Issue Date:

BHP/MTIField/F056 V1 20/05/24

Client: TRIUR Construction Ltd

BHP Ref. No.: 24/07/072-1 Order No: 13 Society Street Not Supplied Date Tested: 20/08/2024 Ballinasloe Test Specification: Galway Customer Spec.

**Test Element:** 

Concrete Dust

FAO: Lurcan Donnellan

Mayo Bridges Investigation - Strade River Bridge Project:

**Location Reference:** Area 1 - Car 1 **Test Standard:** BS 1881 Part 124

Sample Weight (g)	5
Determined Values	
Insoluble residue (%)	32.4
Soluble silica (%)	2.9
Calcium oxide (%)	49
Calculated Values	
Cement Content (%)	
ex silica	13.5
ex lime	76
preferred / mean value %	13.5
Reported to nearest whole figure (%)	13
Aggregate Content (%)	
ex silica	83.4
ex lime	6.6
preferred / mean value	83.4
Aggregate / Cement Ratio	
ex silica	6.2
ex lime	0.1
preferred / mean value	6.2

#### **REMARKS:**

The cement contents were determined in accordance with B.S. 1881:Part 124:2015+A1:2021. The silica content was determined using inductively coupled plasma optical emission spectroscopy.

Assumptions used for the cement and aggregate content calculations:

Silica content of cement (CEM I) 20.2% Soluble silica content of aggregate 0.5% Calcium oxide content of cement (CEM I) 64.5%

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Likos Lalanded

For and On Behalf of BHP Laboratories

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie

This test report shall not be duplicated in full without the permission of the test laboratory. Information identifying the 'Client', 'FAO', 'Project',



21/08/2024

Issue Date:

BHP/MTIField/F056 V1 20/05/24

Client: TRIUR Construction Ltd

TRIUR Construction Ltd

BHP Ref. No.: 24/07/072-2

13 Society Street

Order No: Not Supplied

Ballinasloe

Date Tested: 20/08/2024

Galway

Test Specification: Customer Spec.

**Test Element:** 

Concrete Dust

FAO: Lurcan Donnellan

Project: Mayo Bridges Investigation - Strade River Bridge

Location Reference: Area 2 - Car 2

Test Standard: BS 1881 Part 124

Sample Weight (g)	9
Determined Values	
Insoluble residue (%)	15.2
Soluble silica (%)	4.2
Calcium oxide (%)	43.4
Calculated Values	
Cement Content (%)	
ex silica	19.9
ex lime	67.3
preferred / mean value %	19.9
Reported to nearest whole figure (%)	20
Aggregate Content (%)	
ex silica	75.5
ex lime	17.3
preferred / mean value	75.5
Aggregate / Cement Ratio	
ex silica	3.8
ex lime	0.3
preferred / mean value	3.8

#### **REMARKS:**

The cement contents were determined in accordance with B.S. 1881:Part 124:2015+A1:2021. The silica content was determined using inductively coupled plasma optical emission spectroscopy.

Assumptions used for the cement and aggregate content calculations:

Silica content of cement (CEM I) 20.2%
Soluble silica content of aggregate 0.5%
Calcium oxide content of cement (CEM I) 64.5%

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Likos Lalanded

For and On Behalf of BHP Laboratories

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie

This test report shall not be duplicated in full without the permission of the test laboratory. Information identifying the 'Client', 'FAO', 'Project',



21/08/2024

Issue Date:

BHP/MTIField/F056 V1 20/05/24

Client: TRIUR Construction Ltd

TRIUR Construction Ltd

BHP Ref. No.: 24/07/072-4

13 Society Street

Order No: Not Supplied

Ballinasloe

Date Tested: 20/08/2024

Galway

Test Specification: Customer Spec.

Lurcan Donnellan

Test Element: Concrete Dust

FAO: Lurcan Donnellan

Project: Mayo Bridges Investigation - Strade River Bridge

Location Reference: Area 3.1 - Car 4

Test Standard: BS 1881 Part 124

Sample Weight (g)	12
Determined Values	
Insoluble residue (%)	20.7
Soluble silica (%)	3.3
Calcium oxide (%)	40.6
Calculated Values	
Cement Content (%)	
ex silica	15.4
ex lime	63
preferred / mean value %	15.4
Reported to nearest whole figure (%)	15
Aggregate Content (%)	
ex silica	81
ex lime	22.6
preferred / mean value	81
Aggregate / Cement Ratio	
ex silica	5.2
ex lime	0.4
preferred / mean value	5.2

#### **REMARKS:**

The cement contents were determined in accordance with B.S. 1881:Part 124:2015+A1:2021. The silica content was determined using inductively coupled plasma optical emission spectroscopy.

Assumptions used for the cement and aggregate content calculations:

Silica content of cement (CEM I) 20.2%
Soluble silica content of aggregate 0.5%
Calcium oxide content of cement (CEM I) 64.5%

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Likos Lalanded

For and On Behalf of BHP Laboratories

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie

This test report shall not be duplicated in full without the permission of the test laboratory. Information identifying the 'Client', 'FAO', 'Project',



21/08/2024

Issue Date:

BHP/MTIField/F056 V1 20/05/24

Client: TRIUR Construction Ltd

TRIUR Construction Ltd

BHP Ref. No.: 24/07/072-5

13 Society Street

Order No: Not Supplied

Ballinasloe

Date Tested: 20/08/2024

Galway

Test Specification: Customer Spec.

**Test Element:** 

Concrete Dust

FAO: Lurcan Donnellan

Project: Mayo Bridges Investigation - Strade River Bridge

Location Reference: Area 4 - Car 5

Test Standard: BS 1881 Part 124

Sample Weight (g)	17	
Determined Values		
Insoluble residue (%)	10.3	
Soluble silica (%)	4.4	
Calcium oxide (%)	46.2	
Calculated Values		
Cement Content (%)		
ex silica	21	
ex lime	71.6	
preferred / mean value %	21	
Reported to nearest whole figure (%)	21	
Aggregate Content (%)		
ex silica	74.1	
ex lime	12	
preferred / mean value	74.1	
Aggregate / Cement Ratio		
ex silica	3.5	
ex lime	0.2	
preferred / mean value	3.5	

#### **REMARKS:**

The cement contents were determined in accordance with B.S. 1881:Part 124:2015+A1:2021. The silica content was determined using inductively coupled plasma optical emission spectroscopy.

Assumptions used for the cement and aggregate content calculations:

Silica content of cement (CEM I) 20.2%
Soluble silica content of aggregate 0.5%
Calcium oxide content of cement (CEM I) 64.5%

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Likos Lalanded

For and On Behalf of BHP Laboratories

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie

This test report shall not be duplicated in full without the permission of the test laboratory. Information identifying the 'Client', 'FAO', 'Project',



BHP/MTIField/F056 V1 20/05/24

Client: TRIUR Construction Ltd

BHP Ref. No.: 24/07/072-6 Order No: 13 Society Street Not Supplied Date Tested: 20/08/2024 Ballinasloe Test Specification: Galway Customer Spec.

**Test Element:** 

Concrete Dust

FAO: Lurcan Donnellan

Mayo Bridges Investigation - Strade River Bridge Project:

**Location Reference:** Area 4.1 - Car 6 **Test Standard:** BS 1881 Part 124

Sample Weight (g)	10
Determined Values	
Insoluble residue (%)	9.4
Soluble silica (%)	2.7
Calcium oxide (%)	46.7
Calculated Values	
Cement Content (%)	
ex silica	12.4
ex lime	72.4
preferred / mean value %	12.4
Reported to nearest whole figure (%)	12
Aggregate Content (%)	
ex silica	84.7
ex lime	11
preferred / mean value	84.7
Aggregate / Cement Ratio	
ex silica	6.8
ex lime	0.2
preferred / mean value	6.8

#### **REMARKS:**

The cement contents were determined in accordance with B.S. 1881:Part 124:2015+A1:2021. The silica content was determined using inductively coupled plasma optical emission spectroscopy.

Assumptions used for the cement and aggregate content calculations:

Silica content of cement (CEM I) 20.2% Soluble silica content of aggregate 0.5% Calcium oxide content of cement (CEM I) 64.5%

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Likos Lalanded

For and On Behalf of BHP Laboratories

21/08/2024 Issue Date:

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie

This test report shall not be duplicated in full without the permission of the test laboratory. Information identifying the 'Client', 'FAO', 'Project',



21/08/2024

Issue Date:

BHP/MTIField/F056 V1 20/05/24

Client: TRIUR Construction Ltd

TRIUR Construction Ltd

BHP Ref. No.: 24/07/072-7

13 Society Street

Order No: Not Supplied

Ballinasloe

Date Tested: 20/08/2024

Galway

Test Specification: Customer Spec.

**Test Element:** 

Concrete Dust

FAO: Lurcan Donnellan

Project: Mayo Bridges Investigation - Strade River Bridge

Location Reference: Area 5 - Car 7

Test Standard: BS 1881 Part 124

Sample Weight (g)	12
Determined Values	
Insoluble residue (%)	18.4
Soluble silica (%)	2.1
Calcium oxide (%)	43.1
Calculated Values	
Cement Content (%)	
ex silica	9.6
ex lime	66.9
preferred / mean value %	9.6
Reported to nearest whole figure (%)	10
Aggregate Content (%)	
ex silica	88.2
ex lime	17.7
preferred / mean value	88.2
Aggregate / Cement Ratio	
ex silica	9.2
ex lime	0.3
preferred / mean value	9.2

#### **REMARKS:**

The cement contents were determined in accordance with B.S. 1881:Part 124:2015+A1:2021. The silica content was determined using inductively coupled plasma optical emission spectroscopy.

Assumptions used for the cement and aggregate content calculations:

Silica content of cement (CEM I) 20.2%
Soluble silica content of aggregate 0.5%
Calcium oxide content of cement (CEM I) 64.5%

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Likos Lalanded

For and On Behalf of BHP Laboratories

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie

This test report shall not be duplicated in full without the permission of the test laboratory. Information identifying the 'Client', 'FAO', 'Project',



21/08/2024

Issue Date:

BHP/MTIField/F056 V1 20/05/24

Client: TRIUR Construction Ltd

BHP Ref. No.: 24/07/072-8 Order No: 13 Society Street Not Supplied Date Tested: 20/08/2024 Ballinasloe Test Specification: Galway Customer Spec.

**Test Element:** 

Concrete Dust

FAO: Lurcan Donnellan

Mayo Bridges Investigation - Strade River Bridge Project:

**Location Reference:** Area 5 - Car 8 **Test Standard:** BS 1881 Part 124

Sample Weight (g)	4
Determined Values	
Insoluble residue (%)	25.4
Soluble silica (%)	1.8
Calcium oxide (%)	37.9
Calculated Values	
Cement Content (%)	
ex silica	8
ex lime	58.8
preferred / mean value %	8
Reported to nearest whole figure (%)	8
Aggregate Content (%)	
ex silica	90.2
ex lime	27.7
preferred / mean value	90.2
Aggregate / Cement Ratio	
ex silica	11.3
ex lime	0.5
preferred / mean value	11.3

#### **REMARKS:**

The cement contents were determined in accordance with B.S. 1881:Part 124:2015+A1:2021. The silica content was determined using inductively coupled plasma optical emission spectroscopy.

Assumptions used for the cement and aggregate content calculations:

Silica content of cement (CEM I) 20.2% Soluble silica content of aggregate 0.5% Calcium oxide content of cement (CEM I) 64.5%

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Likos Lalanded

For and On Behalf of BHP Laboratories

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie This test report shall not be duplicated in full without the permission of the test laboratory. Information identifying the 'Client', 'FAO', 'Project',



21/08/2024

Issue Date:

BHP/MTIField/F056 V1 20/05/24

Client: TRIUR Construction Ltd

BHP Ref. No.: 24/07/072-9 Order No: 13 Society Street Not Supplied Date Tested: 20/08/2024 Ballinasloe Test Specification: Galway Customer Spec. **Test Element:** Concrete Dust

FAO: Lurcan Donnellan

Mayo Bridges Investigation - Strade River Bridge Project:

**Location Reference:** Area 6 - Car 9 **Test Standard:** BS 1881 Part 124

Sample Weight (g)	10
Determined Values	
Insoluble residue (%)	35.2
Soluble silica (%)	2.9
Calcium oxide (%)	33
Calculated Values	
Cement Content (%)	
ex silica	13.6
ex lime	51.2
preferred / mean value %	13.6
Reported to nearest whole figure (%)	14
Aggregate Content (%)	
ex silica	83.3
ex lime	37
preferred / mean value	83.3
Aggregate / Cement Ratio	
ex silica	6.1
ex lime	0.7
preferred / mean value	6.1

#### **REMARKS:**

The cement contents were determined in accordance with B.S. 1881:Part 124:2015+A1:2021. The silica content was determined using inductively coupled plasma optical emission spectroscopy.

Assumptions used for the cement and aggregate content calculations:

Silica content of cement (CEM I) 20.2% Soluble silica content of aggregate 0.5% Calcium oxide content of cement (CEM I) 64.5%

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Likos Lalanded

For and On Behalf of BHP Laboratories

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie

This test report shall not be duplicated in full without the permission of the test laboratory. Information identifying the 'Client', 'FAO', 'Project',

**Test Element:** 



21/08/2024

Issue Date:

24/07/072-10

Not Supplied

Customer Spec.

Concrete Dust

20/08/2024

BHP/MTIField/F056 V1 20/05/24

Client: TRIUR Construction Ltd

BHP Ref. No.: Order No: 13 Society Street Date Tested: Ballinasloe Test Specification: Galway

FAO: Lurcan Donnellan

Mayo Bridges Investigation - Strade River Bridge Project:

**Location Reference:** Area 6 - Car 10 **Test Standard:** BS 1881 Part 124

Sample Weight (g)	10
Determined Values	
Insoluble residue (%)	15.7
Soluble silica (%)	3
Calcium oxide (%)	42.1
Calculated Values	
Cement Content (%)	
ex silica	14
ex lime	65.3
preferred / mean value %	14
Reported to nearest whole figure (%)	14
Aggregate Content (%)	
ex silica	82.7
ex lime	19.7
preferred / mean value	82.7
Aggregate / Cement Ratio	
ex silica	5.9
ex lime	0.3
preferred / mean value	5.9

#### **REMARKS:**

The cement contents were determined in accordance with B.S. 1881:Part 124:2015+A1:2021. The silica content was determined using inductively coupled plasma optical emission spectroscopy.

Assumptions used for the cement and aggregate content calculations:

Silica content of cement (CEM I) 20.2% Soluble silica content of aggregate 0.5% Calcium oxide content of cement (CEM I) 64.5%

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Likos Lalanded

For and On Behalf of BHP Laboratories

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie

This test report shall not be duplicated in full without the permission of the test laboratory. Information identifying the 'Client', 'FAO', 'Project',



21/08/2024

Issue Date:

BHP/MTIField/F056 V1 20/05/24

Client: TRIUR Construction Ltd

TRIUR Construction Ltd

BHP Ref. No.: 24/07/072-11

13 Society Street

Order No: Not Supplied

Ballinasloe

Date Tested: 20/08/2024

Galway

Test Specification: Customer Spec.

**Test Element:** 

Concrete Dust

FAO: Lurcan Donnellan

Project: Mayo Bridges Investigation - Strade River Bridge

Location Reference: Area 7 - Car 11

Test Standard: BS 1881 Part 124

Sample Weight (g)	9
Determined Values	
Insoluble residue (%)	19
Soluble silica (%)	2.5
Calcium oxide (%)	41.9
Calculated Values	
Cement Content (%)	
ex silica	11.7
ex lime	64.9
preferred / mean value %	11.7
Reported to nearest whole figure (%)	12
Aggregate Content (%)	
ex silica	85.6
ex lime	20.2
preferred / mean value	85.6
Aggregate / Cement Ratio	
ex silica	7.3
ex lime	0.3
preferred / mean value	7.3

#### **REMARKS:**

The cement contents were determined in accordance with B.S. 1881:Part 124:2015+A1:2021. The silica content was determined using inductively coupled plasma optical emission spectroscopy.

Assumptions used for the cement and aggregate content calculations:

Silica content of cement (CEM I) 20.2%
Soluble silica content of aggregate 0.5%
Calcium oxide content of cement (CEM I) 64.5%

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Likos Lalanded

For and On Behalf of BHP Laboratories

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie

This test report shall not be duplicated in full without the permission of the test laboratory. Information identifying the 'Client', 'FAO', 'Project',

BHP Ref. No.:

Date Tested:

**Test Element:** 

Test Specification:

Order No:

24/07/072-12

Not Supplied

Customer Spec.

Concrete Dust

20/08/2024



21/08/2024

Issue Date:

BHP/MTIField/F056 V1 20/05/24

Project:

Client: TRIUR Construction Ltd

13 Society Street Ballinasloe Galway

FAO: Lurcan Donnellan

Mayo Bridges Investigation - Strade River Bridge

Area 7 - Car 12 **Location Reference: Test Standard:** BS 1881 Part 124

Sample Weight (g)	9	
Determined Values		
Insoluble residue (%)	20.6	
Soluble silica (%)	3.9	
Calcium oxide (%)	39.4	
Calculated Values		
Cement Content (%)		
ex silica	18.4	
ex lime	61	
preferred / mean value %	18.4	
Reported to nearest whole figure (%)	18	
Aggregate Content (%)		
ex silica	77.4	
ex lime	25	
preferred / mean value	77.4	
Aggregate / Cement Ratio		
ex silica	4.2	
ex lime	0.4	
preferred / mean value	4.2	

#### **REMARKS:**

The cement contents were determined in accordance with B.S. 1881:Part 124:2015+A1:2021. The silica content was determined using inductively coupled plasma optical emission spectroscopy.

Assumptions used for the cement and aggregate content calculations:

Silica content of cement (CEM I) 20.2% Soluble silica content of aggregate 0.5% Calcium oxide content of cement (CEM I) 64.5%

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Likos Lalanded

For and On Behalf of BHP Laboratories

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie

This test report shall not be duplicated in full without the permission of the test laboratory. Information identifying the 'Client', 'FAO', 'Project',

# Appendix G





BHP/MTIField/F057 V1 21/05/24

Client: TRIUR Construction Ltd BHP Ref. No.: 24/07/072-1

13 Society StreetOrder No:Not SuppliedBallinasloeDate Tested:12/07/2024GalwayTest Specification:Customer Spec.Lurcan DonnellanTest Element:Concrete Deck

FAO: Lurcan Donnellan Test Element: Concrete

Project: Mayo Bridges - Strade River Bridge

Location Reference: Area 1 C1 Deck
Test Standard: ASTM C876

 Test No.
 1

 No. of Readings
 12

 Median (mV)
 -245


 Mean (mV)
 -239

 Standard Deviation
 19.8

 Lowest (mV)
 -268

 Highest (mV)
 -207

Reinforcement Condition Intermediate Risk of Corrosion



#### **REMARKS:**

This test was performed using a Copper-Copper Sulphate Electrode.

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Sikas Lalanded

For and On Behalf of BHP Laboratories

Issue Date:

14/08/2024

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie



BHP/MTIField/F057 V1 21/05/24

Client: TRIUR Construction Ltd BHP Ref. No.: 24/07/072-2

13 Society Street

Ballinasloe

Date Tested: 12/07/2024

Galway

Test Specification: Customer Spec.

FAO: Lurcan Donnellan Test Element: Concrete Deck

Project: Mayo Bridges - Strade River Bridge

Location Reference: Area 3 Face Deck
Test Standard: ASTM C876

 Test No.
 2

 No. of Readings
 15

 Median (mV)
 -49


 Mean (mV)
 -54.9

 Standard Deviation
 21

 Lowest (mV)
 -97

 Highest (mV)
 -27

Reinforcement Condition Low risk of Corrosion



#### **REMARKS:**

This test was performed using a Copper-Copper Sulphate Electrode.

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Sikas Lalanded

For and On Behalf of BHP Laboratories

Issue Date:

14/08/2024

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie



BHP/MTIField/F057 V1 21/05/24

Client: TRIUR Construction Ltd BHP Ref. No.: 24/07/072-3

13 Society Street

Ballinasloe

Date Tested: 12/07/2024

Galway

Test Specification: Customer Spec.

FAO: Lurcan Donnellan Test Element: Concrete Deck

Project: Mayo Bridges - Strade River Bridge

Location Reference: Area 3.1 Soffit
Test Standard: ASTM C876

 Test No.
 3

 No. of Readings
 12

 Median (mV)
 -335


 Mean (mV)
 -333.5

 Standard Deviation
 13.2

 Lowest (mV)
 -368

 Highest (mV)
 -320

Reinforcement Condition Intermediate Risk of Corrosion



#### **REMARKS:**

This test was performed using a Copper-Copper Sulphate Electrode.

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Sikas Lalanded

For and On Behalf of BHP Laboratories

Issue Date:

14/08/2024

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie



BHP/MTIField/F057 V1 21/05/24

FAO:

Project:

BHP Ref. No.: 24/07/072-4 Client: TRIUR Construction Ltd


> Not Supplied 13 Society Street Order No: Date Tested: 12/07/2024 Ballinasloe Galway Test Specification: Customer Spec. **Test Element:** Lurcan Donnellan Concrete Deck

Mayo Bridges - Strade River Bridge

**Location Reference:** Area 4 Face Deck Test Standard: ASTM C876

> Test No. 4 No. of Readings 12 Median (mV) -233 Mean (mV) -237.7 Standard Deviation 28.3 Lowest (mV) -283 Highest (mV) -198

Reinforcement Condition Intermediate Risk of Corrosion



#### **REMARKS:**

This test was performed using a Copper-Copper Sulphate Electrode.

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Sikas Lalanded

For and On Behalf of BHP Laboratories

Issue Date:

14/08/2024

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie



BHP/MTIField/F057 V1 21/05/24

Client: TRIUR Construction Ltd BHP Ref. No.: 24/07/072-5

13 Society Street Order No: Not Supplied
Ballinasloe Date Tested: 12/07/2024
Galway Test Specification: Customer Spec.

FAO: Lurcan Donnellan Test Element: Concrete Deck

Project: Mayo Bridges - Strade River Bridge

**Location Reference:** Area 4.1 Soffit **Test Standard:** ASTM C876

 Test No.
 5

 No. of Readings
 16

 Median (mV)
 -170


 Mean (mV)
 -165.8

 Standard Deviation
 13

 Lowest (mV)
 -179

 Highest (mV)
 -129

Reinforcement Condition Low risk of Corrosion



#### **REMARKS:**

This test was performed using a Copper-Copper Sulphate Electrode.

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Sikas Lalanded

For and On Behalf of BHP Laboratories

Issue Date:

14/08/2024

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie



BHP/MTIField/F048 V1 30/04/24

Client: TRIUR Construction Ltd

BHP Ref. No.: 24/07/072-1 13 Society Street Order No: Not Supplied Ballinasloe Date Tested: 09/07/2024 Galway **Test Specification:** Client Spec.

FAO: Lurcan Donnellan Material Concrete Element

Mayo Bridges - Strade River Bridge **Project:** 

**Location Reference:** Area 1 Top Deck **Test Standard:** EN 12390-19 2021

RESULTS				
Structural Element		Deck		
Measurement Mode	,	Surface		
Contact Spacing		50mm		
Specimen Shape		Flat		
Dimensions of Test	Area (mm)		400x400	
Minimum Measuren	nent (kΩcm)	106		
Maximum Measurement (kΩcm)		190		
Mean Value (kΩcm)	)	153		
Interpreatation of Re	esult	Negligible risk of corrosion		
Resistivity Measurements (kΩcm)				
106	112	172	185	190
0	0	0	0	0
0	0	0	0	0

#### **REMARKS:**

Resistivity measurements can be used to estimate the likelihood of corrosion. When the electrical resistivity of the concrete is low, the likelihood of corrosion increases. When the electrical resistivity is high, the likelihood of corrosion decreases.

A guide to interpretation of resistivity results is:

When ≥ 100 kΩcm Negligible risk of corrosion When 50 to 100 kΩcm Low risk of corrosion When 10 to 50 kΩcm Moderate risk of corrosion When ≤ 10 kΩcm High risk of corrosion

Equipment used was a Proceq Resipod

Approved By: Signature: Sekon Kalanded Lukasz Zalewski Field Service Manager

For and On Behalf of BHP Laboratories

Issue Date:

28/08/2024

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie



BHP/MTIField/F048 V1 30/04/24

Client: TRIUR Construction Ltd

BHP Ref. No.: 24/07/072-3 13 Society Street Order No: Not Supplied Ballinasloe Date Tested: 09/07/2024 Galway **Test Specification:** Client Spec.

FAO: Lurcan Donnellan Material Concrete Element

Mayo Bridges - Strade River Bridge **Project:** 

**Location Reference:** Area 3 Face dek **Test Standard:** EN 12390-19 2021

RESULTS				
Structural Element		Soffit		
Measurement Mode	,	Surface		
Contact Spacing		50mm		
Specimen Shape		Flat		
Dimensions of Test	Area (mm)		200x200	
Minimum Measuren	nent (kΩcm)	55		
Maximum Measurement (kΩcm)		72		
Mean Value (kΩcm)	)	65		
Interpreatation of Re	esult	Negligible risk of corrosion		
Resistivity Measurements (kΩcm)				
69	55	72	0	0
0	0	0	0	0
0	0	0	0	0

#### **REMARKS:**

Resistivity measurements can be used to estimate the likelihood of corrosion. When the electrical resistivity of the concrete is low, the likelihood of corrosion increases. When the electrical resistivity is high, the likelihood of corrosion decreases.

A guide to interpretation of resistivity results is:

When ≥ 100 kΩcm Negligible risk of corrosion When 50 to 100 kΩcm Low risk of corrosion When 10 to 50 kΩcm Moderate risk of corrosion When ≤ 10 kΩcm High risk of corrosion

Equipment used was a Proceq Resipod

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Likox Lalanded

For and On Behalf of BHP Laboratories

Issue Date:

28/08/2024

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie



BHP/MTIField/F048 V1 30/04/24

Client: TRIUR Construction Ltd

BHP Ref. No.: 24/07/072-4 Order No: 13 Society Street Not Supplied Ballinasloe Date Tested: 09/07/2024 Galway **Test Specification:** Client Spec.

FAO: Lurcan Donnellan Material Concrete Element

**Project:** Mayo Bridges - Strade River Bridge

**Location Reference:** Area 3.1 Soffit **Test Standard:** EN 12390-19 2021

RESULTS				
Structural Element		Soffit		
Measurement Mode	,	Surface		
Contact Spacing		50mm		
Specimen Shape		Flat		
Dimensions of Test	Area (mm)		400x400	
Minimum Measuren	nent (kΩcm)	256		
Maximum Measurement (kΩcm)		303		
Mean Value (kΩcm)	)	279		
Interpreatation of Re	esult	Negligible risk of corrosion		
Resistivity Measurements (kΩcm)				
285	278	303	256	272
0	0	0	0	0
0	0	0	0	0

#### **REMARKS:**

Resistivity measurements can be used to estimate the likelihood of corrosion. When the electrical resistivity of the concrete is low, the likelihood of corrosion increases. When the electrical resistivity is high, the likelihood of corrosion decreases.

A guide to interpretation of resistivity results is:

When ≥ 100 kΩcm Negligible risk of corrosion When 50 to 100 kΩcm Low risk of corrosion When 10 to 50 kΩcm Moderate risk of corrosion When ≤ 10 kΩcm High risk of corrosion

Equipment used was a Proceq Resipod

Approved By:	Signature:
Lukasz Zalewski Field Service Manager	Sekon Kalanded

For and On Behalf of BHP Laboratories

Issue Date:

28/08/2024

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie



BHP/MTIField/F048 V1 30/04/24

Client: TRIUR Construction Ltd

BHP Ref. No.: 24/07/072-5 13 Society Street Order No: Not Supplied Ballinasloe Date Tested: 09/07/2024 Galway **Test Specification:** Client Spec.

FAO: Lurcan Donnellan Material Concrete Element

Mayo Bridges - Strade River Bridge **Project:** 

**Location Reference:** 

**Test Standard:** EN 12390-19 2021

RESULTS					
Structural Element		Face Deck			
Measurement Mode	:	Surface			
Contact Spacing		50mm			
Specimen Shape		Flat			
Dimensions of Test	Area (mm)		200x200		
Minimum Measuren	nent (kΩcm)	156			
Maximum Measurement (kΩcm)		194			
Mean Value (kΩcm)		179			
Interpreatation of Result		Negligible risk of co	rrosion		
	Resistiv	vity Measurements	(kΩcm)		
186	156	194	0	0	
0	0	0	0	0	
0	0	0	0	0	

#### **REMARKS:**

Resistivity measurements can be used to estimate the likelihood of corrosion. When the electrical resistivity of the concrete is low, the likelihood of corrosion increases. When the electrical resistivity is high, the likelihood of corrosion decreases.

A guide to interpretation of resistivity results is:

When ≥ 100 kΩcm Negligible risk of corrosion When 50 to 100 kΩcm Low risk of corrosion When 10 to 50 kΩcm Moderate risk of corrosion When ≤ 10 kΩcm High risk of corrosion

Equipment used was a Proceq Resipod

Approved By: Signature: Likex Laborated Lukasz Zalewski

For and On Behalf of BHP Laboratories

Field Service Manager

Issue Date:

28/08/2024

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie



BHP/MTIField/F048 V1 30/04/24

Client: TRIUR Construction Ltd

BHP Ref. No.: 24/07/072-6 13 Society Street Order No: Not Supplied Ballinasloe Date Tested: 09/07/2024 Galway **Test Specification:** Client Spec.

FAO: Lurcan Donnellan Material Concrete Element

Mayo Bridges - Strade River Bridge **Project:** 

**Location Reference:** Area 4.1

**Test Standard:** EN 12390-19 2021

	RESULTS					
Structural Element		Face Deck				
Measurement Mode	)	Surface				
Contact Spacing		50mm				
Specimen Shape		Flat				
Dimensions of Test	Area (mm)		400x400			
Minimum Measurement (kΩcm)		196				
Maximum Measurement (kΩcm)		272				
Mean Value (kΩcm)		228				
Interpreatation of Result		Negligible risk of co	rrosion			
	Resisti	vity Measurements	(kΩcm)			
196	206	209	255	272		
0	0	0 0 0				
0	0	0	0	0		

#### **REMARKS:**

Resistivity measurements can be used to estimate the likelihood of corrosion. When the electrical resistivity of the concrete is low, the likelihood of corrosion increases. When the electrical resistivity is high, the likelihood of corrosion decreases.

A guide to interpretation of resistivity results is:

When ≥ 100 kΩcm Negligible risk of corrosion When 50 to 100 kΩcm Low risk of corrosion When 10 to 50 kΩcm Moderate risk of corrosion When ≤ 10 kΩcm High risk of corrosion

Equipment used was a Proceq Resipod

Approved By: Signature: Likex Laborated Lukasz Zalewski

For and On Behalf of BHP Laboratories

Field Service Manager

Issue Date:

28/08/2024

Tested by BHP Laboratories, New Road, Thomondgate, Limerick. Phone: (061) 455399 Email: jamespurcell@bhp.ie

# Appendix F. Structure Idealisation Model and Model Inputs




Figure F-1 – 3D Isometric view of the proposed model




Figure F-2 – Top view of the model with support conditions







Figure F-3 – Live load Surface lanes



## **Appendix G. Calculations**



		Project				Jol	o ref
			10	315 Mayo Bridges - A	ssessments	1008	88572
		Part of Structu	ıre	Strade River Bridg	je MO-N58-001.00	Calc sheet n	o. rev
	AtkinsRéalis	Drawing Ref		Calc By	Date	Check by	0 Date
		J. Carrier		VP	17-Dec-24	MG	17/12/2024
Ref	Calculations						tput
	Introduction Spreadsheet Purpose Stage 2 Assessment Calculations	of Filler Beam	Bridge.				
1.2	Limitations There is no clear Data about the F	oundation of th	ne structure.				
2.1	Instructions for use The Assessment is based on TII F Structures and AM-STR-06057 Th Structures.Initial assessments of c analysis as per AM-STR-06026 ar in accordance with TII Publication	e Stage 2 Stru concrete compo nd AM-STR-060	ctural Asses osite decks w 037. Assessr	sment of Sub-Standard ere carried out using th	Road ne strip method		
3.1	Previous Updates Revision Date Made By R0 17-Dec-24 VP	Checked MG	Description				
3.2	Planned/Suggested updates  Date suggested Made By	Description					





Project Name			Job Number		
TO315 Mayo Bridges - Assessments			10088	<b>572</b>	
Part of Structure			Sheet Number		Rev.
Strade River Bridge MO-N58-001.00			of		
Drawing Reference	Originator	Date	Checker	Date	2
	VP	Dec-24	MG	D	ec-24

Ref.	Calcul	ations

#### 1 General

#### AM-STR-06056

Initial assessments of concrete composite decks were carried out using the strip method analysis as per AM-STR-06026 and AM-STR-06037. Assessment live loading comprised 40t HA loading in accordance with TII Publication AM-STR-06026. Abnormal loading considered as part of the assessment comprised SV196 loading in accordance with TII Publication AM-STR-06048 and AM-STR-06030 Loads for Highway Bridges. If the structure fail to attain a 40/44T GVW capacity then a more rigorous assessment in the form of a grillage analysis shall be carried out and a revised capacity and HB rating given.

#### 2 Introduction

#### \* The structure is a Filler beam slab bridge

*	Number of span	=	2
*	The clear skew span 1 / internal dimension is	=	3.79 m
*	The clear skew span 2 / internal dimension is	=	3.81 m
*	The Average thickness of Top slab is	=	0.31 m
*	Overall width of bridge (Width out to out)	=	10.3 m
*	Skew angle is	=	26 degree
*	Average depth of fill (CL804) over slab excluding surfacing	=	0.15 m
*	Width of the carriageway (Perpendicular to traffic)	=	6.89 m
*	Depth of concrete surfacing. (Assumed)	=	0.100 m

3

#### **Material parameters**

BD21/14 AM-STR-06026

Element	Reference	f <sub>ck</sub> or fy (N/mm <sup>2</sup> )
Filler Deck Concrete	As per Investigation	18.9
Assumed Steel beam Section	CI 4.3 -AM-STR-06026	230.0


As per AM-STR-06026 CI 4.3, in the absence of definite information on the characteristic yield strength of the structural steel section it may be assumed as 230  $N/mm^2$ .

Density of Concrete

Density of Road surfacing

Density of Stuructural fill (CL804)

25.0 kN/m³
24.0 kN/m³
20.0 kN/m³





Project Name			Job Number		•
TO315 Mayo Bridges - Assessments			10088	3572	
Part of Structure			Sheet Number	1	Rev.
Strade River Bridge MO-N58-001.00			of		
Drawing Reference	Originator	Date	Checker	Dat	e
	VP	Dec-24	MG		ec-24

#### **Partial Safety Factors**

AM-STR-06030 Table 1 For concrete, the values of γm is taken as 1.2 considering worst credible strengths which is taken from Table 4A (4.3.3.3.) of AM-STR-06031 . For Structural steel the γm is taken as 1.05.


The partial safety factors taken from AM-STR-06030 Table 1 are represented below.

#### Partial Safety Factors for Assessment

Load	γf3 for ULS	γfL for ULS
Dead Load	1.1	1.15
Super Imposed Dead Load	1.1	1.75
Soil Fill	1.1	1.2
Type HA Loading	1.1	1.5
Type HB	1.1	1.3
SV 196	1.1	1.1

#### 4 Grillage Analysis - 3D Model of Box

Since the structure failed in the initial assessment, we created a grillage analysis for accurate bending results.





3D Grillage Model

Composite Section property-Filler Beam

#### 5 Load Calculation

#### Dead Load

Sections are defined in Midas and material property are defined .Self Weight is applied in the Midas.

#### Soil Fill


Unit Weight of Soil Fill = 20.0 kN/m3

Depth of infill material = 0.15 m

Load per meter square = 3.00 kN/m2

Average width of the Beam = 0.60 m

Load per beam = 1.8 kN/m2



#### SIDL -Surfacing

Surfacing depth 100 mm thick =  $1.00 \times 0.1 \times 1 \times 24.0$ 

Weight of Surfacing - Load per meter square = 2.40 kN/m2Average width of the Beam = 0.60 m

Load per beam = 1.44 kN/m2



Project Name			Job Number	
TO315 Mayo Bridges - Assessments			10088	572
Part of Structure			<b>Sheet Number</b>	Rev.
Strade River Bridge MO-N58-001.00			of	
Drawing Reference	Originator	Date	Checker	Date
	VP	Dec-24	MG	Dec-24

#### **Live Load**

Carriageway width = 6.89 m


Number of Notional Lanes =

The loading to be applied for a Stage 2 Structural Assessment shall be in accordance with the requirements of Chapter 5 of AM-STR-06026. Reduction factors for uniformly distributed load (UDL) and knife-edge load (KEL) shall be in accordance with Chapter 5 of AM-STR-06026 unless otherwise agreed with TII. For a Stage 2 Structural Assessment it is important to establish what component of the loading contributes most to the overall load effect. Therefore, load combinations shall be included for dead load, superimposed dead load and live load in isolation as well as in combination.

The Live Load are Defined in the Midas Civil for the Following Cases.

Additional cases will be added according to the requirements.

- i ) Type HA 40t
- ii ) Type HA + HB Combined
- iii ) Type HB 45 units
- iv ) SV 196



Line lane Defined in Midas Civil for Live Load

		Project	TO315	Mayo Bri	dges - Ass	sessments		o ref 38572	
<b>1</b> 1 1	kinsRéalis		Part of Structure				Calc sheet no. rev		
ra Au	Kilishealis	Strade River E Drawing Ref		O-N58-001 Calc By	.00	Date	Check by Date		
		Drawing Ker		VP		17-Dec-24		18-Dec-24	
Ref		- <del>!</del>	Calc	ulations			1	tput	
								-	
6	Investigation Su	<u>ımmary</u>		Filler Bea	m				
	MID SPAN								
				MAIN	1				
App. C1 /SI Report				BEAM 600	_				
/Si Keport			Spacing (mm)	000	1				
			Spac (mr						
					_				
					_				
					1				
					1				
					1				
	Ave	rage beam spac		600	]				
			of beam m Cover	125 37	mm mm				
	NEAR SUPPORT								
			ļ	MAIN	7				
App. C1				BEAM	_				
/SI Report			ng (u	600	_				
			Spacing (mm)		1				
			S						
					1				
					]				
					_				
					1				
					-				
	Ave	erage rebar spac	ing	600	]				
		Depth	of beam m Cover	125 32	mm				
		DUILUI	ii Covel	34	mm				

		Project	TO315	Mayo Brid	dges - Asses	ssments		<b>b ref</b> 38572
	tkinsRéalis	Part of Str	ucture				Calc shee	
	ıkırısı vedilə		er Bridge M		.00	ln	1	0
		Drawing R Strade Rive	<b>er</b> er Bridge M	<b>Calc By</b> ∀P		Date 17-Dec-24	Check by MG	18-Dec-24
Ref		Journal of Mark		ulations		17 000 24		itput
								•
	CALCULATION C	F WORS	T CREDIE	BLE STRI	ENGTH			
		4.0	.1					
	Input a maximum of 1	Core samp	oies					
			ESTIM	IATED				
	LOCATION	CORE		J CUBE	(fc - MEAN) <sup>2</sup>			
Ann C2		REFERENCE	STRENGTH		315.95			
App.C2 SI Report		C1 C2		18.9 21.1	242.58			
Ol Ropolt		C3		49.6	167.06			
 		C4		57.1	417.18	]		
					-			
					-			
					-			
					-			
					-			
			TOTAL	146.7	1142.7675			
		N	o of cores MEAN	4 36.68				
		Standard	Deviation	19.52				
						J		
	WCS will be calculat	ed using 2	different m	ethods:				
	1) LOCATION : Us	ina equation	n from BA 1	1/06 with n	- total numb	or of core sa	  mples	
					cation of inte		limpies 	
	n = 4	iy use tilis ic	or cores tak	en at the lo	cation of inte	1631		
	From BA 44/90,	WCS -	(Total fc*	(100-(20/	n^0 5)))/10	ıΩn		
	1 10111 57 ( 44,00,	******	(Total To	(100 (20)	11 0.0//// 10	WCS =	22.0	N/mm <sup>2</sup>
						WCS =	33.0	14/111111
	2) LOWEST COF	DE STDEN	ICTU .					
	2) LOWEST COF	KE SIKEN	NGIH:					
	Lowest core	strenath -	18 9	N/mm2				
	Lowest out	ouchgur =	10.0	14/111112				
						WCS =	18.9	N/mm <sup>2</sup>
	Using the above	results ar	nd engine	ering iu	dgement			1
		propose	_		N/mm <sup>2</sup>			
	uic	proposed	4 1100 -	10.5				J

				Project	TO315 May	yo Bridges - Ass	sessments		Jo 10088572	ob ref
(	<b>T</b> Atkins	Réalis		Part of Strue Strade River		-N58-001.00			Calc sheet no.	Rev C
•		. Wallo		Drawing ref.		Calc by		Date	Check by	Date
Ref				<u>I</u>	Ca	VP Ilculations		17/12/24	MG	18/12/24
7	Filler Beam Cap	acity								
			CTION PROP	ERTIES (U	sing BS 5	5400 Part 3;2	000) for com	posite section		
	Slab	<u> </u>	Width (mm)	Depth (mm)		fcu <sub>(MPa)</sub>		Panel Length (mm)		Section depth mm
	C.U.D	Slab	600	309		18.9	25.1			123
	Haunch		Width (mm)	Depth (mm)		fcu <sub>(MPa)</sub>	E(short Term)	NA		
		Haunch	0	0		0	0	NA		
	Girder	T Elemen	Width (mm)	Depth (mm)		f <sub>y (MPa)</sub>	E <sub>(GPa)</sub>	_		m o 17
		Top Flange Web	65 10	28 85		<b>230</b> 230	205.0 205.0	+		8.17
		Bottom Flange	123	10		230	205.0			
		Bottom Cover			mm			_		
	e) Plastic Section nb if NA lies below Stress in concrete:	v the web this do	esn't work			Condition fact	tor for RC Filler	-	0.8	}
	Stress in steel = $\sigma_y$		$\gamma_{m} =$	1.05						
		Depth (mm)	Width (mm)	Area (mm²)	Stress (Nmm <sup>-2</sup> )	Force (kN)	Force above NA (kN)	Force below NA (kN)	y above NA (mm)	y below NA (mm)
	Slab*	148.75	600	89250	8	675	675	-	81	-
	Haunch	0 28	0	0 1820	0 219	0 399	0 90	309	0	11
	Top Flange Web	85	65 10	850	219	186	0	186	3 -22	64
	Bottom Flange	10	123	1230	219	269	-	269	-	112
	NA lies in  Depth of Neutral A  Slab  Haunch  Top Flange  Web		<b>ab</b> ]     m=	0.0		ncrete M <sub>plastic</sub> = Beam M <sub>plastic</sub> =		kNm kNm		
De	 epth of Plastic NA		153.7							
9.3.7.2	If m < 0.5 If m > 0.5 If web fully in tension	Check web dept Check web dept on section is comp	h is less than	(34t <sub>w</sub> /m)*(35 (374t <sub>w</sub> /(13m-	•	<sub>w</sub> )^0.5	n/a n/a	mm mm	(Compact?) n/a n/a yes	
	Section is Compa	<u>s</u> .		ASTIC CH	ECKS (U	sing BS 5400	) Part 3;2000	1		
		$M_{plastic} = M_{pe (unfactored)} = M_{pe} / 1.05 \times 1.1 =$	100 105 73	kNm kNm kNm	(Also Adjus	sted by condition	n factor)			
3/9.9.2.2	3. ULS Pure Shear  Depth of panel = d <sub>v</sub>	ve	<u>tion</u> =	85	mm					
	Aspect Ratio = $\phi$ = $b_{fe}$ (top flange) $m_{fw}$ (top flange) = $\sigma$ Minimum value of r $\sigma_y = \sigma_{yw}/\sqrt{3}$	$\sigma_{\rm yf}b_{\rm fe}t_{\rm f}^2/(2{\sf d}^2_{\rm we}t_{\rm w}\sigma_{\rm yw})$		1.000 0 0.1763 0.0426 132.79		$b_{fe}$ (bottom flan $m_{fw}(bot) = \sigma_{yf}b_{fi}$ $\lambda = (d_{we}/t_w)x(\sigma_y)$	$_{\rm e} {\rm t_f}^2/(2{\rm d}^2_{\rm we} {\rm t_w} \sigma_{\rm yw})$	0.0426 6.8		
3/Fig12-18	$\tau_l/\tau_y$ for $m_{fw}$ of $\tau_l/\tau_y$ for $m_{fw}$ of		=	4.005		T <sub>I =</sub>				
3/9.9.2.2	$V_D = (d_w t_w x \tau_I) / (\gamma_m \gamma_I)$	<sub>f3</sub> )	=	101.2	kN	When $m_{fw} =$	0.1763	(Adjusted by cond	lition factor)	
	V <sub>R</sub> = ""		=	101.2	kN	When $m_{fw} =$	0.0000	(Adjusted by cond	lition factor)	



Project TO	O315 Mayo	Bridges - Assessments	3		Jo	b ref	
					10088572		
Part of Structu	ure	0			Calc sheet no.		Rev
Strade River B	ridge MO-N	N58-001.00			1		0
Drawing ref.	C	Calc by		Date	Check by	Date	
	V	/P		17/12/24	MG		18/12/24

Calculations

## SAGGING - SECTION PROPERTIES (Using BS 5400 Part 3;2000) for Steel Section (IGNORING CONCRETE)

Slab		Width (mm)	Depth (mm)		fcu (MPa)	E(short Term)	Panel Length (mm)	9	Section depth mm
	Slab	600	123		18.9	25.103			123
Haunch		Width (mm)	Depth (mm)		fcu (MPa)	E(short Term)	NA		
	Haunch	0	0		0	0	NA		
Girder		Width (mm)	Depth (mm)		f <sub>y (MPa)</sub>	E (GPa)			
	Top Flange	65	28		230	205			
	Web	10	85		230	205			
	Bottom Flange	123	10		230	205			
	Bottom Cover		37	mm		,			
e) Plastic Section	Properties			_	Condition fact	or for RC Filler	-	0.8	

nb if NA lies below the web this doesn't work

Stress in concrete = 0.4\*fcu

Stress in steel =  $\sigma_{\rm V}/\gamma_{\rm m}$ 

 $\gamma_{\rm m} = 1.05$ 

	Depth (mm)	Width (mm)	Area (mm²)	Stress	Force (kN)	Force above	Force below NA	y above NA	y below NA
	Bopar (mm)	Widen (min)	Alea (IIIII )	(Nmm <sup>-2</sup> )	1 0100 (1111)	NA (kN)	(kN)	(mm)	(mm)
Slab*	-37	600	-22200	8	-168	-168	-	61	-
Haunch	0	0	0	0	0	0	-	0	-
Top Flange	28	65	1820	219	399	399	0	65	-51
Web	85	10	850	219	186	112	74	26	17
Bottom Flange	10	123	1230	219	269	-	269	-	39

\*Concrete above beam only taken in properties

Depth of Neutral Axis From Top Slab

Web

NA lies in

Depth (mm) Slab 0.0 Haunch 0.0 Top Flange 0.0 Web 42.3

Concrete  $M_{plastic} =$ -10 kNm Single Beam M<sub>plastic</sub> = 32 kNm

(Compact?)

0.6 m=

Depth of Plastic NA = 42.3

f) Compactness Check

9.3.7.2

If m < 0.5Check web depth is less than  $(34t_w/m)*(355/\sigma_{yw})^0.5$ n/a n/a mm If m > 0.5Check web depth is less than (374t<sub>w</sub>/(13m-1))\*(355/σ<sub>yw</sub>)^0.5 678.5790964 mm yes n/a

If web fully in tension section is compact

#### **Section is Compact**

### SAGGING - PLASTIC CHECKS (Using BS 5400 Part 3;2000)

# 2. ULS Bending Capacity of Section

 $M_{plastic} =$ 30 kNm M<sub>pe (unfactored)</sub> = 32 kNm


 $M_D = M_{pe} / 1.05 \times 1.1 =$ kNm (Also Adjusted by condition factor)


Ref BD21/01 AM-STR-06026  CI 5.3.1.1 of BD44/95 AM-STR-06031  SI Report  Ma  Cor Sec Is te effe Cor	t of Structure ade River Bridge MO-N58-001 wing Ref  Depth of slab Clear Span Effective Span Slab width Total Depth of fill above I Depth of surfacin Condition factor for Reference State  Main Tension Steel	Calcul Filler Beam Filler Slab	Calc By		M-STR-06026 Filler eam  Date 17-Dec-24  ( Significant section los	Calc sheet no. re 5 0 Check by MG 18-Dec- Output  ss and Corrosion)
Ref  BD21/01 AM-STR-06026  CI 5.3.1.1 of BD44/95 AM-STR-06031  SI Report  Ma  Cor Sec Is te effe Cor	Depth of slab Clear Span Effective Span Slab width Total Depth of fill above I Depth of surfacir Condition factor for Residue I  Main Tension Steel	Calcul Filler Beam Filler Slab	ations  (mm) (m) (m) (mm) (mm) (mm)	309 3.81 4.08 600 250 100	Date 17-Dec-24	Check by MG 18-Dec-Output
BD21/01 AM-STR-06026  CI 5.3.1.1 of BD44/95 AM-STR-06031  SI Report  Ma  Cor Sec Is te effe Cor	Depth of slab Clear Span Effective Span Slab width Total Depth of fill above I Depth of surfacir Condition factor for Resterial Details:  Main Tension Steel	Filler Beam Filler Slab	ations  (mm) (m) (m) (mm) (mm) (mm)	309 3.81 4.08 600 250 100		MG 18-Dec- Output
BD21/01 AM-STR-06026  CI 5.3.1.1 of BD44/95 AM-STR-06031  SI Report  Ma  Cor Sec Is te effe Cor	Depth of slab Clear Span Effective Span Slab width Total Depth of fill above I Depth of surfacir Condition factor for Resterial Details:  Main Tension Steel	Filler Beam Filler Slab	(mm) (m) (m) (mm) (mm) (mm)	3.81 4.08 600 250 100	( Significant section los	
CI 5.3.1.1 of BD44/95 AM-STR-06031  SI Report  Cor Sec Is te effe Cor	Depth of slab Clear Span Effective Span Slab width Total Depth of fill above I Depth of surfacir Condition factor for Resterial Details:  Main Tension Steel	Filler Slab ng C Slab	(m) (m) (mm) (mm) (mm)	3.81 4.08 600 250 100	( Significant section los	ss and Corrosion)
BD44/95 AM-STR-06031  SI Report  Cor Sec Is te effe Cor	Clear Span Effective Span Slab width Total Depth of fill above I Depth of surfacin Condition factor for Relaterial Details:  Main Tension Steel	Filler Slab ng C Slab	(m) (m) (mm) (mm) (mm)	3.81 4.08 600 250 100	( Significant section los	ss and Corrosion)
BD44/95 AM-STR-06031  SI Report  Cor Sec Is te effe Cor	Clear Span Effective Span Slab width Total Depth of fill above I Depth of surfacin Condition factor for Relaterial Details:  Main Tension Steel	Filler Slab ng C Slab	(m) (m) (mm) (mm) (mm)	3.81 4.08 600 250 100	( Significant section los	ss and Corrosion)
BD44/95 AM-STR-06031  SI Report  Cor Sec Is te effe Cor	Effective Span Slab width Total Depth of fill above I Depth of surfacir Condition factor for Resterial Details:  Main Tension Steel	Filler Slab ng C Slab	(m) (mm) (mm) (mm)	4.08 600 250 100	( Significant section los	is and Corrosion)
BD44/95 AM-STR-06031  SI Report  Cor Sec Is te effe Cor	Slab width Total Depth of fill above I Depth of surfacin Condition factor for Re  Iterial Details:  Main Tension Steel	Filler Slab ng C Slab	(mm) (mm) (mm)	600 250 100	( Significant section los	is and Corrosion)
SI Report  Cor Sec Is te effe Cor	Total Depth of fill above I  Depth of surfacir  Condition factor for Rel  Iterial Details:  Main Tension Steel	ng C Slab	(mm)	250 100	( Significant section los	is and Corrosion)
SI Report  Cor Sec Is to	Depth of surfacin Condition factor for Rel terial Details : Main Tension Steel	ng C Slab	(mm)	100	( Significant section los	ss and Corrosion )
Cor Sec Is to effe Cor	Condition factor for Relaterial Details:  Main Tension Steel	C Slab			( Significant section los	 ss and Corrosion )
Cor Sec Is to effe Cor	terial Details :  Main Tension Steel			0.80	(Significant section los	ss and Corrosion )
Cor Sec Is to effe Cor	Main Tension Steel	Beam Depth				<u> </u>
Sec Is to effe Cor		Beam Depth				
Sec Is to effe Cor			(mm)	123		
Sec Is to effe Cor		Spacing	(mm)	600	-	
Sec Is to effe Cor	ncrete cover to tension steel	As	(mm2)	4720	7	
Sec Is to effe Cor			(mm)	37	$\dashv$	
Is to effe Cor	condary reinforcement dia		(mm)	0		
Cor	ension steel the outer layer of	rebar?	Y/N	Y	7	
	ective depth	d	(mm)	272	7	
	ncrete Density		kN/m3	25.0		
Sur	facing Density		kN/m3	24.0	7	
Fill	Density		kN/m3	20.0		
Page 1 Cor	ncrete WCS Strength	WCS, fcu		19		
	el Characteristic Strength	fy	(N/mm2)	230		
	erial Factor for Concrete	Ymc		1.20		
BD44/95 Mat	erial Factor for Steel	Yms		1.05		
<u>Ca</u>	Iculation of Moment Ca	pacity of Sec	tion at Mic	l Span :		
		xu	(100.00)	455.4	$\neg$	Filler Beam
=>	Consoity		(mm)	155.1 73	-	Moment Capacity
M. C	Capacity	M <sub>C</sub>	(kNm/m)	/3		72.8 kNm
Ca	Iculation of Shear Capa	acity of Soction	n noar eur	norte :		
					anhangement if applicable	
Sne	ear checked at 2 locations	* * * *		•	enhancement if applicable	ie) I
		(II) $a_v = 2a$ from	race of suppo	ort (without s	shear enhancement)	
100	1/\ \alpha/\bar\bar\bar\bar\bar\bar\bar\bar\bar\bar	_	T	2.0	7	
	As/b <sub>w</sub> d		-	2.9	-	
	oth Factor erial FOS for Concrete in Shear	ξ <sub>s</sub> Ymc	-	1.19 1.15	$\dashv$	
	mate shear stress	VC	(N/mm2)	0.784	$\dashv$	
	ear link diameter	dia.	mm	0.764	$\dashv$	
	Legs	-	111111	0	-	
	ear link spacing	SV	mm	0	-	
Asv		Asv	mm2	0.0	-	
	capacity section	-	kN/m	101	1	Slab
	capacity links	-	kN/m	0	7	Shear Capacity
	apacity at av = 2d	V <sub>C1</sub>	kN/m	101	At 2d	• •
	ear enhancement allowed?	Y/N	-	Υ	At d	101.2 kN/m
S.C	apacity at av = d	V <sub>C2</sub>	kN/m	101	7	
		•	<u>.</u>		_	
	sumed shear carried by stee	el sections only				
Ass						
Ass						Ī
Ass						
Ass						
Ass						
Ass						


	Project		TO315 Mayo	Bridges - Asse	essments	<b>Job ref</b> 10088572
44	Part of Structure		Assess		M-STR-06026 RC	Calc sheet no. rev
AtkinsRéalis	Strade River Bridge MO-N58-001  Drawing Ref	.00	Calc By	Sla	abs Date	6 0 Check by Date
				VP	17-Dec-2	4 MG 18-Dec-24
Ref		Calcu Filler Beam	lations			Output
	Calculation of Moment du		ent Loads	at Mid Spa	ın &	
					<u></u>	
AM-STR-06026	Calculation of Shear due t	<u>o Permanent</u>	t Loads ne	ar support	<u>:s:</u>	
		Load	(kN/m2)	4.9	1	
Table 3.1/ BD21		Yfl	(""")	1.15	1	
Cl.3. 1/ BD21 &	Self weight	Yf3		1.1	]	
Cl. 4.2.3/ BD 44		M <sub>sw</sub>	(kNm/m)	12.9	SLS Shear (kN)	
AM-STR-06031		Vsw Load	(kN/m)	12.6	10.0	
Table 3.1/ BD21		Yfl	(kN/m2)	1.4 1.75	-	
Cl.3. 1/ BD21 &	Surfacing	Yf3		1.1	-	
Cl. 4.2.3/ BD 44	<b>3</b>	M <sub>s</sub>	(kNm/m)	5.8	1	
AM-STR-06031		Vs	(kN/m)	5.7	2.9	
		Load	(kN/m2)	1.8		
Table 3.1/BD21		Yfl Yf3		1.20 1.1	4	Available
Cl. 4.2.3/BD 44	Fill		(IcN Imp /mp)		-	Capacity for LL
CI. 4.2.3/ BD 44 AM-STR-06031		M <sub>fill</sub> V <sub>fill1</sub>	(kNm/m) (kN/m)	4.9 5	3.7	Moment
AIVI-3   R-0003	Hence, Capacity Available for LL,		` '	49	16.6 kN	49.2 kNm
	Distance (x) from support to face		(kNm/m) (mm)	136	10.0 KN	49.2 KNIII
	Shear at support	V <sub>LLsup</sub>	(kN/m)	23	-	
	Shear at $av_1 = 2d$	$V_{LLav1 = 2d}$	(kN/m)	15	1	
	Shear at av <sub>2</sub> = d	$V_{LLav2 = d}$	(kN/m)	18	1	Shear
	Hence, Capacity Available for LL,		(kNm/m)	86	At	
	Hence, Capacity Available for LL,		(kNm/m)	83	-	t d 82.7 kN/m
	Traffic Flows & Surface Co	ondition				
					7	
	Annual Average Daily Traffic (Ref Percentage of heavy vehicles	P I Report)		5364 5%	4	
Cl. 5.21/ BD 21	Annual average hourly HGV flow	(AAHHGVF)		11	-	
AM-STR-06026	Traffic Flow Cl.5.2.2 of BD 21	(//////////////////////////////////////	L/M/H	Medium	-	
	Condition of road surfacing (Good	l/ Poor)		Good	†	<b>Bridge Category</b>
	Therefore Bridge Category			Mg	]	Mg
Figure 5.6	Factor <b>K</b> for 40 tonne loading			0.76		
	HA + KEL and Equiv. 40 t	Assessment	<u>Loading</u>			
AM-STR-06026 Cl. 5.18/ BD21	HA Loading	UDL	(kN/m)	130.9	٦	
OI. J. 10/ DDZ1	TIA LOCALING	KEL	(kN)	120.0	1	
	Lane Factor		(3)	1.0	1	
CI 5.23/ BD 21	Adjustment Factor	AF		1.46	]	
AM-STR-06026	Therefore, Equivalent 40 t	UDL	(kN/m2)	27.26		
	loading	KEL	(kN/m)	24.99	4	
		Yfl Yf3		1.50	4	
	Moment Due 40 tenne leading	M <sub>LL</sub>	(IcNI)	1.1 <b>81</b>	SI S shear	
	Moment Due 40 tonne loading Shear due to 40t at support		(kNm) (kN/m)	80	SLS shear 48 kN	
	Shear due to 40t at support  Shear due to 40t av = 2d	$V_{LLsup}$ $V_{av=2d}$	(kN/m)	58	- TO KIN	
	Shear due to 40t av = 2d	$V_{av = 2d}$ $V_{LLav = d}$	(kN/m)	67	1	
CI 5.27/ BD 21	5.10ai 445 to 40t av = 4	* LLav = d	[ (15/111)	1 31	_	(HA + KEL Eqv.)
	Factor C for Moment at midspan			0.46		Moment Capacity
	Loading Capacity Moment at mids	span		7.5t	as per Figure 5.6	7.5t
	Factor C for Shear at 3*d			0.82		
	Factor C for Shear at d			1.08		Shear Capacity
	Loading Capacity Shear			7.5t	as per Figure 5.6	7.5t
Check bond stress at s	 upport where shear is maximum	<u>.</u>		Bond	Permissble	
				Stress (N/mm2)		
	SLS Shear at support Dead Load	kN	16.58	1.59	0.7	
	SLS Shear at support Live Load	kN	48.38	j		I


	Project	TO315 Mayo Bridges - Asse	essments		o ref 38572
	Part of Structure	Assessment using Al	M-STR-06026 RC	Calc sheet	no. rev
<b>Atkins</b> Réalis	Strade River Bridge MO-N58-001.00	Sla	6	0	
- Alkinshealis	Drawing Ref	Calc By	Date	Check by	Date
		VP	17-Dec-24	MG	18-Dec-24
Ref	Calc	ulations		Ou	tput
	Is bond stress okay? Y/N Load Capacity where bond stress exceeded Adequacy Factor for Bond Stress	N <b>7.5t</b> 101%	Assuming no contribution from Concrete	Bond Cap 7.5t	-
	Adequacy Factor for Moment at Midspan Adequacy Factor for Shear	60% 108%		40 t Adequ 60%	ıacy

	Project		TO315 Mayo	Bridges - Asses	ssments			<b>b ref</b> 88572	<u> </u>
1 AtkinsRéalis	Part of Structure Strade River Bridge MO-N58-001.	.00	Assessme	nt using AM-S	TR-06026	RC Slabs	Calc shee	t no.	
or received to date	Drawing Ref		Calc By	VD	ı	Date	Check by	Date	;
Ref	Strade River Bridge MO-N58-001	.00 Calcula		VP		17-Dec-24	MG O	18-Dut	Jec-
						•		•	
T.I. 504 (	Single Axle Load	Filler Beam		Moment	Shear	Adequacy			
Table 5.3.1 of BD21	Assessment Loading		(Toppo)	Check 3.0	Check	for 40t			
AM-STR-06026	Nominal Single Axle Load		(Tonne) (kN)	43	<b>7.5</b> 86	<b>40.0</b> 170			
7 (W) 6 11 ( 00020	Wheel Contact Area		(m)	0.140	0.198	0.278			
	Minimum Distance Possible from								
	edge of slab to centre line of first	on left side	(m)	1.50	1.50	1.50			
	wheel in width direction	on right side	(m)	3.00	3.00	3.00			
	Dispersion for one axle, in transver		beff b'eff	1.40 2.80	1.52 2.97	1.68 3.21	ļ		
	Dispersion for two axle, in transver Dispersion in longitudinal direction		b <sub>L</sub>	0.70	0.76	0.84			
	=> Load for one axle (P)	1	kN	43.0	86.0	170.0			
	Load for two axle (P')		kN	86	172	340			
	$W = P/b_{eff} b_L$ assuming load dispersed lo	ong. & transversely	kN/m²	43.9	74.9	121.0			
	$W' = P'/b'_{eff} b_L$ assuming load dispersed		kN/m²	43.9	76.3	126.2	†		
	5 2	Yfl		1.50	1.50	1.50			
		Yf3	<u></u>	1.1	1.1	1.1	İ		
	Moment due to one axle	$M_LL$	(kNm)	47	-	153			
	Moment due to two axles	$M_LL$	(kNm)	47	-	160			
	Adequacy Factor			104%	-	31%	İ		
	=>Loading Capacity (Moment)			3t	-	-			
	Shear Due due to one axle at sup				84.9	150.2			
	Shear Due due to two axles at sur				86.6	156.6	Single Ax		
	Shear due to one axle at av = d	$V_{LLav=d}$	(kN/m)	-	79	139	Moment (	Capaci	ity
	Shear due to two axle at av = d	$V_{LLav = d}$	(kN/m)	-	80	145	3t		
	Adequacy Factor	۵۱		-	103%	57%	Shoor Co	it:	
	=>Loading Capacity (Shear) (av = Shear due to one axle at av = 2d		(kN/m)	_	7.5t 72	128	Shear Ca <sub>l</sub> 7.5t	pacity	
	Shear due to two axles av = 2d	V <sub>av = 2d</sub>	<u> </u>	-	74	133	7.50		
	Adequacy Factor	$V_{av = 2d}$	(kN/m)	-	116%	64%	40 t Adeq	uacv	
	=>Loading Capacity (Shear)(av =	2d)		-	7.5t	-	31%	uacy	
		/							
	Single Wheel Load			Moment	Shear	Adequacy			
Table 5.3.1 of				Check	Check	for 40t			
BD21	Assessment Loading		(Tonne)	3.0	7.5	40.0			
AM-STR-06026	Nominal Single Wheel Load		(kN)	21	43	86			
	Wheel Contact Area		(m)	0.138	0.198	0.280			
	Minimum Distance Possible from								
	edge of slab to centre line of first	on left side	(m)	1.50	1.50	1.50			
	wheel	on right side	(m)	3.00	3.00	3.00			
	Dispersion for Wheel Load		beff	0.70	0.76	0.84			
	w = P/b <sub>eff</sub> <sup>2</sup> assuming load dispersed long	g. & transversely YfI	kN/m²	43.1	74.9	122.0			
		Yf3		1.50 1.1	1.50 1.1	1.50 1.1			
	Moment Due Single Wheel Leed		(kNlm)	46.3	1.1	154.7			
	Moment Due Single Wheel Load Adequacy Factor	M <sub>LL</sub>	(kNm)	<b>46.3</b> 106%	-	32%			
	=>Loading Capacity (Moment)			3t	<del>  </del> -	32%	Single Wh	neel I d	nar
	- Localing Capacity (Monient)	<u> </u>	1	J. J.			Moment (		
	Shear Due Single Wheel Load	$V_{LL}$	(kN)	_	84.9	151.6	3t	p.a.o.	- ,
	Shear due to 40t av = d	V <sub>LLav = d</sub>	(kN)	_	78.7	140.4			
	Adequacy Factor	* LLav = d	(1/11/)		105%	59%	Shear Ca	pacity	,
	=>Loading Capacity (Shear) (av =	: d)			7.5t	-	7.5t	, <b>.</b>	
	3 - 2 - 3 - 2 - 3 - 3 - 3 - 3 - 3 - 3 -	,					1.5.		
	Shear due to 40t av = 2d	$V_{av=2d}$	(kN)	-	72.5	129.1	40 t Adeq	uacv	
	Adequacy Factor	av = 2U	()		118%	66%	32%	<b>-</b> - <b>-</b>	
	=>Loading Capacity (Shear)(av =	2d)			7.5t	-			
					•				









Sr No.	b	h	No.	E <sub>s</sub> /E <sub>c</sub>	Area b x h	CG y-y (y)	Ay	Ay <sup>2</sup>	I <sub>self</sub>	
1	600	167.65	1	1.00	100589.9	224.92504	22625198.5	5088973743	235602565	Concrete
2	65	28	1	16.33	29725.53	146	4339927.5	633629414.8	118906.667	Steel
3	10	85	1	16.33	13882.8	89.5	1242510.86	111204721.5	511770.833	Steel
4	123	10	1	16.33	20089.23	42	843747.759	35437405.89	10250	Steel
					ΣΑ	$\Sigma$ y	$\Sigma$ Ay	$\Sigma$ Ay <sup>2</sup>	$\Sigma$ I <sub>self</sub>	]
Sum					164287.5	502.42504	29051384.6	5869245285	236243492	]



Project TO315 May	o Bridges - Assessment	5	Jo	b ref
			10088572	
Part of Structure	Filler Beam Capacity		Calc sheet	Rev
Strade River Bridge MO-	N58-001.00		1	0
Drawing ref.	Calc by	Date	Check by	Date
	VP	17/12/24	MG	18/12/24

Ouptut

9 Check bond stress of section

Ref

		Dimensions	s in mm
Allowable f <sub>cu</sub> =	18.9	b=	600
$\gamma_{mc}$ =	1.05	$d_c=$	308.75
Allowable f <sub>st</sub> =	230	d <sub>s</sub> =	123
$\gamma_{ms}$ =	1.05	$A_{st}=$	1820
$\gamma_{f3}$ =	1.1	t <sub>ft</sub> =	28
Bottom Cover=		$t_{fb} =$	10
		A <sub>sb</sub> =	1230
		$t_w =$	10

Short Term Ec (BD 44/95 cl. 4.3.2.1)


 $Ec = (20 + 0.27f_{cu}) = 25$ 

Es = 205 m = Es / Ec = 8.17

Long Term Ec (BD 44/95 cl. 4.3.2.1)

Twice Short Term m = 16.33

Allowable Conc stress =  $0.75f_{cu}/\gamma_{mc}\gamma_{f3}$  = 12.273 Allowable steel stress =  $f_{st}/\gamma_{ms}\gamma_{f3}$  = **199.134** 



Calculations

### **Uncracked Section for Grillage Analysis**

# Short Term Long Term Ec

8.17 16.33 m =

x = 167.65177.53

Area of section (concrete units) = 217098.78 248947.57 mm<sup>2</sup> Area of section (steel units) = 26584.54 15242.27 mm<sup>2</sup>

 $I_{NA}$  (concrete units)= 1.62E+09 1.74E+09 mm<sup>4</sup>

 $I_{NA}$  (steel units)= 2.16E+08 1.23E+08 mm<sup>4</sup>

#### Cracked Section

#### Short Term Long Term Ec 8.17 16.33

x = 152.65147.18 mm Area of concrete in compression = 91591.59 88307.85 mm<sup>2</sup>

Centroid of conc. in comp.(from NA) = 76.33 73.59

 $I_{NA}$  (cracked section)= 6.74E+08 9.68E+08 mm<sup>4</sup>

 $A * y / I_{NA} = 0.01037$ 0.00671 /mm

AM-STR-06037 CI 8.5.1: "The bond may be assumed to be developed uniformly only over both sides of the web and the upper surface of the top and bottom flanges of the steel beam where there is complete encasement and over both sides of the web and the upper surface of the top flange of the steel beam where the beam soffit is exposed."

Hence, as cover to soffit of bottom flange is 37mm, Ls = 348 mm



Project TO315 Mayo Bridges - Assessments			Job ref			
					10088	3572.00
Part of St	ructure	Filler Beam Capacit	ty		Calc sheet	Rev
Strade Riv	ver Bridge MO-	N58-001.00			2	0
Drawing re	ef.	Calc by		Date	Check by	Date
		VP	1	17/12/2024	MG	18/12/2024

#### Check for Max Shear (at support) HA Loading

Serviceability Loads (F)

Corvidoability Loado (1)		_			
Shear at support	kN		Live Load	Dead Load	
Dead Load	22.00	I Shear Force = FAy/I <sub>NA</sub>	404.27	147.66	N/mm
Live Load	39 00	1			

Bond stress = 1.162 0.424  $N/mm^2$ 


Total bond stress = 1.586 N/mm<sup>2</sup>

Allowable bond stress at SLS =  $0.700 \text{ N/mm}^2$ 

Result: Section is unsuitable for composite action (see BD 61/10 Clause 8.5.1)

#### Check capacity of section unsuitable for composite action

Find distance x such that bond stress due to combined Dead Load and Live Load = 0.7N/mm2



 Serviceability Loads (F)

 Shear at location x
 kN

 Dead Load
 5.00

 Live Load
 20.26

Live Load Dead Load

Longt'l Shear Force =  $FAy/I_{NA}$  210.04 33.56 N/mm Bond stress using = 0.604 0.096 N/mm<sup>2</sup>

Total bond stress= **0.700** N/mm<sup>2</sup>

Allowable bond stress at SLS = 0.700 N/mm<sup>2</sup>

Result: Bond stress okay

#### Check corresponding moment capacity at x

Factor **K** for 40 tonne loading 0.76

Moment Capacity of steel section 30.38 kNm

Moment Capacity of composite section 36.54 kNm


	ULS Moment at x	kNm
	Dead Load	12.24
Available capacit	24.30	
	Live Load	24.00

Factor C for Moment 0.77
Loading Capacity Moment 7.5t
Adequacy Factor 1.01

as per Figure 5.6

(HA + KEL Eqv.)
Moment Capacity
7.5t


## Results from Grillage analysis -Dead Load






Ref

**Project** TO315 Mayo Bridges - Assessments Job ref 10088572 Part of Structure Filler Beam Capacity Calc sheet Rev Strade River Bridge MO-N58-001.00 3 0.00 Drawing ref. Calc by Date Check by Date VΡ 17/12/2024 MG 18/12/2024



#### HA 7.5t GVW Moment Diagram



#### Combined load effect

per m width ULS (Yf3=1.5)
Combined Moment Mx 16.00 kNm 24.00
Combined Shear Vx 20.26 kN 30.39

 ULS (Yf3=1.5)

 Max M
 23.00 kNm
 34.50 kNm

 Max V
 39.00 kN
 58.50 kN



Project TO315 Mayo Bridges - Assessments			Jo	b ref
			1008	8572.00
Part of Structure	Filler Beam Capaci	ity	Calc sheet	Rev
Strade River Bridge	MO-N58-001.00		4	0.00
Drawing ref.	Calc by	Date	Check by	Date
	VP	17/12/20	024 MG	18/12/2024

#### **HB Live Load**

#### Check for Max Shear (at support) 45HB

Serviceability Loads (F)

Shear at support	kN
Dead Load	22.00
Live Load	71.00

Try x =

Live Load Dead Load

Longt'l Shear Force =  $FAy/I_{NA}$  735.99 147.66 N/mm

Bond stress using= 2.115 0.424 N/mm<sup>2</sup>

Total bond stress using = 2.539 N/mm<sup>2</sup> Allowable bond stress at SLS = 0.700 N/mm<sup>2</sup>

**Result:** Bond Stress (2.54) greater or equal than Permissible Bond Stress (0.7) hence section is unsuitable for composite action (see BD 61/10 Clause 8.5.1)

#### Check section at x

45HB Loading Vary x until bond stress = allowable bond stress

1.70 m Load 45.00 HB

x okay Hint:Use Goalseek

Serviceability Loads (F)

Shear at location x	kN
Dead Load	4.00
Live Load	20.91

#### Check for Shear at x - 45HB

#### Note: If bottom flange is exposed use $L_{\text{S1}}$ otherwise use $L_{\text{S2}}$


<u>Live Load</u> <u>Dead Load</u>


Longt'l Shear Force = FAy/I<sub>NA</sub> 217 26.85 N/mm

Bond stress= 0.623 0.077 N/mm<sup>2</sup>

Total bond stress= 0.700 N/mm<sup>2</sup> Allowable bond stress at SLS =  $0.7 \ 0.700$  N/mm<sup>2</sup>

Result: Bond stress okay using Ls2





				ULS		
Vx	4.00 kN	Vx	20.91 kN	31.37	kN	
Vmax	22.00 kN	Vmax	71.00 kN	106.50	kN	
Mx	14.00 kNm	Mx	37.00 kNm	55.50	kNm	
Mmax	17.00 kNm	Mmax	42.00 kNm	63.00	kNm	

Fail

### Check corresponding moment capacity at x

	ULS Moment at x	kNm	1
	Dead Load	16.80	
Available capacit	13.58	Adequacy	
45HB	Live Load	55.50	0.24

Moment Capacity <45HB



Ī	Project TO315 Mayo Bridges - Assessments			Job ref	
				10088	3572.00
ĺ	Part of Structure	Filler Beam Capa	city	Calc sheet	Rev
	Strade River Bridge	MO-N58-001.00		5	0.00
ĺ	Drawing ref.	Calc by	Date	Check by	Date
		VP	17/12/2024	<u>MG</u>	18/12/2024

Ouptut Ref Calculations

#### **HB Live Load**

#### Check for Max Shear (at support) 30HB

Serviceability Loads (F)

Shear at support	kN
Dead Load	22.00
Live Load	70.50

#### <u>Live Load</u> <u>Dead Load</u>

Longt'l Shear Force = FAy/I<sub>NA</sub> 730.80 147.66 N/mm

> Bond stress using= 2.100 0.424 N/mm<sup>2</sup>

N/mm<sup>2</sup> Total bond stress using = 2.524

Allowable bond stress at SLS = 0.700 N/mm<sup>2</sup>

Result: Bond Stress (2.52) greater or equal than Permissible Bond Stress (0.7) hence section is unsuitable for composite action (see BD 61/10 Clause 8.5.1)

#### Check section at x

30HB Loading Vary x until bond stress = allowable bond stress **30.00** HB

**1.62** m Load

x okay Hint:Use Goalseek

Serviceability Loads (F	)
Shear at location x	kN
Dead Load	4.50
Live Load	20.59

#### Check for Shear at x - 30HB

#### Note: If bottom flange is exposed use $L_{\text{S1}}$ otherwise use $L_{\text{S2}}$

Live Load Dead Load


Longt'l Shear Force =  $FAy/I_{NA}$ 213 30.20 N/mm


> Bond stress= 0.613 0.087 N/mm<sup>2</sup>

N/mm<sup>2</sup> Total bond stress= 0.700

N/mm<sup>2</sup> Allowable bond stress at SLS = 0.7 0.700

#### Result: Bond stress okay using Ls2





				ULS
Vx	4.00 kN	Vx	20.59 kN	30.88
Vmax	22.00 kN	Vmax	47.00 kN	70.50
Mx	14.00 kNm	Mx	23.00 kNm	34.50
Mmax	17.00 kNm	Mmax	28.00 kNm	42.00

#### Check corresponding moment capacity at x

	ULS Moment at x	kNm	
	Dead Load	16.80	
Available capaci	ty for live load	13.58	Adequacy
30HB	Live Load	34.50	0.39

quacy Fail

Moment Capacity <30HB

kΝ kΝ kNm kNm



Project 0.00			Job ref		
			Calc sheet no.		
Strade River Bridge MC	5.00 0.				
Drawing ref.			#VALUE!	Date	
0.00	VP	45643.68	MG	45644.68	
	0.00	00/01/1900	<u>Ouptut</u>	00/01/1900	

Ref Calculations Ouptut

#### Check for Max Shear (at support) SV 80

Serviceability Loads (F)

Shear at support	kN
Dead Load	22.00
Live Load	71.00

#### Note: If bottom flange is exposed use $L_{\text{S1}}$ otherwise use $L_{\text{S2}}$

Live Load Dead Load

Longt'l Shear Force = FAy/I<sub>NA</sub> 735.99 147.66 N/mm

> N/mm<sup>2</sup> Bond stress= 2.115 0.424

N/mm<sup>2</sup> Total bond stress= 2.539

Allowable bond stress at SLS = 0.700 N/mm<sup>2</sup>

Result: Bond Stress (2.54) greater or equal than Permissible Bond Stress (0.7) hence section is unsuitable for composite action (see BD 61/10 Clause 8.5.1)

#### Check section at x SV 80HB

Vary x until bond stress = allowable bond stress SV 80 HB

Loading Try x =

**1.70** m Load Hint:Use Goalseek

Serviceability Loads (F)

Shear at location x	kN
Dead Load	4.00
Live Load	20.91

Live Load Dead Load


Longt'l Shear Force = FAy/I<sub>NA</sub> 217 26.85 N/mm


Bond stress= 0.623 0.077 N/mm<sup>2</sup>

N/mm<sup>2</sup> Total bond stress= **0.700** N/mm<sup>2</sup>

Allowable bond stress at SLS = 0.7 **0.700** Result: Bond stress okay using Ls2

#### Live Load at x





				0_0	
Vx	4.00 kN	Vx	13.94 kN	20.91	kN
Vmax	22.00 kN	Vmax	71.00 kN	106.50	kN
Mx	14.00 kNm	Mx	26.00 kNm	39.00	kNm
Mmax	17.00 kNm	Mmax	40.00 kNm	60.00	kNm

	KINM		
	16.80		
Available capacity for live load		13.58	Α
SV 80HB	Live Load	39.00	

Adequacy 0.35 Fail

Moment Capacity <SV 80




Project Name J			Job Number	
TO315 Mayo Bridges - A	10088572	2		
Calculation Location	Sheet Number	Rev.		
Strade River Bridge MO-N58-001.00			15 of	0
Drawing Reference	Originator	Date	Checker	Date
0	VP	Oct-24	MG	Oct-24

#### 10 Grillage Analysis Results Diagram

Since the Filler beam slab failed under 40T GVW, we have carried out a grillage analysis taking into account the transverse distribution.


Dead Load + Super Imposed Dead load (SD\*)



Maximum of Moment along both axis ( Mxx & Myy)

Moment near Support (Sagging) = 5 kNm Maximum Sagging Moment = 17 kNm Maximum Shear at d from support = 53 kN

#### Load effect due to Type HA 40t Loading - ULS Case 1 (SHA-40T\*)



Maximum of Moment along both axis ( Mxx & Myy)


		ULS Case 1			ULS Case 2		
	(SHA-40T*)				(SHA-26T*)		
Moment near Support (Sagging)	=	12	kNm	10	kNm		
Maximum Sagging Moment	=	56	kNm	55	kNm		
Maximum Shear at d from support	=	85	kN	84	kN		

Since the structure also failed to have enough capacity under HA 40T, results for HA 26T units are only shown above.



Project Name July 2012			Job Number		
TO315 Mayo Bridges - A	10088572	<u>)</u>			
Calculation Location S			Sheet Number	Rev.	
Strade River Bridge MO-N58-001.00			15 of	0	
Drawing Reference	Originator	Date	Checker	Date	
0	VP	Oct-24	MG	Oct-24	

#### Load effect due to Type HA +HB -combined (40T HA + HB -45units)




Maximum of Moment along both axis ( Mxx & Myy)

ULS Case 3 (SHA+HB-45\*)

Moment near Support (Sagging) = 20 kNm Maximum Sagging Moment = 84 kNm Maximum Shear at d from support = 146 kN

#### Load effect due to Type HB 45 units Loading




Maximum of Moment along both axis ( Mxx & Myy)

_	ULS Case 4 (SHB-45*)		ULS Case 5			
			(SHB-30*)			
Moment near Support (Sagging)	=	14	kNm	12	kNm	
Maximum Sagging Moment	=	75	kNm	55	kNm	
Maximum Shear at d from support	=	121	kN	87	kN	



Project Name Jo			Job Number	
TO315 Mayo Bridges - A	1008857	2		
Calculation Location	Sheet Number	Rev.		
Strade River Bridge MO-N58-001.00			15 of	0
Drawing Reference	Originator	Date	Checker	Date
0	VP	Oct-24	MG	Oct-24

#### Load effect due to SV 196 Loading - ULS Case 6 (SV 196\*)




Maximum of Moment along both axis ( Mxx & Myy)

Moment near Support (Sagging) = 18 kNm Maximum Sagging Moment = 66 kNm Maximum Shear at d from support = 110 kN

#### Load effect due to SV 80 Loading - ULS Case 7 (SV 80\*)

Since the structure also failed to have enough capacity under SV 100 vehicle, results for SV 80 are only shown below. SV 100 has the same 165 kN axle as SV 196.



Maximum of Moment along both axis ( Mxx & Myy)

Moment near Support (Sagging) = 17 kNm
Maximum Sagging Moment = 60 kNm
Maximum Shear at d from support = 98 kN



Project Name	Job Number				
TO315 Mayo Bridges - A	10088572	2			
Calculation Location	Sheet Number		Rev.		
Strade River Bridge MO-N58-001.00			15 of		0
Drawing Reference	Originator	Date	Checker	Da	te
0	VP	Oct-24	MG Od		ct-24

#### **Assessment Summary Table.**

Load Effect	RA*	SD*	Case 1 SHA-40T*	Case 2 SHA-7.5T*	Case 3 SHA+H45*	Case 4 SHB45*	Case 5 SHB30*	Case 6 SSV196*	Case 7 SSV80*
Moment near Support (Sagging) (kNm)	73	5	12	10	20	14	12	18	17
RA*/SA*		14.6	6.1	7.3	3.6	5.2	6.1	4.0	4.3
Check		ОК	ОК	ОК	ОК	ОК	ОК	ОК	ОК
Maximum Sagging Moment (kNm)	73	17	56	55	84	75	55	66	60
RA*/SA*		4.28	1.30	1.32	0.87	0.971	1.32	1.10	1.21
Check		ОК	ОК	ОК	Not Ok	Not Ok	ОК	ОК	ОК
Maximum Shear at d from support (kN)	101	53	85	84	146	121	87	110	98
RA*/SA*		1.9	1.2	1.2	0.7	0.8	1.2	0.9	1.0
Check		ОК	ОК	ОК	Not Ok	Not Ok	ОК	Not Ok	ОК

Where

RA\* = Assessment Resistance (flexure, shear etc.)

SD\* = Assessment load effects due to dead and superimposed dead loads
SHA\* = Assessment load effect due to the associated Type HA loading

SHB\* = Load effect due to HB loading SA\* = Assessment load effects RA\*/SA\* = Structural Assessment Factor

Element	Load Effect	R <sub>A*</sub>	S <sub>D*</sub>	S <sub>HA40t*</sub>	S <sub>HA+HB45*</sub>	S <sub>HB45*</sub>	S <sub>SV196*</sub>	R <sub>A</sub> */S <sub>A</sub> *
Filler beam slab bridge	Moment near Support (Sagging) (kNm)		5	12	20	14	18	3.64
	Max. Sagging Moment (kNm)	73	17	56	84	75	66	0.87
	Max. Shear (kN)	101	53	85	146	121	110	0.69
	Bond Capacity	7.5 T			< HB 30 units		< SV 80	

Structure ID	Structure Name	Structure Type	No. of Spans	Span Length	Assessed Capacity (ALL)	HB Capacity	SV Capacity
MO-N58-001.00	Strade River Bridge	Filler beam concrete slab	2	3.81	7.5t	Fails HB30 units	Fails SV 80

# **Appendix H. Photographs**



Figure H-1 - View of the carriageway looking south



Figure H-2 - View of the cracking to the northwest corner of the carriageway





Figure H-3 - View of the eastern footway



Figure H-4 - View of the western footway





Figure H-5 - View of the eastern parapet



Figure H-6 - View of the western parapet





Figure H-7 - View of the northwest embankment



Figure H-8 - View of the southeast embankment





Figure H-9 - View of the southwest wing wall



Figure H-10 - View of the south abutment





Figure H-11 - View of the north abutment



Figure H-12 - View of the northeast pier face





Figure H-13 – View of the south pier face



Figure H-14 – View of the cracking to the north face of the pier





Figure H-15 – View of the north span deck slab



Figure H-16 – View of the south span deck slab





Figure H-17 - South span - Cracking sealed with calcite



Figure H-18 - South span - spalling with exposed filler beam





Figure H-19 - North span - cracking sealed with calcite, water staining and spalling



Figure H-20 - North span - exposed filler beam with delamination evident





Figure H-21 – View of riverbed west of structure looking east



Figure H-22 - View of the west elevation





Figure H-23 - View of the east elevation



# **AtkinsRéalis**



#### **WS Atkins Ireland Limited**

Unit 2B 2200 Cork Airport Business Park Cork T12 R279

Tel: +353 21 429 0300

© WS Atkins Ireland Limited except where stated otherwise

# **AtkinsRéalis**



#### **WS Atkins Ireland Limited**

Unit 2B 2200 Cork Airport Business Park Cork T12 R279

Tel: +353 21 429 0300

© WS Atkins Ireland Limited except where stated otherwise