



KARST RISK ASSESSMENT



# Geotechnical Karst Risk Assessment



000

Client MKO

Document Ref. 22098-R-03-02

Project Title Cooloo Wind Farm

Date 19/09/2025





Project Title: Cooloo Wind Farm

Report Title: Geotechnical Karst Risk Assessment

Document Reference: 22098-R-03-02

Client: MKO

Ultimate Client: Neoen

Confidentiality Client Confidential

#### **REVISION HISTORY**

Rev	Date	Reason for Issue	Originator	Checker	Reviewer	Approver
00	20/06/2025	First issue	CE	AP	PQ	PQ
01	16/09/2025	Revision to address client comments	CE	AP	PQ	PQ
02	19/09/2025	Revision to address client comments	CE	CE	TOS	TOS

#### **DISCLAIMER**

Gavin & Doherty Geosolutions Ltd. (GDG) has prepared this report for the sole use of MKO (hereafter the "Client") in accordance with the terms of a contract between the Client and GDG. No other warranty, express or implied, is made as to the professional advice contained in the report or any other services provided by GDG. This report is confidential to the Client and may not be shared with or relied upon by any other party without the prior and express written agreement of GDG. GDG assumes no liability or duty of care to any third party in respect of or arising out of or in connection with this report and/or the professional advice contained within.

This report is the copyright of Gavin & Doherty Geosolutions Ltd. Any unauthorised reproduction or usage (in whole or in part) by any person other than the Client is strictly prohibited.





#### **REVISION SUMMARY**

Rev	Date	Section(s)	Detail of Change
00	20/06/2025	All	First Issue
01	16/09/2025	3, 4.4, 5.6	Revision to address client comments
02	19/09/2025	Executive Summary, 5.6, 6	Revision to address client comments





## **TABLE OF CONTENTS**

Cha	pter		Page
Exe	cutive	Summary	8
1	Intro	duction	9
	1.1	Background	9
	1.2	Statement of Authority	9
	1.3	Proposed Wind Farm	10
	1.4	Overview of Geotechnical Karst Risk	11
		1.4.1 Karst Definition	11
		1.4.2 Karst Landforms	11
		1.4.3 Geotechnical Karst Hazards	14
	1.5	Karst Risk Assessment Workflow	14
2	Desk	Study	16
	2.1	Quaternary Sediments	16
	2.2	Bedrock Geology	16
	2.3	Hydrogeology	17
		2.3.1 Hydrostratigraphic Rock Unit	17
		2.3.2 Karst Features	17
		2.3.3 Bedrock Aquifers	17
		2.3.4 Groundwater Bodies	18
		2.3.5 Groundwater Vulnerability	18
		2.3.6 Subsoil Permeability	19
	2.4	Aerial Imagery	19
	2.5	Topography	21
	2.6	Hydrology	21
	2.7	Land cover and land use;	22
3	Karst	Feature Database	23
4	Grou	nd Investigation	26
	4.1	Site Reconnaissance	26
	4.2	Ground Investigations	26
	4.3	Preliminary Ground Model	27
	4.4	Geophysical Survey	27
5	Karst	t Risk Assessment	29
	5.3	Hazard Assessment	29
	5.4	Geological Hazard Rating	33
		5.4.1 Underlying Rock Type	33
		5.4.2 Proximity to Faults/Geological Boundaries	34
		5.4.3 Thickness of Overburden Cover	34
		5.4.4 Overburden Cover Type	35
	5.5	Evidence-based Hazard Rating	36
		5.5.1 Density of Identified Karst Features	36
		5.5.2 Interaction with Identified Karst Features	37
	5.6	Hazard Assessment Results	38
	5.7	Adverse Consequences Assessment	40





5.8	Risk Assessment	42
6 Mi	tigation Measures	44
6.1	Additional Ground Investigation	44
6.2		44
	6.2.1 Piled Foundations	45
	6.2.2 Rock Infill	45
	6.2.3 Grouting	45
	6.2.4 Bridging layers and Geogrid blankets	46
	<ul><li>6.2.5 Drainage Control</li><li>6.2.6 Monitoring and Maintenance</li></ul>	46 47
6.3	· · · · · · · · · · · · · · · · · · ·	47
6.4	6 ,	47
7 De	sign Risk Assessment	48
8 Co	nclusions and Recommendations	50
Referen	ces	51
Append	ix A Site Layout	53
Append	ix B Geology	54
Append	ix C Hydrogeology	55
Append	ix D Topography	56
Append	ix E Hydrology	57
Append	ix F Landcover	58
Append	ix G Site Reconnaisance and Ground Investigation	60
G.1	L Karst Database	60
G.2	8	112
G.3		113
G.4		114
G.5	Geophysical Survey	115
Append	ix H Hazard Rating Matrix	116
<b>Append</b>	ix I Geotechnical Risk Register	117





## **LIST OF TABLES**

Table 1-1: Doline classification, after Waltham et al. (2005).	12
Table 2-1: Summary of bedrock lithologies (descriptions as per Pracht et al., 2015 and GSI).	17
Table 4-1: Summary of ground conditions	27
Table 5-1: Hazard Assessment factor categories.	30
Table 5-2: Karst Hazard classes	31
Table 5-3: Hazard classification and description of hazard classes.	32
Table 5-4: Bedrock Type, significance and geological hazard score.	33
Table 5-5: Fault/Geological Boundary Class, significance and geological hazard score.	34
Table 5-6: Overburden Thickness Class, significance and geological hazard score.	35
Table 5-7: Overburden Type Class, significance and geological hazard score.	36
Table 5-8: Karst Feature Density Class, significance and evidence score.	37
Table 5-9: Karst Feature Interaction Class, significance and evidence score.	38
Table 5-10: Adverse consequences assessment scoring.	41
Table 5-11: Adverse consequence scores.	42
Table 5-12: Karst risk classes	43
Table 7-1: Design Risk Assessment	48
Table G-1: Site Reconnaissance at Karst feature K1	60
Table G-2: Site Reconnaissance at Karst feature K2	61
Table G-3: Site Reconnaissance at Karst feature K3	63
Table G-4: Site Reconnaissance at Karst feature K4	65
Table G-5: Site Reconnaissance at Karst feature K5	66
Table G-6: Site Reconnaissance at Karst feature K6	68
Table G-7: Site Reconnaissance at Karst feature K7	70
Table G-8: Site Reconnaissance at Karst feature K8	71
Table G-9: Site Reconnaissance at Karst feature K9	73
Table G-10: Site Reconnaissance at Karst feature K10	74
Table G-11: Site Reconnaissance at Karst feature K11	76
Table G-12: Site Reconnaissance at Karst feature K12	77
Table G-13: Site Reconnaissance at Karst feature K13	78
Table G-14: Site Reconnaissance at Karst feature K14	79
Table G-15: Site Reconnaissance at Karst feature K15	81
Table G-16: Site Reconnaissance at Karst feature K16	82
Table G-17: Site Reconnaissance at Karst feature K17	84
Table G-18: Site Reconnaissance at Karst feature K18	84
Table G-19: Site Reconnaissance at Karst feature K19	86
Table G-20: Site Reconnaissance at Karst feature K20	87
Table G-21: Site Reconnaissance at Karst feature K21	88
Table G-22: Site Reconnaissance at Karst feature K22	89
Table G-23: Site Reconnaissance at Karst feature K23	90
Table G-24: Site Reconnaissance at Karst feature K24	91
Table G-25: Site Reconnaissance at Karst feature K25	92
Table G-26: Site Reconnaissance at Karst feature K26	93
Table G-27: Site Reconnaissance at Karst feature K27	94
Table G-28: Site Reconnaissance at Karst feature K28	96
Table G-29: Site Reconnaissance at Karst feature K29	97
Table G-30: Site Reconnaissance at Karst feature K30	98
Table G-31: Site Reconnaissance at Karst feature K31	100
Table G-32: Site Reconnaissance at Karst feature K32	101



O'Hara, 2016).



Table G-33: Site Reconnaissance at Karst feature K33	102
Table G-34: Site Reconnaissance at Karst feature K34	104
Table G-35: Site Reconnaissance at Karst feature K35	104
Table G-36: Site Reconnaissance at Karst feature K36	106
Table G-37: Site Reconnaissance at Karst feature K37	106
Table G-38: Site Reconnaissance at Karst feature K38	107
Table G-39: Site Reconnaissance at Karst feature K39	108
Table G-40: Site Reconnaissance at Karst feature K40	110
Table G-41: Site Reconnaissance at Karst feature K41	111
LIST OF FIGURES	
Figure 1.1: Workflow of the KBA methodology for the accentability of the Proposed Wind Form	15
Figure 1-1: Workflow of the KRA methodology for the acceptability of the Proposed Wind Farm. Figure 2-1: Google Earth aerial imagery for the area around T4 (2009).	20
Figure 2-2: Google Earth aerial imagery for the area around T4 (2009).	20
Figure 2-3: Google Earth aerial imagery for the area around T4 (2016).	21
Figure 3-1: Karst feature K6 (Bing aerial, 2025).	24
Figure 3-2: Karst feature K6 (LiDAR DTM Hillshade; Bluesky, 2022).	24
Figure 3-3: Karst feature K6	25
Figure 5-1: Karst hazard at each turbine location.	39
	39
Figure 5-2: Karst hazard at each infrastructure location.	
Figure 5-3: Risk matrix for karst risk assessment.	43
Figure 6-1: Example of rock infill to remediate small-scale karst sinkholes in Ireland (Madden and	

45





### **EXECUTIVE SUMMARY**

Gavin and Doherty Geosolutions (GDG) was commissioned in October 2024 by MKO to undertake a Geotechnical Karst Risk Assessment (KRA) for the Proposed Wind Farm, located at Cooloo, County Galway. Refer to Appendix A for the Proposed Wind Farm location. Karst features have been identified within the boundaries of the Proposed Wind Farm site, indicating a potential karst risk at the Proposed Wind Farm.

The purpose of this report is to outline the potential for karst risk at the Proposed Wind Farm site, to develop a quantitative karst risk assessment, and to outline mitigation measures and recommendations for consideration at the detailed design and construction stages of the project.

A desk study, site walkovers, ground investigation campaigns, and a risk assessment were conducted to assess the potential karst risk at the Proposed Wind Farm site. The walkover inspections and GI campaign were conducted over a larger search area to assess karst risk across the local area immediately adjacent to the Proposed Wind Farm site. Consultation with the published geological maps indicates that the Proposed Wind Farm site is located in an area susceptible to the development of karst landforms. This is supported by the findings of both the desk study review of aerial and topographic imagery as well as the site walkovers. A total of 41 potential karst features have been identified within 1km of the Proposed Wind Farm site boundary, with 13 potential features identified within the EIAR boundary.

The assessment findings showed that the majority of the proposed infrastructure locations are located in areas of low to medium karst hazard, with additional localised areas of high and very high hazard identified. One turbine (T4) was identified as being located in an area of high karst hazard, with a section of the access track immediately north of T4 also being classified as having a high karst hazard. Areas identified as being of very high karst hazard within the Proposed Wind Farm site do not interact with any of the proposed infrastructure footprint.

The karst risk assessment shows that the risk at each infrastructure location ranges from medium to very high (at T4) before the application of mitigation measures. Following the implementation of mitigation measures, the residual risk at each infrastructure location ranges from low to medium, indicating that development can proceed as long as mitigation measures are implemented and that the risk assessment is further refined following a more detailed confirmatory ground investigation.





## 1 INTRODUCTION

#### 1.1 BACKGROUND

Gavin and Doherty Geosolutions (GDG) was commissioned by MKO to undertake a Geotechnical Karst Risk Assessment (KRA) for the Proposed Wind Farm, located in Cooloo, County Galway. Figure A-1 in Appendix A shows the Proposed Wind Farm location. Karst features have been identified within the boundaries of the Proposed Wind Farm site, indicating a potential karst risk at the Proposed Wind Farm.

This assessment is limited to consideration of the geotechnical risks posed by karstic features to the Proposed Wind Farm. Consideration of the impact of the Proposed Wind Farm on the hydrology and hydrogeology of the Proposed Wind Farm site is outside the scope of this report.

#### 1.2 STATEMENT OF AUTHORITY

GDG has been involved in numerous renewable energy projects in both Ireland and the UK at various stages of development, including preliminary feasibility, planning, design, and construction. In addition to this, the GDG team, comprising engineering geologists, geomorphologists, geotechnical engineers, and environmental scientists, has developed expertise in ground modelling, geotechnical design, and geotechnical risk assessment, including onshore wind and linear infrastructure projects.

GDG combines state-of-the-art research with direct industry experience, offering a bespoke engineering service that delivers the most progressive, reliable, and efficient designs across a wide range of projects and technical areas. This includes providing forensic engineering and expert witness services to the Insurance and Legal sectors. Our clients include large civil engineering contractors, renewable energy developers, semi-state bodies and engineering and environmental consulting firms.

The members of the GDG team involved in this assessment include:

- Paul Quigley Project Director. Paul is a Chartered Engineer with over 28 years of experience in geotechnical engineering and a UK Registered Engineering (RoGEP) Advisor. He has worked on a wide variety of projects for employers, contractors and third parties, gaining a range of experience, including earthworks for major infrastructure schemes in Ireland and overseas, roads, tunnelling projects, flood protection schemes, retaining wall and basement projects, ground investigations and forensic reviews of failures. Paul is adept at designing creative solutions for complex problems and has published numerous peer-reviewed technical papers. He has gained extensive experience working in developments on peatlands, including the Corrib Gas Terminal, wind farm development and linear infrastructure such as roads, rail, gas pipeline, etc. He has also acted as an independent expert for several legal disputes centred on ground-related issues. He is a reviewer for the ICE Geotechnical Engineering Journal, a member of the Eurocode 7 review panel at NSAI and a former Chairman of the Geotechnical Society of Ireland.
- Chris Engleman Project Manager. Chris is a Professional Geologist with a Master's degree in Geological Sciences from the University of Leeds. He is chartered with the Institute of Geologists





Ireland (IGI) and the European Federation of Geologists. He has six years of industry experience within the onshore renewables sector and the field of geological mapping with a particular focus on Quaternary geology, peat stability, ground investigation, ground modelling, GIS mapping and geotechnical design. Chris has worked on several renewable energy projects, particularly wind and solar, for over three years. Chris is the primary author of this report. Chris carried out peat probing, site walkovers and investigation of suspected karst features, and supervised site investigation works at the Proposed Wind Farm in 2024.

- Alasdair Pilmer Senior Hydrogeologist. Alasdair is a Senior Hydrogeologist at GDG and a
  Chartered Hydrogeologist (BSc, MSc, PGeo, EurGeol) with the Institute of Geologists of Ireland
  and European Federation of Geologists. He has seven years of postgraduate experience working
  in the environmental, civil engineering, and renewables sectors in the UK, Ireland, and Africa.
  Alasdair has worked on multiple onshore and offshore wind farm projects, including Yellow River
  Wind Farm, Cushaling Wind Farm, Setanta Wind Park and Codling Wind Park.
- Patrick Kelly. Patrick is an experienced geologist with an Exploration Geology MSc from the Camborne School of Mines. He has five years of experience in engineering geology, exploration and mining, working across Ireland, the UK and Australia. He has worked in underground, brownfield and greenfield sites in both mining and engineering settings, supervising engineering projects such as wind farm ground investigation, foundation design, flood relief ground investigation, ground stabilisation, and various ground monitoring works, and supervising surface and underground drilling programs. Patrick carried out trial pit logging at the Proposed Wind Farm site in 2025.
- Sowmya Reddy Gudipati. Sowmya is a graduate engineer at GDG. She has two years of post-graduate experience working in the environmental, civil engineering, and renewables sectors. Sowmya has worked on multiple onshore wind and solar farm projects in the UK and Ireland. Sowmya carried out peat probing and site walkovers at the Proposed Wind Farm site in 2024.

#### 1.3 PROPOSED WIND FARM

For the purpose of this application, the proposed development, hereafter the 'Proposed Wind Farm', will consist of the following:

- *i.* 9 no. wind turbines with the following parameters:
  - Total turbine tip height of 180 metres;
  - A rotor blade diameter of 150 to 162 metres;
  - A hub height of 99 to 105 metres;
- ii. Permanent turbine foundations, hard-standing and assembly areas;
- iii. Underground electrical (33kV) and communications cabling;
- iv. 1 no. temporary construction compound (including site offices and welfare facilities);
- v. A meteorological mast with a height of 100 metres, security fencing and associated foundation and hard-standing area;
- vi. 1 no. new site entrance on the R332 in the townland Lisavally;
- vii. 1 no. new access and egress point off the L6056 Local Road in the townland of Dangan Eighter;





- viii. 1 no. new access and egress point on to an existing access track in the townland of Dangan Eighter;
- ix. 2 no. new access and egress points off the L6301 Local Road in the townland of Cooloo and Lecarrow;
- x. Upgrade of existing site tracks/roads and provision of new site access roads, clear span crossings, junctions and hard-standing areas;
- xi. A new temporary access road from N63 national road and to R332 Regional Road in the townland of Slievegorm to facilitate the delivery of turbine components and other abnormal sized loads;
- xii. Demolition of an existing derelict house and adjacent outbuilding in the townland of Cooloo;
- xiii. Peat and Spoil Management Areas;
- *xiv.* Tree felling and hedgerow removal;
- xv. Biodiversity Management and Enhancement measures;
- xvi. Site Drainage;
- xvii. Operational Stage site signage; and
- xviii. All ancillary apparatus and site development works above and below ground, including soft and hard landscaping.

Sections of the Proposed Grid Connection as defined in Section 1.1.1 of Chapter 1 Introduction are also included within this KRA. These include the onsite 110kV substation and battery energy storage system (BESS) compound.

#### 1.4 OVERVIEW OF GEOTECHNICAL KARST RISK

#### 1.4.1 KARST DEFINITION

Karst is defined by Drew (2018) as 'a terrain with distinctive hydrology and landforms due to the high solubility of the rock and the high degree of development of secondary permeability in the aquifer'. The development of karstic landscapes occurs most frequently in very pure, well-fractured limestone, such as the Carboniferous limestone in Ireland, but can form in any carbonate rock susceptible to dissolution. Solution of the limestone by acidified runoff is the dominant process by which karstic weathering occurs. The degree of solutional erosion varies both across the surface and below the ground. These variations in intensity, combined with the areal variability of the solution processes on different limestone lithologies and structures, produce a variety of karstic landforms on both large and small scales.

#### 1.4.2 KARST LANDFORMS

Karstic landscapes consist of a highly variable and complex set of features, including fissures, voids and cavities, spread across often quite large areas. These features may range from microscale dissolution (<1m in depth), e.g., grykes in exposed limestone, to kilometre-scale enclosed depressions. A number of the most commonly encountered karst features are as follows.

#### **Enclosed Depressions**


Enclosed depressions, in which runoff is funnelled vertically down to become groundwater recharge, are regarded as the most common karst landforms (Drew, 2018). They range in diameter from a few metres to tens of kilometres and range in depth from a few centimetres to hundreds of metres. They






all represent local zones of concentrated solutional erosion of limestone. The smallest of these features are termed dolines or sinkholes, and these take several forms. A summary of the main types of doline/sinkhole is provided in Table 1-1.

Table 1-1: Doline classification, after Waltham et al. (2005).









#### **Dry Valleys**

In humid climates, valleys or fragments of valleys are often found in karst areas. They develop when not all runoff can become sub-surface recharge. Such valleys may be devoid of streams and relate to different environmental conditions in the past, such as a higher water table, frozen ground, superimposition of the drainage pattern from a cover rock or wetter conditions in the past.

#### Caves

Caves are defined by Ford and Williams (2007) as cavities typically metres or tens of metres across, formed within the rock by its dissolution, and left empty or filled with sediment. In hydrogeological terms, however, every water-transmitting opening greater than 5–10 mm in diameter within the limestone aquifer has turbulent flow and should be considered a conduit (Drew, 2018).

#### **Swallow Holes**





A swallow hole is a surface depression or opening where a stream or surface water disappears underground, recharging the karst aquifer system. These are common in limestone areas where surface water is redirected into subterranean channels (Drew, 2018).

#### **Springs**

A spring is a natural point where groundwater (GW) discharges from aquifers at the surface, often at the base of a slope or cliff (Drew, 2018).

#### **Turloughs**

A turlough is a seasonal lake found in karst lowlands, especially in western Ireland (Coxon, 1987). It fills with water during wet seasons when the water table rises and drains away through underground channels in dry periods (Drew, 2018).

#### 1.4.3 GEOTECHNICAL KARST HAZARDS

The main hazards posed by karst to engineering projects, including wind farm developments, are enclosed depressions, particularly dolines/sinkholes. The main geotechnical hazards associated with dolines and karstic landscapes are:

- Rapid failure of rock or cohesive soil to form collapse or dropout dolines. Instantaneous failures
  of this type can be catastrophic, leading to serious injury or severe structural damage;
- Karst collapse due to loss of buoyant support and effective stress changes in the soil arch following GW lowering (e.g. by road cutting);
- Karst collapse brought on by erosion of soils by downward-moving surface water drainage to rock (seepage erosion/ migration of fines)
- Differential settlement caused by subsidence of soils overlying suffusion of buried dolines;
- Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design.

#### 1.5 KARST RISK ASSESSMENT WORKFLOW

The karst risk assessment methodology adopted for this project is based on assessments undertaken on previous road schemes in Ireland (Rutty and Jennings, 2012; Madden and O'Hara, 2016), discussion in published literature (Waltham et al., 2005; Waltham and Fookes, 2003) and previous project expertise of the project team on large linear infrastructure projects in karstic environments. Figure 1-1 shows a workflow diagram for the KRA.








Figure 1-1: Workflow of the KRA methodology for the acceptability of the Proposed Wind Farm.





## 2 DESK STUDY

#### 2.1 QUATERNARY SEDIMENTS

The map of Quaternary sediments at 1:50,000 scale shown in Figure B- 1 in Appendix B (GSI, 2025) shows that the Proposed Wind Farm site is located in a mixed area consisting primarily of cut-over raised peat and glacial till. Cut-over raised peat consists of discrete, raised, dome-shaped masses of peat that have had part of their peat volume removed by anthropogenic peat harvesting methods. Parts of the Proposed Wind Farm site area consist of uncut raised peat bog, surrounded by cut-over peat. These raised bog areas are located north of T5, between T7 and T9, and north of T2.

Alluvium deposits are not mapped within the site boundary; however, some form of alluvium is expected to be present adjacent to most of the minor watercourses that cross the Proposed Wind Farm site.

Pockets of till derived from limestones are mapped throughout the Proposed Wind Farm, largely corresponding with small ridge features mapped by the Geological Survey Ireland (GSI) as drumlins. Glacial till consists of typically over-consolidated sediments directly deposited by glacial action and can vary between cohesive clays and sands, as well as gravels. T1, T3, T4, T6, T8, the temporary construction compound, and parts of the substation are located in areas mapped by the GSI as till derived from limestone. A small area of gravels derived from limestone and associated with an esker is mapped approximately 300m north of T7, outside of the EIAR boundary.

#### 2.2 BEDROCK GEOLOGY

According to the GSI bedrock geological map of Ireland at 1:100,000 scale (GSI, 2025) (Figure B-2 in Appendix B), the bedrock underlying the Proposed Wind Farm site consists of limestone of the Burren Formation, undifferentiated Viséan limestones and the Croghan Limestone formation. The northern part of the Proposed Wind Farm site, approximately 100m northeast of T7, is mapped as consisting of the Croghan Formation, while the remainder of the Proposed Wind Farm site is mapped as Undifferentiated Viséan Limestones, aside from a small band of Burren Formation rocks, mapped at T7, and running south-east from this location to approximately 150m north of T9. All of the turbine locations, except T7, are mapped as being underlain by Undifferentiated Viséan Limestones.

Pale grey argillaceous and bioclastic packstones and wackestones typify the Burren and Croghan formations. These formations also contain intervals of dark cherty limestones and shales, often associated with oolitic grainstones. Little information is available regarding the Undifferentiated Viséan Limestones; however, they are anticipated to consist of pure, bedded limestone. A summary of the expected lithologies is shown in Table 2-1.

One rotary core borehole (GSI-17-003) from the GSI borehole database was drilled within the Proposed Wind Farm site, approximately 390m east of T7 (Figure B-2 in Appendix B). The available borehole log indicated that bedrock was encountered at 5 meters below ground level (mbgl) and was drilled to a final depth of 122 meters below ground level (mbgl). A dark grey argillaceous





limestone and calcareous mudstone from the Croghan Formation was encountered from 5.0 to 105 m below ground level (mbgl). A very fine-grained argillaceous limestone of the Ballymore Formation was encountered from 105 to 122m below ground level (bgl).

Table 2-1: Summary of bedrock lithologies (descriptions as per Pracht et al., 2015 and GSI).

Bedrock Formation	System	Series	Stage	Brief Description
Burren Formation	Carboniferous	Dinantian	Viséan	Medium- and coarse-grained light and dark grey well- bedded and massive limestone, rare clay bands; frequent coral colonies and brachiopod bands; rare massive fine-grained limestone intervals with cavities; some partial dolomitization.
Croghan Formation	Carboniferous	Dinantian	Viséan	Mostly fine- to medium-grained, dark grey well-bedded argillaceous limestone.
Undifferentiated Viséan Limestone	Carboniferous	Dinantian	Viséan	Undifferentiated Limestones of Viséan age.

#### 2.3 HYDROGEOLOGY

#### 2.3.1 HYDROSTRATIGRAPHIC ROCK UNIT

According to the GSI Hydrostatigraphic Rock Unit dataset (Figure C-1 in Appendix C), the entirety of the Proposed Wind Farm site is underlain by Dinantian Pure Bedded Limestones (DUIL). The limestones in the Dinantian Pure Bedded Limestone Rock Unit Group are described by Drew (2018) as generally pure, pale grey, well-bedded and fine to coarse-grained. The absence of clay minerals within the limestone beds makes these rocks more brittle than the impure limestones, resulting in a high degree of fracturing and, consequently, increased permeability. The degree of bedding, jointing and deformation of these limestones has allowed a high degree of karstification to develop. These limestones are associated with low-density surface drainage networks, a high degree of interconnectivity between surface and groundwater, and the presence of numerous high-yielding springs (>25 l/s).

#### 2.3.2 KARST FEATURES

The GSI Karst database (shown in Figure C-1 in Appendix C) records a total of eight karst features within a 1km buffer of the Proposed Wind Farm boundary, with each of these recorded as enclosed depressions. This dataset has been compiled by GSI using historical mapping, aerial imagery, and site inspections for a number of years since its original issue (Burke, 1998). GSI karst feature mapping is ongoing, and the presence of mapped features often reflects areas with greater field mapping coverage. It does not constitute a definite representation of all features present in the receiving environment. This dataset is not exhaustive, and additional karst features have been identified. Please see Section 3 for additional details.

#### 2.3.3 BEDROCK AQUIFERS

According to the GSI Bedrock Aquifer map (2018), shown in Figure C- 2 in Appendix C, the entirety of the Proposed Wind Farm site is underlain by a Regionally Important Aquifer – Karstified (conduit).





This corresponds to the GSI aquifer category 'Rkc'. This aquifer is classed by the GSI as capable of supporting large public water supplies sufficient to support a large town.

#### 2.3.4 GROUNDWATER BODIES

The entire proposed Wind Farm site is underlain by the Clare-Corrib Groundwater Body (GWB) (GSI, 2025). The extent of the GWB relative to the Proposed Wind Farm site can be seen in Figure C-3 in Appendix C. This GWB covers much of Counties Galway, Mayo, and Roscommon, encompassing a total area of approximately 1,400 km² (GSI, 2004). The north, south and west groundwater divides of the GWB are topographic highs that coincide with surface water catchment boundaries. It is bounded to the west by Lough Corrib.

The River Clare and its tributaries principally drain the area; however, the present-day drainage network has been significantly altered by arterial drainage that took place early in the nineteenth century. Much of the current stream network serves as a storm runoff system and remains inactive during the summer months. Before artificial drainage, streams sank underground via turlough sinks in the GWB. Within the GWB, surface water catchments are often bypassed by groundwater flowing beneath surface water channels and across surface water catchment divides.

The GWB is composed primarily of high transmissivity karstified limestone (Rkc). Transmissivity and well yields are variable, with rapid groundwater flow velocities recorded through groundwater tracing (GSI, 2004). The tracing indicates an anisotropy in the transmissivity, with faster groundwater flow velocities and higher transmissivity in an E-W direction, which may be linked to shallow E-W trending synclinal axes and steeper E-W hydraulic gradients.

The groundwater in this body is generally unconfined but may become locally confined beneath thick, low-permeability subsoil. Most of the groundwater flow occurs in the upper epikarstic layer and in a zone of interconnected solutionally enlarged bedding planes and fissures, generally extending to a depth of 30 m (GSI, 2004).

#### 2.3.5 GROUNDWATER VULNERABILITY

The GSI Groundwater Vulnerability map indicates land where groundwater is susceptible to pollution. The vulnerability category assigned to a site or area is based on how easily water, which may contain pollutants, can reach the groundwater. GSI mapping (2025) indicates that the groundwater vulnerability across the Proposed Wind Farm site is highly variable, ranging from low in central portions of the Proposed Wind Farm site, to extreme/Rock at or near surface or karst in localised areas along watercourses in the centre of the Proposed Wind Farm site, and along the southern access track as far as the temporary construction compound. The GSI groundwater vulnerability map for the Proposed Wind Farm site is shown in Figure C-4 in Appendix C. Areas of low vulnerability generally correspond to areas mapped by the GSI as peat (such as at T2, T5, T7 and T9), with areas of moderate vulnerability mapped by the GSI in areas of glacial till (such as T3, T4, T6 and T8). T1 is mapped in an area of high vulnerability adjacent to an area classified as having extreme vulnerability, suggesting that the bedrock is relatively close to the surface in this location.





#### 2.3.6 SUBSOIL PERMEABILITY

The GSI Subsoil Permeability map, shown in Figure C-5 in Appendix C, indicates that the Proposed Wind Farm site varies between areas of low and moderate permeability. T2, T5, T7, and T9 are mapped in areas of moderate permeability (corresponding to areas mapped as peat), while the remaining turbines are mapped in areas of low permeability (corresponding to areas mapped as till). A small area marked by the GSI as 'not mapped' is located close to T1 and along the southern access, extending as far as the temporary construction compound. This indicates that insufficient data is available for the GSI to assign a subsoil permeability rating, or that bedrock is close to or at the surface.

#### 2.4 AERIAL IMAGERY

Aerial imagery from the following sources has been used to identify potential karst features:

- Bing Aerial Imagery (2025);
- Google Earth Multitemporal Aerial Imagery (2009-2025);
- Ordnance Survey Ireland Orthophoto (OSi, 1995-2013); and
- OSI 6-inch and 25-inch historic base mapping.

Due to the nature of changes in vegetation and land use, as well as seasonal variations in water tables and hydrological conditions, the identification of features must take into account multi-temporal imagery. An example of this is visible for the area surrounding T4, as seen in Google Earth aerial imagery from 2009 (Figure 2-1), 2018 (Figure 2-2) and 2025 (Figure 2-3). A number of features which may be identified as possible enclosed depressions/dolines are visible in the imagery from 2009 and 2018, but many are obscured by vegetation and water table changes in 2025.







Figure 2-1: Google Earth aerial imagery for the area around T4 (2009).



Figure 2-2: Google Earth aerial imagery for the area around T4 (2018).







Figure 2-3: Google Earth aerial imagery for the area around T4 (2025).

#### 2.5 TOPOGRAPHY

A Digital Terrain Model derived from Bluesky's (2022) LiDAR data was used for topographical analysis and is shown in Figure D-1 of the Appendix.

The topography of the Proposed Wind Farm site varies between low, undulating ridges and flat areas of raised bog, and the geomorphology is dominated by low, ribbed moraines and low, NW-SE-oriented ridges mapped by the GSI as drumlins running across the Proposed Wind Farm site. The peat bogs on site occupy generally flat depressions between the drumlins, with raised peat bog areas forming topographic highs relative to areas of cutover peat. The topography of the Proposed Wind Farm site can be described as flat to undulating raised bog plain. The elevation varies between 63 mAOD to 86 mAOD (meters Above Ordnance Datum).

A hillshade raster generated from the LiDAR DTM has been used to aid in identifying potential karst features, and is illustrated in Figure D-2 of Appendix D.

#### 2.6 HYDROLOGY

According to the Ordnance Survey Ireland (OSi) shapefiles of rivers, lakes, and catchments/basins (Figure E- 1 in Appendix E), the Proposed Wind Farm site is located within the watershed of two catchments: Grange (Galway - 010) and Abbert (030). T9 is located 80m from minor watercourse labelled as *Dangan Eighter*, which flows northeast through the northern part of the Proposed Wind Farm site. This watercourse forms part of the Grange catchment, which flows eventually to the Clare River, and eventually the Corrib. Two watercourse crossings are proposed across the *Dangan Eighter*, between T5 and T6, and between T7 and T9. An additional watercourse crossing is proposed across an unnamed minor tributary of the Dangan Eighter between T5 and T9. Two additional minor





watercourses (*Lecarrow* and *Forty Acre*) are identified in the southern portion of the Proposed Wind Farm site. Both of these watercourses flow southwards, forming part of the Abbert catchment and eventually joining the Clare and Corrib river catchments. T1 is located 85m from the *Lecarrow*, and one watercourse crossing is proposed between T1 and T2. An additional watercourse crossing of the *Forty Acre* is proposed close to the southern site entrance. The rest of the projected elements (e.g., turbines, substation) are located more than 50m from any watercourse. Two small lakes, mapped as the Derrynacrick Loughs by the OSI, or located between T6 and T9, with one lake located outside of the EIAR boundary, and one lake just within the EIAR boundary.

The GSI karst database notes the presence of turloughs in the area surrounding the Proposed Wind Farm site. As a result, a review of GSI Groundwater flooding has been conducted, and is shown in Figure E-2 in Appendix E. Historic groundwater flooding is not recorded within the EIAR boundary; however, historic groundwater flooding is noted approximately 100m southwest of the EIAR boundary, approximately 350m southwest of T4, at locations identified in Section 3 as karst features (K16 and K21). Additionally, an area of medium probability for groundwater flooding is recognised by the GSI approximately 170m from the EIAR boundary, approximately 350m east of T6, at the feature recorded at Derrynacrick Lough by the OSI mapping. Flood risk, including groundwater flooding, is discussed in detail in Chapter 9 of the EIAR (Water).

### 2.7 LAND COVER AND LAND USE;

According to the Corine (2018) Land cover map shown in Figure F-1 in Appendix F, the surrounding landscape of the Proposed Wind Farm site comprises peat bog, pastures and mixed agriculture. Land use within the Proposed Wind Farm site is mixed, with peat cutting and agricultural land dominating.





## 3 KARST FEATURE DATABASE

The following resources were used to develop a preliminary database of karst features for the Proposed Wind Farm site, with all features identified within a 1km buffer of the Proposed Wind Farm site EIAR boundary recorded:

- The GSI Karst Feature Database;
- Anomalies recorded based on aerial and historic mapping, including:
  - Bing Aerial Imagery (2025);
  - Google Earth Multitemporal Aerial Imagery (2009-2025);
  - Ordnance Survey Ireland Orthophoto (OSI, 1995-2013);
  - OSI 6-inch and 25-inch historic base mapping; and
  - Changes in topography based on the available detailed topographic LiDAR survey (DTM Bluesky, 2022);
- Additional surface features noted during site walkovers in August and November 2024

A total of 41 potential karst features have been identified within 1km of the Proposed Wind Farm site boundary, of which 13 are located within the EIAR boundary, and 11 of these have been visually inspected on site. The vast majority of identified features are classified as enclosed depressions/dolines, with two possible spring features identified at the Derrynacrick loughs. A full summary of the identified features is included in Appendix G.1, and the location of all identified features is shown in Figure G-1 in Appendix G. The GSI karst database was considered first, with the additional data sources used to sense check and to identify additional features.

Karst feature K6 provides an example of the doline features identified within the Proposed Wind Farm site boundary. This feature was identified from aerial imagery (Figure 3-1) and LiDAR (Figure 3-2), investigated and confirmed on-site (Figure 3-3).








Figure 3-1: Karst feature K6 (Bing aerial, 2025).




Figure 3-2: Karst feature K6 (LiDAR DTM Hillshade; Bluesky, 2022).







Figure 3-3: Karst feature K6





## 4 GROUND INVESTIGATION

#### 4.1 SITE RECONNAISSANCE

GDG and MKO conducted preliminary ground investigation (GI) and site reconnaissance in the form of peat probes (PP), hand shear vanes (HSV), boreholes (BH) and trial pits (TP) between 2021 and 2025. Site reconnaissance included site walkovers by a chartered geologist to record potential karst features and to ground truth features identified from aerial imagery. The walkover inspections and GI campaign were carried out across the Proposed Wind Farm site. Access was limited to some areas, limiting the number of karst features which could be ground-truthed by site inspection.

A number of potential karst features were identified from aerial imagery and confirmed by visual inspection on-site. Two site walkovers targeted at identifying potential karst features were carried out by GDG:

- 27-28<sup>th</sup> August 2024; and
- 1<sup>st</sup> November 2024

#### 4.2 GROUND INVESTIGATIONS

Seven project-specific ground investigations (GI) were carried out at the Proposed Wind Farm site:

- 1) MKO (October 2021-July 2022): 60 no. peat probes
- 2) GDG (August 2022): 35 no. peat probes and 11 no. trial pits.
- 3) Petersen Drilling Services Ltd. (August 2022): Two Rotary Core Boreholes (open hole well boreholes)
- 4) GDG (August 2024): 160 no. peat probes.
- 5) GDG (November 2024): 59 no. peat probes and two hand shear vanes.
- 6) GDG (February 2025): 15 no. trial pits with hand shear vanes, and associated lab testing, including:
  - a) 25 no. Atterberg limit tests
  - b) 28 no. Moisture Content tests
  - c) 26 no. Particle size distribution tests
- 7) Minerex Geophysics Limited (August 2025): Geophysical survey including 4no. Electrical Resistivity Tomography (ERT) Lines (3m electrode spacing, total length 498m) and 1no. Seismic Refraction (P-Wave) Survey (69m).

In summary, intrusive ground investigations were carried out at 344 locations, of which 26 were trial pits, and two were open-hole drilled well boreholes. A map illustrating the available trial pit and borehole locations is included in Figure G-2 in Appendix G. Further information on the peat probing campaign is available in the Peat Stability Risk Assessment in Technical Appendix 8-2 of this EIAR





(GDG, 2025). A geophysical survey was carried out by Minerex in August 2025, targeting suspected karst features in close proximity to a section of access track to the north of T4.

#### 4.3 PRELIMINARY GROUND MODEL

A preliminary ground model based on the available GI is presented in Table 4-1. This is a preliminary interpretation of the available trial pit data, and a detailed ground model will be produced following the completion of a detailed ground investigation. The ground conditions are generally variable across the Proposed Wind Farm site, and comprise Peat, Lacustrine Marl (CLAY/SILT), Cohesive Glacial Till (CLAY/SILT) and Granular Glacial Till (SAND/GRAVEL) layers overlying limestone bedrock. Soft lacustrine marls are encountered underlying the peat in some locations (particularly evident in the vicinity of T9). Topsoil has been encountered across the Proposed Wind Farm site in varying thicknesses. Minimum thicknesses of 0m indicate that the unit has not been encountered in all available GI locations.

Table 4-1: Summary of ground conditions

Strata	Typical Description	Thickness (m)			Depth to top (m BGL)
		Min.	Max.	Median	
Peat		0	7.1	0.4	0
Lacustrine Marl (CLAY/SILT)*	Very soft, greyish white sandy CLAY/SILT.	0	2.7	0.7	0.3 – 3.3
Cohesive Glacial Till (CLAY/SILT)	Soft to very stiff, greyish brown, slightly sandy, slightly gravelly CLAY with low to medium cobble and boulder content.	0	Not proven	Not proven	0.1 – 1.1
Granular Glacial Till (SAND / GRAVEL)**	Sandy GRAVEL with high cobble and boulder content.	0	2.5	0.4-1.95	0.0 – 4.9
Limestone Bedrock**	Weak to strong dark grey LIMESTONE with occasional shaley mudstone layers. Weathered profile is occasionally observed in trial pits.	Not proven	Not proven	Not proven	0.8 – Not Proven

<sup>\*</sup>Soft lacustrine marl is only identified in TP06, TP07, TPBP3 and TPT9.

#### 4.4 GEOPHYSICAL SURVEY

As outlined in Section 4.2, a geophysical survey was carried out in August 2025 by Minerex Geophysics Limited. The full geophysical report is provided in Appendix G.5. This survey was targeted to assess potential karst features K01 and K02, which are located in close proximity to access track AL6, approximately 250m north of T4. The survey consisted of four total ERT lines (3m electrode spacing, total length 498m) and 1no. Seismic Refraction (P-Wave) Survey (total length 69m).

These surveys indicated three distinct layers at the surveyed locations:





- 1) Layer 1 (0- approximately 1.5m bgl). This layer displayed seismic velocities of 400m/s and is interpreted by Minerex as 'soil with a soft or loose stiffness or compaction'.
- 2) Layer 2 (~1.5-~7m bgl) an intermediate layer with a seismic velocity of 2200m/s between approximately 1.5m bgl and 7m bgl interpreted by Minerex as 'overburden with very stiff to hard or very dense strength or compaction or a very weathered rock with poor rock quality'.
- 3) Layer 3 competent bedrock, with a seismic velocity of 4000m/s

Minerex interprets Layer 1 and 2 as sandy gravelly clay and silt overlying well-consolidated glacial till/weathered bedrock. TP 11, carried out by GDG in February 2025, approximately 10m north of ERT line R4 along the R2 line, logged rockhead at 2.35m bgl. This indicates that Layer 2, interpreted by Minerex as very stiff glacial till/weathered bedrock, may most likely consist of weathered bedrock.

The Minerex survey concluded that karst features, or karstified bedrock, were not identified within the survey extents, but noted that potential occurrence of karst features further west cannot be excluded. Based on the available information provided by this survey, karst features K01 and K02 have been excluded from the assessment of karst features, and the Karst Risk Assessment updated accordingly.





## 5 KARST RISK ASSESSMENT

A Karst Risk Assessment (KRA) has been carried out across the Proposed Wind Farm site, considering the karst hazard probability and potential consequences at each infrastructure location, including turbine foundations, turbine hardstands, the substation/BESS compound, the temporary construction compound, the met mast, and the internal access tracks. Following the calculation of hazard and consequence, risk scores are presented in a geotechnical risk register in Appendix I.

#### 5.1 RISK DEFINITION

Risk is the potential or probability of adverse consequences, including economic losses, environmental or social harm, or detriment. Risk is expressed as the product of a hazard (e.g. karst features) and its adverse consequences (Lee & Jones, 2004; Corominas et al., 2014) (Eq. (5.1). Some use approximate synonyms and refer to risk as the product of the likelihood and the impact, or the product of susceptibility and the exposure.

Risk = (Hazard) x (Adverse Consequences) Eq. (5.1)

#### 5.2 GENERAL METHODS FOR RISK ASSESSMENT

There are various levels of risk assessment, ranging between:

- Detailed quantitative risk assessments (DQRA) where the objective is to generate more
  precise measures of the risks (e.g. expressing risk as a specific probability of loss). These
  require a large amount of quantitative input and time, and
- High-level qualitative assessments where the objective is to develop an approximate estimate of the risks, particularly in relative terms (e.g. low, medium, and high levels of risk).

In this assessment, a qualitative approach has been pursued to produce a high-level estimate of the karst risks associated with the Proposed Wind Farm. To apply Eq. (5.1) the factors that determine the hazard and the consequences need to be transformed into subjective ratings. The following sections address the calculation of the two risk components: hazard and consequence.

#### 5.3 HAZARD ASSESSMENT

The karst hazard assessment methodology is compiled by assessing geological attributes likely to give rise to karst hazards, such as the presence of existing or known karst features as determined from site observations, trial pits and other information sources.

The karst hazard has been based on an assessment of the following geological and evidence-based risks outlined in Table 5-1. This hazard assessment has been completed in the absence of confirmatory intrusive ground investigation (e.g. rotary boreholes) or geophysical investigation, and shall be revised accordingly by a suitably qualified geotechnical engineer following detailed ground investigation, at the detailed design stage. Rankings have been assigned to each of the parameters, and these have been multiplied together to form a karst hazard assessment matrix, to which ratings of negligible, low, medium, high and very high have been applied. A detailed description of the





scoring methodology for each contributing factor is given in Sections 5.4 and 5.5. The methodology is based on that proposed by Rutty and Jennings (2012).

Table 5-1: Hazard Assessment factor categories.

Hazard fa	actors	Description	Max Possible Score
	A. Underlying rock type	Susceptibility of the underlying bedrock to karstification.	2
	B. Proximity to mapped geological faults/boundaries	The geological structure of the bedrock can influence its susceptibility to karstification. Discontinuities such as faults, joints, or significant geological boundaries can initiate the formation of fissures, which can be exploited by water and begin the process of dissolution.	2
	C. Thickness of overburden cover	The thickness of overburden cover is considered to influence the distribution of karst features (Burke, 1998; Zhou et al., 2003). This is likely to be caused by a combination of factors, with existing features buried and obscured by the deposition of soil cover during the Quaternary. Thick soil cover may also protect the limestone and prolong the process of sinkhole formation.	3
Geological Factors	D. Overburden cover type	The material characteristics of the overburden cover can directly influence the likelihood and potential severity of karstic features for construction. This is because different soil types can directly influence the form of karstic features (particularly sinkholes/dolines/enclosed depressions) that may develop.	2
Geological Factor Total (AxBxCxD)			24
Evidence Factors	E. Density of identified karst features	A high density of karst features within 250m indicates that the development of karstic features at the location being assessed is more likely.	4





Hazard factors		Description	Max Possible Score
	F. Interaction with identified karst features	Karst features recorded as overlapping with the Proposed Development footprint pose a direct risk to the proposed infrastructure.	3
Evidence	Factor Total (ExF)	12	
Hazard Score Total (Geological x Evidence Factor Scores)			288

The hazard ratings adopted are outlined in Table 5-2.

**Table 5-2: Karst Hazard classes** 

Hazard Class	Rationale
Negligible	Site not underlain by karst-susceptible bedrock.
Low	Significant karst development is unlikely, and unstable ground and significant cavities are not anticipated. Mitigation measures are unlikely to be required.
Medium	Some karst development is possible, which may lead to unstable ground or cavities. Following inspection of formation levels, design mitigation measures may be required.
High	Karst development is likely and active unstable ground and cavities already exist or may exist.  Detailed assessment of the data, additional site investigation and geophysical surveying is recommended and mitigation is likely to be required.
Very High	Karst development is evident, and active unstable ground and cavities already exist or may exist.  Detailed assessment of the data, additional site investigation and geophysical surveying is required and mitigation is likely to be required.

This hazard rating score has been calculated and applied across the Proposed Wind Farm site, with a particular focus on the proposed infrastructure (including turbine) locations. The raster maps used in the site-wide calculations are shown in Figure H-1 to H-10 in Appendix H, and the infrastructure specific hazard matrix is shown in Appendix H.

Each calculated hazard class has been assigned a normalised hazard class score from 1 to 5. The hazard classes are summarised in Table 5-3.





Table 5-3: Hazard classification and description of hazard classes.

Hazard Score	Hazard Class	Description	Normalised Hazard Class Score
0	Negligible	Site not underlain by karst susceptible bedrock.	1
0-12	Low	Significant karst development is unlikely and unstable ground and significant cavities are not anticipated. Mitigation measures are unlikely to be required.	2
12-36	Medium	Some karst development is possible which may lead to unstable ground or cavities. Following inspection of formation levels, design mitigation measures may be required.	3
36-60	High	Karst development is likely and active unstable ground and cavities may exist.  Detailed assessment of the data, additional site investigation and geophysical surveying is recommended and mitigation is likely to be required.	4
>60	Very High	Karst development is evident, and active unstable ground and cavities already exist or may exist. Detailed assessment of the data, additional site investigation and geophysical surveying is required, and mitigation is likely to be required.	5





#### 5.4 GEOLOGICAL HAZARD RATING

The following sections outline the factors that were considered in order to classify the risk rating based on geological factors. The selection of these factors is based on previous assessments carried out on large infrastructure projects in Ireland (Rutty and Jennings, 2012; Madden and O'Hara, 2016).

#### 5.4.1 UNDERLYING ROCK TYPE

The nature of the underlying bedrock strongly influences its susceptibility to karstification. Siliceous or non-carbonate rocks are not susceptible to karstification. The chemical composition and the geological structure of limestone can impact the degree to which limestone is susceptible to karstification. Limestones are rocks which predominantly consist of calcium carbonate or magnesium carbonate (Dolomites). Pure limestone is almost pure carbonate, whereas impure limestone consists of portions of other materials, most commonly mud, shale and chert (Daly et al., 2005)

Pure limestones are more susceptible to karstification than impure limestones. The absence of clay minerals within the limestone beds makes these rocks more brittle than impure limestones, resulting in a high degree of fracturing and, consequently, permeability (Drew, 2018). In contrast, impure limestones tend to deform more readily, sealing up fractures and impeding water movement. It must be noted, however, that a substantial amount of non-carbonate material must exist in the rock to classify the limestone as impure.

The entirety of the Proposed Wind Farm site is mapped as being underlain by limestone bedrock, which is particularly prone to karstification. The rock is classified as pure bedded Dinantian Limestone of the Croghan Formation, Burren Formation, and Undifferentiated Viséan Limestone (likely Croghan Formation), as outlined in Sections 2.2 and 2.3.1. The bedrock-type geological hazard classes are outlined in Table 5-4. The classification is based on Rutty and Jennings (2012).

Table 5-4: Bedrock Type, significance and geological hazard score.

Bedrock Type	Significance	Geological Hazard Score
Pure Limestone	Pure limestones are considered susceptible to karstification.	2
Impure Limestone	Impure limestones are considered to be generally non-susceptible to karstification.	1
Non-Carbonate Rocks	Non-carbonate rocks are not susceptible to karstification. The absence of limestone excludes the risk assessment from progressing further.	0

As the entirety of the Proposed Wind Farm is underlain by pure limestones, all infrastructure is assigned a score of **2** (Figure H-1 in Appendix H).





#### 5.4.2 PROXIMITY TO FAULTS/GEOLOGICAL BOUNDARIES

The geological structure of the bedrock can influence its susceptibility to karstification. Discontinuities such as faults, joints, or significant geological boundaries can initiate the formation of fissures, which can be exploited by water and begin the process of dissolution. These features may be difficult to identify or locate with confidence. One factor which was used was the break in bedrock formation, as mapped by the GSI. However, due to the ambiguity in relation to the exact change in rock formation, a 100m buffer zone was implemented along the seamless formation break.

For the purposes of this KRA, a 100m buffer has been applied to all faults and formation changes mapped by the GSI. A score of 1 is assigned to any areas which fall outside of the 100m buffer for any formation change, while a score of 2 is applied to any area that falls within the 100m buffer (Table 5-5).

Table 5-5: Fault/Geological Boundary Class, significance and geological hazard score.

Bedrock Type	Significance	Geological Hazard Score
Areas within a 100m buffer of fault/formation change	Pure limestones are considered susceptible to karstification.	2
Areas outside of a 100m buffer of fault/formation change	Impure limestones are considered to be generally non-susceptible to karstification.	1

Bedrock geological boundaries between the Croghan Formation, Burren Formation and Undifferentiated Viséan Limestone Formation are mapped by the GSI in the northern part of the Proposed Wind Farm site (Figure H-2 in Appendix H); however, only T7 and portions of the adjacent access tracks fall within a 100m buffer of these boundaries.

#### 5.4.3 THICKNESS OF OVERBURDEN COVER

The thickness of overburden cover is considered to influence the distribution of karst features (Burke, 1999; Zhou et al., 2003). This is likely to be caused by a combination of factors, with existing features being buried and obscured by the deposition of soil cover during the Quaternary period. Thick soil cover may also protect the limestone and prolong the process of sinkhole formation. Based on this, it is generally considered that a thicker overburden cover will reduce the risk of karstic features. It is noted, however, that although very thick soils tend to preclude sinkhole development, it is very difficult to recognise an upper limit for cover thickness (Walthamet al. 2005). The thickness classes below are based on those found in Rutty and Jennings (2012). The hazard scoring for overburden thickness is outlined in Table 5-6.





Table 5-6: Overburden Thickness Class, significance and geological hazard score.

Overburden Thickness Class	Significance	Geological Hazard Score
0-5m Overburden Thickness	Thin overburden provides sufficient cover to bury some features but does not preclude their formation, and may be prone to collapse sinkholes.	3
5-10m Overburden Thickness	Thicker overburden provides greater cover to features and reduces the risk of encountering sinkholes or cavities during construction.	2
>10m Overburden Thickness	Significant thicknesses of overburden provide greater cover to features and reduce the risk of encountering sinkholes or cavities during construction.	1

Bedrock has not been proven at depths greater than 5m below ground level (bgl) in any trial pit or borehole location; however, peat probes have encountered peat/soft clay deposits of greater than 5m in thickness in some instances, particularly in the area between T5, T7, and T9. The hazard scores for overburden thickness are shown in Figure H-3 in Appendix H.

#### **5.4.4 OVERBURDEN COVER TYPE**

The material characteristics of the overburden cover can directly influence the likelihood and potential severity of karstic features for construction. This is because different soil types can directly influence the form of karstic features (particularly sinkholes/dolines/enclosed depressions) that may develop. Lei et al. (2001) suggest that soil type and structure may have a more direct influence on the formation of sinkholes than soil thickness.

Waltham et al. (2010) identify six main types of sinkholes (Section 1.4.2). Of these, three classes are assigned to sinkholes that form in soil cover:

- Dropout/Collapse Sinkholes Sudden cohesive soil collapse
- Suffosion/Subsidence Sinkhole Down-washing of granular soil into fissures within the bedrock
- Buried Sinkholes Soil-filled sinkholes in the rock after environmental change

Dropout/collapse sinkholes pose the greatest risk to construction, as these failures can occur rapidly and often with little to no warning (Waltham et al., 2010). Dropout sinkholes only occur in soils with sufficient cohesion to bridge a cavity or void for long enough to allow a significant subsurface cavity to grow before sudden roof collapse. In granular soils with little or no cohesion, suffusion/subsidence sinkholes occur instead, with material gradually downwashed into the developing cavities.





Buried sinkholes may be covered by either cohesive or granular soils, as the deposition of the soils occurs following the formation of the sinkhole. Due to the increased risk inherent in cohesive overburden cover, the scores outlined in Table 5-7 have been applied for the KRA. These scores are based on a similar approach set out by Rutty and Jennings (2012).

For this KRA, it has been considered that where overburden thickness is less than 1m, any surface karst features will likely be readily apparent or identifiable during topsoil stripping, minimising the risk of sudden collapse sinkhole events. The overburden-type class scoring is outlined in Table 5-7.

Table 5-7: Overburden Type Class, significance and geological hazard score.

Overburden Type Class	Significance	Geological Hazard Score
Cohesive overburden deposits (e.g. cohesive glacial till)	Increased risk of potentially unidentified collapse sinkhole features.	2
Granular overburden deposits (e.g. sands and gravels)	Low risk of collapse sinkhole features. Suffosion features are more likely.	1
Peat	Low risk of collapse sinkhole features. Subsidence features are more likely.	1
Overburden <1m in thickness	For this KRA, it has been considered that where overburden thickness is less than 1m, any surface karst features will likely be readily apparent or identifiable during topsoil stripping, minimising the risk of sudden collapse sinkhole events.	1

The Proposed Wind Farm site is split relatively evenly between areas mapped by the GSI as consisting of peat and areas mapped as till. Turbines e.g. T1, T3, T4, T6 and T8 are mapped as till, with T2, T5, T7 and T9 mapped as peat. Localised areas of <1m of overburden are identified from trial pits close to T1 and at the substation. The overburden-type hazard scores for the Proposed Wind Farm site are shown in Figure H-4 in Appendix H.

#### 5.5 EVIDENCE-BASED HAZARD RATING

The following sections outline the factors considered in classifying the rating based on karst evidence.

#### 5.5.1 DENSITY OF IDENTIFIED KARST FEATURES

As outlined in Section 3, 43 potential karstic features have been identified within a 1km buffer of the Proposed Wind Farm site. The number of identified karst features within 250m of each pixel has been determined using ArcGIS Pro, and score classes assigned (Table 5-8). For infrastructure-specific analysis, the number of karst features within a 250m buffer of each infrastructure location has been





considered. A 250m buffer has been used for this analysis as this is considered to provide a localised yet sufficiently broad spatial context to capture nearby karst features that may pose indirect or cumulative risks to infrastructure. A high density of karst features within 250m indicates that the development of karstic features at the location being assessed is more likely.

Table 5-8: Karst Feature Density Class, significance and evidence score.

Karst Feature Density Class	Significance	Evidence Score
>4 Features within 250m	The greatest assigned risk of encountering karstic features within the footprint of infrastructure.	4
3-4 Features within 250m	Increased risk of encountering karstic features within the footprint of infrastructure.	3
1-2 Features within 250m	Lower risk of encountering karstic features within the footprint of infrastructure.	2
0 Features within 250m	Lowest assigned risk of encountering karstic features within the footprint of infrastructure.	1

Karst features were identified within 250m of T1, T2 hardstand, T4, T5 hardstand, T8 handstand, and various sections of access track alignment. The highest density of karst features was recorded in the area surrounding T4 and access track alignment AL6, with >4 features recorded within 250m of these locations (12 features are recorded within 250m of T4). The karst feature density scores are shown in Figure H-5 in Appendix H.

### 5.5.2 INTERACTION WITH IDENTIFIED KARST FEATURES

Due to the fixed nature of the proposed infrastructure, the most direct risk factor is the potential for karstic features to interact directly with the proposed infrastructure during construction of the Proposed Wind Farm. Although surface features in the surrounding area can indicate the level of karstification in the bedrock, these do not pose a direct risk to the Proposed Wind Farm, unlike those recorded within the Proposed Wind Farm footprint itself. To quantify the risk, the scores outlined in Table 5-9 have been applied to each infrastructure location (turbine foundations, turbine hardstands, substation/BESS compound, temporary construction compound, met mast and new internal access tracks). To visualise this in a map format, a 10m buffer was applied to all identified karst features. Areas within the 10m buffer were classed as being within karst features.





Table 5-9: Karst Feature Interaction Class, significance and evidence score.

Karst Feature Interaction Class	Significance	Evidence Score
Karst feature recorded within the infrastructure location.	The presence of identified karst features within infrastructure locations indicates that karst features may pose a risk during construction.	3
Karst features are absent within the infrastructure location	The absence of identified karst features within infrastructure locations indicates that karst features may pose a reduced risk during construction.	1

Identified karst features were found to overlap with the Proposed Wind Farm infrastructure in one location at access track alignment AL6. Geophysical surveying carried out in August 2025 (Section 4.4) found no evidence for large karstic cavities beneath the AL6 alignment, at the K01 and K02 locations. As a result, these features were removed from the Karst Interaction scoring.

Identified features were located at a distance of >10m from all other proposed infrastructure locations. The karst feature interaction scores are shown in Figure H-5 in Appendix H-6.

### 5.6 HAZARD ASSESSMENT RESULTS

As outlined in Section 5.3, an overall hazard score has been calculated by multiplying the geological hazard score and the evidence-based hazard score. The site-wide hazard calculation is presented in Figure H-7 in Appendix H. A summary of the hazard score calculated at each proposed infrastructure element is outlined in Figure 5-1 to Figure 5-2. The full risk matrix at each location is included in Appendix H.








Figure 5-1: Karst hazard at each turbine location.




Figure 5-2: Karst hazard at each infrastructure location.





The normalised hazard rating across the Proposed Wind Farm site is shown in Figure H-8 in Appendix H. The identified karst risk at the Proposed Wind Farm site is generally classed as low; however, portions of the Proposed Wind Farm site, particularly in the vicinity of T1 and T8, are classified as medium hazard. A portion of the centre of the Proposed Wind Farm site, in the vicinity of T4, is calculated to have a high hazard rating, with small, localised areas of very high hazard rating identified at specific karst features, primarily in the area surrounding T4. A detailed view of the karst hazard at T4 is shown in Figure H-9 in Appendix H. Areas identified as being of very high karst hazard within the Proposed Wind Farm site do not interact with any of the proposed infrastructure footprint.

### 5.7 ADVERSE CONSEQUENCES ASSESSMENT

The adverse consequences assessment has been compiled based on the criteria outlined in Table 5-10. This scoring system has been applied at all infrastructure locations and is presented in the Geotechnical Karst Risk Register in Appendix I. For each infrastructure location, a series of potential risks are identified (e.g. collapse of dolines, subsidence over buried or suffosion dolines, leading to differential settlement at turbine foundations). For each risk, an adverse consequence score is applied.

It is recommended that the consequence assessment be revised and updated at the detailed design stage by a suitably qualified Geotechnical Engineer as new consequences are identified and development timelines and costs are finalised.





## Table 5-10: Adverse consequences assessment scoring.

Description	Project Time Impact	Project Cost Impact	Environmental Impact	Health and Safety Impact	Adverse Consequence Score
Negligible	Negligible	Negligible	Negligible	Injuries requiring first aid treatment or occupational ill-health conditions with no lost time	1
Low	Low	Low	Low	Lost Time Injury (<7 days lost time); or multiple minor injuries; or Occupational Health Condition (<7 days lost time)	2
Medium	Medium	Medium	Medium	Reportable injury or Occupational Health Condition (>=7 days lost time)	3
High	High	High	High	Single non-life changing injury, occupational health condition (>=14 days lost time)	4
Very High	Very High	Very High	Very High	One or more fatalities or major injuries or occupational health conditions resulting in life life-changing disability.	5





Table 5-11: Adverse consequence scores.

Karst Hazard	Description	Engineering Risk	Infrastructure Elements Affected	Adverse Consequence Score (1-5)
Rapid Collapse of Doline	Sudden collapse of a sinkhole.	Immediate and severe ground collapse.	Access tracks, turbine hardstands, turbine foundations, substation/BESS compound, met mast	5
Subsidence Dolines	Gradual settlement into underlying voids.	Progressive settlement and deformation.	Access tracks, turbine hardstands, turbine foundations, substation/BESS compound, met mast	4 (turbine foundations), 3 at other infrastructure locations
Cavities / Voids	Subsurface voids formed by dissolution.	Foundation failure or differential settlement.	Turbine foundations, substation/BESS compound, met mast	3 (turbine foundations), 2 at other infrastructure locations
Variable Rockhead	Irregular rockhead profiles due to dissolution.	Uneven bearing capacity and excavation difficulty.	All infrastructure elements	3 (turbine foundations), 2 at other infrastructure locations
Solutionally Weathered Rock	Deeply weathered limestone with voids and softened zones.	Excavation instability and reduced bearing capacity.	Turbine foundations, access tracks, cable trenches	3 (turbine foundations), 2 at other infrastructure locations

### 5.8 RISK ASSESSMENT

Following the calculation of the hazard and adverse consequence scores at each location, for the individual identified risks, Eq. (5.1) is applied (Section 5.1) to calculate an overall risk score prior to the implementation of mitigation measures. The calculated risk scores are classified following the risk matrix illustrated in Figure 5-3.





		Description	Hazard Score				
		Description	Negligible	Low	Medium	High	Very High
Description			1	2	3	4	5
Adverse Consequence Score	Very High	5	5	10	15	20	25
	High	4	4	8	12	16	20
	Medium	3	3	6	9	12	15
	Low	2	2	4	6	8	10
	Very Low	1	1	2	3	4	5

Figure 5-3: Risk matrix for karst risk assessment.

The risk matrix allows for risk scores to be classified into four risk classes, as outlined in Table 5-12.

Table 5-12: Karst risk classes

Score	Risk Level	Suggested Actions
20-25	Very High	Detailed assessment of the data, additional site investigation and geophysical surveying are recommended and mitigation will be required.
10-19	High	Detailed assessment of the data, additional site investigation, and geophysical surveying is required and mitigation is likely to be required.
4-9	Medium	Additional detailed ground investigation, including geophysical surveying recommended; design mitigation measures may be required.
1-3	Low	Standard detailed ground investigation should proceed. Mitigation measures are unlikely to be required.

The risk classes identified are compiled in the Geotechnical Karst Risk Register in Appendix I. Geophysical surveying carried out in August 2025 (Section 4.4) found no evidence for large karstic cavities beneath the AL6 alignment, at the K01 and K02 locations. As a result, a slight reduction in hazard score was applied at this location in the risk assessment, as noted in Appendix I.





### 6 MITIGATION MEASURES

The findings of the karst risk assessment, as outlined in Section 5.6, indicate that the majority of the Proposed Wind Farm site can be classed as having a low to medium karst risk. In these locations, it is considered that significant karst development is unlikely and unstable ground and significant cavities are not anticipated. All proposed infrastructure has been sited to avoid areas of very high karst hazard. Mitigation measures are not envisaged based on the available information, but the risk of encountering a karst feature is not negligible.

Despite this, all earthworks will be designed by a suitably qualified Geotechnical Engineer during the detailed design stage and informed by a post-consent detailed confirmatory ground investigation (GI) campaign. This investigation will include intrusive methods, such as trial pitting and borehole drilling, with a specified suite of in-situ and geotechnical laboratory testing to further assess the engineering characteristics of the infrastructure locations. Possible mitigation measures in relation to peat instability are considered below. Geophysical surveying is recommended to assist in the identification of any potential karstic voids not identified in this assessment.

Portions of the central areas of the Proposed Wind Farm site (particularly the areas in the vicinity of T4) have been classed as having high karst hazard, with some localised areas being classed as very high hazard. In these locations, high to very-high karst risk scores have been calculated in the most onerous cases, prior to mitigation. In these areas, additional site investigations and mitigation measures may be required. Recommendations for additional ground investigation and potential mitigation measures are considered below.

#### 6.1 ADDITIONAL GROUND INVESTIGATION

To reduce the potential risk of encountering unexpected karstic features within the Proposed Wind Farm footprint, the following additional ground investigation works are to be carried out at infrastructure locations identified as having medium or high karst risk:

- Rotary core boreholes to confirm rockhead depth and quality.
- Geophysical Surveying to detect voids and solution features, including:
  - Electrical Resistivity Tomography (ERT)
  - Ground Penetrating Radar (GPR)
  - Microgravity; and
  - Seismic Refraction
- Trial pits and dynamic probing to assess near-surface variability and collapse-prone soils.

### **6.2 ENGINEERING MITIGATION MEASURES**

Should the additional grounds investigation identify interactions between the Proposed Wind Farm infrastructure footprint and karstic features, where avoidance is not feasible, a suite of engineering





solutions will be implemented as appropriate to ensure structural integrity and long-term performance.

#### 6.2.1 PILED FOUNDATIONS

Where small-scale dissolution and voiding are encountered at turbine foundations during detailed ground investigation, one potential mitigation strategy is the use of drilled or grouted piles. The use of piles transfers structural loads to competent rock beneath karst-affected zones. This approach bypasses voids and weak soils, reducing the risk of differential settlement or collapse.

Waltham (2009) notes that driven piles may lose integrity where they bear on rock over a cave, are bent due to meeting a pinnacle rockhead, or are founded on loose blocks ('floaters') or unstable pinnacles within the soil. It is therefore recommended that drilled/bored or grouted piles be used.

#### 6.2.2 ROCK INFILL

Waltham et al. (2005) and De Bruyn and Bell (2001) outline an approach for the remediation of shallow sinkhole features that are a few metres deep. This methodology involves 'choking' the throat of the sinkhole with coarse granular fill, and progressive backfilling upwards with progressively finer granular fill. All backfill is to be placed in layers 150mm deep and compacted. Soil around the sinkhole is to be excavated to a radius of 3-5m, before being replaced and compacted with or without incorporation of anchored geogrid. This methodology has been used effectively on Irish road projects in similar karst terrains in East Galway (Madden and O'Hara, 2016). An example standard detail is shown in Figure 6-1. This methodology is applicable to the Proposed Wind Farm site access tracks, and shall be implemented if small scale sinkhole features (<5m in depth) are encountered beneath access tracks.




Figure 6-1: Example of rock infill to remediate small-scale karst sinkholes in Ireland (Madden and O'Hara, 2016).

#### 6.2.3 GROUTING

Pressure grouting can be employed to stiffen soil over limestone and prevent its suffosion into fissures, to fill localised fissures, and to stabilise fractured rock. It is worth noting that the injection





of a fluid grout can result in significant losses into adjacent caves before sealing karstic fissures. The detailed designer/contractor shall consider which grouting method would be most appropriate and the potential negative consequences for contamination and pollution of the aquifer.

### 6.2.4 BRIDGING LAYERS AND GEOGRID BLANKETS

One of the most effective and widely adopted engineering solutions to mitigate the risks of unacceptable settlement and unexpected collapse at access tracks is the use of bridging layers reinforced with geogrids.

Bridging layers are designed to span across potential voids or weak zones, redistributing loads and preventing localised collapse. When combined with geogrid reinforcement, these layers gain enhanced tensile strength and load-spreading capacity, allowing them to maintain structural integrity even in the event of subsurface failure.

Geogrids are polymeric materials with a grid-like structure that interlock with the surrounding aggregate. When embedded within a granular fill layer, they:

- Improve load distribution across voids or soft spots.
- Increase the factor of safety against collapse.
- Reduce differential settlement and rutting.
- Enhance the resilience of road and platform structures under dynamic loads (e.g., turbine transport or crane operations).

A 2021 study by Conrado-Palafox et al. demonstrated through finite element modelling that geogrid-reinforced road structures in karst terrain significantly improved performance, even in the presence of up to 19 subsurface cavities. The study found that embedding the geogrid between the subgrade and base layer increased the factor of safety and reduced deformation under heavy truck loads.

Where construction takes place in areas of high or very high karst hazard, and if karstic features are identified elsewhere during construction, the following measures shall be implemented:

- Access tracks will incorporate geogrid-reinforced bridging layers over areas identified as having potential voids or collapse-prone soils.
- Crane hardstands will be designed with enhanced bridging layers to accommodate high point loads and dynamic stresses.

### 6.2.5 DRAINAGE CONTROL

Drainage control is identified by Waltham (2009) as the single most important mitigation measure. Surface and subsurface drainage systems will be designed to prevent water ingress into karst features, reducing the potential for solutional enlargement and subsidence. This includes the installation of sub-drainage systems, the use of impermeable liners or membranes, and pumping and dewatering during construction. Uncontrolled lowering of the water table during construction can lead to sinkhole collapse or the initiation of new sinkholes (Waltham et al., 2005).





Proper drainage control is therefore essential to maintain the stability of foundations and prevent erosion of fill materials. All works will be supervised by a suitably qualified geotechnical engineer or hydrogeologist.

### 6.2.6 MONITORING AND MAINTENANCE

A post-construction monitoring plan will be implemented, including periodic visual inspections, settlement monitoring, and geophysical re-surveys where necessary. This proactive approach ensures that any emerging issues are detected and addressed promptly, maintaining the long-term integrity of the wind farm infrastructure.

#### 6.3 MITIGATION BY AVOIDANCE

All proposed infrastructure has been sited to avoid areas of very high karst hazard. Following additional detailed ground investigation works, if engineering mitigation measures outlined in Section 6.2 are not considered feasible, it is recommended that infrastructure elements (in particular turbine foundations) that are identified to interact with large karst features, such as dolines of subsurface cavities, be micro-sited and that any future development layout iterations avoid areas of identified very high hazard rating.

Avoidance is considered the most effective and least intrusive mitigation strategy.

### 6.4 RESIDUAL RISK

Following the implementation of the mitigation measures outlined in Section 6, the risk scores generated in Section 5.8 have been updated to reflect the residual risk score. The residual risks are included in the Geotechnical Karst Risk Register in Appendix I. Following the implementation of mitigation measures, the residual risk at each infrastructure location ranges from low to medium.





## 7 DESIGN RISK ASSESSMENT

The register included in Table 7-1 lists significant potential karst geotechnical hazards and associated risks concerning the Proposed Wind Farm, and recommended mitigations. Following the implementation of mitigation measures, the residual risk at each infrastructure location ranges from low to medium.

Table 7-1: Design Risk Assessment

Ref.	Risk	Contributing factor	Mitigation
1	Incomplete understanding of karst features	Limited intrusive ground investigations at depth, limited to trial pits and two well boreholes.	The GI completed to date is considered to be thorough and robust for the purposes of the EIAR. Detailed ground investigations, including rotary boreholes, laboratory testing and geophysical surveying, will be carried out at the detailed design phase to inform detailed design and mitigation measures. This karst risk assessment is to be updated when additional GI data becomes available.
2	Uncertainty in the lateral extent of karst features	Karst features identified from aerial imagery/site walkovers. Lack of geophysical surveying.	Following the completion of geophysical surveying at the key infrastructure locations, detailed mapping of subsurface features can be completed to further constrain areas of potential karst risk.
3	Potential for undetected near-surface voids or dissolution channels	Karst features identified from aerial imagery/site walkovers. Lack of geophysical surveying	Assessment of satellite imagery and topographical data for evidence of karst features was carried out as part of the desk study, in addition to site walkovers.  During the site walkovers, the site GDG engineers examined the landscape and the areas surrounding the identified karst features and proposed infrastructure locations.  Some karst features at the surface may not have been identified. It is noted that the geomorphological features associated with dolines and other karst features are softened with time through erosion, drying, and re-vegetation.  Access was limited to some areas of the Proposed Wind Farm site with restrictions relating to raised peat bogs traversed by large drainage ditches. Further inspection will be required during the detailed design stage to inspect for karst features. This will be carried out by the Contractors team. The design team will develop their own inspection and testing criteria to satisfy and de-risk the possibility of karst risk at these locations.
4	Potential for undetected subsurface voids or dissolution channels	Karst features identified from aerial imagery/site walkovers. Lack of geophysical surveying	Assessment of satellite imagery and topographical data for evidence of karst features was carried out as part of the desk study, in addition to site walkovers.  During the site walkovers, the site GDG engineers examined the landscape and the areas surrounding the identified karst features and proposed infrastructure locations.





Ref.	Risk	Contributing factor	Mitigation
			Features at depth within the bedrock, or buried beneath overburden cover, may not have been identified, as these features may not be apparent at the surface. Detailed GI, including rotary core boreholes and geophysical surveying, must be carried out to identify and reduce the risk of subsurface cavities.
5	Misidentification of karst features	Karst features identified from aerial imagery/site walkovers. Lack of geophysical surveying	Assessment of satellite imagery and topographical data for evidence of karst features was carried out as part of the desk study, in addition to site walkovers.  During the site walkovers, the site GDG engineers examined the landscape and the areas surrounding the identified karst features and proposed infrastructure locations.  Some features identified as karst features from the available desk study information and site walkovers may be caused by other geomorphological phenomena (e.g. periglacial features, surface hydrology, anthropomorphic modification of the landscape). A conservative identification approach has been adopted whereby all visible features of uncertain origin have been assumed as karstic for the purposes of risk assessment, until proven otherwise. Detailed ground investigation will be required to ground-truth identified features.





## 8 CONCLUSIONS AND RECOMMENDATIONS

The assessment findings showed that the majority of the proposed infrastructure locations are located in areas of low to medium karst hazard, with localised areas of high and very high hazard identified. One turbine (T4) was identified as being located in an area of high karst hazard, with a section of access track immediately north of T4 also identified as having a high karst hazard. The karst risk assessment shows that the risk at each infrastructure location ranges from medium to very high (at T4) prior to the application of mitigation measures.

Following the implementation of mitigation measures, the residual risk at each infrastructure location ranges from low to medium, indicating that development can proceed as long as mitigation measures are implemented and that the risk assessment is further refined following further confirmatory ground investigation.





## REFERENCES

Burke A.M. (1998) *Assessing Karstification in Ireland*. Unpublished (Research) MSc. Thesis, Department of Geography, Trinity College Dublin.

Conrado-Palafox, A. L., Equihua-Anguiano, L. N., & Hernández-Hernández, V. A. (2021). Numerical evaluation for roads considering the addition of geogrids in karst geohazards zones. Infrastructures, 6(9), 120.

Copernicus Land Monitoring Service. (2018). *CORINE Land Cover 2018 (vector), Europe, 6-yearly* [Data set]. European Environment Agency. https://doi.org/10.2909/71c95a07-e296-44fc-b22b-415f42acfdf0

Corominas, J., van Westen, C., Frattini, P., Cascini, L., Malet, J.-P., Fotopoulou, S., ... others. (2014). Recommendations for the quantitative analysis of landslide risk. *Bulletin of Engineering Geology and the Environment*, 73(2), 209–263.

Coxon, C. E. (1987). The spatial distribution of turloughs. Irish Geography, 20(1), 11-23.

Daly, D., Drew, D., Deakin, J., Ball, D., Parkes, M., & Wright, G. (2005). The Karst of Ireland Booklet. Geological Society of Ireland. Karst Working Group.

De Bruyn, I. A., & Bell, F. G. (2001). The occurrence of sinkholes and subsidence depressions in the Far West Rand and Gauteng Province, South Africa, and their engineering implications. *Environmental & Engineering Geoscience*, 7(3), 281-295.

Drew, D. (2018) Karst of Ireland: Landscape Hydrogeology Methods. Published by Geological Survey Ireland.

Ford, D., & Williams, P. D. (2007). Karst hydrogeology and geomorphology. John Wiley & Sons.

Gutiérrez, F. (2010). 13 Hazards associated with karst. *Geomorphological hazards and disaster prevention*, 161.

Geological Survey Ireland. (2004) Clare-Corrib Groundwater Body: Summary of Initial Characterisation (1st Draft, July 2004).

Geological Survey Ireland. (2025). *GSI Map Viewer*. Retrieved June 16, 2025, from <a href="https://www.gsi.ieGoogle">https://www.gsi.ieGoogle</a>

Google Earth. (2025). *Imagery of [insert location]*. Imagery sources: Maxar Technologies, CNES/Airbus, Landsat/Copernicus, U.S. Geological Survey. Retrieved June 16, 2025, from https://earth.google.com

Lee, E. M., & Jones, D. K. C. (2004). Landslide risk assessment. Thomas Telford London.

Lei, M., Jiang, X., & Yu, L. (2001). New Advances of Karst Collapse Research in China. In B. Beck, & J. Herring, Geotechnical and Environmental Applications of Karst Geology and Hydrology (pp. 145-151). Balkema: Lisse.





Madden, E, & O'Hara, D (2016). The treatment of karst features encountered during road construction in County Galway. Civil Engineering Research in Ireland 2016 – 169.

Microsoft Corporation. (2025). *Bing Maps Aerial Imagery*. Retrieved June 16, 2025, from https://www.bing.com/maps

Ordnance Survey Ireland. (2025). *GeoHive Map Viewer*. Retrieved June 16, 2025, from https://www.geohive.iePracht, M., Somerville, I. D., & Wang, Y. (2015). A revised Mississippian lithostratigraphy of County Galway (western Ireland) with an analysis of carbonate lithofacies, biostratigraphy, depositional environments and palaeogeographic reconstructions utilising new borehole data. *Journal of Palaeogeography*, *4*(1), 1-26.

Rutty P. and Jennings P. (2012) *Investigation, Design and Construction in Karst. Geotechnics on Irish Roads, 2000–2010, A Decade of Achievement*. Conference 11th October, 2012. Engineers Ireland.

Skeffington, M. S., & Gormally, M. (2007). Turloughs: a mosaic of biodiversity and management systems unique to Ireland. *Acta Carsologica*, *36*(2).

Waltham, T. (2009). Foundations of Engineering Geology 3<sup>rd</sup> Edition. CRC press.

Waltham, A. C., & Fookes, P. G. (2003). Engineering classification of karst ground conditions. Quarterly Journal of Engineering Geology and Hydrogeology, 36(2), 101-118.


Waltham, T., Bell, F., & Culshaw, M. S. (2005). Subsidence. Karst and Cavernous Rocks in Engineering and Construction.

Zhou, W., Beck, B. F., & Adams, A. L. (2003). Sinkhole risk assessment along highway I-70 near Frederick, Maryland. In *Sinkholes and the Engineering and Environmental Impacts of Karst* (pp. 591-604).






# **APPENDIX A SITE LAYOUT**








# **APPENDIX B GEOLOGY**














# **APPENDIX C HYDROGEOLOGY**

















# **APPENDIX D TOPOGRAPHY**











# **APPENDIX E HYDROLOGY**










# **APPENDIX F LANDCOVER**







## APPENDIX G SITE RECONNAISANCE AND GROUND INVESTIGATION

## **G.1** KARST DATABASE

Table G-1: Site Reconnaissance at Karst feature K1










Table G-2: Site Reconnaissance at Karst feature K2

Feature ID	К2
Feature Type	Enclosed Depression















Table G-3: Site Reconnaissance at Karst feature K3

Feature ID	кз
Feature Type	Enclosed Depression
Coordinates	E:556152, N:748761
Source	Aerial Imagery/Site Observation
Imagery	DTM:














Table G-4: Site Reconnaissance at Karst feature K4









Table G-5: Site Reconnaissance at Karst feature K5

Feature ID	K5
Feature Type	Enclosed Depression
Coordinates	E:556078, N:748728














Table G-6: Site Reconnaissance at Karst feature K6

Feature Type		Table 4-6. Site Recommissance at Raist leature Ro
Coordinates E:556042, N:748882 Source Aerial Imagery/Site Observation Imagery  DTM:  DTTM:  DTTM:	Feature ID	К6
Source Aerial Imagery/Site Observation  Imagery  DTM:  DTM: DTM:	Feature Type	Enclosed Depression
Imagery DTM:  DTM: DTM:	Coordinates	E:556042, N:748882
0 10 20 m	Source	Aerial Imagery/Site Observation
	Imagery	
Bing Aerial:		0 10 20 m
		Bing Aerial:













Table G-7: Site Reconnaissance at Karst feature K7











Table G-8: Site Reconnaissance at Karst feature K8

Feature ID	К8
Feature Type	Enclosed Depression
Coordinates	E:555871, N:748914











Feature ID	K8
Water Presence	Possible
Additional Information	N/A
Site Photos	N/A

Table G-9: Site Reconnaissance at Karst feature K9











Table G-10: Site Reconnaissance at Karst feature K10

Feature ID	K10
Feature Type	Enclosed Depression
Coordinates	E:555953, N:748671
Source	Aerial Imagery












Feature ID	K10
Additional Information	N/A
Site Photos	N/A

Table G-11: Site Reconnaissance at Karst feature K11










Table G-12: Site Reconnaissance at Karst feature K12

Feature ID	K12
Feature Type	Enclosed Depression
Coordinates	E:556554, N:748717
Source	Aerial Imagery
Imagery	DTM: N/A
	Bing Aerial:








Table G-13: Site Reconnaissance at Karst feature K13

Feature ID	К13
Feature Type	Enclosed Depression
Coordinates	E:556464, N:748669
Source	Aerial Imagery
Imagery	DTM: N/A
	Bing Aerial:








Table G-14: Site Reconnaissance at Karst feature K14

Feature ID	K14
Feature Type	Enclosed Depression
Coordinates	E:556351, N:748726
Source	Aerial Imagery
Imagery	DTM:













Feature ID	K14
Additional Information	N/A
Site Photos	N/A

Table G-15: Site Reconnaissance at Karst feature K15









**Table G-16: Site Reconnaissance at Karst feature K16** 

Feature ID	K16
Feature Type	Enclosed Depression
Coordinates	E:556060, N:748231
Source	GSI
Imagery	DTM:











Feature ID	K16
Additional Information	Described by GSI as an enclosed depression, however, this feature appears to hold significant amounts of water, and is recorded in the GSI historic groundwater flooding database. It is therefore considered as a possible turlough.
Site Photos	N/A

Table G-17: Site Reconnaissance at Karst feature K17




Table G-18: Site Reconnaissance at Karst feature K18

Feature ID	K18
Feature Type	Enclosed Depression
Coordinates	E:556149, N:748243
Source	GSI
Imagery	DTM:












Feature ID	K18
Additional Information	N/A
Site Photos	N/A

**Table G-19: Site Reconnaissance at Karst feature K19** 









**Table G-20: Site Reconnaissance at Karst feature K20** 

Feature ID	K20
Feature Type	Enclosed Depression
Coordinates	E:556176, N:748091
Source	Aerial Imagery
Imagery	DTM: N/A
	Bing Aerial:








Table G-21: Site Reconnaissance at Karst feature K21

Feature ID	K21
Feature Type	Enclosed Depression
Coordinates	E:556118, N:748053
Source	Aerial Imagery
Imagery	DTM: N/A
	Bing Aerial:









Table G-22: Site Reconnaissance at Karst feature K22

Feature ID	K22
Feature Type	Enclosed Depression
Coordinates	E:556616, N:748004
Source	GSI
Imagery	DTM: N/A
	Bing Aerial:







**Table G-23: Site Reconnaissance at Karst feature K23** 

Feature ID	К23
Feature Type	Enclosed Depression
Coordinates	E:556713, N:747813
Source	GSI
Imagery	DTM: N/A
	Bing Aerial:








Table G-24: Site Reconnaissance at Karst feature K24

Feature ID	K24
Feature Type	Enclosed Depression
Coordinates	E:556685, N:748029
Source	GSI
Imagery	DTM: N/A
	Bing Aerial:








Table G-25: Site Reconnaissance at Karst feature K25

Feature ID	K25
Feature Type	Enclosed Depression
Coordinates	E:555999, N:747895
Source	GSI
Imagery	DTM: N/A
	Bing Aerial:








Table G-26: Site Reconnaissance at Karst feature K26

Feature ID	K26
Feature Type	Enclosed Depression
Coordinates	E:556260, N:747849
Source	GSI
Imagery	DTM: N/A
	Bing Aerial:








Table G-27: Site Reconnaissance at Karst feature K27

Feature ID	K27
Feature Type	Enclosed Depression
Coordinates	E:555419, N:747792
Source	Aerial Imagery/Site Observation
Source	DTM:















Table G-28: Site Reconnaissance at Karst feature K28









Feature ID	K28
Site Reconnaissance Outcome	N/A
Water Presence	Possible
Additional Information	N/A
Site Photos	N/A

Table G-29: Site Reconnaissance at Karst feature K29









**Table G-30: Site Reconnaissance at Karst feature K30** 

Feature ID	K30
Feature Type	Enclosed Depression
Coordinates	E:557316, N:749477
Source	Aerial Imagery
Imagery	DTM:












Feature ID	K30
Additional Information	N/A
Site Photos	N/A

Table G-31: Site Reconnaissance at Karst feature K31










Table G-32: Site Reconnaissance at Karst feature K32

Feature ID	K32
Feature Type	Enclosed Depression
Coordinates	E:556527, N:748134
Source	Aerial Imagery
Imagery	DTM: N/A
	Bing Aerial:









Table G-33: Site Reconnaissance at Karst feature K33

Feature ID	K33
Feature Type	Enclosed Depression
Coordinates	E:556527, N:748134
Source	Aerial Imagery
Imagery	DTM:











Feature ID	K33
Additional Information	N/A
Site Photos	N/A

Table G-34: Site Reconnaissance at Karst feature K34




Table G-35: Site Reconnaissance at Karst feature K35

Feature ID	K35
Feature Type	Enclosed Depression
Coordinates	E:556380, N:748666
Source	Aerial Imagery
Imagery	DTM:











Feature ID	К35
Additional Information	N/A
Site Photos	N/A

Table G-36: Site Reconnaissance at Karst feature K36




Table G-37: Site Reconnaissance at Karst feature K37

Feature ID	K37
Feature Type	Enclosed Depression
Coordinates	E:556802, N:748480
Source	Aerial Imagery
Imagery	DTM: N/A
	Bing Aerial:








Table G-38: Site Reconnaissance at Karst feature K38

Feature ID	кз8
Feature Type	Enclosed Depression
Coordinates	E:556527, N:748134
Source	Aerial Imagery
Imagery	DTM: N/A
	Bing Aerial:









Table G-39: Site Reconnaissance at Karst feature K39

Feature ID	K39
Feature Type	Enclosed Depression
Coordinates	E:556527, N:748134
Source	Aerial Imagery
Imagery	DTM:















**Table G-40: Site Reconnaissance at Karst feature K40** 








Feature ID	K40
Site Reconnaissance Date	N/A
Site Reconnaissance Outcome	N/A
Water Presence	Possible
Additional Information	N/A
Site Photos	N/A

Table G-41: Site Reconnaissance at Karst feature K41


	Table G-41: Site Reconnaissance at Karst feature K41
Feature ID	К41
Feature Type	Enclosed Depression
Coordinates	E:556527, N:748134
Source	Aerial Imagery
Imagery	DTM: N/A
	Bing Aerial:
Site Reconnaissance Date	N/A
Site Reconnaissance Outcome	N/A
Water Presence	Possible
Additional Information	N/A
Site Photos	N/A







## **G.2** GROUND INVESTIGATION LOCATIONS







## **G.3** BOREHOLE RECORDS

Pe	eterse	n Dril	ling S	Service	s Lt	d.	on beh	nalf of						HES	S						Rotar	y Drillin	ng Log						
Depth of	1			er's Strat					Sample /	Hole / Tr	Test Details	s				g Details					Standarr	rd Penetrati	tion Test					Ke	metix
Stratum Top (m)	<u> </u>			er's Strat escriptio				No	Туре	Insitu test	From (m)	To (m)	Liner Dia (mm)	Core run time (hhmm)	Total core Recovery ) (m)	Flush Return %	Flush Colour	Self Weight Pen (mm)	75 mm	150 mm	Seating Pen (mm)	75 mm	150 mm	225 mm	300 mm	Main Pen (mm)	N value	Casing Depth (m)	Water/ flush level (m)
	1								RO		0.00	20.00		0000		100	grey											0.00	0.00
0.00	1		Firm t	brown TOPSC	JIL				<u> </u>	Ĺ′	<u> </u>	'	<u> </u>	<u> </u>	<u> </u>	Ĺ_'	Ĺ'	<u> </u>	<u> </u>	Ĺ.,	<u> </u>	Ĺ'	Ĺ'	Ĺ'	<u> </u>	<u> </u>		<u> </u>	$\Box$
	<b></b>							<u> </u>	⊥'	<b></b> '	<b></b>	<u> </u>	<u> </u>	<b></b> '	<u> </u> '	↓'	Д'	<u> </u>	<u> </u>	<u> </u>	↓'	Д'	Д'	Д'	⊥'	<u> </u>	<b></b>	<u> </u>	4
2.00	1	•			0			<u> </u>	<b>↓</b> '	<b></b> '	<b></b>	<u></u> '	<del></del> '	<b></b> '	<u> </u>	<del> </del>	<b></b> '	<del>                                     </del>	<b></b> '	<b></b>	<del>  '</del>	<b></b> '	<del>_</del> '	<b></b> '	<b>↓</b> '	<del>                                     </del>	<b></b> '	<del></del> '	+
0.30	1	Soft	to firm light	nt brown silty gr	ravelly CL	.AY		<u> </u>	<u></u>  '	<b></b> '	<b></b>	<u> </u> '	<del></del>	<b></b>	<u></u> '	<del> </del> '	<b></b> '	<del> </del>	<b></b> '	<del></del>	<u> </u> '	<b></b> '	<b></b> '	<b></b> '	<u></u>  '	<del> </del>	<del></del> '	<del></del> '	1
$\longmapsto$								<del></del> '	<del>  '</del>	+'	<del></del>	<del></del> '	+	<del></del>	<del>  '</del>	<del> </del> '	<del></del> '	+	<del></del> '	<del></del>	<del></del> '	<del></del> '	<del></del> '	<del></del> '	<del>  '</del>	+	<del></del>	+	+
2.10	Stiff grey	ısh brown silt		avelly CLAY wit		nt limestone	→ fracments	<u> </u>	<del> </del> '	+'	+	<del></del> '	+	<del></del>	<del></del> '	<del></del> '	<del></del> '	+	+	<del> </del>	+	+'	<del></del> '	<del></del> '	<del> </del> '	+	<del></del>	$\vdash$	+
2.10	1		possible hi	highly weathere	ed rock			<u> </u> '	+'	<del></del>	<del></del>	+'	+	<del></del>	<del></del>	+	<del></del>	+	$\vdash$	<del></del>	+	+	+	<del></del>	+'	+		$\vdash$	+
<b> </b>	<u> </u>							+	+-	<del></del>	<del>                                     </del>	+'	<del>                                     </del>		<del>                                     </del>	+	+	+		<del></del>	+	$\vdash$	+	+-	+-	+		$\vdash$	
4.90	1	Weak weat!	hered dark r	grey LIMESTO	ONE mud	stone layers	s	<b></b>	+		<b> </b>	+	<del>                                      </del>		+	<del>                                      </del>	+	<del>                                      </del>		<del>                                     </del>	+	$\Box$	+		+	<del>                                      </del>			
	1			•				<b> </b>	+-	$\Box$		+-			<del>                                     </del>						<del>                                      </del>				+-				
	1	-		-				<u> </u>	<u> </u>			<u> </u>				<u></u>	<u> </u>				<u> </u>		<u> </u>	<u> </u>	<u> </u>				
7.00	1		Strong da	ark grey LIMES	STONE																						ſ <u></u>		
,	1																												
, [	1		<u></u> -	<u> </u>					<u> </u>	Ĺ′	<u> </u>	'	<u> </u>	<u> </u>	<u> </u>	Ĺ_'	Ĺ'	<u> </u>	<u> </u>	Ĺ.,	<u> </u>	Ĺ'	Ĺ'	Ĺ'	<u> </u>	<u> </u>		<u> </u>	$\Box$
,	1							'	Д'	<b></b> '	<u> </u>	<u> </u>	<u>                                     </u>	<b></b> '	↓'	↓'	Д'	<u> </u> '	⊥'	<u> </u>	↓'	Д'	Д'	Д'	Д'	<u> </u> '	<b></b> '	<u> </u>	$\perp \perp \mid$
								<u></u> '	<u></u> —'	<u></u> '	<u></u> '	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u></u> —'	<u>'</u>	<u> </u>	<u></u> '	<u></u> '	Щ'	<u></u> '	<u></u> —'	<u> </u>	<u></u> —'	<u>Ш</u>	<u> </u>	<u></u>	Щ
	Shift c	details	'					Dril	iling E		nent De	etails							- Danah		Ground '	Water	Reco	√rd		1 Santh	Ba	ckfill (m	
Start time (hhmm)	Hole (m)	Water (m)	Casing (m)	Casing (C) Open Hole (RO) Coring (RC)	Dia. (mm)	From (m)	To (m)	Barrel	Liner Type	Core Dia (mm)	Bit '	it Type	Casing		Bit serial No	Flush	Polymer	Time of strike	Depth Struck (m)	Casing (m)	Inflow	5 min	10 min	15 min	20 min	Depth Sealed (m)	Туре	From (m)	To (m)
1215	1	1	1 ,	C RO	140.00 154.00		8.00 8.00	+'	+'	<del></del>	DTH F	Button Bit	Sim. C	asing	115	Air	No	1210	2.30	2.30	Slow	0.00	0.00	0.00	0.00	3.00	1 '	1	
Finish time	Hole	Water	Casing	RO	120.00		20.00		ऻ'		_	Button Bit	_			Air	No	1325	7.00	7.00	Slow	0.00	0.00	0.00	0.00	N/S			
(hhmm)	(m)	(m)	(m)	<b>—</b>	+	+	+	<del></del> '	<del>  '</del>	+'	+	'	<del></del>	'	<del>  '</del>	<del> </del> '	<b></b>										<b></b>	+	+-
1735	'		'					<u> </u>	<del></del> '		二					<del></del> '		1400	13.00	8.00	Medium	n 0.00	0.00	0.00	0.00	N/S	<b></b> '	<u> </u>	Щ
Time from	Duration (hhmm)	Remarks	or details	ls of any add	ditional f	testing inf	formation	, Daywor	ks			SPT I.I	.D. Numbe	er	PD	ט1	Calibrati Date		01/02	2/2021	Proj	ject T	ſitle						
1215	1	CAT Scanne	.ed: Yes								Ī	SPT Rc	od Type	Ī	2 3/8 R		SPT Ene Ratio	ergy	0.	0.00				$C_{\ell}$	مام	o WF	_		I
1215	1	Permit Comp	ıpleted: Yes	,							1	Drillinç	g Crew De	etails			1		CSC	CS No	1			C	)UIU	JVVI	Γ.		Ī
	1	DREM (14.5	50m - 15.00 <sup>r</sup>	0m): Fractured	J Rock Zor	ne					!	Suppor	ort Operat	tive		J	John Whyt	te			Weathe	ər		Fi	ine		Project No	33/2	/22
1600	0030	Dayworks: F	Airlift develor	opment of well	ı						Ī	Lead Di	riller			Step	phan Pete	ersen			Date	'		15/08	8/2022		Day	Mono	ıday
,	1										1	Site cat	tegory					Green			Rig type	<i>i</i> e		Knebe	el HY79	, I	Borel	hole Numi	nber
,	1										Ī	Project	t Enginee	er							Inclinati	tion	<u> </u>	Orienta	ation			BH 1	
,	<u> </u>	1									'	Lead D	Oriller's si	ignatur	re						Sheet			1	of	1	Compl	leted	Υ



Pe	eterse	an Dril	ling §	Service	es Lt	.d	on be	half of						HES	S						Rotar	y Drillin	ng Log	<u> </u>					
Depth of	1			er's Strat					Sample /	Hole / T	Test Details	s				ng Details					Standarr	rd Penetrati	tion Test					Ke	metix
Stratum Top (m)	<u></u>			er s Strat escription				No	Туре	Insitu test	From (m)	To (m)	Liner Dia (mm)	Core run time (hhmm)	Total core Recovery ) (m)	Flush Return %	Flush Colour	Self Weight Pen (mm)	75 mm	150 mm	Seating Pen (mm)	75 mm	150 mm	225 mm	300 mm	Main Pen (mm)	N value	Casing Depth (m)	Water/ flush level (m)
	]								RO		0.00	20.00		0000		100	grey										1	0.00	0.00
0.00		,	Soft to firm	n brown peaty T	TOPSOIL	-			<u> </u>	<u> </u>	Ĺ.,	'	<u> </u>	<u> </u>	<u> </u>	'	Ĺ'	<u> </u>	Ĺ'		<u> </u>	Ĺ'	Ĺ_'	<u> </u>	<u> </u>	<u> </u>		<u> </u>	
	<b></b>							<u> </u>	Д'	<del> </del>	<u> </u>	↓'	Д'	<u> </u>	<u> </u>	⊥′	↓′	<u> </u>	<b></b> '	↓	↓'	<b></b> '	Д′	<u> </u>	Д′	<b>↓</b> '	<b></b> '	<u> </u>	$\perp \perp \mid$
	Medium	n dense coarr	e arev well	I rounded SANI	UD AND (	≥RAVEL with	h frequent	'	<del> </del>	<del></del>	<del> </del>	<u></u> '	<u> </u>	<del> </del>	<u> </u>	<b>↓</b> '	<b></b> '	<del>                                     </del>	<u></u>	1	<u></u>   '	<del>_</del> '	↓'	<del> </del>	<b>↓</b> —'	<del>                                     </del>	<b></b> '	<b></b> '	$\perp$
0.40		dones		bles and boulde			почас	<u> </u>	<del> </del>   '	+	<del> </del>	<u> </u>	<del> </del> '	<del> </del>	<u> </u> '	<u> </u> '	<del> </del>	<del>                                      </del>	<b></b> '	+	<del> </del> '	<b></b> '	<b></b> '	<del></del>	<b></b> '	<del> </del>	<del></del> '	<del></del> '	1
$\longmapsto$	<del></del>							<del></del> '	+'	+	<del> </del>	<del></del> '	+	<del>                                     </del>	<b></b> '	<del>  '</del>	<del> </del>	+	<del></del> '	+	<del> </del> '	<del></del> '	<del>  '</del>	<del>                                     </del>	<del>                                     </del>	+	<del></del>	+	-
2.60	Strong to	Very strong د	dark grey L!	_IMESTONE wi	with occas	sional shaley	y mudstone	<u> </u>	+'	+	+	<del></del> '	+	+	<del>  '</del>	<del> </del> '	<del></del>	+	<del></del> '	+	<del></del> '	+'	<del></del> '	+	+'	+	<del></del>	$\vdash$	+
2.00				layers				<u> </u> '	+'	+	+	<del></del>	+	<del>                                     </del>	<u> </u>	<del></del> '	<del></del>	+	<del></del>	+	+	+	<del></del>	+	+'	+	<u> </u>	$\vdash$	+
<b> </b>								+	+	<del>                                     </del>	+	+'	+	<u> </u>	<del>                                     </del>	+-	+	+	+	+	+	$\vdash$	+-	+	+'	+		$\vdash$	<u> </u>
								<b></b>	+	<del>                                     </del>	<del>                                      </del>	+	<del>                                      </del>	<b>†</b>	<del>                                     </del>	+	<del>                                      </del>	<del>                                      </del>	$\vdash$	<del>                                     </del>	+	$\Box$	+	+	+	<del>                                      </del>			
.]								<b> </b>	+-			+-			<del>                                     </del>	<del>                                     </del>	+-				<del>                                     </del>		+-	<del>                                      </del>	+				
		-				-		<u> </u>				<u> </u>	<u></u>		<u> </u>	<u> </u>					<u> </u>								
.]																											Í′		
,																													
	1		<del></del>						<u> </u>	<u> </u>	Ĺ.,	'	Ĺ'	Ĺ '	'	<u> </u>	Ĺ'	<u> </u>	Ĺ'		<u> </u>	Ĺ'	Ĺ'	<u> </u>	<u> </u>	<u> </u>		<u> </u>	
,								'	Д′	<u> </u>	<u> </u>	↓′	<u> </u>	<u> </u>	<u> </u>	⊥'	<u> </u> '	<u> </u>	Д'	1	↓'	Д'	Д'	<u> </u>	Д′	<u> </u>	<b></b> '	<u> </u>	$\bot$
								<u> </u>	<u></u> —'	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u></u>	<u> </u>	<u> </u>	<u>↓</u> '	<u> </u>	<u></u> —'	<u> </u>	<u> </u>	<u> </u>	<del></del>
	Shift	details						Dril	iling E		nent De	etails					'				Ground '	Water	/ Reco	rdر			Ba	ckfill (m	
Start time (hhmm)	Hole (m)	Water (m)	Casing (m)	Casing (C) Open Hole (RO) Coring (RC)	Dia. (mm)	From (m)	To (m)	Barrel	Liner Type	Core Dia (mm)	Bit *	it Type	Casing	- ''	Bit serial No	Flush	Polymer	Time of strike	Depth Struck (m)	Casing (m)	Inflow	5 min	10 min	15 min	20 min	Depth Sealed (m)	Туре	From (m)	To (m)
0805		1	1 '	C RO	140.00 154.00		3.60 3.60	+'	+'	+	DTH F	Button Bit		Casing	115	Air	No	0825	2.00	2.00	Slow	0.00	0.00	0.00	0.00	N/S	1	1	
Finish time (hhmm)	Hole (m)	Water (m)	Casing (m)	RO	120.00	+	20.00			厂	DTH B	Button Bit				Air	No	1725	3.50	3.50	Medium	n 0.00	0.00	0.00	0.00	N/S			
	(111)	(,	(m)	<del></del>	+	<del>                                     </del>	+	<del></del> '	<del></del> '	<del>                                     </del>	+	'	+		<del>  '</del>	<del></del> '	<del></del>	+	<del></del> '	+	<del></del> '	<del></del> '	<del>  '</del>	<del> </del>	<del>  '</del>	<del></del>	<del></del> '	+	++
1540	<u> </u>		'						<u></u> '		上					<u></u>		<u> </u>	<u> </u>		<u> </u>	<u> </u>	<u> </u>		'	<u> </u>	<u> </u>	<u> </u>	
Time from	Duration (hhmm)	Remarks	s or details	ls of any add	ditional	testing inf	formation.	, Daywor	ks			SPT I.I	.D. Numbe	jer	PD	1טי	Calibrati Date		01/02	)2/2021	Pro	ject T	Γitle						
0805		CAT Scanne	ed: Yes								Ī	SPT Rr	od Type		2 3/8 R		SPT Ene	ergy	0	0.00				<b>C</b> (	مام	o WF	_		
0805		Permit Comp	ıpleted: Yes	š							1	Drillinç	g Crew De	Jetails	<u> </u>		Itua		csc	CS No	1			C	JUIU	J VVI	Γ		
	1	DREM (7.50	Jm - 9.00m)	n): Fractured Ro	≀ock Zone	<b>;</b>					ļ	Suppo	ort Operat	tive		J	John Whyt	te			Weathe	er		Var	riable		Project No	33/2	/22
1340	0030	Dayworks: /	Airlift develo	opment of well	l.						,	Lead Di	riller	_	,	Ster	phan Pete	∍rsen			Date			16/08	08/2022		Day	Tues	sday
,											ļ	Site cat	tegory					Green			Rig type	ле		Knebr	el HY79	,	Borel	hole Numi	nber
,											Ī	Project	t Enginee	er							Inclinati	tion		Orienta	ation		1	BH 2	
,	i .										'	Lead D	Oriller's si	ignatur	re						Sheet			1	of	1	Compl	leted	Υ







## **G.4** TRIAL PIT RECORDS

	DG					Т.,	: - I D:	41		TrialPit No	0
	N & DOHERTY					ır	iai Pi	t Log		TP01	
Proje	oct			Proi	ect No.		Co-ords:	556177.00 -	- 748660 00	Sheet 1 of Date	1
Name		Wind	Farm	2209			Level:	m (		18/02/202	5
Loca	tion: Cooloo	, Co. G	Salway Ireland	1			Dimensions		2.50	Scale	
							(m): Depth	2.00		1:25 Logged	
Clien		laa 9 In C	Situ Testing		I	Ι	2.80			PK	
Water Strike	Depth	Type	Results	Depth (m)	Level (m OD)	Legend		Stratum De	escription		
	Борат	1,700	results					comprise of soft bro	own sandy clay wit	h grass	-
	0.80 1.00 2.00	В	HSV 62kPa	0.30			Soft to firm cobbly SILT	mottled light brow  Cobbles are sub	n slightly sandy gr -rounded of limesto lly cobbly CLAY wi eter. Cobbles and	avelly one.	1
				2.75 2.80			Dark grey r	nassive LIMESTO End of Pit			3



	DC	-				_				TrialPit	
GAVI	N & DOHERTY	,				l r	ial Pi	it Log	þ	TP0	2
	SOLUTIONS									Sheet 1	of 1
Proje		o Wind	Farm		ect No.		Co-ords:		00 - 748556.00	Date	
Name	e:			220	98		Level:		m OD	19/02/20	
Locat	tion: Coolod	o, Co. (	Galway Ireland				Dimensions (m):		2.50	Scale 1:25	
Clien	t: MKO						Depth	2.00		Logge	
		olos & In G	Situ Testing				2.60			PK	
Water Strike	Depth	Type	Results	Depth (m)	Level (m OD)	Legend		Stratu	m Description		
	Бериі	туре	Nesuits	. ,	,	X//XX/X	TOPSOIL	comprise of so	ft brown sandy slightly	gravelly	l .
							clay with g	rass rootlets	, , ,		
				0.25		×	Soft to firm	n brown grey s	ightly gravelly sandy c	obbly	
						× × · · · · · · · · · · · · · · · · · ·	CLAY. Col	bles are sub-r	ounded of limestone		-
	0.50		HSV 54kPa			× × × ×					-
						× 0 × 0					-
	0.80	В				× ×					-
						× × · ·					1 -
				1.10		× × · ·	Soft to firm	hrown grov o	ightly sandy gravelly c	obbly	' =
						× 0 × 0	SILT with	occasional bou unded of limes	Iders. Cobbles and bo	ulders	
						X-0-X	are sub-ro	unaea or iimes	sione.		-
						× 0× 0					-
	2.00 B				× 0 ×					-	
						× - 0 ×					
						\$0.50 \$0.50 \$0.50					-
	2.00	В				×0×0×	-				2 -
						× 0 × 0					-
						X-0-x					-
				0.50		× 0×0	3				-
				2.50 2.60			Grey mass	sive LIMESTO			-
								Ena	of Pit at 2.6m		
											-
											3 -
											-
											-
											-
											-
											] :
											4 -
											-
											-
											:
				1	1	1	1				-

Remarks: Terminated due to possible bedrock. Moderate ingress groundwater

Stability: Poor - Collapse from 1m



	DC	-				_	TrialPit No	
GAVI	N & DOHERTY					l r	rial Pit Log TP03	
	SOLUTIONS						Sheet 1 of 1	
Proje		Wind	Farm		ect No.		Co-ords: 555538.00 - 748001.00 Date	
Nam	<b>e</b> :			220	98		Level:         m OD         20/02/2025           Dimensions         2.50         Scale	_
Loca	tion: Cooloo	o, Co. C	Salway Ireland				l , ,	
Clien	t: MKO						(m): 1:25   Logged	
- e	Samp	oles & In S	Situ Testing	Donth	Lovel		2.10 PK	_
Water Strike	Depth	Туре	Results	Depth (m)	Level (m OD)	Legend	Stratum Description	
				0.10			TOPSOIL comprised of clay, grass and reeds	_
				0.10		और और औ क्रांकि और	Firm dark brown oxidising to black very woody course fibrous wet PEAT. H1 B2 R3 W3 N5 A1	-
						जीहरू औरह जी ह औरह औरह		-
	0.50	В				क्षार क्षार क्ष इ. क्षार क्षार क्षार क्षार क्ष		_
	0.50	Ь				2018 2018 20 20 20 20 20 20 20 20 20 20 20 20		-
						s als als als als al		-
						د عادد عادد عادد عادد عا		-
	1.00		HSV 20kPa	1.00		s alis alis alis alis al	Soft grey silty, sandy GRAVEL with abundant boulders	_
						8 0 0 × 0	and cobbles. Cobbles and boulders are sub-rounded of	-
						200 X	limestone.	
						20 X		-
	1.50	В				8.0°.0°.		_
						\$ 00 X		-
								-
						\$ 0 ×		-
				2.00		\$-0.×	Grey massive LIMESTONE 2	_
				2.10			End of Pit at 2.1m	-
								-
								-
								-
								-
								-
								-
							3	-
								-
								-
								-
								-
								-
								-
							4	-
							"	-
								-
								-
								-
								-
								-

Remarks: Terminated due to possible bedrock. Slow ingress of groundwater

Stability: Moderate



									TrialPit No
GAVI	N & DOHERTY					Tr	ial Pi	t Log	TP04
	SOLUTIONS								Sheet 1 of 1
Proje		Wind	Farm		ect No.		Co-ords:	555302.00 - 747590.00	Date
Nam	e:			2209	98		Level:	m OD	20/02/2025
Loca	tion: Cooloo	, Co. C	Salway Ireland				Dimensions (m):	2.50	Scale 1:25
Clien	t: MKO						Depth	2.00	Logged
		los & In S	Situ Testing				1.00		PK
Water Strike	Depth	Type	Results	Depth (m)	Level (m OD)	Legend		Stratum Description	
	Берш	туре	Nesuits		, ,		TOPSOIL co	omprised of soft brown sandy clay w	ith grass
				0.00			rootlets		
				0.20		× × ×	Soft to firm Sand is fine	grey white slightly sandy, gravelly Cl	AY.
	0.40	В				× ×			
			1101/1015			<u>×</u>			-
	0.60		HSV 40kPa	0.60			Firm brown comprise of	gravelly CLAY. Gravel is sub-rounder	d and
				0.75		0-0-X	Soft grey br	own slightly sandy gravelly SILT with	1 -
	0.90	В		0.95		X -0 -X	rounded of I	cobbles. Gravel and cobbles are sub limestone.	
				1.00			Weathered limestone.	grey LIMESTONE. Heavily fractured	/ 1 -
								End of Pit at 1.0m	
									2 -
									-
									-
									3 -
									-
									4 -
									-
	i e	l	i l		I	1	İ		I



	DG					т,	ial Di	+ l oo	TrialPit N	
	N & DOHERTY					11	iai Pi	t Log	TP05 Sheet 1 o	
Proje	OSOLUTIONS			Proi	ect No.		Co-ords:	554936.00 - 748146.00	Date	1 1
Nam		Wind	Farm	2209			Level:	m OD	19/02/202	25
Loca	tion: Cooloc	, Co. G	Salway Ireland	,			Dimensions		Scale	
							(m): Depth	5.00	1:25 Logged	
Clien		laa 9 In C	Nit. Tasting			Ι	0.90	.,	PK	
Water Strike				Depth (m)	Level (m OD)	Legend		Stratum Description		
Water	0.50 0.50 0.70	Type  B B	Results  HSV 52kPa	0.20 0.60 0.80 0.90	Level (m OD)	Legend X Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	TOPSOIL of rootlets  Firm brown rounded of Loose grey sub angula	comprised of soft brown sandy clay was slightly gravelly, sandy SILT. Grave limestone  y sandy GRAVEL. Gravel is sub round or of limestone  ive weather LIMESTONE. Minor oxid	rith grass I is sub-	2
										-



	DG N & DOHERTY SOLUTIONS					Tr	ial Pi	t Log	TrialPit TP00	6
Proje	ct		_	Proj	ect No.		Co-ords:	556183.00 - 749155.00	Date	
Name		Wind	Farm 	220			Level:	m OD	18/02/20	
Locat	tion: Cooloo	, Co. G	Salway Ireland				Dimensions (m):	2.50	Scale 1:25	
Clien	t: MKO						Depth 3.60	2.00	Logge PK	
Water Strike	Samp	les & In S	itu Testing	Depth	Level	Legend		Stratum Description		
% tī	Depth	Туре	Results	(m)	(m OD)	alk alk al	Firm to an a		- ^ -	
						e alle alle alle alle alle alle alle al	Firm to spo Weak orgar	ngy dark brown/black very fibrous PE nic odour. H2 B2 F2 R2 W1 N5 A1	<b>-A1</b> .	
•	1.00 1.10	В	HSV 20kPa	1.00		shle shle shle a sh	W1 N5 A1	brown pseudo-fibrous Peat. H5 B2	F2 R2	2 -
	3.10	В		2.90		Sale	Very soft gr	ey white sandy SILT. Possibly Marl.		3 —
				3.60 3.61		**************************************	Grey massi	ve LIMESTONE End of Pit at 3.6m		4 —
					<u> </u>	1	1		82	

Remarks: Terminated due to possible bedrock. Rapid ingress of groundwater

									- · · · · · ·	
						т.,	: - I D:	41	TrialPit	
	N & DOHERTY					ır	iai Pi	t Log	TP07	
	SOLUTIONS			D	4 NI-		0	550004.00 740005.00	Sheet 1	
Proje Nam		Wind	Farm	220s	ect No.		Co-ords: Level:	556824.00 - 749835.00 m OD	Date 19/02/20	
		Co. (	Saluray Iraland	220			Dimensions		Scale	
Loca	tion: Cooloo	, Co. C	Salway Ireland				(m):	2.00	1:25	
Clien	t: MKO						Depth 3.55	25	Logge PK	d
Water Strike	Samp	les & In S	Situ Testing	Depth	Level	Legend		Stratum Description		
Str	Depth	Туре	Results	(m)	(m OD)	Logona		•		
							TOPSOIL of rootlets	comprised of soft brown sandy clay w	ith grass	-
				0.20		alk alk al		astic dark brown pseudo-fibrous PEA	\Т . Н5	-
						د عاد عاد عاد عاد عا	B2 F2 R2	WINSAI		-
						alia alia alia alia al a alia alia	ļ			-
						مادر مادر ما د مادر مادر	1			-
						હોદિ હોદિ હો હ હોદિ હોદિ				-
						क्षार क्षार क्षा ६ क्षार क्षार क्षार क्षार क्षा				1 -
	1.00		HSV 42kPa	1.00		316 316 31 6 316 316 316 316 31	Plastic bro	wn pseudo-fibrous PEAT. H5 B2 F2 F	R2 W1	1 -
						د عاد عاد عاد عاد عا	NOAT			-
						६ जोह जोह जोह जोह जो	ļ			-
	1.50					alia alia alia alia al a alia alia	ļ			-
						مادر مادر ما د مادر مادر	1			-
						ماند ماند ما د ماند ماند				-
						مادر مادر ما د مادر مادر				-
						क्षार क्षार क्षा ६ क्षार क्षार क्षार क्षार क्षा				2 -
						د عاد عاد عاد عاد عا				-
						र अहि अहि अहि अहि अ				-
						alia alia alia alia al a alia alia	ļ			-
						مادر مادر ما د مادر مادر	1			-
						ماند ماند ما د ماند ماند				-
						مادر مادر ما در مادر مادر				-
						क्षार क्षार क्षा ६ क्षार क्षार क्षार क्षार क्षा				3 —
						દ કોદ કોદ કોદ કોદ કો	ļ			
						s alis alis alis alis al s alis alis				-
	3.50	В		3.30		X X X X X X X X X X X X X X X X X X X		reyish white slightly sandy CLAY (Mar edium.	rl). Sand	-
	0.00			3.55		XXXX		End of Pit at 3.6m		-
										4 —
										-
										4 -
										-
										-
										-
										- - - - -
										-

Remarks: Terminated due to very rapid water ingress. Rapid ingress of groundwater



	DG N & DOHERTY DSOLUTIONS					Tr	ial Pi	t Log	9	TrialPit TP08 Sheet 1	8
Proje	ot	\ \	F	Proj	ect No.		Co-ords:	555699.0	00 - 749633.00	Date	
Name	e: Cooloo	vvina	arm	220	98		Level:		m OD	18/02/20	
Locat	tion: Cooloo	, Co. C	Salway Ireland				Dimensions (m):		2.50	Scale 1:25	
Clien	t: MKO						Depth 2.75	2.00		Logge PK	
e e	Samp	les & In S	Situ Testing	Depth	Level		2.13			FK	
Water Strike	Depth	Туре	Results	(m)	(m OD)	Legend			n Description		
	1.00 1.00	В	HSV 30kPa	1.10 2.70 2.75			Soft-firm lig CLAY with limestone.	ar gravel and	sandy very gravelly coders are sub-rounded of limestone.  sandy very gravelly coders and cobbles complete cobbles (possibly wear of Pit at 2.8m	obbly prise of	2

Remarks: Terminated due to possible bedrock. Slow ingress of groundwater

Stability: Poor - Collapse from 0.5m



										TrialPit N	lo
						Tr	ial Pi	t Loc	מ	TP09	
	N & DOHERTY SOLUTIONS								9	Sheet 1 o	f 1
Proje		Wind	Farm		ect No.		Co-ords:	554930.0	00 - 747229.00	Date	
Name	e: 000100	vviila	i aiiii	2209	98		Level:		m OD	20/02/202	<u>2</u> 5
Locat	tion: Cooloo	, Co. C	Salway Ireland				Dimensions (m):		2.50	Scale 1:25	
Clien	t: MKO						Depth 1.80	2.00		Logged	
e.	Samp	les & In S	Situ Testing	Depth	Level		1.00			FK	
Water Strike	Depth	Туре	Results	(m)	(m OD)	Legend			n Description		
	0.50	В	LIOV 74LD-	0.20			rootlets  Soft to firm rounded of	slightly sandy limestone	oft brown sandy clay was gravelly CLAY . Gravelly CLAY . Gravelly clay was slightly gravelly cobbly limestone.	rel is sub-	
	1.50	В	HSV 74kPa	1.80							1 -
				1.81			Grey mass	ive LIMESTON End c	NE of Pit at 1.8m		3
											-



	DC								TrialPit No	
GAVIN & DOHERTY					Trial Pit Log				TP10	
GEOSOLUTIONS								Sheet 1 of 1		
Project Cooloo Wind Farm Name:				ect No.		Co-ords:	556912.00 - 749360.00	Date		
			220	98		Level:	m OD 2.50	19/02/2025 Scale		
Locat	ion: Cooloo	o, Co. C	Galway Ireland				Dimensions (m):		1:25	
Client	: MKO						Depth 2.70	2.00	Logged PK	
- e	Samples & In Situ Testing			Donth	Lavel		2.10 PK			
Water Strike	Depth			Depth (m)	Level (m OD)	Legend		Stratum Description		
							TOPSOIL comprised of soft brown sandy clay with grass rootlets			
				0.20			Soft brown	slightly sandy slightly gravelly SILT. d. Sand is fine to coarse. Gravel is c	Gravel is	
	0.40	В					limestone.	d. Salid is lille to coarse. Graver is c	· .	
				0.50			Firm brown	grey slightly sandy gravelly cobbley	SILT	
						Firm brown grey slightly sandy gravelly cobb with occasional boulders. Boulders are sub-		onal boulders. Boulders are sub-rou	inded of	
								=		
						A 00 0.0				
	1.00		HSV 96kPa					1 -		
						a 00 9.0				
									:	
	2.00	В							2 -	
									:	
									-	
				2.70		0 000 000	Grey massive LIMESTONE			
				2.72	2.72		\ Grey massi			
									3 -	
									-	
									-	
									4 -	
		1								



	DC								TrialPit No
GAVIN & DOHERTY					Trial Pit Log			TP11	
GEOSOLUTIONS								Sheet 1 of 1	
Project Cooloo Wind Farm Name:				ect No.		Co-ords:	556197.00 - 748883.00	Date	
			2209	98		Level:	m OD	18/02/2025	
Location: Cooloo, Co. Galway Ireland							Dimensions (m):	2.50	Scale 1:25
Client: MKO						Depth 2.35	2.00	Logged PK	
Water Strike	Samp	Samples & In Situ Testing			Level	Lagand		Stratum Decemention	
Wa	Depth	Туре	Results	Depth (m)	(m OD)	Legend		Stratum Description	
N/W Str	0.80 0.80	В	HSV 30kPa	0.20 0.90	(m OD)		Very stiff green CLAY with oare sub-rour	omprised of brown sandy clay with grandy slightly, gravelly SILT. Gravel mestone. Sand is fine to coarse.  By brown slightly sandy, gravelly, colocasional boulders. Cobbles and boulded of limestone  The LIMESTONE  End of Pit at 2.4m	is sub-
									4 -

Remarks: Terminated due to possible bedrock. Slow ingress of groundwater



										_	
GDG  GAVIN & DOHERTY  GEOSOLUTIONS					Trial Pit Log					TrialPit No TP12	
							T			Sheet 1 of 1	
Project Cooloo Wind Farm					Project No.		Co-ords:		00 - 749063.00	Date	
Name:				220	98		Level: Dimensions		m OD 2.50	18/02/2025 Scale	
Location: Cooloo, Co. Galway Ireland							(m):			1:25	
Client: MKO							(m): 00 Depth 00 3.20			Logged PK	
e e	Samp	les & In S	Situ Testing	Depth	Level		3.20			FK	
Water Strike	Depth	Туре	Results	(m)	(m OD)	Legend		Stratu	m Description		
Waa Stri	0.80 1.00	B B	Results  HSV 48kPa				Firm grey I	sandy, slightly limestone	soft brown sandy clay w y gravelly SILT. Gravel i sandy, slightly gravelly ders. Cobbles and bould e	is sub-	
										4 -	

Stability: Moderate



GDG										
					Trial Pit Log					TP13
GEOSOLUTIONS								Sheet 1	of 1	
Project Cooloo Wind Farm					Project No.		Co-ords:	555411.00 - 747813.00	Date	
Name:			2209	98		Level:	m OD	20/02/20		
Location: Cooloo, Co. Galway Ireland							Dimensions 2.50 (m):		Scale 1:25	;
-							Depth	2.00	Logge	d
			)', T ('				2.50		PK	
Water Strike			Situ Testing	Depth (m)	Level (m OD)	Legend		Stratum Description		
> 0	Depth	Depth Type Results			(111 05)	X//XX//XX	TOPSOIL	comprised of slighly sandy gravelly cl	av with	
							grass rootlets		ay willi	-
				0.20			Soft to firm	n light brown sandy slightly gravelly Sl sub-rounded of limestone	SILT.	
	0.40	В					Olavel ale	sub-rounded of limestone		-
	0.50		HSV 38kPa							_
				0.60			Loose to m	nedium dense sandy, GRAVEL with a	bundant	-
							boulders. Boulders are 200-300mm in diameter of limestone.			
										1 —
						6				1 -
										-
										- -
	2.00	В								_
						0 - 0-4				- -
						0000				-
						50.02				-
									2 -	
					6 - 0-				-	
										-
										-
				0.00						_
				2.60 2.61			Grey mass	sive LIMESTONE End of Pit at 2.5m		-
										-
										3 —
										- -
										-
										- -
										_
										- -
										-
										-
										4 -
										-
										-
										- -
										-
	1	1	I		l	1	l			-

Stability: Very poor - Collapse from 1m



									TrialPit No
						Tr	ial Pi	t Log	TP14
	N & DOHERTY DSOLUTIONS							3 – 3	Sheet 1 of 1
Proje		Wind	Farm		ect No.		Co-ords:	555104.00 - 747925.00	Date
Nam				2209	98		Level: Dimensions	m OD 2.50	19/02/2025 Scale
Loca	tion: Cooloc	o, Co. G	Salway Ireland				(m):		1:25
Clien	t: MKO						Depth 0.80	2.00	Logged PK
Water Strike	Samp	les & In S	Situ Testing	Depth	Level	Legend		Stratum Description	
Wa	Depth	Туре	Results	(m)	(m OD)	Legend			
	0.50 0.50	В	HSV 63kPa	0.15			CLAY Firm to stiff SILT with c	comprised of slightly gravelly slightly in f light brown slightly sandy sightly gravecasional boulders. Boulder and cobe and of limestone.	avelly bles are
	0.70	В				× × × ×	cobbles are	e sub-angular of limestone	
				0.80 0.82			Grey brown fracture fac	n weathered LIMESTONE. Oxidation ces and abundant fractures. End of Pit at 0.8m	on 1 -
									on 1 -
									2 -
									3 -
									4 -

Remarks: Terminated due to possible bedrock. No groundwater encountered

Stability: Good



<u>(</u>	DG					Т.,	ial Di	+ l o a	TrialPit N	
	N & DOHERTY DSOLUTIONS					11	iai Pi	t Log	TP15	
Proje	ect Cooloo	Wind	Farm	Proj 220	ect No.		Co-ords:	556313.00 - 749138.00 m OD	Date 18/02/202	
Loca	tion: Cooloo	o, Co. G	Salway Ireland	I			Dimensions	2.50	Scale 1:25	
Clien	t: MKO						(m): Depth	2.00	Logged	b
		les & In S	Situ Testing	Donth	Level		3.15		PK	
Water Strike	Depth	Туре	Results	Depth (m)	Level (m OD)	Legend		Stratum Description		
	1.00 1.00	В	HSV 12kPa	0.30		able, **she, ash  **she, **she, ash  **she, **she, ash  **she, **she, ash  **s		ry fibrous woody PEAT with pockets of White clay		1
•	2.50	В		1.95		LANCANCAN	Grey sandy sub-angula	y cobbly GRAVEL. Gravel and cobble ir and sub-rounded of limestone.	s are	2 —
				3.15 3.16			Grey mass	ive LIMESTONE End of Pit at 3.2m		4 —

Remarks: Terminated due to possible bedrock. Slow ingress of groundwater

Stability: Good





TP01 - 1 of 2



TP01 - 2 of 2





TP02 - 1 of 2



TP02 - 2 of 2


## **North Elevation**

**©** 197°S (T) ● 53.485115, -8.669497 ±3m ▲ 136m






TP03 - 1 of 2



TP03 - 2 of 2





TP04 - 1 of 2



TP04 - 2 of 2





TP05 - 1 of 2




TP05 - 2 of 2





TP06 - 1 of 2




TP06 - 2 of 2





TP07 - 1 of 2



TP07 - 2 of 2

## **West Elevation**

• 112°E (T) • 53.496745, -8.650689 ±3m ▲ 128m





TP08 - 1 of 2



TP08 - 2 of 2





TP09 - 1 of 2



TP09 - 2 of 2





TP10 - 1 of 2



TP10 - 2 of 2

## **East Elevation**

② 255°SW (T) ● 53.492501, -8.64933 ±3m ▲ 139m





TP11 - 1 of 2



TP11 - 2 of 2





TP12 - 1 of 2



TP12 - 2 of 2





TP13 - 1 of 2



TP13 - 2 of 2

## **East Elevation**

© 298°W (T) ● 53.478451, -8.671717 ±3m ▲ 132m





TP14 - 1 of 2



TP14 - 2 of 2





TP15 - 1 of 2



TP15 - 2 of 2



**③** 197°S (T) ● 53.490451, -8.65835 ±3m ▲ 129m





	DG N & DOHERTY DSOLUTIONS	,				Tr	rial Pit Lo	9	TrialPit TPBF Sheet 1	<b>P</b> 1
Projec	t Cooloo W	ind Farm	1		ect No.		Co-ords: 555689.00 - 74	19020.00	Date	)
Name				220	98		Level: Dimensions		30/08/2 Scale	
Locati	on: Cooloo, C	o. Galwa	ay Ireland				_(m):		1:25	5
Client	McCarthy	Keville (	O'Sullivan Ltd. (M	KO)			Depth 3.10		Logge IPP	ed
iter ike	Samp	les & In Si	tu Testing	Depth	Level	Logond		n Description		
Water Strike	Depth	Type	Results  Results	0.80	Level (m)	Legend   Brown slightly sandy sligh medium to coarse. Gravel pockets of black organic relationship in the pockets organic relationship in the pockets of black organic relationship in the pockets organic relationship in the pockets organic relationship in	gravelly SILT. High col s. Gravel is fine to coa 2.6m presence of larg	bble rse,	2 -	
										5 -
Rema Stabili									AC	GS

	DG & DOHERTY SOLUTIONS	,				Tr	rial Pit Lo	9	TrialPit TPBI Sheet 1	P2
Project		ind Farm		Proj	ect No.		Co-ords: 555463.00 - 74	49672.00	Date	
Name:	C00100 VV	iliu i alili		220	98		Level:		30/08/2	
Locatio	n: Cooloo, C	o. Galwa	y Ireland				Dimensions (m):		Scal 1:25	
Client:	McCarthy	Keville C	)'Sullivan Ltd. (M	KO)			Depth 3.00		Logge	ed
e e	Samp	oles & In Sit	u Testing	Depth	Level				III III	
Water	Depth	Туре	Results	(m)	(m)	Legend		n Description		
				3.00			Brown slightly sandy grav to coarse. Gravel is fine to rounded to subrounded.  Grey slightly gravelly SAN  End o		medium oulders,	1 - 3 - 5 -
Remark Stability									A	I GS

	DG N & DOHERTY SOLUTIONS	-				Tr	rial Pit Log		TrialPit TPBF Sheet 1	23
Projec Name:	t Cooloo W	ind Farm	1		ect No.		Co-ords: 555352.00 - 750647.00	)	Date	
	on: Cooloo, C	o Galwa	av Ireland	220	90		Level: Dimensions		31/08/20 Scale	;
Client:			D'Sullivan Ltd. (M	<u>۲</u> ۸)			(m): Depth		1:25 Logge	
		les & In Si					1.93		IPP	
Water	Depth	Туре	Results	Depth (m)	Level (m)	Legend	Stratum Description	on		
				0.40		shte shte shte shte shte shte shte shte	Dark brown peat.  Firm light grey mottled yellow SILT.  Grey slightly sandy gravelly CLAY. S.	and and gra	vels are	1 -
							angular to subangular. Sand is mediu is fine to coarse. Presence of boulde TP due to rock head.	um to coarse	e, gravel	
	dece.			1.93			End of Pit at 1.93m			3
Remai									AC	is
Stabili	ıy:								9.	

	DG N & DOHERTY DSOLUTIONS	-				Tr	rial Pit Lo	g	TrialPit TPSS Sheet 1	SA
Projec	t Cooloo W	ind Farr	n		ect No.		Co-ords: 557466.00 - 7	749301.00	Date	)
Name	•			220	98		Level: Dimensions		31/08/20 Scale	
	on: Cooloo, C						_(m):		1:25	
Client	-		O'Sullivan Ltd. (M	KO)	ı		Depth 2.80		Logge IPP	;u
Water Strike	Samp Depth	les & In S Type	itu Testing Results	Depth (m)	Level (m)	Legend	Stratu	ım Description		
Rema	rks:			2.80		Silke Silke Silke  Silke Silke	Light grey slightly sandy cobbles. Sand is medium subrounded. Gravel is fir subrounded.	slightly gravelly SILT wit n to coarse, subangular t	to	1   1   1   1   1   1   1   1   1   1
Stabili									AC	S

G	DG	7			Trial Pit Log					
	N & DOHERT	Y						9	TPSS Sheet 1	
Project		<i>r</i> =		Proj	ect No.		Co-ords: 557383.00 - 7	48868.00	Date	
Name:	Cooloo W	vind Farm	1	220	98		Level:		31/08/20	
Locatio	n: Cooloo, (	Co. Galwa	ay Ireland				Dimensions (m):		Scale 1:25	
Client:	McCarthy	, Kavilla (	 O'Sullivan Ltd. (M	IKU)			Depth		Logge	
<del>                                     </del>				T			2.10		IPP	
Water Strike	Depth	ples & In Si Type	Results	Depth (m)	Level (m)	Legend		m Description		
							[TOPSOIL] Brown slightly Gravel and sand are ang	r gravelly slightly sandy ular to subangular, fine	CLAY. to	=
				2.10			coarse. Grey slightly sandy very of to subangular boulders. Signare is fine to coarse, but the subangular boulders.	gravelly SILT with large Sand is medium to coars	angular se.	1 — — — — — — — — — — — — — — — — — — —
Remar Stabilit									AC	is

	DG N & DOHERTY SOLUTIONS	-				Tr	rial Pit Log		TrialPit TPT	2
Projec Name:	t Cooloo Wi	nd Farm	1	Proj 2209	ect No.		Co-ords: 555608.00 - 748029.00 Level:		Date 30/08/20	
	on: Cooloo, C	o. Galwa	av Ireland	220	90		Dimensions	1	Scale	)
Client:			D'Sullivan Ltd. (Mł	(O)			(m): Depth	-	1:25 Logged	
		les & In Si					1.64		IPP	
Water	Depth	Туре	Results	Depth (m)	Level (m)	Legend	Stratum Description			
				0.50		Alle Alle Alle Alle Alle Alle Alle Alle	Dark brown slightly mottled orange PEAT with content  Light grey slightly sandy clayey GRAVEL. Sar medium to coarse, subangular to rounded. Gr to coarse, subangular to subrounded.  Grey slightly sandy gravelly SILT. Gravel is fin angular to subangular with few cobbles.  End of Pit at 1.64m	nd is avel	is fine	1 2 3 3 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Remai Stabili									AC	I IS
JUDIII	٠,٠									

	DG N & DOHERTY DSOLUTIONS	-				Tı	rial Pit Log	TrialPit TPT Sheet 1	3
Projec Name	Cooloo W	ind Farn	n	Proj 220	ject No. 98		Co-ords: 555566.00 - 748639.00 Level:	Date 30/08/2	
	on: Cooloo, C	o. Galw	ay Ireland		<del></del>		Dimensions (m):	Scal 1:25	е
Client:	: McCarthy	Keville	O'Sullivan Ltd. (M	KO)			Depth 2.10	Logge IPP	ed
Water Strike			itu Testing	Depth (m)	Level (m)	Legend	Stratum Description		
	Depth	Type	Results	0.90		Alle Alle Alle Alle Alle Alle Alle Alle	Grey slightly sandy slightly gravelly SILT with son cobble content. Gravel is subangular to angular, to coarse.  Grey SILT. Cobble content increases with depth.	ne fine to	2
									5 —
Rema Stabili					1			A	GS

G	DG				Tr	rial Pit Log	TrialPit TPT	
	N & DOHERTY SOLUTIONS						Sheet 1	
Projec Name:	t Cooloo Wind Fa	arm		ect No.		Co-ords: 556170.00 - 748592.00	Date	
			220	98		Level: Dimensions	30/08/2	
	on: Cooloo, Co. Ga	·				(m): Depth	1:25 Logge	
Client:		le O'Sullivan Ltd. (MK	D)	I	1	2.70	IPP	,u
Water Strike	Depth Type		Depth (m)	Level (m)	Legend	Stratum Description		
			2.70			Orangish brown slightly gravelly CLAY. Gravel is to medium, angular to subangular.  Brownish grey slightly sandy slightly gravelly CLA Presence of large boulders (<0.50m). Gravel and angular to subangular. High water content.  End of Pit at 2.70m		3
Remai Stabili				1			AC	II S

	DG 1 & DOHERTY SOLUTIONS	[ 				Tr	rial Pit Lo	g	TrialPit TPT Sheet 1	6
Project	Coolee W	ind Farm	1	Proj	ect No.		Co-ords: 555649.00 - 7	49698.00	Date	
Name:	000100 W	III T GIIII	!	220	98		Level:		30/08/2	
Locatio	n: Cooloo, C	o. Galwa	y Ireland				Dimensions (m):		Scale 1:25	
Client:	McCarthy	Keville C	D'Sullivan Ltd. (N	ИКО)			Depth 3.20		Logge IPP	ed
Water Strike	Samp	oles & In Sit	tu Testing	Depth	Level	Legend		m Description		
St W	Depth	Туре	Results	(m)	(m)		Light brown CLAY.			-
										-
										-
						<u> </u>				-
				0.70		 × × × × ×	Grey gravelly SILT with c	obble content. Gravel is	fine to	
						× × × × × × × × × × × × × × × × × × ×	coarse, angular to subroumaterial at 1m deep. Ver	unded. Pocket of organi	С	
						(	rounded at 2.7m deep.			1 -
						× × × ×				-
						× × × × × ×				-
						(				-
						(				-
						× × × × ×				-
						(				
						X X X X X				2 -
						$\times \times $				-
						× × × × × × × × × × × × × × × × × × ×				-
						( × × × × × × × × ×				-
						××××				-
						× × × × × × × × × × × × × × × × × × ×				-
				3.00		\$	Cobbles and boulders. Be to subrounded. [Possible	oulders are 0.2-0.5m su weathered bedrock]	bangular	3 -
				3.20		0,000	End	of Pit at 3.20m		=
										-
										-
										-
										4 -
										-
										-
										-
										5 -
Remar	ks:								· ·	
									Δſ	2.5
Stabilit	y:								AC	JU

GDG GAVIN & DOHERTY GEOSOLUTIONS			Tr	ial Pit Loç	9	TrialPit TPT8 Sheet 1	8
Project Coolea Wind Form		ject No.		Co-ords: 556994.00 - 74	19351.00	Date	;
Name:	220	)98		Level: Dimensions		31/08/20 Scale	
Location: Cooloo, Co. Galway Irela	and 			(m):		1:25	
Client: McCarthy Keville O'Sulliv	van Ltd. (MKO)			Depth 3.50		Logge IPP	ed
Samples & In Situ Testin	Deptil	Level	Legend		n Description		
Depth Type F	1.00 3.50	(m)		Brown gravelly CLAY. Grasubangular to subrounded  Light grey slightly sandy g to coarse. Gravel is fine to boulders (>0.5m) rounded	vel is fine to coarse, I. Presence of rounded  ravelly CLAY. Sand is	medium	2
Remarks: Stability:						AC	5 - 3 S

GDG GAVIN & DOHERTY					Trial Pit Log					TrialPit No TPT9	
GAVIN & DOHERTY GEOSOLUTIONS								Sheet 1 of 1			
Project	Cooloo Wi	nd Farr	n		ect No.		Co-ords: 556825.00 - 7	49874.00	Date		
Name:				220	98		Level:	-	31/08/20		
Location: Cooloo, Co. Galway Ireland						Dimensions (m):		Scale 1:25			
Client: McCarthy Keville O'Sullivan Ltd. (MKO			IKO)			Depth 4.00		Logged IPP			
Water Strike	Sampl Depth	les & In S Type	itu Testing  Results	Depth (m)	Level (m)	Legend	Stratum Description				
				0.25 1.20 4.00		SI/E SI/E SI/E SI/E SI/E SI/E SI/E SI/E	Cream slightly sandy SILT  Very soft yellowish brown  Very soft white SILT.	T. Shell content.		2	
Remark Stability									AC	5 — IS	





## **G.5 GEOPHYSICAL SURVEY**

## Cooloo Wind Farm Cooloo, County Galway

## **Geophysical Survey**

Report Status: Final

MGX Project Number: 6903

MGX File Reference: 6903f-005.doc

5<sup>th</sup> September 2025

### **Confidential Report To:**

MKO Tuam Road

Tuam Road Galway H91 VW84

### Report submitted by: Minerex Geophysics Limited

Issued by:

Unit F4, Maynooth Business Campus Maynooth, Co. Kildare, W23X7Y5

Ireland

Tel.: 01-6510030 Email: <u>info@mgx.ie</u> Author: Jan Stach (Geophysicist)

Reviewer: John Connaughton (Geophysicist)



Subsurface Geophysical Investigations

### **EXECUTIVE SUMMARY**

- 1. Minerex Geophysics Ltd. (MGX) carried out a geophysical survey consisting of the methods 2D-Resistivity (ERT) and Seismic Refraction (p-wave). The survey was carried out for the ground investigation for the Cooloo Wind Farm, Co Galway.
- 2. The main objectives of the survey are to detect possible karstified zones within the rock or karst features, to determine the ground conditions under the site and to determine the depth to rock and the overburden thickness.
- 3. Ground conditions were modelled with two layers.
- 4. Layer A is interpreted as highly consolidated overburden consisting of sandy gravelly clay and silt, which may represent glacial till or weathered limestone.
- 5. Layer B is interpreted as fresh limestone, with a depth generally shallower than 10 m across most of the site, except in the western sections of lines R3 and R4, where it deepens and exceeds 10 m bgl.
- 6. No karst features or karstified rock were identified within the survey area, but considering the increasing depth to bedrock to the west, their potential occurrence further west cannot be excluded.
- 7. Trial Pit logs were provided after the survey. TP11 was carried out within the survey area and terminates on possible bedrock at 2.4m.

# **CONTENTS**

1.	INTRODUCTION	1
1.1	1 Background	1
1.2	2 Objectives	1
1.3	3 Site Description	1
1.4		
1.5	5 Report	2
2.	GEOPHYSICAL SURVEY	3
2.1	1 Methodology	3
2.2	2 2D-Resistivity (ERT)	3
2.3	3 Seismic Refraction (p-waves)	4
2.4	4 Site Work	4
3.	RESULTS AND INTERPRETATION	5
3.1	1 2D-Resistivity (ERT)	5
3.2	2 Seismic Refraction (p-wave)	6
4.	CONCLUSIONS	7
5	REFERENCES	8

## **List of Tables, Maps and Figures:**

Title	Pages	Document Reference
Table 1: Geophysical Survey Locations and Acquisition Parameters	1 x A4	6903f_Tab1.xls
Table 2: Summary of Interpretation	In text	In text
Map 1: Geophysical Survey Location Map	1 x A3	6903f_Drawings.dwg
Figure 1: Models of Geophysical Survey	1 x A3	6903f_Drawings.dwg
Figure 2: Interpretation of Geophysical Survey	1 x A3	6903f_Drawings.dwg

#### 1. INTRODUCTION

#### 1.1 Background

Minerex Geophysics Ltd. (MGX) carried out a geophysical survey for the ground investigation for Cooloo Wind Farm, Co Galway. The survey consisted of 2D-Resistivity (ERT) and Seismic Refraction (p-wave). The survey was commissioned by MKO acting on behalf of Neoen Ltd.

This survey utilized two complementary geophysical methods to improve the final interpretation. The role of geophysics as a non-destructive fast method is to provide a geological interpretation over a wide area to complement direct ground investigation at specific locations.

The geophysical survey was carried out in the area close to the proposed wind turbine T04, as part of the Environmental Impact Assessment Report (EIAR). The objective of the survey was to investigate potential karst features in the bedrock, previously identified in the risk assessment (GDG, 2025) as an area of a high hazard. Within the survey area, surface depressions (dips) were observed, which often indicate the presence of karst features. The results were intended to confirm the presence or absence and nature of karst structures and to provide data to support the development of appropriate mitigation measures.

#### 1.2 Objectives

The main objectives of the geophysical survey were:

- To detect possible karstified zones within the rock or karst features
- To determine the ground conditions under the site
- To determine the depth to rock and the overburden thickness

#### 1.3 Site Description

The site is located in the townland Cooloo, Co. Galway. The survey area is on one grass field. Elevations across the area range from 79.5 mOD to 83.5mOD with the lowest elevations in the northern edge of the site and the highest elevations in the south. The area is surrounded by agricultural fields. Access was available from the local farm road to the north.

#### 1.4 Geology

Online geological maps of Ireland (GSI, 2025) give the following information:

The overburden geology consists of till derived from limestones.

In terms of rock the survey area is underlain by the Visean Limestones, described as undifferentiated Limestone

The Visean Limestones is karstifiable and there are karst features noted in close proximity of the site described as Enclosed Depression.

#### 1.5 Report

This report includes the results and interpretation of the geophysical survey. Maps, figures and tables are included to illustrate the results of the survey. More detailed descriptions of geophysical methods and measurements can be found in GSEG (2002), Milsom (1989) and Reynolds (1997).

The description of soil, rock and the use of geotechnical terms (soft, stiff, dense etc) follows Eurocode (2007) and BSI (2020) standards. The terms are defined in the standards and the physical parameters are related from experience. This geophysical survey has been acquired, processed, interpreted and reported in accordance with these guidelines.

An aerial image was used as the map background as we did not receive a topographical survey map or Ordnance Survey background map. Elevations were surveyed on site and are used in the vertical sections.

The interpretative nature and the non-invasive survey methods must be taken into account when considering the results of this survey and Minerex Geophysics Limited, while using appropriate practice to execute, interpret and present the data, give no guarantees in relation to the existing subsurface.

### 2. GEOPHYSICAL SURVEY

# 2.1 Methodology

The methodology consists of using four 2D-Resistivity (ERT) lines as well as one seismic line along a proposed access road in order to detect potential karst features.

The survey locations are indicated on Map 1. The lines and parameters are tabulated in Table 1.

Table 1: Geophysical Survey Locations and Acquisition Parameters

Resistivity Line	Electrode Spacing/m	Number of Electrodes	Line Length/m
R1	3	53	156
R2	3	53	156
R3	3	32	93
R4	3	32	93
SUM			498
Seismic Line	Geophone Spacing/m	Number of Geophones	Line Length/m
S1	3	24	69
SUM			69

### 2.2 2D-Resistivity (ERT)

2D-Resistivity lines were surveyed with electrode spacing of 3m, up to 53 electrodes per set-up and a maximum length of 156m per set-up. The readings were taken with a Tigre Resistivity Meter, Imager Cables, stainless steel electrodes and a laptop with ImagerPro acquisition software.

During 2D-Resistivity surveying, data is acquired in the form of linear arrays using a suite of metal electrodes. A current is induced into the ground via a pair of electrodes whilst a potential difference is measured across a second pair of electrodes. This allows for the recording of the apparent resistivity in a two-dimensional arrangement below the line. The data is inverted after the survey to obtain a model of subsurface resistivities. The generated model resistivity values and their spatial distribution can then be related to typical values for different geological materials.

The penetration depth of a resistivity set-up increases towards the centre where it reaches an approx. value of 1/6<sup>th</sup> of the array length.

2D-Resistivity has previously proven zones of karstified rock with lateral extents of 5m and more.

# 2.3 Seismic Refraction (p-waves)

The seismic refraction line was surveyed with geophone spacing of 3 m and 24 geophones resulting in a 69m length line. The recording equipment consisted of a 24 Channel GEOMETRICS ES-3000 engineering seismograph with 4.5Hz vertical geophones. The seismic energy source consisted of a hammer and plate. A zero-delay trigger was used to start the recording. Seven shot points were used.

The seismic refraction survey method focuses on propagating p-waves travelling through the subsurface, which are generated by a seismic source. As the wave propagates through the subsurface, its velocity varies as it travels through overburden, rock with different elastic properties, and along geological boundaries. Velocity data is recorded via the surveying equipment, which is then processed, allowing geological layer thicknesses and boundaries to be established.

Seismic Refraction generally determines the depth to horizontal or near horizontal layers where the compaction or strength or rock quality changes with an accuracy of around 20% of the depth to that layer. Where the layers are shallower than the geophone spacing depth deviations of +- 1m to top of layers can occur. Where low velocity layers or shadow zones are present (e.g., below solid ground surface) or where layers dip with more than 20 degrees angle the accuracy becomes much less.

The seismic refraction set-up with 69 m length has a reasonable penetration depth of around 15 m. An internationally accepted maximum depth estimate for a seismic refraction set-up is 1/6 of the set-up length including offshots. The depth penetration varies according to the velocity structure of the subsurface.

### 2.4 Site Work

The data acquisition was carried out on the 26<sup>st</sup> of August 2025. The weather conditions were fair throughout the acquisition period. Health and safety standards were adhered to at all times.

The locations and elevations were surveyed with a Carlson NR3 RTK-GPS to accuracy < 0.05m.

#### 3. RESULTS AND INTERPRETATION

The interpretation of geophysical data is executed utilizing the known response of geophysical measurements, typical physical parameters for subsurface features that may underlay the site, and the experience of the authors.

The interpretation is primarily based on the 2D-Resistivity method. One seismic line was carried out for the purpose of correlating the resistivity data.

## 3.1 2D-Resistivity (ERT)

The 2D-Resistivity data was positioned and inverted with the RES2DINV inversion package. The programme uses a smoothness constrained least-squares inversion method to produce a 2D model of the subsurface resistivities from the recorded apparent resistivity values. Three variations of the least squares method are available and for this project the Jacobian Matrix was recalculated for the first three iterations, then a Quasi-Newton approximation was used for subsequent iterations. Each dataset was inverted using seven iterations resulting in a typical RMS error of <3.0%. The resulting models were colour contoured with the same resistivity scale for all lines and they are displayed as cross sections (Figure 1).

Resistivities are characteristic for certain overburden and rock types. If there is a high content of clay minerals (which are electrically conductive) then the overburden resistivity will be lower than as if there is a high content of clastic grains like sand or gravel. The purer the clay and the lower the sand and gravel content, the lower the resistivity. Water content in overburden layers can influence the resistivities, but generally clay content has a more dominating effect.

Karstified rock is defined in this report as a formerly intact clean limestone rock, liable to karstification, that has been partially dissolved by water over long geological time scales and where the cavities and voids have either remained empty (filled by air) or became filled by overburden sediment (clay, silt, sand), weathering product of the broken rock itself or water. This process would lead to a reduction of the resistivity of the overall rock and therefore karstified rock has a lower resistivity than intact clean limestone rock. This is generally indicated by lower resistivities embedded within high resistivity at depth.

The resistivities cover a range typical for materials from clay rich overburden (low resistivities) to fresh strong unweathered bedrock (high resistivities). The ranges have been taken into the consideration for the interpretation. Lower resistivity values ( $<500\Omega$ m) typically indicate overburden with clay content. Higher resistivities ( $>500\Omega$ m) indicate bedrock types like clean limestone.

Table 2: Summary of Interpretation (Resistivity only)

Layer	General Resistivity Range (Ωm)	Interpretation
Α	<500	Overburden (Sandy gravelly Clay and Silt) or weathered limestone
		, , , , ,
В	>500	Fresh Limestone

# 3.2 Seismic Refraction (p-wave)

The seismic refraction data was positioned and processed with the SEISIMAGER software package to give a layered model of the subsurface. The number of layers has been determined by analysing the seismic traces and 3 layers are used in the models. All seismic lines were subject to a standardised processing sequence which consisted of a topographic correction which was based on integrated elevation data, first break picking, tomographic inversion, travel-time computation via ray-tracing and velocity modelling. Residual deviations of typically 0.4 to 1.8 msec RMS have been obtained for each line. Following each processing stage QC procedures were adhered to. The resulting layer boundaries are shown as thick lines overlaid on the 2D-Resistivity cross sections (Figure 1). The average seismic velocities obtained within the layers are annotated on the sections as bold black numbers.

The p-wave seismic velocity is closely linked to the density of subsurface materials and to parameters like compaction, stiffness, strength and rock quality. The higher the density of the subsurface materials the higher the seismic velocity. More compacted, stiffer, denser and stronger material will have a higher seismic velocity. For rock, the seismic velocity is higher when the rock is stronger, less weathered and has a higher quality. If the rock is more weathered, broken, fractured, fissured or karstified then the seismic velocity will be reduced compared to that of intact fresh rock.

Because of the above relationship, the seismic refraction method and seismic velocities are suitable to investigate ground where the layers get denser, more compacted and stronger with depth.

The modelled seismic data has created the following layered ground model:

Layer 1 has a thickness of around 1.5 m and seismic velocities of 400m/s. This overburden would be soil with a soft or loose stiffness or compaction.

Layer 2 velocity of 2200m/s indicate overburden with very stiff to hard or very dense strength or compaction or a very weathered rock with poor rock quality. The thickness varies between 5 and 7m.

Competent rock (Layer 3) is indicated by seismic velocity of 4000m/s and the depth to the top of this rock varies between 7 and 9m bgl.

Layer 2 identified in the seismic refraction survey corresponds to Layer A from the resistivity interpretation Overburden (Sandy gravelly Clay and Silt) or weathered limestone, while Layer 3 correlates with Layer B (fresh limestone).


## 4. CONCLUSIONS

The following conclusions are made:

- The geophysical surveys carried out at the Cooloo Wind Farm, Co. Galway consisted of 2D-Resistivity (ERT) and Seismic Refraction (p-wave).
- The main objective of the survey was to identify possible karst feature or karstified rock within the survey area.
- The interpretation is based on 2D-Resistivity data, and two layers have been identified. The seismic refraction survey ties in well with the results from the 2D-Resistivity survey.
- Layer A with resistivities <500 Ωm is interpreted as overburden consisting of sandy gravelly clay and silt or weathered limestone.
- This layer may represent glacial till and, as it corresponds to seismic Layer 2 with a p-wave velocity
  of 2200 m/s, it is described as a highly consolidated overburden. The resistivities and seismic
  velocities could also be interpreted as weathered limestone.
- Layer B with resistivities >500 Ωm is interpreted as fresh limestone. The depth to this layer varies along the lines between 7 and 13 m, but in the most of the site is shallower than 10 m.
- The depth to good bedrock is relatively consistent along the entire length of the survey lines, except in the western sections of lines R3 and R4, where it deepens and exceeds 10 m bgl.
- Considering the increasing depth to good bedrock to the west, the potential occurrence of karst features further west cannot be excluded.
- No karst features or karstified rock were identified within the survey area.
- The trial pit log TP11 describes very stiff slightly sandy gravelly cobbly clay from 0.9 2.35m bgl which would be consistent with glacial till. The trial pit terminates on possible bedrock at 2.4m bgl within layer A.

# 5. REFERENCES

- BSI, 2020. BS5930: 2015+A1:2020, Code of Practice for Ground Investigations, British Standards Institute 2020
- 2. Eurocode, 2007. EN 1997-2:2007. Eurocode 7. Part 2 Ground Investigation and Testing 2007
- 3. **GSEG, 2002.** Geophysics in Engineering Investigations. Geological Society Engineering Geology Special Publication 19, London, 2002
- 4. GSI, 2025. www.gsi.ie. Online Geological Map of Ireland. Geological Survey of Ireland 2025
- 5. Milsom, 1989. Field Geophysics. John Wiley and Sons, 1989
- 6. Reynolds, 1997. An Introduction to Applied and Environmental Geophysics. John Wiley and Son, 1997
- 7. Weaver, 1975. Geological Factors significant in the Assessment of Rippability, 1975
- 8. GDG, 2025. Geotechnical Karst Risk Assessment. Gavin & Doherty Geosolutions, 2025





Unit F4, Maynooth Business Campus Maynooth, Co. Kildare Tel. (01) 6510030 Email: info@mgx.ie Web: www.mgx.ie

CLIENT	MKO
PROJECT	Cooloo Wind Farm, Co. Galway Geophysical Survey
TITLE	Map 1: Geophysical Survey Location Map

ARTHUR DESIGNATION	Control of Additional Property
SCALE:	1:1000 @ A3
PROJECT:	6903
DRAWN:	JS
DATE:	05/09/2025
MGX FILE:	6903f_Drawings.dwg
STATUS:	Final


Geoph	ysical Survey Locations:
R2	2D-Resistivity Line
S1	Seismic Refraction Line


Locations are in Irish Transverse Mercator (ITM), Elevations are in mOD (Malin Head)


Direct Ground Investigation Locations:




Trial Pit









# Abbreviated GI Logs:

TP01 Trial Pit Name and Location


CI Clay Slt Silt



Unit F4, Maynooth Business Campus Maynooth, Co. Kildare Tel. (01) 6510030 Email: info@mgx.ie Web: www.mgx.ie

CLIENT	МКО
PROJECT	Cooloo Wind Farm, Co. Galway Geophysical Survey
TITLE	Figure 1: Models of Geophysical Survey

SCALE:	1:1000 @ A3, VE x 2
PROJECT:	6903
DRAWN:	JS
DATE:	05/09/2025
MGX FILE:	6903f_Drawings.dwg
STATUS:	Final




Layers from Seismic Refraction Model:


Ground Surface/Top of Layer 1 (400 m/s)


Top of Layer 2 (2200 m/s)


Top of Layer 2 (2200 m/s)
Top of Layer 3 (4000 m/s)

2200 Seismic Velocity in m/s











Email: info@mgx.ie Web: www.mgx.ie

CLIENT	MKO
PROJECT	Cooloo Wind Farm, Co. Galway Geophysical Survey
TITLE	Figure 2: Interpretation of Geophysical Survey

SCALE:	1:1000 @ A3, VE x 2
PROJECT:	6903
DRAWN:	JS
DATE:	05/09/2025
MGX FILE:	6903f_Drawings.dwg
STATUS:	Final

# Interpretation Figures:

1 Overburden (Sandy gravelly Clay and Silt) or Weathered Limestone

2 Fresh Limestone

# Abbreviated GI Logs:

TP01 Trial Pit Name and Location


Cl Clay Slt Silt








# **APPENDIX H HAZARD RATING MATRIX**


	A	В	С	D		Е	F				
	Underlying Rock	Bedrock Formation Change	Rating of Overburden Thickness	Cover	Geological	Density of Karstic Features within 250m	Karst within	Evidence - Rating= E* F		Hazard	Normalised Hazard Class Score
Location	Susceptible = 2 Non Susceptible Limestone = 1 Not Susceptible= 0	Within 100m = 20ver 100m = 1	1-5M = 3.5-10M = 2	Low Cover=1 Granular=1 Peat=1 Glacial Deposits=2	Min=0 Max=24	None=1 1-2=2 3-4=3 >4=4	Yes=3 No=1	Min=1 Max=12	Min=1 Max=288	High36-60 Medium 12 -	Very High= 5, High=4, Medium=3, Low=2, Negligible = 1
T1	2	1	3	2	12	2	1	2	24	Medium	3
T1 Hardstand	2	1	3	2	12	1	1	1	12	Low	2
Т2	2	. 1	3	1	6	1	1	1	6	Low	2
T2 Hardstand	2	1	3	1	6	2	1	2	12	Low	2
Т3	2	1	3	2	12	1	1	1	12	Low	2
T3 Hardstand	2	1	3	2	12	1	1	1	12	Low	2
T4	2	1	3	2	12	4	1	4	48	High	4
T4 Hardstand	2	1	3	2	12	4	1	4		High Law	4
T5 T5 Hardstand	2	1	3	1	6	1	1	1		Low Low	2
To Harastana		1								LOW	
Т6	2	1	3	2	12	1	1	1	12	Low	2
T6 Hardstand	2	1	3	2	12	1	1	1	12	Low	2
T7	2	2	3	1	12		1	1		Low	2
T7 Hardstand	2	2	3	1	12		1	1		Low	2
T8 T8 Hardstand	2	1	3	2	12 12		1	2		Low Medium	3
To Harastana		1	3		12		1		24	riculani	
Т9	2	1	3	1	6	1	1	1	6	Low	2
T9 Hardstand	2	1	3	1	6	1	1	1	6	Low	2
Substation	2	1	3	1	6	1	1	1	6	Low	2
Construction Compound	2	1	3	2	12	1	1	1		Low	2
Met Mast	2	1	3	1	6	1	1	1		Low	2
AL1 AL1_B	2	1	3	2 2	<del> </del>	1	1	1		Low Low	2
AL1_B	2	1	3	2	<del> </del>	2	1	2	-	Medium	3
AL3	2	1	3	2	<del> </del>			2		Medium	3
AL3b	2	1	3	2	12	4	1	4		High	4
AL4	2	1	3	1	6	1	1	1		Low	2
AL4 Float AL4b	2	1	2	1	6	2	1	2		Low Low	2
AL4b Float	2	2	2	1	8	1	1	1		Low	2
AL4c	2	2	3	1	12	_1	1	1		Low	2
AL5	2	1	3	1	6	1	1	1		Low	2
AL5_Float AL5b	2	1	2	1	4	1	1	1		Low	2
AL5b_Float	2	1	2	1	4 A	2	1	2		Low Low	2
AL6	2	1	3	2	12		1	4		High	4
AL6b	2	1	3	2	12	3		3	36	Medium	3
AL6c	2	1	3	2				2		Medium	3
AL8	2	1	3	2	12	1	1	1	12	Low	2


























# **APPENDIX I GEOTECHNICAL RISK REGISTER**

Geotechnical Risk	Infratructure Location	Hazard Title	Risk Description F	isk Cause	Risk Impact	Hazard Score Impact Score	Risk Rating	Mitigation massures	Residual Hazard	Residual	Residual Risk
1		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Risk of severe injuries or death     2.Bearing capacity failure.  3. Severe damage to foundations and plant	3 5	15	Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered	Score 1	Impact Score	Rating 5
2		Subsidence of soils overlying suffosion or buried dolines	Subsidence over buried or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled	3 4	12	Detailed ground investigation if required, mitigation through use of grouted piled foundations, or bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.	1	4	4
3	T1 Foundation	Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.  2. Bearing capacity failure.	3 3	9	Detailed ground investigation, mitigation through use of grouted piled foundations, or bridging cavities with concrete, or geogrid and coarse	1	3	3
			foundations or geotechnical re-design  Variable rockhead, or unexpected cavities leading to	Development of subsurface cavities due to karstification of	Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Requirement for remediation through e.g.		_	granular fll if appropriate.  Detailed ground investigation, mitigation through			
4		Variable rockhead,	unforeseen requirement for piled foundations or geotechnical re-design	underlying bedrock, with cohesive soil cover.	ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.	3 3	9	use of piled foundations if appropriate.	1	3	3
5		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	Requirement for remediation through e.g. ground improvement or the use of piled foundations.	3 3	9	Detailed ground investigation, mitigation through use of piled foundations if appropriate	1	3	3
4		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Risk of severe injuries or death     2.Bearing capacity failure.      3. Severe damage to foundations and plant	2 5	10	Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered	1	5	5
					Unacceptable amounts of settlement.						
5		Subsidence of soils overlying suffosion or buried dolines	Subsidence overburied or suffosion dolines, leading to differential settlement at hardstand	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	2. Bearing capacity failure.	2 3	6	Detailed ground investigation if required, mitigation through bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.		3	3
	T1 Hardstand				3. Requirement for remediation through e.g. ground improvement						
6		Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 2	4	Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	1	2	2
7		Variable rockhead, or unexpected cavities	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. ground improvement      Unacceptable amounts of settlement.	2 2	4	Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	1	2	2
8		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 2	4	Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	1	2	2
9		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Risk of severe injuries or death     2.Bearing capacity failure.      3. Severe damage to foundations and plant     1. Unacceptable amounts of settlement.	2 5	10	Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered	1	5	5
10		Subsidence of soils overlying suffosion or buried dolines	Subsidence over buried or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.	2 4	8	Detailed ground investigation if required, mitigation through use of grouted piled foundations, or bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.	1	4	4
11	T2 Foundation	Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 3	6	Detailed ground investigation, mitigation through use of grouted piled foundations, or bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	1	3	3
12		Variable rockhead,	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. ground improvement or the use of piled foundations.      Unacceptable amounts of settlement.	2 3	6	Detailed ground investigation, mitigation through use of piled foundations if appropriate.	1	3	3
13		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	2. Bearing capacity failure.     3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death	2 3	6	Detailed ground investigation, mitigation through use of piled foundations if appropriate	1	3	3
14		Rapid collapse of sikhole/doline cavity  Subsidence of soils	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	2.Bearing capacity failure.  3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.	2 5	10	Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered  Detailed ground investigation if required, mitigation	1	5	5
15		overlying suffosion or buried dolines	Subsidence overburied or suffosion dolines, leading to differential settlement at hardstand	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	2. Bearing capacity failure.     3. Requirement for remediation through e.g. ground improvement     1. Unacceptable amounts of settlement.     2. Bearing capacity failure.	2 3	6	through bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.		3	3
16	T2 Hardstand	Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 2	4	Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	1	2	2
17		Variable rockhead, or unexpected cavities	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. ground improvement      Unacceptable amounts of settlement.	2 2	4	Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	1	2	2
18		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.      1. Risk of severe injuries or death	2 2	4	Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	1	2	2
19		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	2.Bearing capacity failure.      3. Severe damage to foundations and plant     1. Unacceptable amounts of settlement.	2 5	10	Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered  Detailed ground investigation if required, mitigation	1	5	5
20		Subsidence of soils overlying suffosion or buried dolines	Subsidence over buried or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.      1. Unacceptable amounts of settlement.      2. Regging capacity failure.	2 4	8	through use of grouted piled foundations, or bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.	1	4	4
21	T3 Foundation	Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 3	6	Detailed ground investigation, mitigation through use of grouted piled foundations, or bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	1	3	3
22		Variable rockhead,	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. ground improvement or the use of piled foundations.      Unacceptable amounts of settlement.	2 3	6	Detailed ground investigation, mitigation through use of piled foundations if appropriate.	1	3	3
23		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.      1. Risk of severe injuries or death	2 3	6	Detailed ground investigation, mitigation through use of piled foundations if appropriate	1	3	3
24		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	2.Bearing capacity failure.  3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.	2 5	10	Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered  Detailed ground investigation if required, mitigation	1	5	5
25		Subsidence of soils overlying suffosion or buried dolines	Subsidence overburied or suffosion dolines, leading to differential settlement at hardstand	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement      1. Unacceptable amounts of settlement.	2 3	6	Detailed ground investigation if required, mitigation through bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.	1	3	3
26	T3 Hardstand	Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 2	4	Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	1	2	2
27		Variable rockhead, or unexpected cavities	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. ground improvement      Unacceptable amounts of settlement.	2 2	4	Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	1	2	2
28		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 2	4	Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	1	2	2

		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Risk of severe injuries or death 2.Bearing capacity failure. 4 3. Severe damage to foundations and plant	5	20	Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered	1	5	5
30		Subsidence of soils overlying suffosion or buried dolines	Subsidence over buried or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled	4	16	Detailed ground investigation if required, mitigation through use of grouted piled foundations, or bridging cavities if appropriate, micrositing of	2	4	8
31	T4 Foundation	Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled	Development of subsurface cavities due to karstification of	foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g.  4	3	12	Detailed ground investigation, mitigation through use of grouted piled foundations, or bridging	2	3	6
32		Variable rockhead,	foundations or geotechnical re-design  Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or	underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of	ground improvement or the use of piled foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled  4	2	12	cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through	2	2	-
33		Solutionally Weathered	geotechnical re-design  Excavation instability and reduced bearing capacity.	underlying bedrock, with cohesive soil cover.  Deeply weathered limestone with voids and softened zones.	foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g.  4	3	12	Detailed ground investigation, mitigation through	2	3	6
34		Rapid collapse of	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of	ground improvement or the use of piled foundations.  1. Risk of severe injuries or death  2.Bearing capacity failure.  4	5	20	use of piled foundations if appropriate  Detailed ground investigation if required, micrositing of turbine if significant cavities are	1	5	5
35		Subsidence of soils overlying suffosion or	Subsidence overburied or suffosion dolines, leading to differential settlement at hardstand	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g.	3	12	Detailed ground investigation if required, mitigation through bridging cavities if appropriate, micrositing	2	3	6
36	T4 Hardstand	buried dolines  Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	ground improvement  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g.  4	2	8	of turbine if significant cavities are encountered.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and	2	2	4
37		Variable rockhead, or unexpected cavities	foundations or geotechnical re-design  Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	ground improvement or the use of piled foundations.  1. Requirement for remediation through e.g. ground improvement	2	8	coarse granular fll if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	2	2	4
38		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled	2	8	Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	2	2	4
39		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	foundations.  1. Risk of severe injuries or death  2.Bearing capacity failure.  2  3. Severe damage to foundations and plant	5	10	Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered	1	5	5
40		Subsidence of soils overlying suffosion or buried dolines	Subsidence over buried or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled  2	4	8	Detailed ground investigation if required, mitigation through use of grouted piled foundations, or bridging cavities if appropriate, micrositing of	1	4	4
41	T5 Foundation	Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled	Development of subsurface cavities due to karstification of	foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.	2	6	Detailed ground investigation, mitigation through use of grouted piled foundations, or bridging	1	2	2
			foundations or geotechnical re-design  Variable rockhead, or unexpected cavities leading to	underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of	3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Requirement for remediation through e.g.	3	6	cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through		3	2
42		Variable rockhead,  Solutionally Weathered	unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g.  2	3	6	use of piled foundations if appropriate.  Detailed ground investigation, mitigation through	1	3	3
44		Rock Rapid collapse of	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of	ground improvement or the use of piled foundations.  1. Risk of severe injuries or death 2.Bearing capacity failure.	5	10	use of piled foundations if appropriate  Detailed ground investigation if required, micrositing of turbine if significant cavities are	1	5	5
45		Subsidence of soils overlying suffosion or	Subsidence overburied or suffosion dolines, leading to differential settlement at hardstand	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g.	3	6	encountered  Detailed ground investigation if required, mitigation through bridging cavities if appropriate, micrositing	1	3	3
46	T5 Hardstand	buried dolines  Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	ground improvement  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g.  2	2	4	of turbine if significant cavities are encountered.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and	1	2	2
47		Variable rockhead, or unexpected cavities	foundations or geotechnical re-design  Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	ground improvement or the use of piled foundations.  1. Requirement for remediation through e.g. ground improvement	2	4	coarse granular fll if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	1	2	2
48		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled	2	4	Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	1	2	2
49		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	foundations.  1. Risk of severe injuries or death  2.Bearing capacity failure.  2  3. Severe damage to foundations and plant	5	10	Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered	1	5	5
50		Subsidence of soils overlying suffosion or buried dolines	Subsidence over buried or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  2	4	8	Detailed ground investigation if required, mitigation through use of grouted piled foundations, or bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.	1	4	4
51	T6 Foundation	Cavities / Voids	Foundation failure or differential settlement. Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g.  2	3	6	Detailed ground investigation, mitigation through use of grouted piled foundations, or bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	1	3	3
52					ground improvement or the use of piled				1		
53		Variable rockhead,	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	ground improvement or the use of piled foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled 2 foundations.	3	6	Detailed ground investigation, mitigation through use of piled foundations if appropriate.	1	3	3
		Variable rockhead,  Solutionally Weathered Rock	unforeseen requirement for piled foundations or	•	foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled	3	6		1	3	3
54		Solutionally Weathered	unforeseen requirement for piled foundations or geotechnical re-design	underlying bedrock, with cohesive soil cover.	foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. 2	3 3		use of piled foundations if appropriate.  Detailed ground investigation, mitigation through	1 1	3	3
54		Solutionally Weathered Rock Rapid collapse of	unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.  Development of subsurface cavities due to karstification of	foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death 2. Bearing capacity failure.  2. Severe damage to foundations and plant  1. Unacceptable amounts of settlement. 2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement	3 3 5	6	use of piled foundations if appropriate.  Detailed ground investigation, mitigation through use of piled foundations if appropriate  Detailed ground investigation if required, micrositing of turbine if significant cavities are	1 1	3 3 5	3 3 5
	T6 Hardstand	Solutionally Weathered Rock  Rapid collapse of sikhole/doline cavity  Subsidence of soils overlying suffosion or	unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.  Rapid collapse of cavity roof during construction  Subsidence overburied or suffosion dolines, leading	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death  2. Bearing capacity failure.  2. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  2. Bearing capacity failure.  2. Requirement for remediation through e.g.	3 3 5 3	6	use of piled foundations if appropriate.  Detailed ground investigation, mitigation through use of piled foundations if appropriate  Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered  Detailed ground investigation if required, mitigation through bridging cavities if appropriate, micrositing	1 1 1 1	3 3 5 3	3 3 3
55	T6 Hardstand	Solutionally Weathered Rock  Rapid collapse of sikhole/doline cavity  Subsidence of soils overlying suffosion or buried dolines	unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.  Rapid collapse of cavity roof during construction  Subsidence overburied or suffosion dolines, leading to differential settlement at hardstand  Foundation failure or differential settlement. Unforeseen requirement for piled	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death  2. Bearing capacity failure.  3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Requirement for remediation through e.g. ground improvement  1. Unacceptable amounts of settlement.	3 3 5 2 2	6	Detailed ground investigation, mitigation through use of piled foundations if appropriate  Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered  Detailed ground investigation if required, mitigation through bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	1 1 1 1 1	3 3 5 2 2	3 3 5 2 2
55	T6 Hardstand	Solutionally Weathered Rock  Rapid collapse of sikhole/doline cavity  Subsidence of soils overlying suffosion or buried dolines  Cavities / Voids  Variable rockhead, or	unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.  Rapid collapse of cavity roof during construction  Subsidence overburied or suffosion dolines, leading to differential settlement at hardstand  Foundation failure or differential settlement. Unforeseen requirement for piled foundations or geotechnical re-design  Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Deeply weathered limestone with voids and softened zones.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death  2. Bearing capacity failure.  3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	3 3 5 2 2	6	Detailed ground investigation, mitigation through use of piled foundations if appropriate  Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered  Detailed ground investigation if required, mitigation through bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	1 1 1 1 1 1	3 3 5 2 2	3 3 5 2 2
55 56 57	T6 Hardstand	Solutionally Weathered Rock  Rapid collapse of sikhole/doline cavity  Subsidence of soils overlying suffosion or buried dolines  Cavities / Voids  Variable rockhead, or unexpected cavities  Solutionally Weathered	unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.  Rapid collapse of cavity roof during construction  Subsidence overburied or suffosion dolines, leading to differential settlement at hardstand  Foundation failure or differential settlement. Unforeseen requirement for piled foundations or geotechnical re-design  Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death  2. Bearing capacity failure.  3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Requirement for remediation through e.g. ground improvement  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	3 3 5 2 2 2	6	Detailed ground investigation, mitigation through use of piled foundations if appropriate  Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered  Detailed ground investigation if required, mitigation through bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered	1 1 1 1 1 1 1	3 3 5 2 2 2	3 3 5 2 2 2
55 56 57 58	T6 Hardstand	Solutionally Weathered Rock  Rapid collapse of sikhole/doline cavity  Subsidence of soils overlying suffosion or buried dolines  Cavities / Voids  Variable rockhead, or unexpected cavities  Solutionally Weathered Rock  Rapid collapse of	unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.  Rapid collapse of cavity roof during construction  Subsidence overburied or suffosion dolines, leading to differential settlement at hardstand  Foundation failure or differential settlement. Unforeseen requirement for piled foundations or geotechnical re-design  Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death  2. Bearing capacity failure.  3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Requirement for remediation through e.g. ground improvement  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death  2. Bearing capacity failure.  3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	3 3 5 3 2 2 2 5	6 10 6 4 4	Detailed ground investigation, mitigation through use of piled foundations if appropriate  Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered  Detailed ground investigation if required, mitigation through bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	1 1 1 1 1 1 1 1 1	3 3 5 2 2 2 4	3 3 5 2 2 2 5
55 56 57 58	T6 Hardstand  T7 Foundation	Solutionally Weathered Rock  Rapid collapse of sikhole/doline cavity  Subsidence of soils overlying suffosion or buried dolines  Cavities / Voids  Variable rockhead, or unexpected cavities  Solutionally Weathered Rock  Rapid collapse of sikhole/doline cavity  Subsidence of soils overlying suffosion or	unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.  Rapid collapse of cavity roof during construction  Subsidence overburied or suffosion dolines, leading to differential settlement at hardstand  Foundation failure or differential settlement. Unforeseen requirement for piled foundations or geotechnical re-design  Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.  Rapid collapse of cavity roof during construction  Subsidence over buried or suffosion dolines, leading	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with voids and softened zones.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death  2. Bearing capacity failure.  3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death  2. Bearing capacity failure.  3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	3 3 5 3 2 2 2 4	6 10 6 4 4 10	Detailed ground investigation, mitigation through use of piled foundations if appropriate  Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered  Detailed ground investigation if required, mitigation through bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered  Detailed ground investigation if required, mitigation through use of grouted piled foundations, or bridging cavities if appropriate, micrositing of	1 1 1 1 1 1 1 1 1 1	3 3 5 2 2 2 4	3 3 5 2 2 2 4
55 56 57 58 59 60		Solutionally Weathered Rock  Rapid collapse of sikhole/doline cavity  Subsidence of soils overlying suffosion or buried dolines  Cavities / Voids  Variable rockhead, or unexpected cavities  Solutionally Weathered Rock  Rapid collapse of sikhole/doline cavity  Subsidence of soils overlying suffosion or buried dolines	unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.  Rapid collapse of cavity roof during construction  Subsidence overburied or suffosion dolines, leading to differential settlement at hardstand  Foundation failure or differential settlement. Unforeseen requirement for piled foundations or geotechnical re-design  Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.  Rapid collapse of cavity roof during construction  Subsidence over buried or suffosion dolines, leading to differential settlement at turbine foundations  Foundation failure or differential settlement. Unforeseen requirement for piled	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Deeply weathered limestone with voids and softened zones.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death  2. Bearing capacity failure.  3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death  2. Bearing capacity failure.  3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.	3 3 5 3 2 2 2 4 3	6 10 4 4 10 8	Detailed ground investigation, mitigation through use of piled foundations if appropriate  Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered  Detailed ground investigation if required, mitigation through bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll frequired, micrositing of turbine if significant cavities are encountered  Detailed ground investigation if required, mitigation through use of grouted piled foundations, or bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.  Detailed ground investigation, mitigation through use of grouted piled foundations, or bridging cavities with concrete, or geogrid and coarse	1 1 1 1 1 1 1 1 1 1	3 3 2 2 2 4 3	3 3 3 2 2 2 2 4 3
55 56 57 58 59 60		Solutionally Weathered Rock  Rapid collapse of sikhole/doline cavity  Subsidence of soils overlying suffosion or buried dolines  Cavities / Voids  Variable rockhead, or unexpected cavities  Solutionally Weathered Rock  Rapid collapse of sikhole/doline cavity  Subsidence of soils overlying suffosion or buried dolines  Cavities / Voids	unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.  Rapid collapse of cavity roof during construction  Subsidence overburied or suffosion dolines, leading to differential settlement at hardstand  Foundation failure or differential settlement.Unforeseen requirement for piled foundations or geotechnical re-design  Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.  Rapid collapse of cavity roof during construction  Subsidence over buried or suffosion dolines, leading to differential settlement at turbine foundations  Foundation failure or differential settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Deeply weathered limestone with voids and softened zones.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death  2. Bearing capacity failure.  3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Requirement for remediation through e.g. ground improvement  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death  2. Bearing capacity failure.  3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	3 3 5 2 2 2 5 4 3	6 10 6 4 4 10 8 6	use of piled foundations if appropriate.  Detailed ground investigation, mitigation through use of piled foundations if appropriate  Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered  Detailed ground investigation if required, mitigation through bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered  Detailed ground investigation if required, mitigation through use of grouted piled foundations, or bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.  Detailed ground investigation, mitigation through use of grouted piled foundations, or bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through use of grouted piled foundations, or bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	1 1 1 1 1 1 1 1 1 1 1 1	3 3 5 2 2 2 3 3 3	3 3 5 2 2 2 2 3 3 3
55 56 57 58 59 60 61		Solutionally Weathered Rock  Rapid collapse of sikhole/doline cavity  Subsidence of soils overlying suffosion or buried dolines  Cavities / Voids  Variable rockhead, or unexpected cavities  Solutionally Weathered Rock  Rapid collapse of sikhole/doline cavity  Subsidence of soils overlying suffosion or buried dolines  Cavities / Voids  Variable rockhead,  Solutionally Weathered	unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.  Rapid collapse of cavity roof during construction  Subsidence overburied or suffosion dolines, leading to differential settlement at hardstand  Foundation failure or differential settlement. Unforeseen requirement for piled foundations or geotechnical re-design  Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.  Rapid collapse of cavity roof during construction  Subsidence over buried or suffosion dolines, leading to differential settlement at turbine foundations  Foundation failure or differential settlement. Unforeseen requirement for piled foundations or geotechnical re-design  Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death  2. Bearing capacity failure.  3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death  2. Bearing capacity failure.  3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Linacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Linacceptable amounts of settlement.  2. Bearin	3 3 5 2 2 2 3 3 3 3 3 3	6 10 4 4 10 8 6	Detailed ground investigation, mitigation through use of piled foundations if appropriate  Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered  Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered.  Detailed ground investigation, mitigation through bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered  Detailed ground investigation if required, mitigation through use of grouted piled foundations, or bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.  Detailed ground investigation, mitigation through use of grouted piled foundations, or bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through use of piled foundations, or bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	3 3 5 2 2 2 3 3 3 3	3 3 5 2 2 2 2 4 3 3
55 56 57 58 59 60 61 62		Solutionally Weathered Rock  Rapid collapse of sikhole/doline cavity  Subsidence of soils overlying suffosion or buried dolines  Cavities / Voids  Variable rockhead, or unexpected cavities  Solutionally Weathered Rock  Rapid collapse of sikhole/doline cavity  Subsidence of soils overlying suffosion or buried dolines  Cavities / Voids  Variable rockhead,  Solutionally Weathered Rock  Rapid collapse of	Excavation instability and reduced bearing capacity.  Rapid collapse of cavity roof during construction  Subsidence overburied or suffosion dolines, leading to differential settlement at hardstand  Foundation failure or differential settlement. Unforeseen requirement for piled foundations or geotechnical re-design  Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.  Rapid collapse of cavity roof during construction  Subsidence over buried or suffosion dolines, leading to differential settlement at turbine foundations  Foundation failure or differential settlement. Unforeseen requirement for piled foundations or geotechnical re-design  Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Deeply weathered limestone with voids and softened zones.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death  2. Bearing capacity failure.  3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death  2. Bearing capacity failure.  3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death  2. Bearing capacity failure.	3 3 5 3 2 2 2 2 3 3 3 3 3 3 3	6 10 4 4 10 8 6 6	Detailed ground investigation, mitigation through use of piled foundations if appropriate  Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered  Detailed ground investigation if required, mitigation through bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fil if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fil if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fil if appropriate.  Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered  Detailed ground investigation if required, mitigation through use of grouted piled foundations, or bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.  Detailed ground investigation, mitigation through use of grouted piled foundations, or bridging cavities with concrete, or geogrid and coarse granular fil if appropriate.  Detailed ground investigation, mitigation through use of piled foundations if appropriate.  Detailed ground investigation, mitigation through use of piled foundations if appropriate.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	3 3 5 2 2 2 3 3 3 3	3 3 5 2 2 2 2 3 3 3 3 3
55 56 57 58 59 60 61 62		Solutionally Weathered Rock  Rapid collapse of sikhole/doline cavity  Subsidence of soils overlying suffosion or buried dolines  Cavities / Voids  Variable rockhead, or unexpected cavities  Solutionally Weathered Rock  Rapid collapse of sikhole/doline cavity  Subsidence of soils overlying suffosion or buried dolines  Cavities / Voids  Variable rockhead,  Cavities / Voids  Variable rockhead,  Solutionally Weathered Rock  Rapid collapse of sikhole/doline cavity  Subsidence of soils overlying suffosion or buried dolines	unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.  Rapid collapse of cavity roof during construction  Subsidence overburied or suffosion dolines, leading to differential settlement at hardstand  Foundation failure or differential settlement. Unforeseen requirement for piled foundations or geotechnical re-design  Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.  Rapid collapse of cavity roof during construction  Subsidence over buried or suffosion dolines, leading to differential settlement at turbine foundations  Foundation failure or differential settlement. Unforeseen requirement for piled foundations or geotechnical re-design  Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.  Rapid collapse of cavity roof during construction  Excavation instability and reduced bearing capacity.  Rapid collapse of cavity roof during construction  Subsidence overburied or suffosion dolines, leading to differential settlement. Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death  2. Bearing capacity failure.  3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death  2. Bearing capacity failure.  3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death  2. Bearing capacity failure.  3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.  2. Bearing capacity failure.  3. Severe damage to foundations and pl	3 3 5 3 2 2 2 3 3 3 3 3 3	6 10 6 4 4 10 8 6 6 6 10	Detailed ground investigation, mitigation through use of piled foundations if appropriate  Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered  Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fil if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fil if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fil if appropriate.  Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered  Detailed ground investigation if required, mitigation through use of grouted piled foundations, or bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.  Detailed ground investigation, mitigation through use of grouted piled foundations, or bridging cavities with concrete, or geogrid and coarse granular fil if appropriate.  Detailed ground investigation, mitigation through use of piled foundations if appropriate.  Detailed ground investigation, mitigation through use of piled foundations if appropriate.  Detailed ground investigation, mitigation through use of piled foundations if appropriate.  Detailed ground investigation, mitigation through bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.  Detailed ground investigation, mitigation through bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	3 3 5 3 2 2 2 3 3 3 3	3 3 5 2 2 2 4 3 3 3
55 56 57 58 59 60 61 62 63	T7 Foundation	Solutionally Weathered Rock  Rapid collapse of sikhole/doline cavity  Subsidence of soils overlying suffosion or buried dolines  Cavities / Voids  Variable rockhead, or unexpected cavities  Solutionally Weathered Rock  Rapid collapse of sikhole/doline cavity  Subsidence of soils overlying suffosion or buried dolines  Cavities / Voids  Variable rockhead,  Solutionally Weathered Rock  Rapid collapse of sikhole/doline cavity  Subsidence of soils overlying suffosion or buried dolines	unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.  Rapid collapse of cavity roof during construction  Subsidence overburied or suffosion dolines, leading to differential settlement at hardstand  Foundation failure or differential settlement. Unforeseen requirement for piled foundations or geotechnical re-design  Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.  Rapid collapse of cavity roof during construction  Subsidence over buried or suffosion dolines, leading to differential settlement at turbine foundations  Foundation failure or differential settlement. Unforeseen requirement for piled foundations or geotechnical re-design  Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design  Excavation instability and reduced bearing capacity.  Rapid collapse of cavity roof during construction  Subsidence overburied or suffosion dolines, leading to differential settlement at hardstand  Foundation failure or differential settlement. Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.  Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement. 2. Bearing capacity failure. 3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death 2. Bearing capacity failure. 3. Severe damage to foundations and plant 1. Unacceptable amounts of settlement. 2. Bearing capacity failure. 3. Requirement for remediation through e.g. ground improvement 1. Unacceptable amounts of settlement. 2. Bearing capacity failure. 3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death 2. Bearing capacity failure. 3. Severe damage to foundations and plant 1. Unacceptable amounts of settlement. 2. Bearing capacity failure. 3. Severe damage to foundations and plant 1. Unacceptable amounts of settlement. 2. Bearing capacity failure. 3. Requirement for remediation through e.g. ground improvement or the use of piled foundations. 1. Unacceptable amounts of settlement. 2. Bearing capacity failure. 3. Requirement for remediation through e.g. ground improvement or the use of piled foundations. 1. Unacceptable amounts of settlement. 2. Bearing capacity failure. 3. Requirement for remediation through e.g. ground improvement or the use of piled foundations. 1. Unacceptable amounts of settlement. 2. Bearing capacity failure. 3. Requirement for remediation through e.g. ground improvement or the use of piled foundations. 1. Capacity failure. 3. Requirement for remediation through e.g. ground improvement or the use of piled foundations. 1. Capacity failure. 3. Requirement for remediation through e.g. ground improvement or the use of piled foundations. 1. Risk of severe injuries or death 2. Bearing capacity failure. 3. Severe damage to foundations and plant 1. Unacceptable amounts of settlement. 2. Bearing capaci	3 3 5 3 2 2 2 3 3 3 3 3 3	6 10 6 4 4 10 8 6 6 6 6	Detailed ground investigation, mitigation through use of piled foundations if appropriate  Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered  Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered  Detailed ground investigation if required, mitigation through use of grouted piled foundations, or bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.  Detailed ground investigation, mitigation through use of grouted piled foundations, or bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.  Detailed ground investigation, mitigation through use of piled foundations if appropriate.  Detailed ground investigation, mitigation through use of piled foundations if appropriate.  Detailed ground investigation, mitigation through use of piled foundations if appropriate.  Detailed ground investigation, mitigation through use of piled foundations if appropriate.  Detailed ground investigation, mitigation through use of piled foundations if appropriate.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	3 3 5 3 2 2 2 3 3 3 3 3	3 3 5 2 2 2 3 3 3 3 3

60		Rapid collapse of		Development of subsurface cavities due to karstification of	Risk of severe injuries or death     2.Bearing capacity failure.		40	Detailed ground investigation if required,	_	į
69		sikhole/doline cavity	Rapid collapse of cavity roof during construction	underlying bedrock, with cohesive soil cover.	3. Severe damage to foundations and plant     1. Unacceptable amounts of settlement.	2 5	10	micrositing of turbine if significant cavities are encountered  Detailed ground investigation if required, mitigation	5	5
70		Subsidence of soils overlying suffosion or buried dolines	Subsidence over buried or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.      1. Unacceptable amounts of settlement.	2 4	8	through use of grouted piled foundations, or bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.	4	4
71	T8 Foundation	Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 3	6	Detailed ground investigation, mitigation through use of grouted piled foundations, or bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	3	3
72		Variable rockhead,	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 3	6	Detailed ground investigation, mitigation through use of piled foundations if appropriate.	3	3
73		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled	2 3	6	Detailed ground investigation, mitigation through use of piled foundations if appropriate	3	3
74		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	foundations.  1. Risk of severe injuries or death  2. Bearing capacity failure.  3. Severe damage to foundations and plant	3 5	15	Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered	5	5
75		Subsidence of soils overlying suffosion or buried dolines	Subsidence overburied or suffosion dolines, leading to differential settlement at hardstand	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.     3. Requirement for remediation through e.g. ground improvement     1. Unacceptable amounts of settlement.	3 3	9	Detailed ground investigation if required, mitigation through bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.	3	3
76	T8 Hardstand	Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	3 2	6	Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	2	2
77		Variable rockhead, or unexpected cavities	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. ground improvement	3 2	6	Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	2	2
78		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	3 2	6	Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	2	2
79		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Risk of severe injuries or death     2.Bearing capacity failure.      3. Severe damage to foundations and plant     1. Unacceptable amounts of settlement.	2 5	10	Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered	5	5
80		Subsidence of soils overlying suffosion or buried dolines	Subsidence over buried or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 4	8	Detailed ground investigation if required, mitigation through use of grouted piled foundations, or bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.	4	4
81	T9 Foundation	Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled	2 3	6	Detailed ground investigation, mitigation through use of grouted piled foundations, or bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	3	3
82		Variable rockhead,	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	foundations.  1. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 3	6	Detailed ground investigation, mitigation through use of piled foundations if appropriate.	3	3
83		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 3	6	Detailed ground investigation, mitigation through use of piled foundations if appropriate	3	3
84		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Risk of severe injuries or death     2.Bearing capacity failure.  3. Severe damage to foundations and plant	2 5	10	Detailed ground investigation if required, micrositing of turbine if significant cavities are encountered	5	5
85		Subsidence of soils overlying suffosion or buried dolines	Subsidence overburied or suffosion dolines, leading to differential settlement at hardstand	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement      1. Unacceptable amounts of settlement.	2 3	6	Detailed ground investigation if required, mitigation through bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.	3	3
86	T9 Hardstand	Cavities / Voids	Foundation failure or differential settlement. Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 2	4	Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	2	2
87		Variable rockhead, or unexpected cavities	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. ground improvement      Unacceptable amounts of settlement.	2 2	4	Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	2	2
88		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 2	4	Detailed ground investigation, mitigation through bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	2	2
89		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Risk of severe injuries or death     2.Bearing capacity failure.  3. Severe damage to foundations and plant	2 5	10	Detailed ground investigation if required, micrositing of compound if significant cavities are encountered	5	5
90		Subsidence of soils overlying suffosion or buried dolines	Subsidence overburied or suffosion dolines, leading to differential settlement at hardstand	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement      1. Unacceptable amounts of settlement.	2 3	6	Detailed ground investigation if required, mitigation through use of grouted piled foundations, or bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.	3	3
91	Substation/BESS Compound	Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 2	4	Detailed ground investigation, mitigation through use of grouted piled foundations, or bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	2	2
92		Variable rockhead, or unexpected cavities	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. ground improvement      Unacceptable amounts of settlement.      Bearing capacity failure.	2 2	4	Detailed ground investigation, mitigation through use of piled foundations if appropriate.	2	2
93		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.  Development of subsurface cavities due to karstification of	3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Risk of severe injuries or death	2 2	4	Detailed ground investigation, mitigation through use of piled foundations if appropriate  Detailed ground investigation if required,	2	2
94		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	underlying bedrock, with cohesive soil cover.	2.Bearing capacity failure.      3. Severe damage to foundations and plant      1. Unacceptable amounts of settlement.	2 5	10	micrositing of compound if significant cavities are encountered  Detailed ground investigation if required, mitigation	5	5
95		Subsidence of soils overlying suffosion or buried dolines	Subsidence overburied or suffosion dolines, leading to differential settlement at hardstand	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement      1. Unacceptable amounts of settlement.      2. Bearing capacity failure.	2 3	6	through use of grouted piled foundations, or bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.  Detailed ground investigation, mitigation through	3	3
96	Construction Compound	Cavities / Voids	Foundation failure or differential settlement. Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	<ul><li>2. Bearing capacity failure.</li><li>3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.</li></ul>	2 2	4	use of grouted piled foundations, or bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	2	2
97		Variable rockhead, or unexpected cavities	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. ground improvement     Unacceptable amounts of settlement.	2 2	4	Detailed ground investigation, mitigation through use of piled foundations if appropriate.	2	2
98		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	2. Bearing capacity failure.     3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.      1. Risk of severe injuries or death	2 2	4	Detailed ground investigation, mitigation through use of piled foundations if appropriate  Detailed ground investigation if required,	2	2
99		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	2.Bearing capacity failure.      3. Severe damage to foundations and plant      1. Unacceptable amounts of settlement.	2 5	10	Detailed ground investigation if required, micrositing of Met Mast if significant cavities are encountered  Detailed ground investigation if required, mitigation	5	5
100		Subsidence of soils overlying suffosion or buried dolines	Subsidence overburied or suffosion dolines, leading to differential settlement at hardstand  Foundation failure or differential	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	2. Bearing capacity failure. 3. Requirement for remediation through e.g. ground improvement 1. Unacceptable amounts of settlement.	2 3	6	through use of grouted piled foundations, or bridging cavities if appropriate, micrositing of turbine if significant cavities are encountered.  Detailed ground investigation, mitigation through	3	3
101	Met Mast	Cavities / Voids	Foundation failure or differential settlement. Unforeseen requirement for piled foundations or geotechnical re-design  Variable rockhead, or unexpected cavities leading to	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 2	4	use of grouted piled foundations, or bridging cavities with concrete, or geogrid and coarse granular fll if appropriate.	2	2
102		Variable rockhead, or unexpected cavities	unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g.     ground improvement      1. Unacceptable amounts of settlement.	2 2	4	Detailed ground investigation, mitigation through use of piled foundations if appropriate.	2	2
103		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 2	4	Detailed ground investigation, mitigation through use of piled foundations if appropriate	2	2
104		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Risk of severe injuries or death      2.Bearing capacity failure.      3. Severe damage to foundations and plant	2 5	10	Detailed ground investigation if required, micrositing of access track alignment if significant buried cavities with potential for collapse are encountered	5	5
105		Subsidence of soils overlying suffosion or buried dolines	Subsidence overburied or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.      2. Bearing capacity failure.      3. Requirement for remediation throughe .g. geogrid blanket, or thicker structural fill make up	2 2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features	2	2
106	Access Track - AL1	Variable rockhead, or unexpected cavities	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Requirement for remediation through e.g. geogrid blanket, or thicker structural fill make up	2 2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features	2	2
107		Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features	2	2

108		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled	2 2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over	2	2
109		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	foundations.  1. Risk of severe injuries or death 2.Bearing capacity failure.  3. Severe damage to foundations and plant	2 5	10	Detailed ground investigation if required, micrositing of access track alignment if significant buried cavities with potential for collapse are encountered	5	5
110		Subsidence of soils overlying suffosion or buried dolines	Subsidence overburied or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation throughe .g. geogrid blanket, or thicker structural fill make up	2 2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features	2	2
111	Access Track - AL1b	Variable rockhead, or unexpected cavities	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. geogrid blanket, or thicker structural fill make up		4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features	2	2
112		Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.      2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features	2	2
113		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features	2	2
114		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Risk of severe injuries or death     2.Bearing capacity failure.  3. Severe damage to foundations and plant	- 3 5	15	Detailed ground investigation if required, micrositing of access track alignment if significant buried cavities with potential for collapse are encountered	5	5
115		Subsidence of soils overlying suffosion or buried dolines	Subsidence overburied or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.      3. Requirement for remediation throughe .g. geogrid blanket, or thicker structural fill make up	3 2	6	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features	2	2
116	Access Track - AL2	Variable rockhead, or unexpected cavities	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. geogrid blanket, or thicker structural fill make up		6	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	2	2
117		Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.      1. Unacceptable amounts of settlement.	3 2	6	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features  Detailed ground investigation if required, inspection	2	2
118		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled	3 2	6	of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	2	2
119		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	foundations.  1. Risk of severe injuries or death  2.Bearing capacity failure.  3. Severe damage to foundations and plant	3 5	15	Detailed ground investigation if required, micrositing of access track alignment if significant buried cavities with potential for collapse are encountered	5	5
120		Subsidence of soils overlying suffosion or buried dolines	Subsidence overburied or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.      3. Requirement for remediation throughe .g. geogrid blanket, or thicker structural fill make up	3 2	6	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features	2	2
121	Access Track - AL3	Variable rockhead, or unexpected cavities	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. geogrid blanket, or thicker structural fill make up		6	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features	2	2
122		Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	3 2	6	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features	2	2
123		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	3 2	6	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features	2	2
124		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Risk of severe injuries or death     2.Bearing capacity failure.  3. Severe damage to foundations and plant	4 5	20	Detailed ground investigation if required, micrositing of access track alignment if significant buried cavities with potential for collapse are encountered	5	5
125		Subsidence of soils overlying suffosion or buried dolines	Subsidence overburied or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.      3. Requirement for remediation throughe .g. geogrid blanket, or thicker structural fill make up	4 2	8	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 2 installation of geogrid/geofabric reinforcement over features	2	4
126	Access Track - AL3b	Variable rockhead, or unexpected cavities	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. geogrid blanket, or thicker structural fill make up		8	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 2 installation of geogrid/geofabric reinforcement over features	2	4
127		Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.      1. Unacceptable amounts of settlement.	4 2	8	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 2 installation of geogrid/geofabric reinforcement over features  Detailed ground investigation if required, inspection	2	4
128		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	4 2	8	of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 2 installation of geogrid/geofabric reinforcement over features	2	4
129		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Risk of severe injuries or death     2.Bearing capacity failure.  3. Severe damage to foundations and plant	2 5	10	Detailed ground investigation if required, micrositing of access track alignment if significant buried cavities with potential for collapse are encountered	5	5
130		Subsidence of soils overlying suffosion or buried dolines	Subsidence overburied or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.      3. Requirement for remediation throughe .g. geogrid blanket, or thicker structural fill make up	2 2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features	2	2
131	Access Track - AL4	Variable rockhead, or unexpected cavities	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Requirement for remediation through e.g. geogrid blanket, or thicker structural fill make up		4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features	2	2
132		Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.	2 2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features	2	2
133		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	2	2
134		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Risk of severe injuries or death     2.Bearing capacity failure.  3. Severe damage to foundations and plant	2 5	10	Detailed ground investigation if required, micrositing of access track alignment if significant buried cavities with potential for collapse are encountered	5	5
135		Subsidence of soils overlying suffosion or buried dolines	Subsidence overburied or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.      3. Requirement for remediation throughe .g. geogrid blanket, or thicker structural fill make up	2 2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	2	2
136	Access Track - AL4 Float	Variable rockhead, or unexpected cavities	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Requirement for remediation through e.g. geogrid blanket, or thicker structural fill make up		4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features	2	2
137		Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features	2	2
138		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features	2	2
					iodiladiolis.					

139		Rapid collapse of sikhole/doline cavity  Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Risk of severe injuries or death     2.Bearing capacity failure.  3. Severe damage to foundations and plant	2	5	10	Detailed ground investigation if required, micrositing of access track alignment if significant buried cavities with potential for collapse are encountered	1	5	5
140		Subsidence of soils overlying suffosion or buried dolines  Subsidence overburied or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.      3. Requirement for remediation throughe .g. geogrid blanket, or thicker structural fill make up	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2
141	Access Track - AL4b	Variable rockhead, or unexpected cavities leading to unexpected cavities unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. geogrid blanket, or thicker structural fill make up	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2
142		Foundation failure or differential Cavities / Voids settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.      1. Unacceptable amounts of settlement.	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2
143		Solutionally Weathered Rock  Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2
144		Rapid collapse of sikhole/doline cavity  Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Risk of severe injuries or death     2.Bearing capacity failure.      3. Severe damage to foundations and plant	2	5	10	Detailed ground investigation if required, micrositing of access track alignment if significant buried cavities with potential for collapse are encountered	1	5	5
145		Subsidence of soils overlying suffosion or buried dolines  Subsidence overburied or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation throughe .g. geogrid blanket, or thicker structural fill make up	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2
146	Access Track - AL4b Float	Variable rockhead, or unexpected cavities leading to unexpected cavities unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. geogrid blanket, or thicker structural fill make up	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2
147		Foundation failure or differential Cavities / Voids settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2
148		Solutionally Weathered Rock Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2
149		Rapid collapse of sikhole/doline cavity  Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Risk of severe injuries or death     2.Bearing capacity failure.  3. Severe damage to foundations and plant  1. Unacceptable amounts of settlement.	2	5	10	Detailed ground investigation if required, micrositing of access track alignment if significant buried cavities with potential for collapse are encountered	1	5	5
150		Subsidence of soils overlying suffosion or buried dolines  Subsidence overburied or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	2. Bearing capacity failure.  3. Requirement for remediation throughe .g. geogrid blanket, or thicker structural fill make up	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2
151	Access Track - AL4c	Variable rockhead, or unexpected cavities leading to unexpected cavities  Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. geogrid blanket, or thicker structural fill make up	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2
152		Foundation failure or differential Cavities / Voids settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2
153		Solutionally Weathered Rock  Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2
154		Rapid collapse of sikhole/doline cavity  Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Risk of severe injuries or death     2.Bearing capacity failure.  3. Severe damage to foundations and plant	2	5	10	Detailed ground investigation if required, micrositing of access track alignment if significant buried cavities with potential for collapse are encountered	1	5	5
155		Subsidence of soils overlying suffosion or buried dolines Subsidence overburied or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation throughe .g. geogrid blanket, or thicker structural fill make up	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2
156	Access Track - AL5	Variable rockhead, or unexpected cavities leading to unexpected cavities  Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. geogrid blanket, or thicker structural fill make up	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2
157		Foundation failure or differential Cavities / Voids settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.      1. Unacceptable amounts of settlement.	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2
158		Solutionally Weathered Rock  Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2
159		Rapid collapse of sikhole/doline cavity  Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Risk of severe injuries or death     2.Bearing capacity failure.  3. Severe damage to foundations and plant	2	5	10	Detailed ground investigation if required, micrositing of access track alignment if significant buried cavities with potential for collapse are encountered	1	5	5
160		Subsidence of soils overlying suffosion or buried dolines  Subsidence overburied or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.      3. Requirement for remediation throughe .g. geogrid blanket, or thicker structural fill make up	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2
161	Access Track - AL5 float	Variable rockhead, or unexpected cavities leading to unexpected cavities  Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. geogrid blanket, or thicker structural fill make up	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2
162		Foundation failure or differential Cavities / Voids settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2
163		Solutionally Weathered Rock  Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2
164		Rapid collapse of sikhole/doline cavity  Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Risk of severe injuries or death     2.Bearing capacity failure.  3. Severe damage to foundations and plant	2	5	10	Detailed ground investigation if required, micrositing of access track alignment if significant buried cavities with potential for collapse are encountered	1	5	5
165		Subsidence of soils overlying suffosion or buried dolines  Subsidence overburied or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.      3. Requirement for remediation throughe .g. geogrid blanket, or thicker structural fill make up	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2
166	Access Track - AL5b	Variable rockhead, or unexpected cavities leading to unexpected cavities unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Requirement for remediation through e.g. geogrid blanket, or thicker structural fill make up	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2
167		Foundation failure or differential Cavities / Voids settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.      3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.      1. Unacceptable amounts of settlement.	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2
168		Solutionally Weathered Rock  Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2	2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	1	2	2

169		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Risk of severe injuries or death     2.Bearing capacity failure.	2 5	10	Detailed ground investigation if required, micrositing of access track alignment if significant buried cavities with potential for collapse are	5	5
					Severe damage to foundations and plant     Unacceptable amounts of settlement.			encountered  Detailed ground investigation if required, inspection		
170		Subsidence of soils overlying suffosion or buried dolines	Subsidence overburied or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	2. Bearing capacity failure.  3. Requirement for remediation throughe .g. geogrid blanket, or thicker structural fill make up	2 2	4	of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features	2	2
171	Access Track - AL5b Float	Variable rockhead, or unexpected cavities	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. geogrid blanket, or thicker structural fill make up	2 2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features	2	2
172		Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features	2	2
173		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	Unacceptable amounts of settlement.     Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features	2	2
174		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover. Slight reduction in hazard score applied due to lack of evidence for large cavities in geophysical surveying.	1. Risk of severe injuries or death     2.Bearing capacity failure.  3. Severe damage to foundations and plant	1 5	5	Detailed ground investigation if required, micrositing of access track alignment if significant buried cavities with potential for collapse are encountered	5	5
175		Subsidence of soils overlying suffosion or buried dolines	Subsidence overburied or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.     3. Requirement for remediation throughe .g. geogrid blanket, or thicker structural fill make up	4 2	8	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	2	4
176	Access Track - AL6	Variable rockhead, or unexpected cavities	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. geogrid blanket, or thicker structural fill make up	4 2	8	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	2	4
177	-	Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	4 2	8	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	2	4
178		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	4 2	8	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	2	4
179		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Risk of severe injuries or death     2.Bearing capacity failure.  3. Severe damage to foundations and plant	3 5	15	Detailed ground investigation if required, micrositing of access track alignment if significant buried cavities with potential for collapse are encountered	5	5
180		Subsidence of soils overlying suffosion or buried dolines	Subsidence overburied or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.      3. Requirement for remediation throughe .g. geogrid blanket, or thicker structural fill make up	3 2	6	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	2	2
181	Access Track - AL6b	Variable rockhead, or unexpected cavities	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. geogrid blanket, or thicker structural fill make up	3 2	6	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	2	2
182		Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Unacceptable amounts of settlement.     Requirement for remediation through e.g. ground improvement or the use of piled foundations.	3 2	6	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	2	2
183		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	3 2	6	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	2	2
184		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Risk of severe injuries or death     2.Bearing capacity failure.  3. Severe damage to foundations and plant	3 5	15	Detailed ground investigation if required, micrositing of access track alignment if significant buried cavities with potential for collapse are encountered	5	5
185		Subsidence of soils overlying suffosion or buried dolines	Subsidence overburied or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation throughe .g. geogrid blanket, or thicker structural fill make up	3 2	6	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	2	2
186	Access Track - AL6c	Variable rockhead, or unexpected cavities	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. geogrid blanket, or thicker structural fill make up	3 2	6	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	2	2
187		Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	3 2	6	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	2	2
188		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.	3 2	6	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	2	2
189		Rapid collapse of sikhole/doline cavity	Rapid collapse of cavity roof during construction	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Risk of severe injuries or death     2.Bearing capacity failure.  3. Severe damage to foundations and plant     1. Unacceptable amounts of settlement.	2 5	10	Detailed ground investigation if required, micrositing of access track alignment if significant buried cavities with potential for collapse are encountered  Detailed ground investigation if required, inspection	5	5
190	_	Subsidence of soils overlying suffosion or buried dolines	Subsidence overburied or suffosion dolines, leading to differential settlement at turbine foundations	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	2. Bearing capacity failure.      3. Requirement for remediation throughe .g. geogrid blanket, or thicker structural fill make up	2 2	4	of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, 1 installation of geogrid/geofabric reinforcement over features	2	2
191	Access Track - AL8	Variable rockhead, or unexpected cavities	Variable rockhead, or unexpected cavities leading to unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	Requirement for remediation through e.g. geogrid blanket, or thicker structural fill make up	2 2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	2	2
192		Cavities / Voids	Foundation failure or differential settlement.Unforeseen requirement for piled foundations or geotechnical re-design	Development of subsurface cavities due to karstification of underlying bedrock, with cohesive soil cover.	1. Unacceptable amounts of settlement.     2. Bearing capacity failure.  3. Requirement for remediation through e.g. ground improvement or the use of piled foundations.  1. Unacceptable amounts of settlement.	2 2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	2	2
193		Solutionally Weathered Rock	Excavation instability and reduced bearing capacity.	Deeply weathered limestone with voids and softened zones.	Requirement for remediation through e.g. ground improvement or the use of piled foundations.	2 2	4	Detailed ground investigation if required, inspection of subformation following topsoil strip, backfill of cavities with selected coarse granular fill, installation of geogrid/geofabric reinforcement over features	2	2





### **GLOBAL PROJECT REACH**



# Offices

# **Dublin (Head Office)**

Gavin & Doherty Geosolutions Unit A2, Nutgrove Office Park Rathfarnham Dublin 14, D14 X627 Phone: +353 1 207 1000

# Cork

Gavin & Doherty Geosolutions First Floor, 12 South Mall Cork T12 RD43

# London

Gavin & Doherty Geosolutions (UK) Limited 85 Great Portland Street, First Floor London W1W 7LT

# Utrecht

Gavin & Doherty Geosolutions WTC Utrecht, Stadsplateau 7 3521 AZ Utrecht The Netherlands

# Belfast

Gavin & Doherty Geosolutions (UK) Limited Scottish Provident Building 7 Donegall Square West Belfast BT1 6JH

# Edinburgh

Gavin & Doherty Geosolutions (UK) Limited 22 Northumberland Street SW Lane Edinburgh EH3 6JD

# **Rhode Island**

Gavin & Doherty Geosolutions Inc. 225 Dyer St, 2nd Floor Providence, RI 02903 USA



Website: <a href="www.gdgeo.com">www.gdgeo.com</a>
Email: <a href="mailto:info@gdgeo.com">info@gdgeo.com</a>



