

## **Appendix A.13.7**

### **Detailed field Inspection Results Plates**

### A.13.7

---

## Plates



Plate 13.1 - Sea Road (TB 1), facing southwest



Plate 13.2 - Overgrown fields at southern extent of proposed road development, facing northwest



Plate 13.3 - Relict field system, facing northeast



Plate 13.4 - AH 1/CH 4, drystone wall enclosure facing northeast



Plate 13.5 - Drystone granite walling with enclosure entrance, facing



Plate 13.6 - Stone lined laneway adjacent to AH 1/CH 4, facing northeast





Plate 13.7 – Spring or well, facing south



Plate 13.8 - TB 2/AAP 1, facing southwest along watercourse



Plate 13.9 - Stream in 117, facing northeast, facing east



Plate 13.10 - TB 3, facing northwest





Plate 13.11 - TB 4, facing southeast



Plate 13.12 – CH 7, facing west



Plate 13.13 - Walled laneway in 168, facing east



Plate 13.14 - Location of CH 10, facing east



Plate 13.15 - TB 5, facing west



Plate 13.16 – CH 13, facing east



Plate 13.17 – CH 11, facing north



Plate 13.18 - TB 6, facing southeast





Plate 13.19 - Mound immediately west of stream at AAP 2



Plate 13.20 - TB 7, facing northeast



Plate 13.21 - TB 7, stone wall, facing southeast



Plate 13.22 - CH 18, facing northeast





Plate 13.23 - TB 8, levelled boundary, facing north



Plate 13.24 - TB 9, stone wall and hedgerow, facing west



Plate 13.25 - TB 10 and AAP 3, facing north



Plate 13.26 - Machine straightened watercourse feeding Bearna Stream (AAP 3), facing southeast



Plate 13.27 - 'Lazy Beds' facing south in 213



Plate 13.28 – CH 20, facing west



Plate 13.29 – CH 22, facing northeast



Plate 13.30 – CH 21, facing southwest





Plate 13.31 – CH 23 immediately west of proposed road development, facing north



Plate 13.32 - TB 11, walled laneway, facing northeast



Plate 13.33 - TB 11 showing construction of drystone granite wall



Plate 13.34 - AAP 4, facing northeast





Plate 13.35 - Disturbed area and straightened watercourse, facing east



Plate 13.36 - Unfinished stone wall, facing northeast



Plate 13.37 - View north towards TB 12



Plate 13.38 – CH 25, stone built shed, facing east





Plate 13.39 – CH 26, Ruined vernacular dwelling, facing east



Plate 13.40 – CH 27, vernacular dwelling, facing north



Plate 13.41 - TB 13, facing east



Plate 13.42 - TB 14, facing north



Plate 13.43 - BH 2, facing southeast



Plate 13.44 - Hollow trackway (CH 71), facing southwest



Plate 13.45 - View north towards CH 30



Plate 13.46 - CH 32, facing northeast





Plate 13.47 - TB 15, facing southwest



Plate 13.48 - Location of AH 1 and AAP 5, facing northeast



Plate 13.49 - AH 1, purported location of Bullaun Stone, facing south



Plate 13.50 - AAP 5, facing north



Plate 13.51 - Overgrown walled laneway, associated with CH 33,  
facing east



Plate 13.52 – CH 35, Renovated farmhouse and barn, facing northeast



Plate 13.53 - Area of standing water to the east of Letteragh Road,  
facing southeast



Plate 13.54 - TB 17, facing northwest





Plate 13.55 - Watercourse traversing area of bog (AAP 7), facing southwest



Plate 13.56 - TB 18, facing east



Plate 13.57 - TB 19, facing southeast



Plate 13.58 – CH 37, facing east



Plate 13.59 – CH 37, facing southeast



Plate 13.60 – Undulating marginal land within AAP 8, facing northeast



Plate 13.61 - TB 21, facing west



Plate 13.62 – CH 39, facing southwest





Plate 13.63 - BH 4, facing west



Plate 13.64 – CH 40, facing south



Plate 13.65 – CH 42, facing north



Plate 13.66 – CH 41, facing south





Plate 13.67 - AH 34, facing north



Plate 13.68 - AH 14, facing north



Plate 13.69 - AH 15/BH 9, facing east



Plate 13.70 – River Corrib crossing (AAP 8), facing northeast





Plate 13.71 - Inlet from the River Corrib (CH 45), facing south



Plate 13.72 - AH 11/BH 2, facing east



Plate 13.73 – CH 46, facing south



Plate 13.74 - Walled trackway (CH 72) bounding DL 8, facing northwest





Plate 13.75 – CH 49 in 564, facing west



Plate 13.76 - Modern cairn of stones, facing south



Plate 13.77 - View east towards CH 50



Plate 13.78 - TB 23, facing southwest





Plate 13.79 - View east across the quarry



Plate 13.80 - TB 22 in 223, facing west



Plate 13.81 - View northwest across AAP 10 towards AH 21



Plate 13.82 - BH 12, facing north



Plate 13.83 - Bottom of 'Pollinapreaghaun' AH 24/AAP 11, facing southeast



Plate 13.84 – CH 53, facing southwest



Plate 13.85 - TB 26, facing northeast



Plate 13.86 - AH 26, facing north





Plate 13.87 - TB 28, facing southwest



Plate 13.88 - TB 29, facing northeast



Plate 13.89 - AH 27, facing southwest



Plate 13.90 - AH 29/BH 17, facing west





Plate 13.91 – CH 57, facing northeast



Plate 13.92 – CH 58, facing north



Plate 13.93 - TB 41, facing



Plate 13.94 - Relict field boundaries in 126





Plate 13.95 - Raised rectangular platform (CH 38), facing west



Plate 13.96 - Grassed over field boundary (CH 38) facing northwest



Plate 13.97 - View from CH 38, facing northeast



Plate 13.98 - BH 7, facing southwest



Plate 13.99 - BH 5, facing northwest



Plate 13.100 - Outbuildings to rear of BH 5, facing northwest



Plate 13.101 - Section of enclosing wall at BH 5, facing north



Plate 13.102 – Possible mass rock (CH 69), facing southeast





Plate 13.103 – Interior of walled garden, facing east



Plate 13.104 – Route of proposed pipeline, facing northeast



Plate 13.105 – The remains of 'Loughaunnafraska' (AAP 12),  
facing south-southwest



Plate 13.106 – Remains of railway bed (CH 68), facing southeast





Plate 13.107 – Railway culvert (CH 70), facing north-northeast



Plate 13.108 – CH 63, facing east



Plate 13.109 - TB 20, facing WNW



Plate 13.110 - disturbance around, facing north





Plate 13.111 - Path of the southern section of the proposed road development, facing north

