

Printed on ___% Post-Consumer Recycled Content Paper

Schedule Of Building Fabric Repair Works

Please note, all works to historic buildings will be carried out in accordance with the Conservation Architects recommendations.

Please see the Conservation Architect's Specifications for further information. Summary of works

Windows:

Early timber windows to remain in situ following repair by specialist joiners.

unless otherwise stated.

All blocked openings and missing windows within the existing facade to be replaced with multi-pane vertical sliding sash in box frames unless otherwise stated.

Roof Salvage all existing stone slate on the historic structures for reuse on the building. Remove all concrete roof tiles and other contemporary roof finishes, repair, replace and treat roofing elements as necessary, and finish with salvaged and replacement stone slates.

Historic roof timbers to be repaired on a minimum intervention basis.

Leadwork

Chimney Repair Generally all existing brick chimneys are to be repaired and repointed. Chimneys that are plaster rendered are to have render removed, flashings replaced and rerendered.

In cases where the masonry is loose and damaged and there is risk of moisture penetration the conservation architect may instruct the top few courses of brick to be removed and rebedded on a bitumen coated lead dpc.

Existing Timber Floor Generally all existing suspended timber floors are to be retained, repaired and upgraded to meet loading requirements. Internal Plaster Repair

Repair all existing line plaster in accordance with Conservation Architects recommendations.

Rainwater Goods Replace all circular down pipes & decorative hopper heads with heritage cast iron rainwater goods.

Brick Restoration System Clean and treat brickwork in accordance with Conservation Architects recommendations. Allow for repointing of brickwork and repairs to brickwork and stone as necessary.

Painting Specification All internal plaster surfaces and joinery to be finished in matt emulsion and oil paints, and external plaster rendered surfaces

to be finished in mineral paint as recommended by the Conservation Architect. Existing Door Upgrading

used in conjunction with intumescent paints to achieve 30 min fire rating.

Building Usage Aparthotel Commercial Cafe | Restaurant | Bar Cultural Retail Residential

Residential Garden

lead lined gutters

Proposal Key:

2 Re-bed stone/concrete copings

(4) New glazed Atrium roof falling to new lead lined gutter

(5) Aparthotel lower roof (refer to proposed roof plan)

6 Open atrium landing area

Fire escape with possible maintenance access to lower level Aparthotel roof



New Construction

Existing Construction

All modern uPVC/alumin windows within the existing facade to be replaced with multi-pane vertical sliding sash in box frames

All existing lead flashings, parapet gutters and dpc to roof fabric to be removed and replaced with appropriate materials as recommended by the Conservation Architect.

An intumescent system is to be used to upgrade raised and fielded panel doors to fire rated doors. Envirograf papers to be

Existing tiled roof finish to be carefully removed and set aside for re-use where possible all in accordance with Conservation Officers recommendations including new reinstated lead flashing /

Remediation works and consolidation to existing chimneys / feature water tables

PROJECT

Opera Site

CLIENT

Limerick City and County Council

CONSULTANT

AECOM The Clarence Street West Building 2 Clarence Street West Belfast BT2 7GP United Kingdom Tel +44 (0)28 90607200 www.aecom.com

For Site Levels refer to Landscape Architects Drawings All levels referenced to Malin Head Datum

KEY PLAN

SUE/REVISION HISTORY	
	_
	_
- Jan 19 Planning Submission	
I/R DATE DESCRIPTION	
PROJECT NUMBER	
60568520	
SHEET TITLE	
Parcel 2A - Proposed Fourth Floor Plan	
• .	
1 : 100@A0	
1 : 100@A0 SHEET NUMBER RE	V