


Printed on ___% Post-Consumer Recycled Content Paper



Summary of works

Windows: Early timber windows to remain in situ following repair by specialist joiners.

replaced with multi-pane vertical sliding sash in box frames unless otherwise stated.

All blocked openings and missing windows within the existing facade to be replaced with multi-pane vertical sliding sash in box frames unless otherwise stated.

Roof Salvage all existing stone slate on the historic structures for reuse on the building. Remove all concrete roof tiles and other contemporary roof finishes, repair, replace and treat roofing elements as necessary, and finish with salvaged and replacement stone slates.

Historic roof timbers to be repaired on a minimum intervention basis. Leadwork

All existing lead flashings, parapet gutters and dpc to roof fabric to be removed and replaced with appropriate materials as recommended by the Conservation Architect.

Chimney Repair Generally all existing brick chimneys are to be repaired and repointed. Chimneys that are plaster rendered are to have render removed, flashings replaced and rerendered.

In cases where the masonry is loose and damaged and there is risk of moisture penetration the conservation architect may instruct the top few courses of brick to be removed and rebedded on a bitumen coated lead dpc.

Existing Timber Floor Generally all existing suspended timber floors are to be retained, repaired and upgraded to meet loading requirements.

Internal Plaster Repair Repair all existing lime plaster in accordance with Conservation

Rainwater Goods Replace all circular down pipes & decorative hopper heads with heritage cast iron rainwater goods.

Brick Restoration System

Clean and treat brickwork in accordance with Conservation Architects recommendations. Allow for repointing of brickwork and repairs to brickwork and stone as necessary.

Painting Specification All internal plaster surfaces and joinery to be finished in matt emulsion and oil paints, and external plaster rendered surfaces to be finished in mineral paint as recommended by the Conservation Architect.

Existing Door Upgrading An intumescent system is to be used to upgrade raised and fielded panel doors to fire rated doors. Envirograf papers to be used in conjunction with intumescent paints to achieve 30 min fire rating.



New Construction

Existing Construction

Building Usage

Aparthotel

- Commercial
- Cafe | Restaurant | Bar
- Cultural
- Retail
- Residential



PROJECT

Opera Site

CLIENT

Limerick City and County Council

CONSULTANT

AECOM The Clarence Street West Building 2 Clarence Street West Belfast BT2 7GP United Kingdom Fax +44 (0)28 9079 5651 Tel +44 (0)28 90607200 www.aecom.com

Note: All levels referenced to Malin Head Datum For site levels refer to Landscape Architects drawings KEY PLAN

<image/>			
-	Jan 2019	Planning Submission	
I/R	DATE	DESCRIPTION	
PROJECT NUMBER			
60568520			
SHEET TITLE			
Parcel 3A+4 - Proposed Basement Floor Plan			
1:100 @ A0			
SHE	ET NUME	BER	REV
OPRA-ACM-Z3A4-BM-DR-AR-11000			