

Please note, all works to historic buildings will be carried out in accordance with the Conservation Architects recommendations. Repair works to the Granary building are limited to those necessitated by the removal of the existing extension, the introduction of two new external vertical circulation cores as detailed on the drawings, and the appropriate reinstatement of archways at the internal courtyard.

Please see the Conservation Architects specifications for further information.

Clean and treat stone work in accordance with Conservation Architects recommendations and allow for repointing and repairs as necessary.

Re-establish historic brick arches facing onto the internal courtyard at the existing nightclub to the north of the plan, and finish with seamless structural glazing and entrance doors as necessary.



1 Proposed Front Elevation (East - Michael Street)

SCALE: 1 : 100



2 Proposed Side Elevations (North - Bank Place)

SCALE: 1 : 100



3 Proposed Side Elevation (South)

SCALE: 1 : 100

Note: All levels referenced to Malin Head Datum



IR	DATE	DESCRIPTION
1	Jan 16	Planning Submission

60533080

Parcel 6 - Proposed Elevations (Sheet 01)