

Sure Partners Limited

ARKLOW BANK WIND PARK
PHASE 2

**ONSHORE GRID
INFRASTRUCTURE**

VOLUME III

Chapter 12 APPENDICES

Appendix 12.2 Site Photography



ARUP

 **sse**
Renewables

Appendix 12.2

Site Photography

Appendix 12.2. Site photographs



Photograph 1. Coast (LS1 and CS1) looking south from landfall location (Refer to Appendix 12.4 Sheet 1)



Photograph 2. Scrub on cliff habitat (WS1/CS1) near landfall location (Refer to Appendix 12.4 Sheet 1)



Photograph 3. Hottentot Fig recorded near landfall location (Refer to Appendix 12.4 Sheet 13)



Photograph 4. Semi Natural grassland (GS1) (Refer to Appendix 12.4 Sheet 4)



Photograph 5. Grassland (GA1) west of Templerainy Stream (Refer to Appendix 12.4 Sheet 6)



Photograph 6. Wheat field (BC1) along proposed cable route (Refer to Appendix 12.4 Sheet 6)



Photograph 7. Hemlock water dropwort on Templerainy Stream (Refer to Appendix 12.4 Sheet 6)



Photograph 8. Treeline (WL2) along Templerainy Stream (Refer to Appendix 12.4 Sheet 6)



Photograph 9. Mixed broadleaved woodland northwest of M11 (WD1) (Refer to Appendix 12.4 Sheet 8)



Photograph 10. Sheepwalk Culvert (FW1) and Woodland habitat (Refer to Appendix 12.4 Sheet 8)



Photograph 11. Sheepwalk Stream Culvert (FW1) (Refer to Appendix 12.4 Sheet 8)



Photograph 12. Stand of Japanese knotweed, (in winter) southwest of substation site (Refer to Appendix 12.4 maps Sheet 10)



Photograph 13. Trackway (BL3) below main access road to substation (Refer to Appendix 12.4 Sheet 9)



Photograph 14. Scrub/Wet grassland (WS1/GS4) between river and raised bank, north bank of river (Refer to Appendix 12.4 Sheet 9 and Sheet 11)



Photograph 15. Avoca River (FW2) looking upstream (Refer to Appendix 12.4 Sheet 12)



Photograph 16. Avoca River (FW2) looking upstream from NETN crossing point (Refer to Appendix 12.4 Sheet 11)



Photograph 17. Canal (FW3) south of substation site (Refer to Appendix 12.4 Sheet 9 and Sheet 11)