

**Gortyrahilly WF (GWF), Co. Cork**

**Photographs**



Recently excavated drainage observed during Surface Water Sampling R1 12/08/2020, near WC2.



Natural drainage, deeply eroded channel in till observed during Site surveys 16/06/2020, near WC2.



Natural drainage, deeply eroded channel in till observed during site surveys 16/06/2020, near WC2.





Exposed bedrock along existing access track observed during Surface Water Sampling R1 12/08/2020, near WC2 and WC4.




Evidence of peat cutting observed during site surveys 16/06/2020.



Steep and complex topography and exposed bedrock observed during site survey 16/06/2021.



Exposed and weathered bedrock outcrop observed during site survey 16/06/2021.



Exposed and weathered bedrock outcrop observed during site survey 18/06/2020.



Exposed and weathered bedrock outcrop observed during site survey 18/06/2020.



Recent forestry activity observed during site survey 18/06/2020.



Recent forestry activity observed during site survey 18/06/2020.