

**Inspector Report Discharge Form****314760-22**Lead Reporting Inspe...  Caryn...**General**

File No: 314760-22

Please complete all relevant sections – (whether recommendation is to grant or to refuse)

(1) New Issues

New Issues No

If 'Yes', provide brief description:

(2) Residential Development(i) Number of dwellings: _____ as per my recommendation
(enter...none...if refusal)

No. of Apts.

No. of Houses

Total No. of Units

(ii) Part V, Social and Affordable Housing

Section 96, Part V condition applies:

(3) Development Contributions (s. 48, s. 48(2) (c) and s.49)

Section 48 Development Contribution Scheme condition applies: Yes

Section 48 (2) (c) Special Development Contribution condition applies:

Section 49 Supplementary Development Contribution Scheme condition applies

(4) Material Contravention of Development Plan

Section 37(2)(b) provisions apply:

(5) Statutory Notices (e.g. s.131/s.132)

Have all statutory notice periods expired? If 'No', the file should not be discharged. Yes

(6) Habitats Directive

Is the integrity of a European site likely to be negatively affected? No

Has AA, or screening for AA, previously been carried out by the EPA, and if so, has regard been had to this? No

(7) EIA Development (including sub-threshold)Does this application relate to an activity for which an IPPC or Waste Licence (or review of a Licence) is required from the EPA? No
Yes

If an EIS was submitted, was the EPA notified and observations sought/received?

In the case of sub-threshold development where the submission of an EIS has not been sought, has the EPA been notified of this view and observations sought/received?

N/A

 Caryn Coogan

Date

23/04/2024


Notes

Caryn Coogan




An
Bord
Pleanála


File ABP 314760 Continued use and operation of a quarry at Spink, Co. Laois




Photos taken on site 15th of March 2024



Site Context




More photos taken on site 15th of March 2024



1. Entrance to the quarry



2. Sightline to the east along the R340. Road in good condition and wide at the entrance



3. Sightline to the west at the entrance along the R340





An
Bord
Pleanála

5. Harding standing area where the refuelling will take place. Existing weigh bridge in place. There will be an office and a wheel wash at this location.



6. A view from the hardstanding area towards the access road to the entrance gate onto the R340



7. Southern quarry face in the background and stockpiles



10. Views from the quarry floor facing east



11. From the quarry floor facing south



7. View South across the existing quarry



8. Orange is western quarry face. Yellow are the settlement ponds



8. Arrow denotes the location of the settlement ponds



9. Existing aggregate storage bays




11. Southern quarry face




12. Western quarry face. Yellow arrows denote settlement ponds



13. View eastwards at the existing settlement ponds fronting the western quarry face



14. View southeast from the settlement ponds at the western quarry face




15. View north. There is an overflow from the settlement ponds to the north




16. View of the southern quarry face







18. Eastern quarry face and sump



19. Eastern quarry face and sump



21. View of western quarry face where arrow is pointing



22. Undeveloped eastern portion of quarry currently covered in gorse bushes



23. Another view of the eastern portion of the quarry which is to be extracted during the lifetime of the quarry



24. The view of the quarry site on approach from the east along the R340



25. A view of the quarry on approach from the west along the R340. Third party appellant's house in the foreground



26. A view from the west towards the subject quarry



