PRICENED: ODOTROZ



# **APPENDIX 7-1**

**TRIAL PIT LOGS** 



**Date started:** 06/06/2023

**Date finished:** 06/06/2023

Trial Pit No: TP01

Project No: P1601-0

**Easting:** 152418

Site: Lomaunaghbaun,

**Northing:** 256464

Client: MKO

			SUBSU	RFACE	PROFILE	
Depth	Symbol	Description	Depth/Elev.	Water Strikes	Comments	Well Completion Details
0		Ground Surface	0.0			
		Topsoil	0.0			
2-		Greyish brown, silty, sandy GRAVEL with rounded cobbles and boulders  Grey, sandy GRAVEL with rounded cobbles and boulders	-0.9 0.9			
3			-3.0 3.0	_		
Remar	ks:			Drillin	g Contractor:	Scale as shown
				Drillin	g type:	<b>Sheet:</b> 1 of 1
						• • • • • • • • • • • • • • • • • • •
				Logge	ed by: DB	



**Date started:** 06/06/2023

**Date finished:** 06/06/2023

Trial Pit No: TP02

Project No: P1601-0

**Easting:** 152292

Site: Lomaunaghbaun,

Northing: 256481

Client: MKO

			SUBSU	RFACE	PROFILE	90,
Depth	Symbol	Description	Depth/Elev.	Water Strikes	Comments	Well Completion Details
0	***	Ground Surface Topsoil	0.0			
2-		Grey, silty, sandy GRAVEL with rounded cobbles and boulders  Grey, sandy, silty GRAVEL with rounded cobbles and boulders	-1.9 1.9		Refusal at 2.4mbgl, assumed bedrock	
Remarks	s:			Drillin	g Contractor:	Scale as shown
					g type:	<b>Sheet:</b> 1 of 1
					<b>ed by:</b> DB	55 <b>3</b> . 5
		AL SERVICES 22 Lower Main Street Dungo				



Trial Pit No: TP03

Project No: P1601-0

**Date started:** 06/06/2023

**Date finished:** 06/06/2023

**Easting:** 152328

Site: Lomaunaghbaun,

**Northing:** 256407

Client: MKO

	1	SUBSU	RFACE	PROFILE	
Depth Symbol	Description	Depth/Elev.	Water Strikes	Comments	Well Completion Details
	Ground Surface  Topsoil  Grey, sandy, gravelly SILT with angular cobbles (broken bedrock)	0.0 0.0 -0.1 0.1		Refusal at 1.4mbgl, assumed bedrock	
Remarks:		1	Drillin	g Contractor:	Scale as shown
			Drillin	g type:	Sheet: 1 of 1
			Logg	ed by: DB	



**Date started:** 06/06/2023

**Date finished:** 06/06/2023

Trial Pit No: TP04

Project No: P1601-0

**Easting:** 152131

Site: Lomaunaghbaun,

**Northing:** 256461

Client: MKO

		SUBSUI	RFACE	PROFILE	3
Depth Symbol	Description	Depth/Elev.	Water Strikes	Comments	Well Completion Details
	Ground Surface Topsoil  Grey, gravelly, sandy SILT with angular cobbles (broken bedrock)  Broken LIMESTONE bedrock	0.0 0.0 -0.1 0.1			
Remarks:	1	l		g Contractor: g type:	Scale as shown Sheet: 1 of 1
PRO-ENVIRONMEN	NTAL SERVICES 22 Lower Main Street Dungo	arvan Co. V		<b>ed by:</b> DB d Tel: 058-44122 Email: info@hy	droenvironmental.ie



**Date started:** 06/06/2023

**Date finished:** 06/06/2023

**Trial Pit No:** TP05

Project No: P1601-0

**Easting:** 152181

Site: Lomaunaghbaun,

**Northing:** 256364

Client: MKO

Ground Surface csoil  ey, silty, sandy GRAVEL gular cobbles (broken drock)	0.0 0.0 0.0 0.1	Water Strikes	Comments	Well Completion Details
ey, silty, sandy GRAVEL gular cobbles (broken				
ey, silty, sandy GRAVEL gular cobbles (broken				
gular cobbles (broken	0.1			
	-1.6 1.6		Refusal at 1.6m, assumed bedrock	
		Drillin	g Contractor:	Scale as shown
		Drillin	g type:	<b>Sheet:</b> 1 of 1
		Logg	ed by: DB	
	<b>ERVICES</b> 22 Lower Main Street Dunga		Drillin Drillin Logg	-1.6 1.6  Refusal at 1.6m, assumed bedrock  Drilling Contractor: Drilling type: Logged by: DB  ERVICES 22 Lower Main Street Dungarvan Co. Waterford Tel: 058-44122 Email: info@hyc