

APPENDIX 14.1: CULTURAL HERITAGE PHOTOGRAPHIC RECORD



Plate 14.1: General view towards ringfort CL057-037----from east with existing farm track in foreground



Plate 14.2: View of infilled quarry adjacent to ringfort CL057-037---- from east with existing farm track left of frame



Plate 14.3: View of interior of ringfort CL057-037---- from north



Plate 14.4: View of large drainage channel to south of Enclosure CL057-023---- from southwest



Plate 14.5: View of field containing Turbine 1 and flood compensation areas from east



Plate 14.6: View towards location of Turbine 2 from east



Plate 14.7: View towards location of Turbine 3 from north



Plate 14.8: View towards location of onsite substation from southwest



Plate 14.9: View towards location of temporary compound from east



Plate 14.10: View towards location of spoil area from west



Plate 14.11: View of section of road along grid connection and turbine delivery route in Moanmore Upper townland



Plate 14.12: View of section of road along grid connection and turbine delivery route in Moanmore South townland