

RECEINED. 2017/2024

Appendix 11-1 Photographic Record

Proposed Quarry Extraction and Restoration, Ballyquin, Co. Clare



PECENED. 2017/2024



Photographic Record of Proposed Development Site



Plate 1: Area of Proposed inspection shed, looking ESE.



Plate 2: Existing internal roadway and office, looking S.

PECENED. 2017/2024





PRICENED. 2017 ROSA

Plate 3: Area of proposed settlement ponds, looking SW.



Plate 4: Proposed extraction and restoration area at south-east end of Proposed Development site, looking SE.





Plate 5: As above, looking NE.



Plate 6: Proposed restoration area, looking NNE.

PRCHNED: 29/1/2024





PRICENED. 2017 ROCK

Plate 7: Proposed restoration area at east side of Proposed Development site, looking NE.



Plate 8: Proposed restoration at NE side of Proposed Development site, looking NW.





PROBINED. 2017 ROSA

Plate 9: As above, looking SW.



Plate 10: Greenfield at north end of proposed restoration area, looking S.





PECENED. 2017 ROSA

Plate 11: Previously quarried area at NE end of proposed restoration area, looking SE.



Plate 12: Greenfield at east side of proposed extraction and restoration area, looking NW.





PRICEINED. 2017 ROSA

Plate 13: General view of east side of previously quarried proposed extraction and restoration area, looking SW.



Plate 14: Previously unquarried field at SE end of proposed extraction and restoration area, looking SW.





PECENED. 2017 ROSA

Plate 15: Previously unquarried field at south end of proposed extraction and restoration area, looking S.



Plate 16: Site of enclosure CL044-078 at SE end of Proposed Development site, looking SSE.