



Environmental Impact Assessment Report (EIAR)

Volume 3: Appendices

Ros an Mhíl Deep Water Quay

Department of Agriculture, Food and the Marine

November 2025

Project No.	Doc. No.	Rev.	Date	Prepared By	Checked By	Approved By	Acceptance Code / Status
24984	6003	P01	15/11/2025	EP	CF	CF	ISSUED

MWP, Engineering and Environmental Consultants
Address: Reen Point, Blennerville, Tralee, Co. Kerry, V92 X2TK, Ireland
www.mwp.ie



Disclaimer: This Report, and the information contained in this Report, is Private and Confidential and is intended solely for the use of the individual or entity to which it is addressed (the “Recipient”). The Report is provided strictly on the basis of the terms and conditions contained within the Appointment between MWP and the Recipient. If you are not the Recipient you must not disclose, distribute, copy, print or rely on this Report (unless in accordance with a submission to the planning authority). MWP have prepared this Report for the Recipient using all the reasonable skill and care to be expected of an Engineering and Environmental Consultancy and MWP do not accept any responsibility or liability whatsoever for the use of this Report by any party for any purpose other than that for which the Report has been prepared and provided to the Recipient.

Contents

APPENDIX 1A: Consultee Responses 2025

APPENDIX 2A: Construction Environmental Management Plan (CEMP)

APPENDIX 6A: Ground Investigation Interpretative Report

APPENDIX 6B: Geophysical Survey Report (Marine)

APPENDIX 7A: Flood Risk Assessment

APPENDIX 7B: Water Level and Wave Modelling Study

APPENDIX 7C: DIVAST Modelling Studies

APPENDIX 8A: Aquafact Marine Survey Report

APPENDIX 9A: Údarás na Gaeltachta Letter Confirming Landowner Consent and Availability of Connection to their Local Effluent Treatment Plant for Future Works

APPENDIX 10A: Archaeological Marine Survey Information

APPENDIX 10B: Archaeological Marine Monitoring Report 2024

APPENDIX 11A: Calibration Certificates

APPENDIX 11B: Noise Monitoring Location Photos

APPENDIX 11C: Pre and Post Structural Photos

APPENDIX 11D: Continuous Vibration Monitoring Report

APPENDIX 14A: Idaso Traffic Survey Report

APPENDIX 14B: PICADY Junction Analysis