

Ballyfeeny Green Energy Project



Environmental Impact Assessment Report Volume III

Appendix 8.3 – Photolog September 2025

This page is left intentionally blank

RECEIVED: 15/09/2025



Photo 1: A2 area heavily overgrown



Photo 3: A3 clear stream through an area of grassland – easily accessed



Photo 4: A3 sample clear and odourless




Photo 5: B1 area overgrown



Photo 6: B1 sample clear and odourless



Photo 7: B2 area overgrown. This sample was visually clear and odourless



RECEIVED: 15/09/2025

Photo 9: B3 This sampling point was not easily accessible and was heavily overgrown



Photo 10: B3 This sample was visually clear and odourless



Photo 11: C1 This sampling point was overgrown with briars crossing the stream. The electric fencing would suggest this stream is adjacent to agricultural farmlands.



Photo 12: C1 This sample appeared to be clear with a yellow hue and was odourless



RECEIVED: 15/09/2025

Photo 9: C2 This sample was odourless and visually clear



Photo 10: C2