


Kerdiffstown LandFill Remediation Project
 Imagery depicting the view towards the development site



Easting (IG): 292649
 Northing (IG): 222089
 Direction of View 30° W of Grid North
 Angle of View: 80°

Lens: 50mm / Full Frame Sensor
 Camera: Canon 1-D Mark II digital SLR
 Camera Height: 1.7m Above Ground Level

Date: 15-Nov-16
 Time: 15:12

Montage View - B
 Post Planting - 1 year



Montage View - C
 Post Planting - 7 years




These are 80° panoramic montages captured and presented in accordance with the guidance set by the British Landscape Institute 2011 - Advice Note 01/11.

To view these panoramas on a flat surface one must move from left to right along its length whilst maintaining a perpendicular viewing direction and the specified **correct viewing distance of 30cm**. To see this entire panoramic scene in reality would necessitate turning one's head through 40°.



Kerdiffstown LandFill Remediation Project

Imagery depicting the view towards the development site



Easting (IG): 292649
 Northing (IG): 222089
 Direction of View 30° W of Grid North
 Angle of View: 80°

Lens: 50mm / Full Frame Sensor
 Camera: Canon 1-D Mark II digital SLR
 Camera Height: 1.7m Above Ground Level

Date: 08-Mar-17
 Time: 18:55

Existing View
Nighttime



Montage View - D
Nighttime with sportsground spotlights




These are 80° panoramic montages captured and presented in accordance with the guidance set by the British Landscape Institute 2011 - Advice Note 01/11.

To view these panoramas on a flat surface one must move from left to right along its length whilst maintaining a perpendicular viewing direction and the specified **correct viewing distance of 30cm**. To see this entire panoramic scene in reality would necessitate turning one's head through 40°.



Kerdiffstown LandFill Remediation Project
 Imagery depicting the view towards the development site



Easting (IG): 291792
 Northing (IG): 221533
 Direction of View 83° W of Grid North
 Angle of View: 80°

Lens: 50mm / Full Frame Sensor
 Camera: Canon 1-D Mark II digital SLR
 Camera Height: 1.7m Above Ground Level

Date: 15-Nov-16
 Time: 15:21

Existing View



Montage View - A
 Post earthworks and seeding




These are 80° panoramic montages captured and presented in accordance with the guidance set by the British Landscape Institute 2011 - Advice Note 01/11.

To view these panoramas on a flat surface one must move from left to right along its length whilst maintaining a perpendicular viewing direction and the specified **correct viewing distance of 30cm**. To see this entire panoramic scene in reality would necessitate turning one's head through 40°.



Kerdiffstown LandFill Remediation Project
Imagery depicting the view towards the development site



Easting (IG): 291792
 Northing (IG): 221533
 Direction of View 83° W of Grid North
 Angle of View: 80°

Lens: 50mm / Full Frame Sensor
 Camera: Canon 1-D Mark II digital SLR
 Camera Height: 1.7m Above Ground Level

Date: 15-Nov-16
 Time: 15:21

These are 80° panoramic montages captured and presented in accordance with the guidance set by the British Landscape Institute 2011 - Advice Note 01/11.

To view these panoramas on a flat surface one must move from left to right along its length whilst maintaining a perpendicular viewing direction and the specified **correct viewing distance of 30cm**. To see this entire panoramic scene in reality would necessitate turning one's head through 40°.

Montage View - B
Post Planting - 1 year

Mitigation planting not visible from this location



Montage View - C
Post Planting - 7 years

Mitigation planting not visible from this location

