



Door Now in Place
And WALL STEPPED
BACK FROM Existing
WALL.

J1276641567 J55E63D5330513 3. JPA Emma 1+

Boyer

J1276641567 J55E63D5330513 10. JPA Emma +

Boyer



Baldore

J1276641567 JSSE6305330513 8. Jrs Emma 1+

Baldore

J1276641567 JSSE6305330513 7. Jrs Emma 1+



Balene

J1276641567 JS5E63D5330513 6. Jp9 emma 1+

Balene

J1276641567 JS5E63D5330513 4. Jp9 emma 1+



Balger

J1276641567 J55E6305330513 L.J.P. Emma 1+

Balger

J1276641567 J55E6305330513 S.J.P. Emma 1+



Beje

J1276641567 J55E63D5330513 9.jpg emma 1+



STARTED WITH A ROLLER
SHUTTER
THEN DOOR
NOW A WALL
HAS BEEN STEPPED
BACK FROM EXISTING WALL

0004.JPG
J1276531752 J7F1CF1P0311205.JPG emm3 1+

No Boundary WALL
To match Existing Houses

0009.JPG
J1276589335 J561D710643135 2.JPG emm3 1+



8 M Section of
Guttering TAKES RAIN
WATER OF COMPLETE
ROOF No Gully TRAP

0003.JPG
J1276631152 J7E1D1D831M4 4.119 emma 1+

0004.JPG
J127658935 J661D710643135 7.119 emma 1+



0002.JPG
J127658935 J661D710643135 9.jpg emma 1st

For some reason
THIS DOSE No seem
to Have Been converted
to Be Wheelchair
Friendly

0000.JPG
J127658935 J661D710643135 11.jpg emma 1st



J1276641567 JSSE6305330513 22. Jpa emma +

emma

J1276641567 JSSE6305330513 23. Jpa emma +

emma



J1276641567 JSSE6305330513 11. JPA emma +

50219

J1276641567 JSSE6305330513 15. JPA emma +

50219



J1276641567 JSSE63D5330513 14. J-P9 Emma +

5028 A ~~XXXXXXXXXX~~

J1276641567 JSSE63D5330513 13. J-P9 Emma +

5028 A ~~XXXXXXXXXX~~



J1276641567 JSSE6305330513 18. jps emma +

30513

J1276641567 JSSE6305330513 12. jps emma +

30513



windows too small
No windows this size
in Existing Houses

0002. JPN
J127663 052 J7E1CF1D831124 3. JPS emma +

No Boundary WALLS
to MATCH Area.

J127664 1567 J5E63D5330513 19. JPS emma +

3/23
A



No Lenthals
Over HEAD windows
and No concrete
sills SAME AS
Existing Houses

J1276641567 JSSE6305330513 20. JPA Emma +

Handwritten signature

J1276641567 JSSE6305330513 21. JPA Emma +

Handwritten signature



J1276641567 JSSE6305330513 11.1ps emm3 +

5/2/02

ROOF Removed
NOW Boundary WALL
standing with NO
Supporting Pillars
in place.
At Back of Building

J1276641567 JSSE6305330513 17.1ps emm3 +

5/2/02



NO EFFORT TO MATCH
Finish Around windows
And windows in Area
Windows Also 2 small
Don't MATCH Area.

Handwritten signature


J127654155 J5265305330513 6. JPS emma +

0004.JP5
J127658935 J661D71D643135 7. JPS emma 1st



0002.JPG
J127658935 J661D710643135 9.jpg emma 1et

0003.JPG
J127658935 J661D710643135 8.jpg emma 1et



0000.JPG
J1276531752 JE1CF1D83112
1.1.19 8mm 14
Suttering Takes ~~ALL~~ RAIN
WATER OFF ROOF NO
Gully in place.
Door Removed And WALL
stepped Back from Existing
Building And smooth Plaster
Finish on ~~NEW~~ WALL HALF
OF ~~Old~~ Door installed And REVERSED
Bad side FACING out

0007.JPG
J127653235 J6610710043135
4.1.19 8mm 14
75 LYNNWOOD PK
SHOP Knicked
WAS A SIMILAR Building
NEW House Built



0000.JPG
J127658935 J6610710643135 1.jpg emma 1st

MAcks
SHOP CHAU LAGHAN Court
Garryowen
Currently Being renovated
WAS A LEFT ROOF
Building

0005.JPG
J127658935 J6610710643135 6.jpg emma 1st

75 Lynwood PK
FORMALLY COONEYS SHOP
COMPLETED Demolished
And New House Built



FS

LYNWOOD

PK

0001.JPG
J127653035 J661D710643135 10.jpg emma 1+

0000.JPG
J1276531752 J7E1CF1D631124 1.jpg emma 1+



0008.JPG
J127658935 J661D710643135 3. Jpg emma 1st

0001.JPG
J1276631752 J7E1061083124 3. Jpg emma 1st

WINDOWS AND DOORS
DO NOT MATCH EXISTING
HOUSES SMOOTH PLASTER
FINISH EXISTING HOUSES
DASH FINISH
WINDOWS OVER SIZED
1 WINDOW ~~plus~~ DOOR IN EXISTING
HOUSES