TIRAWLEY WIND FARM, CO. MAYO

VOLUME III
APPENDICES

TABLE OF CONTENTS

Appendix No.	Description
1.1	Author Qualifications and Experience
1.2	Cumulative Windfarm Sites
1.3	Scoping Opinion
1.4	Glossary of Common Acronyms
1.5	Other Major Developments or Proposed Developments (bigger than a one-off house) within 10km of the Proposed Development Site
1.6	Pre-Application Community Consultation (PACC) Report
2.1	Construction Environmental Management Plan (CEMP)
6.1	Plant Species Lists for Main Habitats within the Proposed Wind Farm Site
6.2	Bat Survey Report, Tirawley Proposed Wind Farm. Eire Ecology Environmental Consultants, February 2025
6.3	Aquatic Ecology Assessment, Tirawley Wind Farm. Ecofact Environmental Consultants, July 2025
6.4	Biodiversity Enhancement and Management Plan (BEMP)
6.5	Note on Baseline Surveys Lifespan
7.1	VP Survey Details, 2021-2023
7.2	Bird Survey VP Flight Line Data, 2021-2023
7.3	Bird Survey VP Flight Line Maps, 2021-2023
7.4	Lackan Bay Shoreline Surveys Details, 2021-2023
7.5	Transect Surveys - Survey Details, 2022-2023
7.6	Transect Surveys - Results, 2022-2023

Appendix No.	Description
7.7	Merlin, Woodcock and Wader Breeding Survey Details,2023
7.8	Winter Hen Harrier Roost Survey Details, 2022-2023
7.9	Collision Risk Modelling Report
8.1	Peat Stability Risk Assessment. Whiteford Geoservices Ltd. 21st July 2025
9.1	Flood Risk Assessment
9.2	Laboratory Reports
9.3	WFD Compliance Assessment Report
10.1	Scottish Government – Carbon Calculator Input and Output Data
11.1	Photos of Noise Monitors In-situ
11.2	Methodology for Calculating Wind Shear, Different Hub Heights and Standardising Hub Height Wind Speed
11.3	Derived Background Noise Levels, Background Plus 5 Trendline with the Predicted Noise Levels Against a Noise Limit of 43dB(A) at Each Receptor
11.4	SoundPlan Noise Outputs
11.5	Calibration Certificates of Noise Instruments
11.6	Candidate Turbine Manufacturer's Noise Emission Data
12.1a	Visual Receptor Sensitivity
12.1b	Magnitude of Visual Impacts at Representative Viewpoint Locations
13.1	Forestry Report
14.1	Cultural Heritage Plates
14.2	Inventory Descriptions
15.1	Shadow Flicker Analysis
16.1	Fire Safety Assessment and Advice Report
17.1	Turbine Delivery Route Delivery Report
17.2	Palmerstown Bridge Structural Assessment Report
18.1	Summary of Mitigation Measures