

# **MetroLink**

Transport Infrastructure Ireland

**EIAR Addendum: Photomontages** 

| P01.1

27/03/2024



**EIAR Addendum: Photomontages** 



### **MetroLink**

Project No: 32108600

Document Title: EIAR Addendum: Photomontages

Document No.:

Revision: P01.1 Date: 27/03/24

Client Name: Transport Infrastructure Ireland

Client No:

Project Manager: Paul Brown
Author: Shannon Byrne

File Name: EIAR Addendum: Photomontages

Jacobs Engineering Ireland Limited

Merrion House Merrion Road Dublin 4, D04 R2C5 Ireland T +353 1 269 5666 F +353 1 269 5497 www.jacobs.com

© Copyright 2018 Jacobs Engineering Ireland Limited. The concepts and information contained in this document are the property of Jacobs. Use or copying of this document in whole or in part without the written permission of Jacobs constitutes an infringement of copyright.

Limitation: This document has been prepared on behalf of, and for the exclusive use of Jacobs' client, and is subject to, and issued in accordance with, the provisions of the contract between Jacobs and the client. Jacobs accepts no liability or responsibility whatsoever for, or in respect of, any use of, or reliance upon, this document by any third party.

#### **Document history and status**

Revision	Date	Description	Author	Checker	Reviewer	Approver
P01.1	27/03/24		SB	RH	RH	РВ



# Introduction

This addendum provides an overview of the updates to photomontages since the Railway Order submission.

### 1.1 Photomontages

LLCA	Change	Viewpoints Affected
4	Updates to reflect changes following Arboricultural Impact Assessment update	<ul><li>VVM4.4</li><li>VVM4.5</li><li>VVM4.6</li><li>VVM4.7</li><li>VVM4.8</li></ul>
6	Updates to reflect changes following Arboricultural Impact Assessment  Addition of no BusConnects scenario in photomontages	<ul> <li>VVM6.1</li> <li>VVM6.2</li> <li>VVM6.3</li> <li>VVM6.4</li> <li>VVM6.5</li> <li>VVM6.6</li> <li>VVM6.7</li> <li>VVM6.8</li> </ul>
7	Addition of no BusConnects scenario in photomontages	<ul> <li>VVM 7.1</li> <li>VVM 7.2</li> <li>VVM 7.3</li> <li>VVM 7.4</li> <li>VVM 7.5</li> </ul>
8	Updates to reflect changes following Arboricultural Impact Assessment update	<ul><li>VVM 8.1</li><li>VVM 8.2</li><li>VVM 8.3</li><li>VVM 8.4</li></ul>
9	Addition of no BusConnects scenario in photomontages	• VVM 9.1
12b	New viewpoint added for Santry Lodge Updates for changes to footpaths at Santry Lodge	<ul><li>VVM 12b.1</li><li>VVM 12b.2</li><li>VVM 12b.3</li><li>VVM 12b.4</li></ul>
13	Addition of no BusConnects scenario in photomontages	<ul><li>VVM 13.1</li><li>VVM 13.2</li><li>VVM 13.4</li></ul>
14	Addition of no BusConnects scenario in photomontages	<ul><li>VVM 14.1</li><li>VVM 14.2</li><li>VVM 14.3</li><li>VVM 14.4</li></ul>
15	Addition of no BusConnects scenario in photomontages	<ul><li>VVM 15.1</li><li>VVM 15.2</li><li>VVM 15.4</li></ul>
17	Updates to reflect changes following Arboricultural Impact Assessment	<ul><li>VVM 17.1</li><li>VVM 17.2</li><li>VVM 17.3</li></ul>

1





LLCA	Change	Viewpoints Affected
		• VVM 17.4
		• VVM 17.5 • VVM 18.1
18		<ul><li>VVM 18.1</li><li>VVM 18.2</li></ul>
		• VVM 18.3
	Updates to reflect changes following Arboricultural Impact Assessment	• VVM 18.4
		• VVM 18.5
	Addition of no BusConnects scenario in photomontages	• VVM 18.6
		• VVM 18.7
		• VVM 18.8
19		• VVM19.1
	Updates to reflect changes following Arboricultural Impact Assessment	• VVM19.2
	Updates to reflect design changes in skylights	• VVM19.3
	Opdates to reflect design changes in skylights	<ul> <li>VVM19.4</li> </ul>
	Addition of new viewpoint from Berkely Road	• VVM19.5
	Addition of new viewpoint from Berkely Road	• VVM19.6
		• VVM20.1
		• VVM20.2
20		• VVM20.3
		• VVM20.4
		• VVM20.5
	Update to O'Connell Street and Moore Street entrances	• VVM20.6
		• VVM20.7
	Updates to reflect tree retention on O'Connell Street	• VVM20.8
		• VVM20.9
		• VVM20.10
		• VVM20.11
		• VVM20.12
23		<ul><li>VVM20.13</li><li>VVM23.1</li></ul>
		<ul><li>VVM23.1</li><li>VVM23.2</li></ul>
	Updates to reflect changes following Arboricultural Impact Assessment	• VVM23.2 • VVM23.3
	Opuales to reliect changes following Arbonicultural impact Assessment	<ul><li>VVM23.3</li><li>VVM23.4</li></ul>
	Updates to include Charlemont Layby	<ul><li>VVM23.4</li><li>VVM23.5</li></ul>
	apasto to morado orianoment Edyby	<ul><li>VVM23.5</li><li>VVM23.6</li></ul>
		• VVM23.7