



Dyrick Hill Wind Farm

Figure 6.12

Haul Route Widening Location 3

- Recently Felled Conifer Plantation WS5
- Conifer Plantation WD4
- Improved Agricultural Grassland GA1
- Site Boundary



Drawn By	PD
Date	29/05/2023
Data Source	Bing