## EIA Pre-screening - EIAR Not Submitted

An Bord Pleanála Case Reference			ABP-309500-21			
Development Summary			Are the roof repair works comprising re-slating the side (east) aisle of the Church of the Assumption (a protected structure) exempt development?			
1. Does proje	the pro	oposed de	velopment constitute an EIA		Yes	<b>/</b>
(that is in	nvolving	g construction	on works, demolition, or interventions		No	
2. If YES, does the proposed development, or any part of it, fall within a class of development set out in Part 1 or Part 2, Schedule 5 of the Planning and Development Regulations?						
Tick Thr		Threshold		Comment	Conclusion	
				(if relevant)		
No	<b>/</b>	N/A			No EIAR or Preliminary Examination required	
Yes	If YES, tick one of the following:					
		Exceeds / Is equal to No Thresh	1		EIAR re	equired
		Sub threst	nold		(Issue le	nary nation required tter to EPA if IED/ ste licence)
3. If Preliminary Examination is required, has Schedule 7A information been submitted?					Yes No N/A	

EOI SEO flush hilly Date: 24/03/2021

•