

## Board Direction PL93.246487

The submissions on this file and the Inspector's report were considered at a Board meeting held on August 11<sup>th</sup> 2016.

The Board decided to refuse permission generally in accordance with the Inspector's recommendation, subject to the amendments shown in the reasons and considerations set out below.

## Reasons and Considerations.

- The development by reason of its height, design and use, contravenes
  materially a condition attached to the original permission for the development,
  namely Condition No. 8 of planning registration number PD 04/1494, and is
  therefore contrary to the proper planning and sustainable development of the
  area.
- 2. Having regard to the underlying regionally important fissured aquifer where the groundwater is deemed to be extremely vulnerable to contamination and the T-value calculated on the site relating to the original permission, planning registration number, PD04/1494, which indicated rapid percolation rates, the Board is not satisfied the existing development on the site can be treated satisfactorily, the development would, therefore be, prejudicial to public health.

<b>Note</b> : On the basis of submissions made in connection with the planning application
and the appeal, and general observations on site, it appears to the Board the use of
the structure may not be as described in the submission documents, and may in fact
be unauthorised. Accordingly it is considered it would be inappropriate for the Board
to consider a grant of permission for the development under such circumstances.

<b>Board Member</b>		Date:	11 <sup>th</sup> August 2016
	Paul Hyde		