


E-E Section through No 5 Patrick St, Podium and Aparthotel SCALE: 1 : 100





Printed on ___% Post-Consumer Recycled Content Paper

Schedule Of Building Fabric Repair Works

Please note, all works to historic buildings will be carried out in accordance with the Conservation Architects recommendations. Please see the Conservation Architect's Specifications for further information. Summary of works

Windows: Early timber windows to remain in situ following repair by specialist joiners. All modern uPVC/alumin windows within the existing facade to be replaced with multi-pane vertical sliding sash in box frames unless otherwise stated. All blocked openings and missing windows within the existing facade to be replaced with multi-pane vertical sliding sash in box frames unless otherwise stated.

Roof Salvage all existing stone slate on the historic structures for reuse on the building. Remove all concrete roof tiles and other contemporary roof finishes, repair, replace and treat roofing elements as necessary, and finish with salvaged and replacement stone slates.

Historic roof timbers to be repaired on a minimum intervention basis. Leadwork All existing lead flashings, parapet gutters and dpc to roof fabric to be removed and replaced with appropriate materials as recommended by the Conservation Architect.

Chimney Repair Generally all existing brick chimneys are to be repaired and repointed. Chimneys that are plaster rendered are to have render removed, flashings replaced and rerendered.

instruct the top few courses of brick to be removed and rebedded on a bitumen coated lead dpc. Existing Timber Floor Generally all existing suspended timber floors are to be retained, repaired and upgraded to meet loading requirements.

Internal Plaster Repair Repair all existing lime plaster in accordance with Conservation Architects recommendations. Rainwater Goods

Replace all circular down pipes & decorative hopper heads with heritage cast iron rainwater goods. Brick Restoration System Clean and treat brickwork in accordance with Conservation Architects recommendations. Allow for repointing of brickwork and repairs to brickwork and stone as necessary.

Painting Specification All internal plaster surfaces and joinery to be finished in matt emulsion and oil paints, and external plaster rendered surfaces to be finished in mineral paint as recommended by the Conservation Architect.

Existing Door Upgrading An intumescent system is to be used to upgrade raised and fielded panel doors to fire rated doors. Envirograf papers to be used in conjunction with intumescent paints to achieve 30 min fire rating.

Proposal Key - Sections:

3)	New balcony supported on CHS 88.9x6.3 with PFC's to pe with resin anchor to structural engineers details. Stainless supports with toughened glazing recessed into channels at
5)	Raised podium at first floor level provides private garden s Street. Waste storage is screened from view under.
6)	Ashlar stone.
2)	Balconies to Aparthotel screened from residential with slidi frame. Glass guard with s/s metal handrail behind and to screens also provide solar shading - north facing balconies screens.

(26) Atrium link from Aparthotel to Georgian Suite conversions.

In cases where the masonry is loose and damaged and there is risk of moisture penetration the conservation architect may

perimeter tied into existing wall ss steel handrails and side at floor and u/s of handrail

space for No's 4 + 5 Patrick

sliding timber screens on metal to sides. Sliding timber nies therefore do not require

PROJECT **Opera Site**

CLIENT -----

Limerick City and County Council

CONSULTANT

AECOM The Clarence Street West Building 2 Clarence Street West Belfast BT2 7GP United Kingdom Tel +44 (0)28 90607200 www.aecom.com



All levels referenced to Malin Head Datum **KEY PLAN**

SUE/REVISION HISTORY					
- I/R	Jan 19 DATE	Planning Submission DESCRIPTION			
		1			
		AWIDER .			
	60568520				
SHEET TITLE					
Parcel 2A - Building Sections - Proposed Sheet 3 of 3					
1 : 100@A0					
SHE	SHEET NUMBER REV				
OPRA-ACM-Z2A-ZZ-DR-AR-12003					