GENERAL NOTES

by David Slattery Conservation Architects."

"Surviving original multi-page seek windows to link building to be carefully conserved, retaining single.

"All taking down and removals to be carefully undertaken in accordance with Conservation Specifications

"Surviving original multi-pane sash windows to link building to be carefully conserved, retaining single panes of glass in accordance with Conservation Specifications by David Slattery Conservation

Architects."

"Non-original 20th Century sash windows to Seminary to be spliced where beads and half cills are decayed. New slimglaze double glazed units to be fitted into existing sashes. All in accordance with detail drawings showing glazing bar profile impact and Conservation Specifications by David Slattery Conservation Architects."

"All services to Seminary to reuse existing routes where possible with any new routes and installarions to be carried out in accordance with Conservation Specifications by David Slattery Conservation

"Minor repairs to leaded and stained glass in Assembly Hall are limited to repair of opening sections and glass replacement where panes are broken. No storm or secondary glazing proposed. All to be carried out in accordance with Conservation Specifications by David Slattery Conservation Architects."

"Stained glass over front entrance to chapel is set in a timber frame and is to be carefully removed to agreed location in accordance with Conservation Specifications by David Slattery Conservation

"Slate roofs to Seminary and Chapel to be restored using Blue Bangor slate and stepped lead valleys in accordance with Conservation Specifications by David Slattery Conservation Architects."

"All cast-iron rainwater goods to be retained and renewed with any replacements where goods are beyond repair to be in cast iron. All in accordance with Conservation Specifications by David Slattery

"Render to be lightly cleaned with dilute biocide in accordance with Conservation Specifications by David Slattery Conservation Architects."

"Limestone strings and cills to be carefully cleaned using Doff or similar steam cleaning - no abrasive or chemical cleaning. All in accordance with Conservation Specifications by David Slattery Conservation

"Granite cills, cappings etc to be carefully cleaned using a light calcium carbonate abrasive in

accordance with Conservation Specifications by David Slattery Conservation Architects."


in accordance with Conservation Specifications by David Slattery Conservation Architects."

"Wholesale repointing is not required and localised pointing where necessary will be carried out using a lime (NHL3.5) mortar and aggregate and lime mix to match existing bedding mortar tone and texture. All


KEY - WINDOWS


D. NEW WINDOW

A. EXISTING WINDOW RETAINED
B. EXISTING WINDOW REMOVED
C. EXISTING WINDOW REPLACED











APPLICANT NAME

CWTC Multi Family ICAV acting on behalf of its sub-fund DBTR DR1 Fund

Holy Cross College SHD

PROJECT NUMBER

Holy Cross College, Clonliffe Road, Dublin 3 and Drumcondra Road Lower, Drumcondra, Dublin 9

Seminary Building - Proposed South Elevation

 CLN-MCM-00-ZZ-M3-A-C0003
 06/02/20

 SCALE@ A0:
 DRAWN/CHECKED:

 As indicated
 IB/ ROC

 STATUS CODE:
 DRAWING NUMBER
 REVIS

 A1
 CLN-MCM-E1-ZZ-DR-A-P-111
 P2

Henry J Lyons Architecture + Interiors henryjlyons.com +353 1 888 3333 henryjlyons.com 51-54 Pearse Street Dublin D02 KA66

Architecture + Interiors henryjlyons.com +353 1 888 3333 51-54 Pearse Stre Dublin D02 KA66

O'Donnell+Tuomey

mcculloughmulvinarchitects





BARRETT MAHONY

OCSC

POCINION I SITTER I CADRIN

PRESENTATION I CADRINI

CONTROL I CADRI