


BALLINA FLOOD RELIEF SCHEME EIAR

Appendix 18.2: Plates - Cultural Heritage



rpsgroup.com

Plates

Plate 18-1 View towards junction of northern Lower Bridge elevation and tree-lined Bachelor's Walk area with commercial premises opposite	1
Plate 18-2 View of existing flood wall elevation along Bachelor's Walk	
Plate 18-3 View towards northern elevation of Lower Bridge along Bachelor's Walk	
Plate 18-4 View towards existing flood walling along Bachelor's Walk and mid-twentieth century	
housing fronting along same (from Clare Street – Howley Street)	2
Plate 18-5 View towards floating jetty along northern area of Bachelor's Walk works location	
Plate 18-6 View towards temporary works area at former Ballina Dairy/Co-Op north of Bachelor's Walk	
Plate 18-7 Lower Bridge wing wall (northern elevation) tie-in with existing flood relief walling (left)	
Plate 18-8 Existing flood walling along Clare Street (Howley Street)	
Plate 18-9 Wing wall of Lower Bridge and tie-in with existing flood walling along Clare Street (Howley Street)	
Plate 18-10 View towards north (downstream) along existing flood walling at Clare Street (Howley	0
Street)	5
Plate 18-11 View of (modified) riverbank/fishing access CH01 along flood walling at Clare Street (Howley Street)	6
Plate 18-12 View of riverbank/fishing access CH02 along flood walling at Clare Street (Howley Street)	
Plate 18-13 View of roadside riverbank/fishing to stone access to steps CH02 access along flood	
walling at Clare Street (Howley Street)	7
Plate 18-14 View from riverbank of roadside access to pier CH03 along flood walling at Clare Street (Howley Street)	7
Plate 18-15 View of Pier CH03 along riverbank at Clare Street (Howley Street)	
Plate 18-16 View of Marian Shrine (1954) CH04 along riverbank at Clare Street (Howley Street)	
Plate 18-17 View of junction between Upper Bridge curving wing wall and Cathedral Road existing flood walling	
Plate 18-18 View of masonry tie-in of Upper Bridge to existing flood walling along Cathedral Road	
Plate 18-19 View of roadside flood walling elevation adjacent Upper Bridge along Cathedral Road.	
Note protruding lower courses and later repointing with 'FAS 1996' inscription	10
Plate 18-20 View of flood wall terminus, access steps and riverside stone paved platform/quayside	
adjacent Upper Bridge along Cathedral Road.	10
Plate 18-21 View of riverside elevation of flood walling and stone paved platform/quayside adjacent	
Upper Bridge along Cathedral Road. Note considerable wall height	11
Plate 18-22 View of cut stone drainage feature along base of flood wall at riverside elevation adjacent	
Upper Bridge, Cathedral Road	11
Plate 18-23 View of stone access steps to riverside quay area near Upper Bridge, Cathedral Road	
Plate 18-24 View of roadside elevation flood walling adjacent Lower Bridge, Cathedral Road	
Plate 18-25 View along flood walling and riverside access from Lower Bridge area, Cathedral Road	
Plate 18-26 View towards Upper Bridge of riverside access footpath/platform	
Plate 18-27 View towards Cathedral Road existing flood walling and public riverside access from	
Emmet Street	14
Plate 18-28 View towards Cathedral Road existing flood walling and St Muredach's Cathedral from Emmet Street	14
Plate 18-29 View towards public access to riverside along Cathedral Road	
Plate 18-30 View towards existing public riverside amenity area and street furniture along Cathedral	
Road	15
Plate 18-31 View of railings of St Muredach's Cathedral (RPS 30) along Cathedral Road	
Plate 18-32 View towards interior area of medieval Augustinian Abbey SMR MA030-074001- along Cathedral Road	
Plate 18-33 View towards elaborate west door opening of medieval Augustinian Abbey SMR MA030-	10
074001- along Cathedral Road	17

Plate 18-34 View towards junction of Emmet Street with Upper Bridge. Note no change in masonry	
style from wing wall to quay wall	17
Plate 18-35 View along quayside walling at Emmet Street, towards Upper Bridge	18
Plate 18-36 View along quayside at Emmet Street towards Lower Bridge with modern railing inserts	18
Plate 18-37 View of river access steps along quayside at Emmet Street	19
Plate 18-38 View of river access steps and mooring point along quayside at Emmet Street	19
Plate 18-39 View towards recently renovated pair of semi-detached townhouses (Mary Robinson	
birthplace) and Emmet Street quayside	20
Plate 18-40 View from Emmet Street quayside towards opposite riverbank and St Muredach's	
Cathedral	20
Plate 18-41 View of vegetated abutting flood walling to Upper Bridge southern wing wall at Ridgepool	
Road	21
Plate 18-42 View of tie-in location of existing wall with Upper Bridge at Ridgepool Road. Note	
roughcast render	21
Plate 18-43 View from Upper Bridge of stop-start upstanding flood walling with interspersed modern	
railings along Ridgepool Road	22
Plate 18-44 View of walling along Ridgepool Road with interspersed railings and curved coping	
treatment	22
Plate 18-45 View towards Salmon Weir and adjacent weir building fronting Ridgepool Road	
Plate 18-46 External wall elevation to Salmon Weir building, restored 2011	
Plate 18-47 View towards cast concrete flood walling and pedestrian bridge	
Plate 18-48 View towards cast concrete stepped riverside wall elevation along Ridgepool Road	
Plate 18-49 View towards riverside wall elevation (rendered and painted) upstream from pedestrian	
bridge, along Ridgepool Road	25
Plate 18-50 View of railing abutment to southern parapet of Upper Bridge to rear of Ballina Manor	-
Hotel	25
Plate 18-51 View along riverfront at rear of Ballina Manor Hotel. Note modernised surface treatment,	-
modern railings and access ramps/steps	26
Plate 18-52 View along riverfront at rear of Ballina Manor Hotel. Note modern stepped platform,	
railings and stepped angling river access	26
Plate 18-53 View towards south and terminus area to rear of Ballina Manor Hotel	
Plate 18-54 View towards Salmon Weir and rear area of Barrett Street including derelict warehouses	
and Ballina Arts Centre (red roof)	27
Plate 18-55 View towards rear area of Ballina Arts Centre. Note that riverside access to the former	
warehouse(s) fronting the river was not possible during field survey	
Plate 18-56 View towards river frontage area to rear of derelict warehouses and Ballina Arts centre	
requiring replacement flood walling	28
Plate 18-57 View towards river frontage area to rear of Ballina Manor Hotel requiring replacement	
glass walling in combination with replacement flood walling	29
Plate 18-58 View along Brusna riverbank adjacent to access bridge to Shanaghy Heights	
Plate 18-59 View upstream along Brusna rivebanks adjacent to R294	
Plate 18-60 Community installed information signage at Rathkip roadside amenity area	
Plate 18-61 Replica ringfort community installation at Rathkip along the R294	
Plate 18-62 View downstream to River Brusna and works area riverbank (left) from Rathkip Bridge	
Plate 18-63 View of Rathkip Bridge (northern parapet)	
Plate 18-64 View of railway bridge south of Tullyegan works area (in active use)	
Plate 18-65 View of Rahans Bridge MA-N26-001.00 eastern parapet along N26	
Plate 18-66 View for Kanaris Bridge MA-N26-001.00 eastern parapet along N26 Plate 18-66 View toward Tullegan stream elevation of Rahans Bridge (N26)	
Plate 18-67 View towards west from N26 Rahans Bridge of heavily vegetated stream banks to	აა
• • •	24
Tullyegan stream Plate 18-68 View towards culverted open channel area of Bunree stream, adjacent N59 at Moyvale	34
	24
Park	
Plate 18-69 View towards gabion baskets and culverted section of Bunree stream at Moyvale Park	30

Plate 18-70 View east along Behy Road	35
Plate 18-71 View towards Creteboom SS in River Moy from Moy Boat Club	
Plate 18-72 View towards west elevation Moy Boat Club building (modern) at Creggs Road/Quay Rad	
junction	36
Plate 18-73 View towards north elevation Moy Boat Club building (modern) at Creggs Road/Quay Rad	
junction	37
Plate 18-74 View of Crocketts Quay (ACA) area, River Moy (Quignamanger enviorns)	37

18 PLATES



Plate 18-1 View towards junction of northern Lower Bridge elevation and tree-lined Bachelor's Walk area with commercial premises opposite



Plate 18-2 View of existing flood wall elevation along Bachelor's Walk




Plate 18-3 View towards northern elevation of Lower Bridge along Bachelor's Walk



Plate 18-4 View towards existing flood walling along Bachelor's Walk and mid-twentieth century housing fronting along same (from Clare Street – Howley Street)



Plate 18-5 View towards floating jetty along northern area of Bachelor's Walk works location



Plate 18-6 View towards temporary works area at former Ballina Dairy/Co-Op north of Bachelor's Walk



Plate 18-7 Lower Bridge wing wall (northern elevation) tie-in with existing flood relief walling (left)



Plate 18-8 Existing flood walling along Clare Street (Howley Street)




Plate 18-9 Wing wall of Lower Bridge and tie-in with existing flood walling along Clare Street (Howley Street)



Plate 18-10 View towards north (downstream) along existing flood walling at Clare Street (Howley Street)



Plate 18-11 View of (modified) riverbank/fishing access CH01 along flood walling at Clare Street (Howley Street)



Plate 18-12 View of riverbank/fishing access CH02 along flood walling at Clare Street (Howley Street)



Plate 18-13 View of roadside riverbank/fishing to stone access to steps CH02 access along flood walling at Clare Street (Howley Street)



Plate 18-14 View from riverbank of roadside access to pier CH03 along flood walling at Clare Street (Howley Street)



Plate 18-15 View of Pier CH03 along riverbank at Clare Street (Howley Street)



Plate 18-16 View of Marian Shrine (1954) CH04 along riverbank at Clare Street (Howley Street)



Plate 18-17 View of junction between Upper Bridge curving wing wall and Cathedral Road existing flood walling



Plate 18-18 View of masonry tie-in of Upper Bridge to existing flood walling along Cathedral Road



Plate 18-19 View of roadside flood walling elevation adjacent Upper Bridge along Cathedral Road. Note protruding lower courses and later repointing with 'FAS 1996' inscription



Plate 18-20 View of flood wall terminus, access steps and riverside stone paved platform/quayside (CH05) adjacent Upper Bridge along Cathedral Road.



Plate 18-21 View of riverside elevation of flood walling and stone paved platform/quayside adjacent Upper Bridge along Cathedral Road. Note considerable wall height



Plate 18-22 View of cut stone drainage feature along base of flood wall at riverside elevation adjacent Upper Bridge, Cathedral Road



Plate 18-23 View of stone access steps to riverside quay area near Upper Bridge, Cathedral Road



Plate 18-24 View of roadside elevation flood walling adjacent Lower Bridge, Cathedral Road



Plate 18-25 View along flood walling and riverside access from Lower Bridge area, Cathedral Road



Plate 18-26 View towards Upper Bridge of riverside access footpath/platform



Plate 18-27 View towards Cathedral Road existing flood walling and public riverside access from Emmet Street



Plate 18-28 View towards Cathedral Road existing flood walling and St Muredach's Cathedral from Emmet Street



Plate 18-29 View towards public access to riverside along Cathedral Road



Plate 18-30 View towards existing public riverside amenity area and street furniture along Cathedral Road




Plate 18-31 View of railings of St Muredach's Cathedral (RPS 30) along Cathedral Road



Plate 18-32 View towards interior area of medieval Augustinian Abbey SMR MA030-074001- along Cathedral Road




Plate 18-33 View towards elaborate west door opening of medieval Augustinian Abbey SMR MA030-074001along Cathedral Road



Plate 18-34 View towards junction of Emmet Street with Upper Bridge. Note no change in masonry style from wing wall to quay wall



Plate 18-35 View along quayside walling at Emmet Street, towards Upper Bridge




Plate 18-36 View along quayside at Emmet Street towards Lower Bridge with modern railing inserts



Plate 18-37 View of river access steps along quayside at Emmet Street




Plate 18-38 View of river access steps and mooring point along quayside at Emmet Street



Plate 18-39 View towards recently renovated pair of semi-detached townhouses (Mary Robinson birthplace) and Emmet Street quayside



Plate 18-40 View from Emmet Street quayside towards opposite riverbank and St Muredach's Cathedral



Plate 18-41 View of vegetated abutting flood walling to Upper Bridge southern wing wall at Ridgepool Road



Plate 18-42 View of tie-in location of existing wall with Upper Bridge at Ridgepool Road. Note roughcast render



Plate 18-43 View from Upper Bridge of stop-start upstanding flood walling with interspersed modern railings along Ridgepool Road



Plate 18-44 View of walling along Ridgepool Road with interspersed railings and curved coping treatment



Plate 18-45 View towards Salmon Weir and adjacent weir building fronting Ridgepool Road



Plate 18-46 External wall elevation to Salmon Weir building, restored 2011



Plate 18-47 View towards cast concrete flood walling and pedestrian bridge



Plate 18-48 View towards cast concrete stepped riverside wall elevation along Ridgepool Road



Plate 18-49 View towards riverside wall elevation (rendered and painted) upstream from pedestrian bridge, along Ridgepool Road



Plate 18-50 View of railing abutment to southern parapet of Upper Bridge to rear of Ballina Manor Hotel



Plate 18-51 View along riverfront at rear of Ballina Manor Hotel. Note modernised surface treatment, modern railings and access ramps/steps



Plate 18-52 View along riverfront at rear of Ballina Manor Hotel. Note modern stepped platform, railings and stepped angling river access




Plate 18-53 View towards south and terminus area to rear of Ballina Manor Hotel



Plate 18-54 View towards Salmon Weir and rear area of Barrett Street including derelict warehouses and Ballina Arts Centre (red roof)



Plate 18-55 View towards rear area of Ballina Arts Centre. Note that riverside access to the former warehouse(s) fronting the river was not possible during field survey




Plate 18-56 View towards river frontage area to rear of derelict warehouses and Ballina Arts centre requiring replacement flood walling



Plate 18-57 View towards river frontage area to rear of Ballina Manor Hotel requiring replacement glass walling in combination with replacement flood walling



Plate 18-58 View along Brusna riverbank adjacent to access bridge to Shanaghy Heights




Plate 18-59 View upstream along Brusna rivebanks adjacent to R294



Plate 18-60 Community installed information signage at Rathkip roadside amenity area




Plate 18-61 Replica ringfort community installation at Rathkip along the R294




Plate 18-62 View downstream to River Brusna and works area riverbank (left) from Rathkip Bridge




Plate 18-63 View of Rathkip Bridge (northern parapet)



Plate 18-64 View of railway bridge south of Tullyegan works area (in active use)



Plate 18-65 View of Rahans Bridge MA-N26-001.00 eastern parapet along N26



Plate 18-66 View toward Tullegan stream elevation of Rahans Bridge (N26)



Plate 18-67 View towards west from N26 Rahans Bridge of heavily vegetated stream banks to Tullyegan stream



Plate 18-68 View towards culverted open channel area of Bunree stream, adjacent N59 at Moyvale Park



Plate 18-69 View towards gabion baskets and culverted section of Bunree stream at Moyvale Park



Plate 18-70 View east along Behy Road



Plate 18-71 View towards Creteboom SS in River Moy from Moy Boat Club



Plate 18-72 View towards west elevation Moy Boat Club building (modern) at Creggs Road/Quay Rad junction



Plate 18-73 View towards north elevation Moy Boat Club building (modern) at Creggs Road/Quay Rad junction



Plate 18-74 View of Crocketts Quay (ACA) area, River Moy (Quignamanger enviorns)