



POOR GROUND
NOT SURVEYED


NG1

POOR GROUND
NOT SURVEYED

NG2

NG3

NG4



Project: Regional Wastewater Treatment Plant (WwTP),
Greater Dublin Drainage, North County Dublin

Figure: Raw (drift/median correction) greyscales:
Newtowncorduff, NG1-NG3

Figure No: 25 Scale: 1/1500 @ A4 Ref: TAG 13003

POOR GROUND
NOT SURVEYED

NG5

NG1

POOR GROUND
NOT SURVEYED

NG2

NG3

NG4

NG6

N

