


Flooding at Jackson's Bridge

· ·






Confluence of two streams/rivers flowing down from Ballycurraghan to Jackson's Bridge and the Lyreen River plain.



Flooding affecting the southern boundary of both Gheel Autism Centre (foreground) and Patrick Comerford's land (background).



Extent of flooding adjacent to private lands following heavy rainfall. Photo taken from Jackson's Bridge.



River flowing under Jackson's Bridge in an easterly direction towards Lyreen River plain. Huge volume of water.




Extensive flooding on lands at Ballycurraghan, Maynooth. West/South-West perspective.

Photo taken by Stephen Collins - 05.08.23




Photo taken at Jackson's Bridge, easterly perspective towards Maynooth, showing the river flood plain.


Photo taken by Stephen Collins – 05.08.23




Lyreen River flood plain easterly direction towards Maynooth.




Flooding adjacent to the rail line at Jackson's Bridge, Maynooth.



Lyreen River flood plain from easterly direction, taken at Jackson's Bridge.



Lyreen River flood plain. Taken from easterly direction towards housing estates in Maynooth. Photo taken by Stephen Collins $-\,05.08.23$




The L5042 is very narrow in places and is totally unsuitable for HGVs due to road width and very heavy traffic in the am and pm. It is effectively a bypass for Maynooth West. This bridge is also a serious issue, single traffic access at this point only.

Photo taken by Stephen Collins - 11.10.23



Crinstown Cross Roads – L5042 meets Newtown Road R408. Very dangerous cross roads, particularly during rush hour am and pm.



No HGV's permitted on the L5042 and L5041 (to Jackson's Bridge). Also, previous weight restrictions.

Photo taken by Stephen Collins - 11.10.23