

A3-7

Derelict Property Inspection Report
Address: CPO Site 7, CW26683F
Reference: VHOL11
Date of Inspection: 27th April 2026

I confirm that a drone inspection of the above-mentioned site was carried out on 27 April 2026.

Following this inspection, I can confirm that the site remains vacant. The site is not being maintained to an acceptable standard and continues to exhibit characteristics consistent with vacancy and underutilisation.





Conclusion:

The site is confirmed to be vacant as of the date of inspection.

Signed: Angela Whelan
 Angela Whelan,
 Executive Technician
 Date: 27.04.2026