


A3-9

Derelict Property Inspection Report  
Address: CPO Site 9, CW33143F  
Reference: VHOL12  
Date of Inspection: 27 April 2026

I confirm that a drone inspection of the above-mentioned site was carried out on 27 April 2026. Following this inspection, I can confirm that the site remains vacant. The site is not being maintained to an acceptable standard and continues to exhibit characteristics consistent with vacancy and underutilisation.



Signed:   
Angela Whelan,  
Executive Technician  
Date: 27.04.2026