PREFACE

This Environmental Impact Statement (EIS) for the proposed Ringaskiddy Resource Recovery Centre consists of four volumes, of which this is the fourth:

- Volume 1 Non Technical Summary
- **Volume 2** EIS (Main Text)
- Volume 3 Figures
- Volume 4 Appendices

List of Appendices

1. Introduction

- 1.1 Letter from An Bord Pleanála
- 1.2 Consultation

2. Planning and Policy Framework and Need for the Scheme

3. Alternatives

- 3.1 Site Evaluation Criteria
- 3.2 ESB Networks Feasibility Study (D/47/6043/1064)

4. Description of the Proposed Development

- 4.1 EWC Codes of Waste Accepted by Indaver
- 4.2 Furnace Start Up and Shut Down Procedures
- 4.3 Interlock System
- 4.4 Compliance with Best Available Techniques (BAT)
- 4.5 Architectural Design Statement

5. Construction Activities

6. Population and Human Health

- 6.1 Hazard Identification and Risk Assessment by Byrne Ó'Cléirigh (2015)
- 6.2 Health Impact Assessment by EHA (2015)
- 6.3 Sampling and Analysis of Soil and Sediment Samples for PCDDs, PCDFs and PCBs at Various Locations around Cork Harbour
- 6.4 Modelling of PCDD/F Intake for Ringaskiddy Resource Recovery Centre 2015 by AWN

7. Roads and Traffic

- 7.1 Junction Analysis Results
- 7.2 Staff Mobility Management Plan
- 7.3 HGV Booking System Step-by-Step Process Flowchart

8. Air Quality

- 8.1 Air Quality Study by AWN (2015)
- 8.2 Description of AERMOD Model
- 8.3 Air Quality Impact from Traffic Sources
- 8.4 Cumulative Impact Assessment
- 8.5 Sensitivity Assessment of Modelling Input Parameters
- 8.6 Process Information
- 8.7 Detailed NO_x Process Calculations

9. Climate

10. Noise and Vibration

10.1 Noise Monitoring Results

11. Landscape and Visual

12. Biodiversity

- 12.1 Flora Survey
- 12.2 Bird Survey
- 12.3 Mammal Survey
- 12.4 Intertidal Survey
- 12.5 Site Synopsis
- 12.6 Winter and Breeding Bird Survey

13. Soils, Geology, Hydrogeology, Hydrology & Coastal Recession

- 13.1 Soil and Hydrogeological Investigation by KT Cullen & Co Report (November 2000 and January 2001)
- 13.2 Hydrogeological Assessment for Hammond Lane Metal Company by O'Callaghan Moran & Associates (2011)
- 13.3 Coastal Study 2015 by Arup
- 13.4 Flood Risk Assessment by Arup (2015)

14. Archaeological, Architectural & Cultural Heritage

- 14.1 Archaeology Architecture & Cultural Heritage Correspondences
- 14.2 Archaeology Architecture & Cultural Heritage Excavations
- 14.3 Archaeology Architecture & Cultural Heritage Local Cultural Heritage of Study Area
- 14.4 Archaeology Architecture & Cultural Heritage Descriptions of Archaeological Sites