

P1227-8 Ardderroo Wind Farm, Co. Galway
Appendix 8.2 - Temporary Construction Road Gouge Cores Logs

GC No.	Easting	Northing	Peat Depth (m)	Description
GC1	117300	236740	2	Refusal on rock (bedrock presumed)
GC2	117250	236705	1	Weathered rock or gravelly subsoil
GC3	117200	236670	1.5	Weathered rock or gravelly subsoil
GC4	117148	236636	0.15	Weathered rock or gravelly subsoil
GC5	117094	236598	0.1	Weathered rock or gravelly subsoil
GC6	117039	236560	0.5	0.2m gravelly SILT over rock (bedrock presumed)
GC7	116986	236526	0.5	Refusal on rock (bedrock presumed)
GC8	116932	236490	0.6	Refusal on rock (bedrock presumed)
GC9	116871	236464	0.5	Refusal on rock (bedrock presumed)
GC10	116812	236470	3	Refusal on rock (bedrock presumed)
GC11	116771	236496	2.2	Refusal on rock (bedrock presumed)
GC12	116728	236527	1	Refusal on rock (bedrock presumed)
GC13	116683	236557	13	Refusal on rock (bedrock presumed)
GC14	116639	236590	0	Refusal on rock (bedrock presumed)
GC15	116593	236619	0	Refusal on rock (bedrock presumed)
GC16	116539	236631	0	Refusal on rock (bedrock presumed)
GC17	117275	236774	1	Refusal on rock (bedrock presumed)
GC18	117226	236743	0	Gravelly, sandy SILT
GC19	117176	236712	2.5	Gravelly, sandy SILT
GC20	117120	236681	2	Weathered rock or gravelly subsoil
GC21	117066	236652	0.1	Gravelly, sandy SILT
GC22	117011	236622	0.15	Refusal on rock (bedrock presumed)
GC23	116953	236591	1	Weathered rock or gravelly subsoil
GC24	116894	236561	0.5	Gravelly, sandy SILT
GC25	116843	236534	0.2	Weathered rock or gravelly subsoil
GC26	116785	236519	0.15	Gravelly, sandy SILT