Concorde site

Verified Photomontages and CGIs

April 2019

MODEL WORKS



VISUAL IMPACT ASSESSMENT T.+353 1 2899 039

Project : Concorde site	Issue Date: 25-04-2019			Camera Location Map	

MODEL WORKS

VISUAL IMPACT ASSESSMENT T.+353 1 2899 039

Project : Concorde site	Issue Date: 24-04-2019	Photo Info. 07-01-2018 11:42	VIEW 01		BASELINE

MODEL WORKS

VISUAL IMPACT ASSESSMENT T.+353 1 2899 039

Project : Concorde site	Issue Date: 24-04-2019	Photo Info. 07-01-2018 11:42	VIEW 01		PROPOSED

Angle of View 73° Horizontal

Angle of View 39° Horizontal

MODEL WORKS

VISUAL IMPACT ASSESSMENT T.+353 1 2899 039

Project : Concorde site	Issue Date: 24-04-2019	Photo Info. 21-06-2018 08:00	VIEW 01	SUMMER	PROPOSED

Angle of View 73° Horizontal

Angle of View 39° Horizontal

MODEL WORKS

VISUAL IMPACT ASSESSMENT T.+353 1 2899 039

Project : Concorde site	Issue Date: 24-04-2019	Photo Info. 22-12-2018 12:19	VIEW 02		BASELINE

Angle of View 73° Horizontal

Angle of View 39° Horizontal

MODEL WORKS

VISUAL IMPACT ASSESSMENT T.+353 1 2899 039

Project : Concorde site	Issue Date: 24-04-2019	Photo Info. 22-12-2018 12:19	VIEW 02		PROPOSED

Angle of View 73° Horizontal

Angle of View 39° Horizontal

MODEL WORKS

VISUAL IMPACT ASSESSMENT T.+353 1 2899 039

Project : Concorde site	Issue Date: 25-04-2019	Photo Info. 22-12-2018 11:31	VIEW 03		BASELINE

Angle of View 73° Horizontal

Angle of View 39° Horizontal

MODEL WORKS

VISUAL IMPACT ASSESSMENT T.+353 1 2899 039

Project : Concorde site	Issue Date: 25-04-2019	Photo Info. 22-12-2018 11:31	VIEW 03		PROPOSED

Angle of View 73° Horizontal

Angle of View 39° Horizontal

MODEL WORKS

VISUAL IMPACT ASSESSMENT T.+353 1 2899 039

Project : Concorde site	Issue Date: 25-04-2019	Photo Info. 22-12-2018 11:40	VIEW 04 A		BASELINE

Angle of View 73° Horizontal

Angle of View 39° Horizontal

MODEL WORKS

VISUAL IMPACT ASSESSMENT T.+353 1 2899 039

Project : Concorde site	Issue Date: 25-04-2019	Photo Info. 22-12-2018 11:40	VIEW 04 A		PROPOSED

Angle of View 73° Horizontal

Angle of View 39° Horizontal

MODEL WORKS

VISUAL IMPACT ASSESSMENT T.+353 1 2899 039

Project : Concorde site	Issue Date: 25-04-2019	Photo Info. 04-01-2019 10:44	VIEW 04 B		BASELINE



MODEL WORKS

VISUAL IMPACT ASSESSMENT T.+353 1 2899 039

Project : Concorde site	Issue Date: 25-04-2019	Photo Info. 04-01-2019 10:44	VIEW 04 B		PROPOSED

Angle of View 73° Horizontal

Angle of View 39° Horizontal

MODEL WORKS

VISUAL IMPACT ASSESSMENT T.+353 1 2899 039

Project : Concorde site	Issue Date: 25-04-2019	Photo Info. 22-12-2018 11:54	VIEW 05		BASELINE

Angle of View 73° Horizontal

Angle of View 39° Horizontal

MODEL WORKS

VISUAL IMPACT ASSESSMENT T.+353 1 2899 039

Project : Concorde site	Issue Date: 25-04-2019	Photo Info. 22-12-2018 11:54	VIEW 05		PROPOSED

Angle of View 73° Horizontal

Angle of View 39° Horizontal

MODEL WORKS

VISUAL IMPACT ASSESSMENT T.+353 1 2899 039

Project : Concorde site	Issue Date: 25-04-2019	Photo Info. 22-12-2018 12:07	VIEW 06		BASELINE

Angle of View 73° Horizontal

Angle of View 39° Horizontal

MODEL WORKS

VISUAL IMPACT ASSESSMENT T.+353 1 2899 039

Project : Concorde site	Issue Date: 25-04-2019	Photo Info. 22-12-2018 12:07	VIEW 06		PROPOSED

VISUAL IMPACT ASSESSMENT T.+353 1 2899 039

Project : Concorde site	Issue Date: 24-04-2019	Photo Info. 21-06-2019 10:00	CGI 01		PROPOSED

VISUAL IMPACT ASSESSMENT T.+353 1 2899 039

Project :	Issue Date:	Photo Info:	
Concorde site	**24-04-2019**	21-06-2019 18:00	**CGI 02**

VISUAL IMPACT ASSESSMENT T.+353 1 2899 039

Project : Concorde site	Issue Date: **24-04-2019**	Photo Info. 21-06-2019 10:00	**CGI 03**		**PROPOSED**

VISUAL IMPACT ASSESSMENT T.+353 1 2899 039

Project : Concorde site	Issue Date: 25-04-2019	Photo Info. 21-06-2019 22:00	CGI 04		PROPOSED