


## TREE CONDITION CATEGORIES

A TREES OF HIGH VALUE AND QUALITY



C TREES OF LOW QUALITY AND VALUE





TREE CONSTRAINTS

TREE SURVEY BOUNDARY

AP refers to trees not shown on topographical survey drawing but located approximately on the this drawing only. Exact locations may need to be ascertained if the trees are to be retained.

Drawing to be interpreted with reference to Tree Survey document

Tree constraints shown are calculated from guidelines contained within BS5837 (2012)withn dimensions contained within Section 8 of the Tree Survey document. This outline should not be interpreted as the exact extent of root spread however it is considered the optimal area to be retained free of developmental impacts. Natural and/or man made barriers such as waterlogged soil or buildings may restrict the spread of tree roots. Crown spreads may also prove to be a constraint particularly where crown reduction may not be possible.
The constraints lines shown on this drawing are therefore a guide only. An on—site assessment should be undertaken in the event of any developments being planned within the areas shown for retained trees.

Horticulture & Arboriculture				
CIIENT:	PROJECT:			JOB NO.
ARDSTONE PROPERTIES	PROPOSED DEVELOPMENT AT CAPDOO, CLANE, CO. KILDARE			TCAP001
	DRAWING:	DATE:	SCALE:	DRAWING NO.
	Tree Survey & Constraints	25-03-19	1:1500 @ A1	102
NOTES Do Not Scale. Use Figured Dimensions Only. Not for Construction Purposes unless Specifically Marked.	DRAWN BY: Ciaran Keating		CK INITIALS	REVISION.
© THIS DRAWING IS COPYRIGHT OF CMK HORTICULTURE + ARBORICULTURE	STATUS: Planning			