

APPENDIX 9.1

UNATTENDED NOISE MONITORING GRAPHED RESULTS

9.1 Location N1




Figure A9.1 Graphed Noise monitoring results at Location N1

9.2 Location N2




Figure A9.2 Graphed Noise monitoring results at Location N2