



Location:
Viewpoint Elevation:
Distance to Site:
Horizontal Angle of View:

Viewpoint 7 78m AOD (Malin Head) 1010m 90 Degrees



Fig 9.10



Viewpoint 7 North from L80142.

View South from minor road L80142 approx 1km from the subject site. From this section of road the existing temporary overburden is clearly visible, however areas of proposed extraction would not be visible due to a combination of intervening vegetation and topography.

Tromman Quarry, Rathmolyan

Photo Viewpoint 7

Landscape & Visual Effects		Baseline Landscape				
Viewpoint	Duration	& Visual Sensitivity	Magnitude	M	Predicted Effect	
7	Long Term	Medium - Low (Landscape) Low (Visual)	Low Medium	Considered sequence of extraction and phased restoration. Review all boundaries for opportunities to improve screening through earthworks and planting. Gradual removal of existing overburden stockpile. Minor (Beneficial)		
Client Keegan Quarries Ltd.			date July. 19	scale NTS@A3	by pjm	notes Image represents an eyelevel impression of view at monocular distance of 30cm

mullin design associates

Headoffice: 559 Ormeau Road, Rosetta, Belfast, BT7 3JA
mail@mullindesignassociates.com T. 0044 289029 6843

Chartered landscape architects