



Location:
Viewpoint Elevation:
Distance to Site:
Horizontal Angle of View:

Viewpoint 3 73m AOD (Malin Head) 850m 90 Degrees



Fig 9.6



Viewpoint 3 South from L80141.

View South from minor road L80141 less than 1km from the subject site. From this open section of road the existing temporary overburden is clearly visible, however areas of proposed extraction would not be visible due to a combination of intervening vegetation, buildings and topography.

Tromman Quarry, Rathmolyan

Photo Viewpoint 3

chartered landscape architects

mullin design associates

Headoffice: 559 Ormeau Road, Rosetta, Belfast, B17 3JA
mail@mullindesignassociates.com T. 0044 289029 6843

due to a combination of intervening vegetation, buildings and topography.						
Landscape & V Viewpoint	isual Effects  Duration	Baseline Landscape & Visual Sensitivity	Magnitude	۸	Mitigation	Predicted Effect
3	Long Term	Medium - Low (Landscape) Low (Visual)	Low Medium	Considered sequence of extraction and phased restoration. Review all boundaries for opportunities to improve screening through earthworks and planting. Gradual removal of existing overburden stockpile.  Minor (Beneficial)		
Client Keegan Quarries Ltd.			date July. 19	scale NTS@A3	by pjm	Image represents an eyelevel impression of view at monocular distance of 30cm