


**Location:**  
Viewpoint Elevation: 72m AOD (Malin Head)  
Distance to Site: 993m  
Horizontal Angle of View: 90 Degrees



**Viewpoint 4 Southwest from L80141.**  
View South from minor road L80141 less than 1km from the subject site. From this open section of road the existing temporary overburden is clearly visible, however areas of proposed extraction would not be visible due to a combination of intervening vegetation and topography.

Photo Viewpoint 4

Fig 9.7

Landscape & Visual Effects		Baseline Landscape & Visual Sensitivity	Magnitude	Mitigation	Predicted Effect
Viewpoint	Duration				
4	Long Term	Medium - Low (Landscape) Low (Visual)	Low Medium	Considered sequence of extraction and phased restoration. Review all boundaries for opportunities to improve screening through earthworks and planting. Gradual removal of existing overburden stockpile.	Minor Minor ( Beneficial )
<b>client</b>	Keegan Quarries Ltd.	<b>date</b>	July. 19	<b>scale</b>	NTS@A3
		<b>by</b>	pjm	<b>notes</b>	Image represents an eyelevel impression of view at monocular distance of 30cm

**Tromman Quarry, Rathmolyon**