



Location:

Viewpoint Elevation: Distance to Site: Horizontal Angle of View:

Viewpoint 5

75m AOD (Malin Head) 1128m 90 Degrees





Viewpoint 5 West from L80140.

View South from minor road L80140 approx 1.1km from the subject site. From this section of road the existing temporary overburden is clearly visible, however areas of proposed extraction would not be visible due to a combination of intervening vegetation and topography.

Baseline Landscape **Predicted Effect** Viewpoint Duration Magnitude & Visual Sensitivity Considered sequence of extraction and phased restoration. Review all boundaries for Low Long Term Medium - Low (Landscape) opportunities to improve screening through earthworks and planting. Gradual removal of existing overburden stockpile. Low (Visual) Medium Minor (Beneficial) date **notes** Image represents an eyelevel impression of view at July. 19 Keegan Quarries Ltd. NTS@A3 pjm monocular distance of 30cm

Photo Viewpoint 5

Fig 9.8

Tromman Quarry, Rathmolyan



mullin design associates
Headoffice: 559 Ormeau Road, Rosetta, Belfast, BT7 3JA
mail@mullindesignassociates.com T. 0044 289029 6843

chartered landscape architects