



**Location:**  
Viewpoint Elevation: 77m AOD (Malin Head)  
Distance to Site: 1096m  
Horizontal Angle of View: 90 Degrees



**Viewpoint 5 West from L80140.**  
View South from minor road L80140 approx 1km from the subject site. From this section of road the existing temporary overburden is clearly visible, however areas of proposed extraction would not be visible due to a combination of intervening vegetation and topography.

Photo Viewpoint 6

Fig 9.9

Viewpoint	Duration	Baseline Landscape & Visual Sensitivity	Magnitude	Mitigation	Predicted Effect					
6	Long Term	Medium - Low (Landscape) Low (Visual)	Low Medium	Considered sequence of extraction and phased restoration. Review all boundaries for opportunities to improve screening through earthworks and planting. Gradual removal of existing overburden stockpile.	Minor Minor ( Beneficial )					
<b>client</b>	Keegan Quarries Ltd.		<b>date</b>	July. 19	<b>scale</b>	NTS@A3	<b>by</b>	pjm	<b>notes</b>	Image represents an eyelevel impression of view at monocular distance of 30cm

**Tromman Quarry, Rathmolyan**