

Appendix to Chapter 15: Material Assets (Roads)


Appendix 15.3: Site Photographs of UWF Grid Connection Roads, Bridges & Culverts

The data and descriptions in this appendix have informed the cumulative evaluations in the EIA Main Report.

Photos of UWF GRID CONNECTION Roads	
	L2166-0 at Coole
	L6013-0 at Freagh

	L2156-0 at Rockvale
	L2157 at Ahane
	L6009 at Castlewaller

	L503 at Derryleigh
	R503 at Rear Cross
	R503 at Knockmaroe

	L2264-50 at Knockmaroe
	L6188-0 at Knockmaroe

Photos of UWF GRID CONNECTION Bridges / Culverts	
	Watercrossing Structure W4
	Watercrossing Structure W5
	Watercrossing Structure W6

 A photograph of a concrete bridge structure over a stream, heavily overgrown with moss and vines. A large fallen tree trunk lies across the top of the bridge.	Watercrossing Structure W7
 A photograph of a concrete bridge structure over a stream, heavily overgrown with moss and vines. A large fallen tree trunk lies across the top of the bridge.	Watercrossing Structure W8
 A photograph of a concrete bridge structure over a stream, heavily overgrown with moss and vines. A large fallen tree trunk lies across the top of the bridge.	Watercrossing Structure W9

 A photograph showing a dark, circular culvert opening in a grassy area. A small stream of water flows out of the culvert onto a muddy bank. The surrounding vegetation includes tall grasses and some small green plants.	Watercrossing Structure W10
 A photograph of a small, narrow stream flowing through a wooded area. The water is brown and murky. The banks are covered with moss, ferns, and fallen leaves. A tree trunk is visible on the left side of the frame.	Watercrossing Structure W11
 A photograph of a large, dark, circular culvert opening. The culvert is surrounded by dense vegetation, including tall grasses and leafy plants. A small stream of water flows out of the culvert.	Watercrossing Structure W12

 A photograph showing a watercrossing structure (W13) in a forest. The structure is a small, rectangular opening in a mossy, rocky bank, partially obscured by ferns and other vegetation. The water is dark and still.	Watercrossing Structure W13
 A photograph showing a watercrossing structure (W14) in a forest. The structure is a small, rectangular opening in a mossy, rocky bank, partially obscured by ferns and other vegetation. The water is dark and still.	Watercrossing Structure W14
 A photograph showing a watercrossing structure (W15) in a forest. The structure is a small, rectangular opening in a mossy, rocky bank, partially obscured by ferns and other vegetation. The water is dark and still.	Watercrossing Structure W15

	Watercrossing Structure W16
	Watercrossing Structure W17
	Watercrossing Structure W18

 A photograph showing a small, narrow watercourse flowing through a dense forest. The water is dark and reflective, surrounded by lush green moss and ferns on the banks. A fallen log is visible in the water.	Watercrossing Structure W19
 A photograph of a watercrossing structure, likely a culvert or bridge, partially obscured by dense vegetation and ferns. The structure appears to be made of concrete or stone, with water flowing underneath.	Watercrossing Structure W20
 A photograph showing a stone wall or structure, possibly a watercrossing structure, heavily covered in moss and ferns. The structure is built with rough-hewn stones and is surrounded by dense forest vegetation.	Watercrossing Structure W21

	Watercrossing Structure W22
	Watercrossing Structure W23
	Watercrossing Structure W24

	Watercrossing Structure W25
	Watercrossing Structure W26
	Watercrossing Structure W27


 A photograph showing a small, narrow water crossing structure, possibly a culvert or bridge, surrounded by dense green ferns and vegetation. The structure is partially obscured by the foliage.	Watercrossing Structure W28
 A photograph showing a water crossing structure, likely a culvert, with water flowing over a rocky bed. The surrounding area is covered in moss and vegetation.	Watercrossing Structure W29
 A photograph showing a water crossing structure, likely a culvert, with water flowing over a rocky bed. The surrounding area is covered in moss and vegetation.	Watercrossing Structure W30

	Watercrossing Structure W31
	Watercrossing Structure W32
	Watercrossing Structure W33

	Watercrossing Structure W34
	Watercrossing Structure W35
	Watercrossing Structure W36

 A photograph showing a grassy embankment. A red and black survey pole is planted vertically in the ground. The background shows a line of trees under a cloudy sky.	Watercrossing Structure W37
 A photograph of a culvert opening. Water is flowing through the structure. The surrounding area is overgrown with dry grass and some rocks.	Watercrossing Structure W38
 A photograph looking down into a large, circular culvert opening. The interior of the pipe is visible, and there is some debris or sediment at the bottom.	Watercrossing Structure W39

	Watercrossing Structure W40
	Watercrossing Structure W41
	Watercrossing Structure W42

	Watercrossing Structure W43
	Watercrossing Structure W44
	Watercrossing Structure W45

 A photograph showing a narrow, dark, and shallow water channel flowing through a dense thicket of tall grasses and moss-covered rocks. The water is dark brown and the surrounding vegetation is lush and green.	Watercrossing Structure W46
 A photograph showing a small, clear water channel flowing over a rocky, moss-covered surface. The water is clear and the surrounding vegetation is dense and green.	Watercrossing Structure W47
 A photograph showing a small, clear water channel flowing through a grassy area. The water is clear and the surrounding vegetation is dense and green.	Watercrossing Structure W48

 A photograph of a stone archway structure, likely a culvert or bridge, built with rough-hewn stones. The arch is dark and recessed, with some vegetation growing on the stone walls. The background shows a line of evergreen trees under a cloudy sky.	Watercrossing Structure W49
 A photograph showing water flowing over a stone structure, possibly a spillway or a small dam. The water is turbulent and white with foam. The structure is made of rough stone and is surrounded by a rocky, wooded area.	Watercrossing Structure W50
 A photograph of a stone structure, possibly a culvert or bridge, with water flowing over it. The structure is surrounded by dense green vegetation and moss. The water is brown and turbulent, flowing over rocks in the foreground.	Watercrossing Structure W51

	Watercrossing Structure W52
	Watercrossing Structure W53
	Watercrossing Structure W54

	Watercrossing Structure W55
	Watercrossing Structure W56
	Watercrossing Structure W57

	Watercrossing Structure W58
	Watercrossing Structure W59
	Watercrossing Structure W60

	Watercrossing Structure W61
	Watercrossing Structure W62
	Watercrossing Structure W63

 A photograph of a stone masonry structure, likely a culvert or bridge, built with large, flat stones. The structure is partially covered by moss and vegetation, with a small opening visible in the center.	Watercrossing Structure W64
 A photograph of a stone masonry structure, likely a culvert or bridge, built with large, flat stones. The structure is partially covered by moss and vegetation, with a small opening visible in the center.	Watercrossing Structure W65
 A photograph of a stone masonry structure, likely a culvert or bridge, built with large, flat stones. The structure is partially covered by moss and vegetation, with a small opening visible in the center.	Watercrossing Structure W66

	Watercrossing Structure W67
	Watercrossing Structure W68