

Summary Local Area Report


This Flood Report summarises all flood events within 2.5 kilometres of the map centre.

The map centre is in:

County: Dublin

NGR: O 226 256

This Flood Report has been downloaded from the Web site www.floodmaps.ie. The users should take account of the restrictions and limitations relating to the content and use of this Web site that are explained in the Disclaimer box when entering the site. It is a condition of use of the Web site that you accept the User Declaration and the Disclaimer.



Map Scale 1:13,657

Map Legend	
	Flood Points
	Multiple / Recurring Flood Points
	Areas Flooded
	Hydrometric Stations
	Rivers
	Lakes
	River Catchment Areas
	Land Commission *
	Drainage Districts *
	Benefiting Lands *

* Important: These maps do not indicate flood hazard or flood extent. Their purpose and scope is explained in the Glossary.

18 Results

	1. Shanganagh Carrickmines Nov 2002 County: Dublin Additional Information: Reports (1) More Mapped Information	Start Date: 26/Nov/2002 Flood Quality Code:3
	2. Shanganagh Carrickmines Dec 1997 County: Dublin Additional Information: Reports (1) More Mapped Information	Start Date: 18/Dec/1997 Flood Quality Code:3
	3. Shanganagh Carrickmines May 1993 County: Dublin Additional Information: Photos (3) Reports (4) More Mapped Information	Start Date: 26/May/1993 Flood Quality Code:1
	4. Shanganagh Carrickmines Nov 1982 County: Dublin Additional Information: Reports (3) More Mapped Information	Start Date: 06/Nov/1982 Flood Quality Code:3
	5. Flooding at Little Meadow, Pottery Road, Cabinteely, Dublin 18 on 24th Oct 2011 County: Dublin	Start Date: 24/Oct/2011 Flood Quality Code:2