



Energy for
generations

Derrybrien Wind Farm Project

Gort Windfarms Ltd.

Substitute Consent Application Volume 2 Section 2 Appendices

Date: July 2020

Document No.: QS-000280-01

Engineering and Major Projects, One Dublin Airport Central, Dublin Airport, Cloghran, Co. Dublin,
K67 XF72, Ireland.

Phone +353 (0)1 703 8000

www.esb.ie

Volume 2 – Section 2 Contents

Volume 2 Environmental Documents

Section 2: Remedial Impact Assessment Report

Appendices

Non Technical Summary

Chapter 1 Introduction

Chapter 2 Project Description

Chapter 3 Alternatives

Chapter 4 Population and Human Health

Chapter 5 Noise and Vibration

Chapter 6 Shadow Flicker

Chapter 7 Biodiversity (Terrestrial Ecology)

Chapter 8 Aquatic Ecology & Fisheries

Chapter 9 Landscape and Visual

Chapter 10 Soils, Land and Geology

Chapter 11 Hydrology and Hydrogeology

Chapter 12 Air and Climate

Chapter 13 Material Assets

Chapter 14 Traffic and Transport

Chapter 15 Cultural Heritage

Chapter 16 Major Accidents and Disasters

Chapter 17 Interaction of Impacts

Chapter 18 Summary of Remedial Measures

Volume 2 Environmental Documents

Section 2: Remedial Environmental Impact Assessment Report Appendices Part 1

Non Technical Summary

None

Chapter 1 Introduction

Appendix 1-1 Newsletter

Appendix 1-2 Information Sheet issued to statutory
and non statutory consultees

Appendix 1-3 Figures at A3, A2, A1 and A0 - See Volume 3 Section 3: A0, A1 & A3 Figures

Chapter 2 Project Description

Appendix 2.1 Wind Farm Details - See Volume 3 Section 3: A0, A1 & A3 Figures

Appendix 2.2 Grid Connection Details - See Volume 3 Section 3: A0, A1 & A3 Figures

Appendix 2.3 A3 Figures - See Volume 3 Section 3: A0, A1 & A3 Figures

Chapter 3 Alternatives

None

Chapter 4 Population and Human Health

Appendix 4.1 Tourism Information

Appendix 4.2 Human Health

Appendix 4.3 A3 Figures - See Volume 3 Section 3: A0, A1 & A3 Figures

Chapter 5 Noise and Vibration

Appendix 5.1 – Noise Sensitive Receivers – Coordinates (ITM)

Appendix 5.2 – Glossary of Acoustic Terminology

Appendix 5.3 – Special Characteristics

Appendix 5.4 – Health Affects Research

Appendix 5.5 – Noise Monitoring Data

Appendix 5.6 – Calibration Certificates

Appendix 5.7 – Turbine Sound Power Data

Appendix 5.8 – Figures at A3, A2, A1, A0 - See Volume 3 Section 3: A0, A1 & A3 Figures

Chapter 6 Shadow Flicker

Appendix A – Wind turbine locations

Appendix B – Shadow Flicker Calculation: Main Results

Appendix C - Shadow Flicker Calculation: Shadow Calendar

Chapter 7 Biodiversity (Terrestrial Ecology)

Appendix 7-1 Rare and/or Protected Species within the 10 km Grid Squares M50 and M60

Appendix 7-2 Hen Harrier Definition of Habitat and Behaviour codes

Appendix 7-3 Photographs Relating to Hen Harriers

Appendix 7-4 Details of bat detector deployments and total number of bat passes for 2016 (Tables 1-2) and 2019 (Tables 3-4)

Appendix 7-5 – A3 Figures – Figures at A3, A2, A1, A0 - See Volume 3 Section 3: A0, A1 & A3 Figures

Chapter 8 Aquatic Ecology & Fisheries

Appendix 8-1 Significance Terminology - Table 3.3 of the Guidelines (EPA, 2017)

Appendix 8-2 Macroinvertebrate Tables (2011-2020)

Appendix 8-3 Macroinvertebrate Sampling Site Descriptions and Photos

Appendix 8-4 Lough Cutra Sediment Photos (2019)

Appendix 8-5 Electrofishing Results (2011, 2014, 2019)

Appendix 8-6 Galway County Council Historic Water Monitoring Data

Appendix 8-7 A3 Figures - See Volume 3 Section 3: A0, A1 & A3 Figures

Chapter 9 Landscape and Visual

All appendices are within Volume 3 Section 3: A0, A1 & A3 Figures

Photomontages are within Volume 3 Section 4: Photomontages

Chapter 10 Soils, Land and Geology

Appendix A 2004 Final Report on Landslide Oct 2003 & Post Landslide Appraisal

Appendix B Geotechnical Stability Report 1

Appendix C Geotechnical Stability Report 2

Appendix D Geotechnical Stability Report 3 - Grid Connection

Appendix E Derrybrien WF PSRA for Turbary Plots

Appendix F A3, A2, A1, A0 Figures

Chapter 11 Hydrology and Hydrogeology

Appendix 11A Flood Risk Assessment

Appendix 11B Flooding Assessment of the Derrybrien Wind Farm Project on Turlough Flooding in the Gort Lowlands Catchment

Appendix 11C Figures at A3, A2, A1, A0 - See Volume 3 Section 3: A0, A1 & A3 Figures

Chapter 12 Air and Climate

Appendix 12.1 Carbon emission calculations including the Peat Slide

Appendix 12.2 Carbon emission calculations excluding the Peat Slide

Appendix 12.3 Figures at A3, A2, A1 and A0 - See Volume 3 Section 3: A0, A1 & A3 Figures

Chapter 13 Material Assets

Appendix 13A Figures at A3, A2, A1 and A0 - See Volume 3 Section 3: A0, A1 & A3 Figures

Chapter 14 Traffic and Transport

Appendix 14-A Project Phases

Appendix 14-B Decommissioning Material Movements

Appendix 14-C A3 Figures - see Volume 3 Section 3: A0, A1 & A3 Figures

Chapter 15 Cultural Heritage

Appendix 15-1 Archaeological Survey of Ireland site descriptions

Appendix 15-2 Photographic Record

Appendix 15-3 Archaeological report on 2004-5 phase of construction

Appendix 15-4 Archaeological impact assessment of peat slide and proposed remediation

Chapter 16 Major Accidents and Disasters

None

Chapter 17 Interaction of Impacts

None

Chapter 18 Summary of Remedial Measures

None



Energy for
generations

Derrybrien Wind Farm Project

Gort Windfarms Ltd.

Substitute Consent Application Volume 2 Section 2 Appendices Part 1 of 3

Document No.: QS-000280-01

Date: July 2020

Engineering and Major Projects, One Dublin Airport Central, Dublin Airport, Cloghran, Co. Dublin,
K67 XF72, Ireland.

Phone +353 (0)1 703 8000

www.esb.ie

Volume 2 – Section 2 Contents

Volume 2 Environmental Documents

Section 2: Remedial Impact Assessment Report

Appendices

Non Technical Summary

Chapter 1 Introduction

Chapter 2 Project Description

Chapter 3 Alternatives

Chapter 4 Population and Human Health

Chapter 5 Noise and Vibration

Chapter 6 Shadow Flicker

Chapter 7 Biodiversity (Terrestrial Ecology)

Chapter 8 Aquatic Ecology & Fisheries

Chapter 9 Landscape and Visual

Chapter 10 Soils, Land and Geology

Chapter 11 Hydrology and Hydrogeology

Chapter 12 Air and Climate

Chapter 13 Material Assets

Chapter 14 Traffic and Transport

Chapter 15 Cultural Heritage

Chapter 16 Major Accidents and Disasters

Chapter 17 Interaction of Impacts

Chapter 18 Summary of Remedial Measures

Volume 2 Environmental Documents

Section 2: Remedial Impact Assessment Report Appendices

Non Technical Summary

None

Chapter 1 Introduction

Appendix 1-1 Newsletter

Appendix 1-2 Information Sheet issued to statutory
and non statutory consultees

Appendix 1-3 Figures at A3, A2, A1 and A0 - See Volume 3 Section 3: A0, A1 & A3 Figures

Chapter 2 Project Description

Appendix 2.1 Wind Farm Details - See Volume 3 Section 3: A0, A1 & A3 Figures

Appendix 2.2 Grid Connection Details - See Volume 3 Section 3: A0, A1 & A3
Figures

Appendix 2.3 A3 Figures - See Volume 3 Section 3: A0, A1 & A3 Figures

Chapter 3 Alternatives

None

Chapter 4 Population and Human Health

Appendix 4.1 Tourism Information

Appendix 4.2 Human Health

Appendix 4.3 A3 Figures - See Volume 3 Section 3: A0, A1 & A3 Figures

Chapter 5 Noise and Vibration

Appendix 5.1 – Noise Sensitive Receivers – Coordinates (ITM)

Appendix 5.2 – Glossary of Acoustic Terminology

Appendix 5.3 – Special Characteristics

Appendix 5.4 – Health Affects Research

Appendix 5.5 – Noise Monitoring Data

Appendix 5.6 – Calibration Certificates

Appendix 5.7 – Turbine Sound Power Data

Appendix 5.8 – Figures at A3, A2, A1, A0 - See Volume 3 Section 3: A0, A1 & A3 Figures

Chapter 6 Shadow Flicker

Appendix A – Wind turbine locations

Appendix B – Shadow Flicker Calculation: Main Results

Appendix C - Shadow Flicker Calculation: Shadow Calendar

Chapter 7 Biodiversity (Terrestrial Ecology)

Appendix 7-1 Rare and/or Protected Species within the 10 km Grid Squares M50 and M60

Appendix 7-2 Hen Harrier Definition of Habitat and Behaviour codes

Appendix 7-3 Photographs Relating to Hen Harriers

Appendix 7-4 Details of bat detector deployments and total number of bat passes for 2016 (Tables 1-2) and 2019 (Tables 3-4)

Appendix 7-5 – A3 Figures – Figures at A3, A2, A1, A0 - See Volume 3 Section 3: A0, A1 & A3 Figures

Chapter 8 Aquatic Ecology & Fisheries

Appendix 8-1 Significance Terminology - Table 3.3 of the Guidelines (EPA, 2017)

Appendix 8-2 Macroinvertebrate Tables (2011-2020)

Appendix 8-3 Macroinvertebrate Sampling Site Descriptions and Photos

Appendix 8-4 Lough Cutra Sediment Photos (2019)

Appendix 8-5 Electrofishing Results (2011, 2014, 2019)

Appendix 8-6 Galway County Council Historic Water Monitoring Data

Appendix 8-7 A3 Figures - See Volume 3 Section 3: A0, A1 & A3 Figures

Chapter 9 Landscape and Visual

All appendices are within Volume 3 Section 3: A0, A1 & A3 Figures

Photomontages are within Volume 3 Section 4: Photomontages

Chapter 10 Soils, Land and Geology

Appendix A 2004 Final Report on Landslide Oct 2003 & Post Landslide Appraisal

Appendix B Geotechnical Stability Report 1



Energy for
generations

Derrybrien Wind Farm Project

Gort Windfarms Ltd.

Substitute Consent Application Volume 2 Section 2 Appendices Part 2 of 3

Document No.: QS-000280-01

Date: July 2020

Engineering and Major Projects, One Dublin Airport Central, Dublin Airport, Cloghran, Co. Dublin,
K67 XF72, Ireland.

Phone +353 (0)1 703 8000

www.esb.ie

Chapter 10 Soils, Land and Geology

Appendix B Geotechnical Stability Report 1 continued



Energy for
generations

Derrybrien Wind Farm Project

Gort Windfarms Ltd.

Substitute Consent Application

Volume 2 Section 2

Appendices Part 3 of 3

Document No.: QS-000280-01

Date: July 2020

Engineering and Major Projects, One Dublin Airport Central, Dublin Airport, Cloghran, Co. Dublin,
K67 XF72, Ireland.

Phone +353 (0)1 703 8000

www.esb.ie

Chapter 10 Soils, Land and Geology

Appendix B Geotechnical Stability Report 1 continued

Appendix C Geotechnical Stability Report 2

Appendix D Geotechnical Stability Report 3 - Grid Connection

Appendix E Derrybrien WF PSRA for Turbary Plots

Appendix F A3, A2, A1, A0 Figures

Chapter 11 Hydrology and Hydrogeology

Appendix 11A Flood Risk Assessment

Appendix 11B Flooding Assessment of the Derrybrien Wind Farm Project on Turlough Flooding in the Gort Lowlands Catchment

Appendix 11C Figures at A3, A2, A1, A0 - See Volume 3 Section 3

Chapter 12 Air and Climate

Appendix 12.1 Carbon emission calculations including the Peat Slide

Appendix 12.2 Carbon emission calculations excluding the Peat Slide

Appendix 12.3 Figures at A3, A2, A1 and A0 - See Volume 3 Section 3: A0, A1 & A3 Figures

Chapter 13 Material Assets

Appendix 13A Figures at A3, A2, A1 and A0 - See Volume 3 Section 3

Chapter 14 Traffic and Transport

Appendix 14-A Project Phases

Appendix 14-B Decommissioning Material Movements

Appendix 14-C A3 Figures - see Volume 3 Section 3: A0, A1 & A3 Figures

Chapter 15 Cultural Heritage

Appendix 15-1 Archaeological Survey of Ireland site descriptions

Appendix 15-2 Photographic Record

Appendix 15-3 Archaeological report on 2004-5 phase of construction

Appendix 15-4 Archaeological impact assessment of peat slide and proposed remediation

Chapter 16 Major Accidents and Disasters

None

Chapter 17 Interaction of Impacts

None

Chapter 18 Summary of Remedial Measures

None