



**Location:** Cartron  
**Viewpoint 1**  
 Distance to Site Boundary: 1236m  
 Horizontal Angle of View: 90 Degrees



**Panoramic View**



**Viewpoint 1 West from Knockacarrigeen, Belclare.**

View West from minor road in Townland of Catherhugh - The views across farmland are drawn towards the raised feature of Knockmaa Hill. A small clustering of houses and electric poles add a built element to this rural view. The majority of quarrying visible from this viewpoint relates to the adjoining Mortimer Quarry. Partial views of the subject quarry are visible from this viewpoint although little relating to unauthorised works.

Photo Viewpoint 1

**Fig 9.3**

Landscape & Visual Effects Viewpoint	Baseline Landscape & Visual Sensitivity	Magnitude (Unauthorized Elements)	Impacts Occurred (Jan 2015 to Jun 2019)	Impacts Occurring Jun 2019 to Present)	Expected to Occur (with Remediation/Restoration)
1	Medium - Low (Landscape) High (Visual)	Very Low Very Low	Negligible Minor	Negligible Negligible/None	Moderate (Beneficial) Minor (Beneficial)
<b>client</b> McTigues	<b>date</b> May. 21	<b>scale</b> NTS@A3	<b>by</b> pjm	<b>notes</b> Image represents an eyelevel impression of view at monocular distance of 30cm	

**Cartron Quarry, Tuam, Co Galway**