


**Location:** Viewpoint 2  
 Distance to Site Boundary: 699m  
 Horizontal Angle of View: 90 Degrees



**Panoramic View**



**Viewpoint 2 Northwest from Ballaghbaun, Belclare.**

View Northwest from minor road in Ballaghbaun, across farmland between groups of residential properties aligning the road. Knockmaa Hill is a visual focal point, however the existing quarry operations (particularly the Northern faces of Mortimers Quarry) are clearly visible. The boundaries of both quarries are marked by the distinct band of Leylandii hedge. There are no views relating to the unauthorised development works.

Photo Viewpoint 2

**Fig 9.4**

Landscape & Visual Effects Viewpoint	Baseline Landscape & Visual Sensitivity	Magnitude (Unauthorized Elements)	Impacts Occurred (Jan 2015 to Jun 2019)	Impacts Occurring Jun 2019 to Present)	Expected to Occur (with Remediation/Restoration)
2	Medium - Low (Landscape) High (Visual)	Very Low Very Low	Negligible Minor	Negligible Negligible/None	Moderate (Beneficial) Minor (Beneficial)
<b>client</b> McTigues	<b>date</b> May. 21	<b>scale</b> NTS@A3	<b>by</b> pjm	<b>notes</b> Image represents an eyelevel impression of view at monocular distance of 30cm	

**Cartron Quarry, Tuam, Co Galway**