

12

Powerstown



Hedge H12

Hedge H17


Hedge H17

Hedge H15

Hedge H15



- Category A Trees (high value)
- Category B Trees (moderate value)
- Category C Trees (low value)
- Category U Trees (Poor Condition)
- Tree Protection Fence Indicative Line
- Approximate extent of Specialist Ground Protection used to built up ground levels and protect soils inside the RPAs of Trees



NOTES:
Please see Tree Survey Report for further detail.
All drawings to be read in conjunction with the consulting architects and engineers drawings.

Independent Tree Surveys Ltd

Our Lady's Cottage
Drummond
Rosenallis
Co. Laois
057 8628597 • 087 1380687
jmorgan@independenttreesurveys.ie
www.independenttreesurveys.ie

Project Name: Hollystown Phase 2 & 3,
Kilmartin, Dublin

Drawing Title: Tree Protection Plan

Drawing Number: 21064_TPP_12

Client: Glenveagh Homes

Agent:

Date: 13/12/2021

Scale: 1:500@A1