



Site Investigation Legend					
Number	ID	ITM (X-Coordinate)	ITM (Y-Coordinate)	Depth Reached	In situ Test Completed
TP-01	Trial Pit	557218.29	574818.78	3m	
TP-02	Trial Pit	557279.02	574789.96	3.6m	
TP-03	Trial Pit	557366.05	574837.00	3m	
TP-04	Trial Pit	557390.99	574729.00	3m	
TP-05	Trial Pit	557325.98	574653.08	1.7m	Infiltration Test Complete
TP-06	Trial Pit	557475.99	574634.01	1.7m	Infiltration Test Complete
TP-07	Trial Pit	557422.73	574567.01	2.8m	
TP-08	Trial Pit	557355.03	574513.10	1.7m	
TP-09	Trial Pit	557412.16	574444.10	3.2m	
TP-10	Trial Pit	557254.03	574749.06	1.7m	Infiltration Test Complete
TP-11	Trial Pit	557313.07	574719.01	3.3m	
TP-12	Trial Pit	557341.78	574612.44	3.1m	
TP-13	Trial Pit	557412.03	574509.00	3.3m	
BH-01	Borehole	557257.34	574834.26	3.3m	
BH-01A	Borehole	557258.49	574834.41	4.5m	
BH-02	Borehole	557336.88	574652.45	9.7m	
BH-03	Borehole	557364.95	574434.04	9.95m	
BH-04	Borehole	557355.60	574868.44	6.2m	
BH-05	Borehole	557429.99	574677.97	9.8m	

NOTES:
 All dimensions in metres.
 Do not scale from drawing.
 For any discrepancies found please consult with design office.
 This drawing should be read in conjunction with all contract drawings, documents and specifications.

- Legend:**
- River/Stream
 - Trial Pit
 - Borehole
 - Site Boundary

Rev	By	Date	Description

Drawing Status: PLANNING
NOT CERTIFIED FOR CONSTRUCTION

Project Title: Cloghroe Development

Drawing Title: Site Investigation Sheet 1 of 2

Client: Cloghroe Development Limited

M.H.L. & Associates Ltd.
Consulting Engineers
 Carrig Mór House, 10 High Street, Douglas Road, Cork
 Tel: 021-4840214 Fax: 021-4840215 E-Mail: info@mhl.ie

Designed: SM	Drawn: SFM	Checked: KM
Scale: 1:500 @ A1 1:1000 @ A3	Date: September 2020	
Job No: 19083 HD	Drawing No: RL1_SI_P01	Revision:

36.40