



Ashgrove House
26 Foxrock Court
Dublin 18
D18 R2K1

Mob. 086-3819011
e-mail - thetreefile@eircom.net

Graphic Representation of Tree Form, balance and Protection Zone

Canopy Extent
Cardinal Radii
Category Code
Stem Circumference

Root Protection Area (RPA)
This area relates to the "RPA" radius as defined in the Tree Survey Table and is measured from the tree centre. This area defines the primary Construction Exclusion Zone (CEZ) that must be protected by siting from the potentially damaging effects of construction activity.

- Tree Quality (Categorisation)
- Category "A" Trees (Green Button)
Excellent Trees
 - Category "B" Trees (Blue Button)
Good Trees
 - Category "C" Trees (Grey Button)
Mediocre to Poor Trees
 - Category "U" Trees (Red Button)
Dead, Dying or Otherwise Compromised
Trees that are Unsustainable.

Hedge and "Group" locations as Represented on Topographical Drawings

Hedges

Tree Retention and Loss

Trees Intended for Retention - Solid Green Crown Outline

Trees Intended for Removal in Conjunction With Development Works - Broken Pink Crown Outline

Hedges Being Retained

Hedges Being Removed

This Drawing Must Be
Read in Conjunction with
the Associated
Arboricultural Report

Client: Cairn Homes PLC
Scale: 1:500 @ A1 Date: February 2022
Project: Tree Survey, Coolagad, Greystones, Co Wicklow
Description: Tree Constraints Plan
Drawing Title:
Coolagad Tree Impacts Plan South