Appendix A14.1 Scheme Walkover Summary





Contents

Appen	dix A14.1: Scheme Walkover Summary	1
1.1	Introduction	1
1.2	Summary	1
1.3	Photos	3



Appendix A14.1: Scheme Walkover Summary

1.1 Introduction

The following is a summary of the observations by the Land, Soils, Geology and Hydrogeology Environmental Impact Assessment Team following a physical walkover of the Proposed Scheme. The walkover occurred on 20 February 2020 and 31 January 2022.

Not all observations have been included in this summary for conciseness. Typically, only observations that could not have been determined from a desk study and that are relevant to the Land, Soils, Geology and Hydrogeology Chapter have been included. The omission of an observation or a feature does not negate the feature's importance in terms of the Land, Soils, Geology and Hydrogeology environmental impact assessment.

The observations are summarised in Table 1 and the corresponding photos in Table 2 of this Appendix.

1.2 Summary

The main observations relate to the proposed widening of the road along the Nutley Lane, proposed road widening along the Rock Road where a major level change of up to 5m was observed. The Proposed Scheme runs adjacent to the Booterstown Marsh which is a proposed Natural Heritage Area (pNHA).

Observation	General Arrangement (GA) Drawing Sheet Number (refer to Volume 3 of the EIAR for GA drawings)	Description	Possible Impact	Photo Number
Nutley Lane proposed road widening	Sheets 22 to 23	Proposed widening of the road along Nutley Lane along the boundary of Elm Park Golf & Sports Club near St. Vincent's University Hospital.	A Lane along the boundary of Elm Golf & Sports Club near St. assessment.	
Nutley Lane proposed road widening	Sheet 22	Proposed widening of the road along Nutley Lane between the entrance of Elm Park Golf & Sports Club and RTE studios.	Ased widening of the road along Y Lane between the entrance of Park Golf & Sports Club and RTE	
Booterstown Marsh	Sheets 8 to 9	Approximately 40m of new boundary wall is proposed to be set back into the proposed Natural Heritage Areas (pNHA).	set back into the earthworks balance and waste	
Location of a construction compound along Rock Road	Sheet 6	A construction compound is to be located in Booterstown Car Park, within Blackrock Park, along the R118, opposite Willow Terrace.	This may pose an issue for the earthworks balance and waste assessment.	Belfield Black_Image_04
Rock Road	Sheets 4 to 5	eets 4 to 5Proposed widening of the scheme along the Rock Road near the Blackrock Clinic where minor level changes were notedThis may pose an issue for the earthworks balance and waste assessment.		Belfield Black_Image_05
Rock Road	k Road Sheets 4 to 5 Proposed widening of the scheme along the Rock Road where significant level changes are observed of up to 5m within Blackrock Park This may pose an issue for the earthworks balance and waste		Belfield Black_Image_06	
Land Boundary, Merrion Shopping Centre	Sheet 12 Proposed widening of the scheme outside the Merrion Shopping Centre arthworks balance and waste assessment.		Belfield Black_Image_07	

Table 1: Scheme Walkover Summary



Observation	General Arrangement (GA) Drawing Sheet Number (refer to Volume 3 of the EIAR for GA drawings)	Description	Possible Impact	Photo Number
Land boundary, Clayton Hotel Ballsbridge	Sheet 15	Proposed widening along this section of the scheme near the Clayton Hotel Ballsbridge. Boundary walls may need to be removed and topsoil stripped to accommodate the works.	This may pose an issue for the earthworks balance and waste assessment.	Belfield Black_Image_08
Land Boundary Herbert Avenue	Sheet 11	Proposed Road widening between Herbert Avenue and St. Vincent's University Hospital	This may pose an issue for the earthworks balance and waste assessment.	Belfield Black_Image_09
Land Boundary Estate Avenue			Belfield Black_Image_10	
Land Boundary opposite strand road	Sheet 10	Proposed removal of existing boundary for road widening opposite Strand Road	This may pose an issue for the earthworks balance and waste assessment.	Belfield Black_Image_11




1.3 Photos


Table 2: Scheme Walkover Photos

Photo ID	Caption	Date Taken	Coordinates
Belfield Black_Image_01	Nutley Lane proposed road widening along the Elm Park Golf & Sports Club boundary near St. Vincent's University Hospital	20/02/2020	718762,731067 (ITM)
ey plan Circle denotes and with triangle den	pproximate location of photo noting approximate direction of pho	to	
	B 400 6 10 6 20 6 20 7 20 7 7 7 7 7 7 7 7 7 7 7 7		B 500
		+ NUT	
SHEET 23 SHEET 22			


















Belfield / Blackrock to City Centre Core Bus Corridor Scheme

Environmental Impact Assessment Report (EIAR) Volume 4 of 4 Appendices











Photo ID Belfield Black_Image_08	Caption Land boundary at the Clayton Hotel, Ballsbridge	Date Taken 20/02/2020	Coordinates 720983,729683 (ITM)
Key plan			
Circle denotes approxima with triangle denoting a	te location o pproximate di	of photo rection of photo	
A STOOL HEET 14 SHEET 14	SET BACK	Y OF PROPOSED ENING	RELOCATED BUS STOP



Photo ID	Caption	Date Taken	Coordinates
Belfield Black_Image_09	Proposed Road widening between Herbert Avenue and St. Vincent's University Hospital	31/01/2022	719329,731191 (ITM)
Key plan			
Circle denotes appr with triangle denot	oximate location of p ing approximate direc	hoto tion of photo	
TO BE	ING BOUNDARY WALL REMOVED AND NEW CONSTRUCTED ALONG OSED ROAD WIDENING		TO BE REMOVED AND NEW WALL CONSTRUCTED ALONG PROPOSED ROAD WIDENING HOSPITAL







