

REPORT

REMEDIAL ENVIRONMENTAL IMPACT ASSESSMENT REPORT AND NON-TECHNICAL SUMMARY

*To Accompany a Substitute Consent Application for a Quarry at Ballynabarney,
Redcross, Co. Wicklow*

Submitted to:

An Bord Pleanála

64 Marlborough Street
Rotunda
Dublin 1
D01 V902

Submitted by:


Golder Associates Ireland Limited – WSP Ireland Consulting Ltd

Town Centre House, Dublin Road, Naas,
Co. Kildare, W91 TD0P Ireland

+353 45 810 200

21496996.R01.B1

August 2022

A large, solid red graphic element that starts as a thin line on the left and expands into a large, irregular shape covering the bottom half of the page.

Distribution List

An Bord Pleanála - 6 Copies

ECT Sand and Gravel - 1 Copy

WSP - 1 Copy

Table of Contents

1.0 INTRODUCTION, SCOPE AND METHODOLOGY	1-1
1.1 Requirement for rEIAR.....	1-2
1.2 Structure and Content of the rEIAR	1-7
1.3 Limitations and Difficulties in Compiling the Specified Information (Schedule 6 of SI 600 of 2001, as amended)	1-13
1.4 rEIAR Contributors and Guarantee of Competency and Independence	1-14
1.5 The Applicant / Developer.....	1-16
1.6 rEIAR Process – Prediction of Impacts and Effects and Assessment of Remedial Mitigation Measures	1-17
1.7 The Need for the Development and Consideration of Alternatives	1-20
2.0 PROJECT DESCRIPTION	2-1
2.1 Location of Project Lands	2-4
2.2 Context and Landscape Character of Subject Lands	2-4
2.3 Development of Subject Site from Baseline to Current Time	2-4
2.4 Major Accidents and Disasters	2-15
3.0 POPULATION & HUMAN HEALTH	3-1
3.1 Introduction	3-1
3.2 Methodology.....	3-1
3.3 Baseline	3-16
3.4 Characteristics of the Development.....	3-29
3.5 Potential Effects	3-30
3.6 Cumulative Impacts.....	3-37
3.7 Remedial Mitigation.....	3-37
3.8 Monitoring	3-38
3.9 Residual Effects	3-38
3.10 Difficulties Encountered	3-38
3.11 References.....	3-38
4.0 ECOLOGY AND BIODIVERSITY	4-1
4.1 Introduction	4-1
4.2 Policy and Legislation Context.....	4-3

4.3	Assessment methodology and significance criteria	4-4
4.4	Baseline Results	4-10
4.5	Habitat Assessment	4-13
4.6	Baseline Habitats 2022	4-21
4.7	Retrospective Habitat Assessment	4-28
4.8	Evaluation	4-32
4.9	Impact Assessment.....	4-34
4.10	Remedial Mitigation, Compensation and Enhancement Measures	4-37
4.11	Residual Effects	4-39
4.12	Cumulative Impacts.....	4-39
4.13	Summary and Conclusions	4-39
4.14	References	4-40
5.0	SOILS, LAND AND GEOLOGY.....	5-1
5.1	Introduction	5-1
5.2	Legislative and Policy Context	5-2
5.3	Assessment Methodology and Significance Criteria.....	5-4
5.4	Baseline Conditions (1990 to 2022).....	5-7
5.5	Characteristics of the Development	5-18
5.6	Potential Effects	5-21
5.7	Cumulative Impacts.....	5-25
5.8	Remedial Mitigation and Monitoring.....	5-25
5.9	Difficulties Encountered	5-25
5.10	References	5-26
6.0	WATER.....	6-1
6.1	Introduction	6-1
6.2	Legislative and Policy Context	6-2
6.3	Assessment Methodology and Significance Criteria.....	6-5
6.4	Baseline and Subsequent Conditions (1990 to 2022)	6-10
6.5	Hydrological and Hydrogeological Conceptual Model	6-47
6.6	Selection of Sensitive Receptors	6-48
6.7	Characteristics of the Development	6-50

6.8	Potential Effects	6-51
6.9	Remedial Measures Required	6-54
6.10	Residual Effects	6-54
6.11	Cumulative Effects	6-54
6.12	Monitoring	6-55
6.13	Difficulties Encountered	6-55
6.14	Summary and Conclusions	6-56
6.15	References	6-56
7.0	AIR QUALITY AND CLIMATE	7-1
7.1	Introduction	7-1
7.2	Policy and Legislation Context	7-2
7.3	Existing Environment	7-5
7.4	Assessment Methodology	7-15
7.5	Potential Effects	7-15
7.6	Climate Factors	7-16
7.7	Cumulative Effects	7-16
7.8	Summary and Conclusions	7-17
7.9	References	7-18
8.0	NOISE AND VIBRATION	8-1
8.1	Introduction	8-1
8.2	Policy and Legislative Context	8-1
8.3	Assessment Methodology	8-2
8.4	Baseline Conditions	8-6
8.5	Potential Effects	8-8
8.6	Cumulative Impacts	8-12
8.7	Summary and Conclusions	8-12
9.0	CULTURAL HERITAGE	9-1
9.1	Introduction	9-1
9.2	Policy and Legislative Context	9-3
9.3	Assessment Methodology and Significance Criteria	9-6
9.4	Baseline Conditions	9-8

9.5	Potential Effects	9-13
9.6	Mitigation and Monitoring	9-14
9.7	Residual Effects	9-14
9.8	Cumulative Effects	9-14
9.9	Remedial Measures	9-14
9.10	Summary and Conclusions	9-14
9.11	References	9-15
10.0	LANDSCAPE AND VISUAL	10-1
10.1	Introduction	10-1
10.2	Methodology	10-1
10.3	Receiving Environment	10-10
10.4	Development which has Occurred	10-22
10.5	Assessment of Effects	10-23
10.6	Mitigation	10-33
11.0	TRAFFIC & TRANSPORTATION	11-1
11.1	Introduction	11-1
11.2	Description of Development	11-2
11.3	Methodology	11-2
11.4	Primary Sources of Information	11-2
11.5	Receiving Environment	11-3
11.6	Trip Distribution	11-6
11.7	Road Impact	11-6
11.8	Mitigation Measures	11-10
11.9	Access for People with Disabilities	11-10
12.0	MATERIAL ASSETS	12-1
12.1	Introduction	12-1
12.2	Legislative Requirements	12-1
12.3	Assessment Methodology and Significance Criteria	12-1
12.4	Baseline	12-5
12.5	Characteristics of the Development	12-7
12.6	Potential Effects	12-8

12.7	Cumulative Impacts.....	12-11
12.8	Remedial Mitigation.....	12-11
12.9	Monitoring	12-11
12.10	Residual Effects	12-11
12.11	Difficulties Encountered	12-11
13.0	INTERACTIONS AND INTER-RELATIONSHIPS	13-1
13.1	Introduction	13-1
13.2	Methodology.....	13-2
13.3	Conclusions.....	13-6

List of Appendices

Appendix 1.1	Order of An Bord Pleanála ABP-307472-20 9 July 2021
Appendix 4.1	O'Donnell (March 2022) Walkover Survey Report
Appendix 7.1	Dust Assessment
Appendix 9.1	Cultural Heritage Gazetteer
Appendix 10.1	Concept Restoration Plan
Appendix 11.1	Detailed Results of Traffic Survey
Appendix 11.2	Percentage of Development Traffic at each Junction
Appendix 11.3	Detailed Junction Capacity Analysis