



NOTES

- 1. Base Mapping: OpenStreetMap © (www.openstreetmap.org/copyright)
- 2. CYAL50316488
- © Ordnance Survey Ireland/Government of Ireland.

LEGEND

- ED2/ED3/ED4 - Spoil and bare ground, recolonising bare ground, active quarries and mines
- FW4 - Drainage ditches
- GA1 - Improved agricultural grassland
- GS1 - Dry calcareous and neutral grassland
- GS4 - Wet grassland
- Potential Sand Martin Nests
- Stradone site outline
- WD1 - (Mixed) broadleaved woodland
- WL1 - Hedgerows
- WL2 - Treelines
- WS1 - Scrub

SLR SLR CONSULTING
 7 DUNDRUM BUSINESS PARK
 WINDY ARBOUR
 D14 N2Y7
 T +353 (0)1296 4667
 www.slrconsulting.com

P&S CIVIL WORKS LTD.
ENVIRONMENTAL IMPACT ASSESSMENT REPORT
**QUARRY AT MULLYMAGOWAN,
 STRADONE, CO. CAVAN**

HABITAT MAP

FIGURE 5-2

Scale 1:50000 @ A3	Date FEBRUARY 2023
-----------------------	-----------------------

SLR Projects\904200 P&S Civil Works\064821 Stradone EIA\05 Biodiversity