

## **SURFACE WATER SAMPLING FIELD RECORD SHEET**

Site location: Stradone, Co. Cavan **SLR job number:** 501.064821.00001

Date: 22/11/2022 **Time:** 09:30am – 2pm Staff: Orlaith Tyrrell

Equipment: Aquatroll probe, Scoop

	QV1 (Quarry Void)	SW1 (Discharge Point)
Temperature (°C)	9.70	7.62
Dissolved oxygen (%)	94.39	100.90
Dissolved oxygen (mg/l)	10.27	11.59
Specific conductivity (μS/cm)	1237.6	466.4381
Conductivity (μS/cm)	875.96	311.626
рН	8.25	7.94
pHmv	-65.706	-49.05

Odour	No	No
Sheen	No	No
Silt	No	No
Colour	Clear	Clear/slight yellow



	QV1 (Quarry Void)	SW1 (Discharge Point)
Free product	No	No

## Any other field observations:

**SW1:** Sample taken slightly upstream of mapped discharge point (c. 20m) due to accessibility issues at location (oversaturated and sloped ground). No odour from the sample/stream itself, but mild smell of manure from cattle fields with run-off from fields going to the stream.